

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18003664/K1tbn2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 02-03-2018	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGV 7511Y	Veh. Inspected	SH 7441Y	
Policy No.	5091479234	Coverage (\$)	0.00	
Claim No.	MT/0983124-002	Excess (\$)	0.00	
Assign From		Assign Date	21/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI SONATA	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	KMHET41VMBA807319	Colour	BLUE	
Odometer	306851	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	MAXXIS	7 mm	
L/H Front Tyre	215/60 R16	MAXXIS	7 mm	
R/H Rear Tyre	215/60 R16	MAXXIS	7 mm	
L/H Rear Tyre	215/60 R16	MAXXIS	7 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	21/02/2018	Inspection Date	21/02/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days			