

ASS. REC. BY:

REF: CS/AWA18063692/11rd367 Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Tan Kah Leong of AWAC Date/Time: 26/2/18 @ 11:05am

Estimated Cost: Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLT 30642 Insured: GBG 6648Gat Workshop m/s Cycle & Carriage Industries Tel: 9186 5112of 188 Pandan loopPolicy No: BVCP SB089941700 Claim No: GBG 6648G / BT

Sum Insured: Excess:

Make of Veh: D.O.A. 22/2/18
(Client's Record)

CA / REV / REP. / REV 24 HRS 'w/p'

H.O.D. Endorsement:

Date/Time: 11:11am @ 26/2/18 Person Contacted: Alan Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLT 30642 - X</u>
	<u>GBG 6648G - X</u>
	Confirm <u>\$2841.22, 3 days (Red: \$2423.42, 46%)</u>

Signature

Tamper

REF: AWA

ASSIGNMENT

From: _____ Date: 12032018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLT 3064Z

at Workshop m/s Cycle & Carriage

of 188 Pandan Loop

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Flon

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLT 3064Z Yr Regn: 2017 / Oct

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz GLC200 c.c. 1991

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 11316 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDC 2539422 F311117

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235 / 60 R18

R: 27

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 12/5/18 R350

Survey held at C&C Pandan Loop

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 26 SEP 2018

Date/Time. File Pass to?

☐

: Preli. Report

1) Input

☒

: Final Report

Date/Time. File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: -

Survey Fee:

Transportation:

Report Format: TP

Lump Sum / I.B.I. (\$) 2841.22

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RS. \$

) Photos

) Others

TOTAL

200

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA18003692/T1rd3

(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Date : 27-02-2018



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 6648G	Veh. Inspected	SLT 3064Z
Policy No.	BVCPSPB0089941700	Coverage (\$)	0.00
Claim No.	GBG 6648G/BT	Excess (\$)	0.00
Assign From	TAN KAH LEONG	Assign Date	27/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/02/2018	Inspection Date
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Nivitha (LKK Auto)

From: Tan, KahLeong <KahLeong.Tan@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Monday, 26 February 2018 11:05 AM
To: 'assignments'
Cc: sur@lkkauto.com; Alan Quek Ai Lun
Subject: TP Survey assignment for SLT 3064Z - DOA: 22/02/2018 Our ref: GBG 6648G/BT

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us **do** have consensus in the appointment of **Mr Mohammed Rasul** as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	SLT 3064 Z
Insured Vehicle	:	GBG 6648 G
Policy Number	:	BVCPSB0089941700
Name of Workshop	:	Cycle & Carriage Industries Pte Ltd
Contact Number	:	6771 4377 / 9186 5112
Person to Contact	:	Alan Quek
Estimated Cost of repairs	:	\$ 5,633.16

Regards,
Claims Division

Copy to { Cycle & Carriage Industries Pte Ltd via Email

Note -

- (x)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
 2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
 3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
 4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards
Motor Claims
Claims Group
Global Market

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/02/2018 13:20
Date Of Accident	22/02/2018 16:00
Exact Location Of Accident	ANG MO KIO / LORONG CHUAN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT3064Z
Insured/Policyholder	
Name Of Registered Owner	TAN WOON KUAN
NRIC No	S6870976H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92718928
Alternative Phone No	OFFICE-92718928

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	GLC200
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700067224
Cover Note Number	

Driver

Name of Driver	TAN WOON KUAN
NRIC No	S6870976H
Date Of Birth	17/02/1968
Occupation	INDOOR
Date Of Driving Pass	29/05/1996
Driving Experience	21 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92718928
Fax Number	
Contact Number	OFFICE-92718928
Email Address	NOEMAIL

Address	754 BEDOK RESERVOIR ROAD #15-11
Postcode	479258
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY CAR (SLT3064Z) COME TO A COMPLETE STOP AT TRAFFIC LIGHT JUNCTION. ALL OF SUDDEN, CAR B (GBG6648G) COLLIDED MY REAR. NO ONE WAS INJURE AND WE EXCHANGE PARTICULAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG6648G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ALIMAH BINTE ABDUL KADER
NRIC/Passport Number	
Contact Number	92712470
Address	
Postcode	
Insurance Company Name	ALLIED WORLD ASSURANCE COMPANY, LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time



Reporting Centre Personnel's
Name: Alan Quak
NRIC/FIN No.:

SKETCH PLAN



(A) SLT 30642

(B) GBG 66486

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

'A' vehicle come to a complete stop at traffic light
Junction. All of sudden 'B' vehicle collided my rear.
No one was injure and we exchange particular.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's
Name: Alan Quek
NRIC/FIN No.:



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLT3064Z

ALLIED WORLD ASSURANCE COMPANY, L

MOTOR CLAIM DEPARTMENT
60 ANSON ROAD #09-01
MAPLETREE ANSON
SINGAPORE 079914
62201188Main

Vehicle & Document Information

WIP No **21520**
Reg No/Reg Date **SLT3064Z / 25/10/2017**
Date In/Mileage **/ 0**
Chassis No **WDC2539422F311117**
Engine No **27492031160359**
Make/Model **MB/MB GLC 200 SUV (X253)**
Colour/Trim **029 992 Selenite Gr/ 041 101 ARTICO Blac**

Account No	Terms	Date/Time Printed	CSE	Operator
WA000179	Credit	26/02/2018/ 09:28	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :1700067224 // 22-02-2018 DRIVE IN:23-02-2018 // TP CAR NO:GBG6648G (ALLIED WORLD ASSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
A BPILAB REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.			960	1440.00
A BPIRES RESPRAY REAR BUMPER			600	720.00
M REAR BUMPER	1.00	830.87	00.00	830.87
M REAR BOTTOM TRIM PANEL	1.00	471.35	00.00	471.35
M REAR BOTTOM PANEL CHROME	1.00	429.87	00.00	429.87
M CT/R PARKING SENSOR	1.00	172.07	00.00	172.07
M CT/R PARKING SENSOR SEAL	1.00	6.42	00.00	6.42
M CT/R BASIC MOUNTING FOR BUMPER	1.00	126.42	00.00	126.42
M REAR CROSS MEMBER	1.00	687.64	00.00	687.64

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Tanpin 92495749
12/3/18 @ 13:50
Resurvey new parts
sup @ kkanat.com
3 days

Confirmed & accepted by
Insurance Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Authorized signatory and company stamp

No illegal modification(s) is allowed

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Signature:



CYCLE & CARRIAGE

WE DRIVE FIRST CLASS

Nett 5,264.64
7% GST on 5264.64 368.52
Total Payable 5,633.16

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLT3064Z

ALLIED WORLD ASSURANCE COMPANY, L

MOTOR CLAIM DEPARTMENT
60 ANSON ROAD #09-01
MAPLETREE ANSON
SINGAPORE 079914
62201188Main

Vehicle & Document Information
WIP No 21520
Reg No/Reg Date SLT3064Z / 25/10/2017
Date In/Mileage 12/03/2018/ 11316
Chassis No WDC2539422F31117
Engine No 27492031160359
Make/Model MB/MB GLC 200 SUV (X253)
Colour/Trim 029 992 Selenite Gr/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator					
WA000179	Credit	23/05/2018/ 15:33	AQ	383 / Cheong Chin Leong					
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
H. BPNSUN									
POLICY NO/ACC DATE :1700067224 // 22-02-2018									
DRIVE IN:23-02-2018 // TP CAR NO:GB66648G (ALLIED WORLD ASSURANCE)									
DATE IN/DATE SURVEY:12-03-2018 // LKK TAUFIKH									
TP DIRECT SETTLEMENT // BEN TANG- 5-3-18- ALLIED WORLD ASS									
A BPILAB							0.10	380.00	
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT									
A BPILAB								960.00	
REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.									
A BPIRES								600.00	
RESPRAY REAR BUMPER									
X	REAR BOTTOM TRIM PANEL				1.00	471.35	00.00	471.35	
X	REAR BOTTOM PANEL CHROME				1.00	429.87	00.00	429.87	

Finalization

Confirmed & accepted by

7% GST on **Nett** 2,841.22
198.89

Authorized signatory and company stamp

Total Payable 3,040.11

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD		Ref : CS/AWA18003692/T1rd3e2		
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Date : 17-10-2018		
Code : AWA				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 6648G	Veh. Inspected	SLT 3064Z	
Policy No.	BVCPSPB0089941700	Coverage (\$)	0.00	
Claim No.	GBG 6648G/BT	Excess (\$)	0.00	
Assign From	TAN KAH LEONG	Assign Date	26/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ GLC200	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WDC2539422F311117	Colour	GREY	
Odometer	11316	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/60 R18	PIRELLI	6 mm	
L/H Front Tyre	235/60 R18	PIRELLI	6 mm	
R/H Rear Tyre	235/60 R18	PIRELLI	6 mm	
L/H Rear Tyre	235/60 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/02/2018	Inspection Date	12/03/2018	
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 3064Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOTTOM TRIM PANEL (SN)	DEFORMED	471.35	471.35
1	REAR BOTTOM PANEL CHROME (SN)	CUT	429.87	429.87
1	CT/R PARKING SENSOR (SN)	NOT NECESSARY	172.07	-
1	CT/R PARKING SENSOR SEAL (SN)	NOT NECESSARY	6.42	-
1	CT/R BASIC MOUNTING FOR BUMPER (SN)	NOT NECESSARY	126.42	-
1	REAR CROSS MEMBER (SN)	NOT NECESSARY	687.64	-
1	REAR BUMPER (SN)	TO REPAIR SEE LABOUR	830.87	-
			2,724.64	901.22
	LABOUR			
	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.		380.00	380.00
	REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		1,440.00	960.00
	RESPRAY REAR BUMPER.		720.00	600.00
			2,540.00	1,940.00
	GRAND TOTAL		5,264.64	2,841.22
	RECOMMENDED COST OF REPAIRS			2,841.22

Report Ref No. CS/AWA18003692/T1rd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.