

ASS. REC. BY:

REF: CS/C7118603716/Svd327

Special Instruction:

Surveyor:
Merimen

Sebastian

ASSIGNMENT (Office)

From (Person):

joel Goh

of

C71

Date/Time:

27/2/18 @ 11:41am

Estimated Cost:

Bill to:

OBY TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 8708B

Insured:

at Workshop m/s

SMRT

Tel:

68662628

6555 5556

of

60 woodlands Ind. Prk E4

68581234

Policy No:

DMP SN 3076671701

Claim No:

SNM18D00938C01

64691234

Sum Insured:

Excess:

\$250.00

Susan

Make of Veh:

(Client's Record)

D.O.A

15/02/2018

CA / (REV)

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:45am @ 27/2/18

Person Contacted:

Vehicle IN OUT

Date/Time	Action/Instruction
	() Estimate
	SJR 8708B - NA / C7118603250 / 21
	N.O.A: 15/2/18
1/3/18	Revert by merimen, est LS \$9000
2/3/18	Rec ppm \$5900 from Susan by merimen
2/3/18	@ 330pm Eddie said to authorise on the front portion first
2/3/18	Informed Susan cla ex 250 (except RH front portion, & under carriage)

REF:

28581254

Jensen

ASSIGNMENT

Form: _____ Date: _____

Estimated Cost: _____

CD / TR / WS / TR RES / CO RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop No: _____

/

Insurance: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.

Bal or Market Value: 31k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Sent: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJR 87083 Vr Regn: 25/11/2009Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Toyota Camry G.S. 1978Colour: Silver A/C: ☒ Insured / ☐ Std / ☐ Nil / ☐ NASp. Reading: 145041 T/Radio: ☒ Insured / ☐ Std / ☐ Nil / ☐ NA

Eng No: _____

C/No: MR053 BK 4107049767Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ BurntSteering: ☒ In Order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In Order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ S/Rim / ☐ STD A/Rim orTyre Size: F: 215/60R16R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front: _____ Rear: _____

F/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 15 1/2 / 18 D.O.I. 27 1/2 / 18Survey held at Carz AutoDes. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop orFrt, O/S, Pvt

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time / Action / Instruction

3/5/18 LS \$ 5050 confirmed by email (Ref 8013-50, 619)

RECEIVED 7 MAY 2018

Date/Time File Pass to:

☐ : Prel. Report☐ : Final Report

Date/Time File Return to:

3/5 - typist

Report Format:

Lump Sum / I.B.I. / S

merimen

5050

Days Of Repair: 8Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ _____) \$ + RS. _____☐ : Interview (\$ _____) Phone _____☐ : Tech. Invs (\$ _____) Other _____☐ : Weekend (\$ _____)

TOTAL

Survey Fee:

Transportation:

220220

Survey Department Check List (Case Handler)

Reference No. : CS/CTI 1800 3716 Svd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 3/5/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18003716/Svd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 27-02-2018



Code : CTI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SJR 8708B
Policy No.	DMPCSN3076671701	Coverage (\$)	0.00
Claim No.	SNM18D00938C01	Excess (\$)	250.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	27/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	15/02/2018	Inspection Date	27/02/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Feb 2018 Sendback Est	26 Feb 2018 14:06 \$13,068.50	27 Feb 2018 11:41 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	TAN PENG YIAM, ID: S1549113B		
Vehicle Reg. No.:	SJR8708B	Date of Loss:	15/02/2018 00:00 - :59
Claim Type:	OD / SNM18D00938C01	Policy/Cover Note No.:	DMPCSN3076671701 (Comprehensive)
		Excess:	S\$250.00
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/03/2018]		
Driver/Custodian:	TAN PENG YIAM (/ Male), NRIC: S1549113B		
Adj Asg. Remarks:	OD SURVEY AND REVERT. EXCESS \$250.00 AFTER WAIVER		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ☐

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 2 March 2018 4:52 PM
To: Susan Tan Soh Chern (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Cc: SUR
Subject: SJR 8708B-DOA: 15/2/2018 (CHINA TAIPING OD)
Attachments: REVISED EST (CHINA TAIPING).pdf

Dear Susan,

As instructed by our client , please proceed to repair the insured vehicle **SJR 8708B (Excess \$250/-), Except RH front portion and undercarriage.**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Please refer adjust revised from China TaiPing.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SJR8708B (SNM18D00938C01)

OD

Feb 15 2018 12:00AM

[TAN PENG YIAM]

SMRT Automotive Services Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 02/03/2018 14:12 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$5900.00) - SJR8708B - Claim Handler: Joel Goh

Approved:5900.00:damages not consistent to accident damage

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Joel Goh	Date:	01 Mar 2018

Preliminary Advice

Vehicle No	: SJR8708B	Accident Date	: 15/02/2018
Make	: TOYOTA CAMRY	Policy No.	: DMPCSN3076671701
Assignment Date	: 27/02/2018	Excess	: S\$250.00
Date of Inspection	: 27/02/2018	Est. Duration of Repair	: 8.00
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS) 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,063.50
Revised Amount	:S\$	9,178.02
Check Items (Estimated)	:S\$	2,097.98
Total	:S\$	11,276.00

Lump Sum Repair (Estimated)	:S\$	9,000.00
-----------------------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	31,000.00
COE / PARF Rebate	:S\$	18,385.00
Salvage Value	:S\$	
Margin for Repair	:S\$	12,615.00

Brake System	: In Order
Steering System	: In Order
Tyre Condition (Front)	: 6/6 mm
Tyre Condition (Rear)	: 6/6 mm

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

3/1/2018

Rich Text Editor, SVCDOCtrcontent

Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 9113B

Vehicle Details

Vehicle No.: SJR8708B
Vehicle to be Exported: No
Intended De-registration Date: 22 Feb 2018
Vehicle Make: TOYOTA
Vehicle Model: CAMRY 2.0 AUTO ABS AIRBAG
Primary Colour: Silver
Manufacturing Year: 2009
Engine No.: 1AZE149757
Chassis No.: MR053BK4107049767
Maximum Power Output: 108.0 kW (144 bhp)
Open Market Value: \$27,271.00
Original Registration Date: 25 Nov 2009
First Registration Date: 25 Nov 2009
Transfer Count: 1
Actual ARF Paid: \$27,271.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 24 Nov 2019
PARF Rebate Amount: \$14,999.00

Intended COE Rebate Details

COE Expiry Date: 24 Nov 2019
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$19,830.00
COE Rebate Amount: \$3,386.00
Total Rebate Amount: \$18,385.00

The information contained herein is correct as at 22 Feb 2018

OK



SELL USED CAR PARTS
& ACCESSORIES *online!*



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Year Coe Renewal Toyota Vios 1.5A



\$2500 Downpayment Monthly
From \$580 Onwards. Lowest
3.68%P.A@GV Cars Financing.
GV Credit Pte Ltd StarAd



**Lake View
Credit Pte Ltd**

[view our cars](#)

- Low prices guaranteed
- Specialist in Japanese cars
- Easy loan approval
- All terms are negotiable

Browse by Category

Sort by Date Posted 80 results/page

14 vehicles

Camry 2.0A

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Camry 2.0A	Any	Any	2009	Any	Any	Any	Available
	Toyota Camry 2.0A	\$28,800	\$9,680 /yr	23-Sep-2009	1,998 cc	140,000 km	Luxury	Available
100% Cheapest In The Market! No Gimmicks. Powerful And Responsive. Well Maintained By Previous Owner. Genuine Mileage. Quick Sale! First Come First Serve Basis. We Are A Case Trusted Company, Buy With...								PREMIUM AD
Mayfair Motoring Posted: 26-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota								
	Toyota Camry 2.0A	\$25,800	\$10,020 /yr	27-May-2009	1,998 cc	-	Luxury	Available
Camry 2.0, Black Colour. Quiet And Good Engine. With 4 New Michelin Tyres., New SLV Car Plate, Nice Number. Call To View At Any Location.								OFFER DRIVE
Posted: 26-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota								
	Toyota Camry 2.0A	\$29,800	\$12,420 /yr	26-Jun-2009	1,998 cc	130,000 km	Luxury	Available
1 Owner Only And Well Taken Care Of Regular Servicing And Maintenance! Low Genuine Mileage And Immaculate Bodywork And Interior, No Repairs Needed, Come And View To Believed, Another Pristine Car By O...								PREMIUM AD
Orchard Credit Pte Ltd Posted: 25-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota								
	Toyota Camry 2.0A	\$26,800	\$10,300 /yr	19-Jun-2009	1,998 cc	-	Luxury	Available
Elegant Silver, Spacious Sedan, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-house Loan Packages Available.								
Prime Motor & Leasing Posted: 25 Feb 2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota								
Car Buying	Car Selling	Car Aftermarket						
Car Ownership	On The Move	Lifestyle						
								▶ Buy Tyres Online! ▶ Latest Special Offers From Tyrepack!
	Toyota Camry 2.0A	\$32,800	\$10,910 /yr	01-Dec-2009	1,998 cc	-	Luxury	Available
Accident Free! Very Good Condition! No Repairs Needed! All Trade In Welcome, Major Bank And In House Loan Available! Night And Door Step Viewing Available! Hurry Call Our Friendly Staff To View And Di...								
Posted: 23-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota								
	Toyota Camry 2.0A	\$27,800	\$11,310 /yr	09-Jun-2009	1,998 cc	-	Luxury	Available
Well Kept And Maintained By Previous Owner, Ideal For Short Term Usage, Most Popular Japanese Sedan With Comfortable Legroom, Trade In And Loan Available, Hurry Make An Appt To View This Unit Now.								PREMIUM AD
Lay Auto Pte Ltd Posted: 21-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota								
	Toyota Camry 2.0A	\$31,800	\$10,900 /yr	29-Oct-2009	1,998 cc	119,000 km	Luxury	Available
Low Mileage, Excellent Condition! View To Believe! Hurry! Trade In Welcome, Car Available In Showroom For Viewing Now. Contact For More Details.								
Posted: 13 Feb 2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota								
	Toyota Camry 2.0A	\$25,800	\$9,700 /yr	11-Jun-2009	1,998 cc	-	Luxury	Available
10% Downpayment. \$1,451/mth. Good Condition. Flexible Loan Package. Instant Approval. Ex Bankrupt Welcome. High Trade In.								
Posted: 08-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota								



Toyota Camry 2.0A

\$21,800

\$8,950 /yr

23-Feb-2009

1,998 cc

-

Luxury

Available

Luxurious Yet Fuel Efficient Sedan That Comes Standard With Enormous Boot And Spacious Interior For Your Utmost Comfort. Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awar...

Dickson Automobile

Posted: 05-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.0A

\$28,000

\$11,950 /yr

21-May-2009

1,998 cc

152,500 km

Luxury

Available

100% Accident Free, Very Low Mileage Done! Very Well Maintained By Owner. View To Appreciate! Drive This Pristine Silver Exterior With Beige Camry Worry Free Now! Trade In Are Welcomed. Flexible Loans...

PREMIUM AD

Posted: 20-Jan-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.0A

\$32,000

\$12,010 /yr

09-Sep-2009

1,998 cc

132,846 km

Luxury

Available

Very Well Maintained Car By Fussy Owner. Beautiful Exterior, Clean And Sweet Smelling Interior And Super Smooth Drive.

PREMIUM AD

Posted: 17-Jan-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.0A

\$27,800

\$12,000 /yr

13-May-2009

1,998 cc

-

Luxury

Available

1 Owner Only! Rare Condition! Luxurious Sedan, Well Kept In Superb Condition For You To Drive And Feel The Difference In It! Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding A...

Dickson Automobile

Posted: 05-Jan-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.0A

\$32,700

\$12,340 /yr

15-Sep-2009

1,998 cc

107,000 km

Luxury

Available

Elegant And Stunning Medium Silver! Face Lifted Model! Only 2 Owners! Well Maintained By Meticulous Owner With Low Mileage Done! Zero Modification! Buy With A Peace Of Mind From A Company With 30 Year...

Posted: 05-Jan-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.0A

\$28,800

\$13,660 /yr

27-Apr-2009

1,998 cc

116,188 km

Luxury

Available

Been Owned By A Well Known Actor! Used Mostly Over The Weekends! A Very Affordable, Spacious And Fuel Economy Car At A Low Price! Tip Top Condition, 100% Accident Free! Was Trade In For A Brand New E2...

Car House Pte Ltd

Posted: 27-Dec-2017 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view **Expired ads**

80 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Camry 2.0A, Camry 2.0A Singapore, used Camry 2.0A Singapore, used Camry 2.0A, used vehicles Singapore or even buy used Camry 2.0A Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!


Post an Ad

Advertiser Login

Ways of Selling

2008 Mercedes S Class S350 W221.

Low Mileage And Great Interior
And Exterior.
Direct Owner - StarAd



Browse by Category ▼

« Back (1 2) Next »







Sort by Date Posted ▼

20 results/page ▼

23 vehicles

TOYOTA CAMRY

Advanced Search 🔍

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	TOYOTA CAMRY		Any	Any	2009	Any	Any	Any	Available
	Toyota Camry 2.4A G		\$27,800	\$9,030 /yr	18-Mar-2009	2,362 cc	121,699 km	Luxury	Available
In House Finance With Low Monthly Instalment Of \$554 Available! One Of The Best Japanese Luxury Sedan! Engineered In All Aspect To Comfort, Class And Power. Rear Seat Passengers Will Amazed With The A...									
Speedo Motoring									
Posted: 26-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota									
	Toyota Camry 2.0A		\$28,800	\$9,690 /yr	23-Sep-2009	1,998 cc	140,000 km	Luxury	Available
100% Cheapest In The Market! No Gimmicks. Powerful And Responsive. Well Maintained By Previous Owner. Genuine Mileage. Quick Sale! First Come First Serve Basis. We Are A Case Trusted Company, Buy With...									
Mayfair Motoring									
Posted: 26-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota									
	Toyota Camry 2.4A		\$27,800	\$10,590 /yr	08-Jun-2009	2,362 cc	86,000 km	Luxury	Available
Best Unit To Consider For COE Renewal, Super Low Mileage Of Just 86,000km By 1 Careful Owner, Fully BORNEO MOTOR Service And Maintain, Accident Free, 4 x New Tyres, Absolutely Perfect Undercarriage, N...									
Posted: 26-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota									
	Toyota Camry 2.0A		\$25,800	\$10,040 /yr	27-May-2009	1,998 cc	-	Luxury	Available
Camry 2.0, Black Colour. Quiet And Good Engine, With 4 New Michelin Tyres., New SLV Car Plate, Nice Number. Call To View At Any Location.									
Posted: 26-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota									
<div>Car Buying</div> <div>Car Ownership</div> <div>Car Selling</div> <div>On The Move</div> <div>Car Aftermarket</div> <div>Lifestyle</div> <div>Buying a pre-owned car, but Unsure of its Condition? Get. STA Car Evaluation</div>									
	Toyota Camry 2.0A		\$29,800	\$12,450 /yr	26-Jun-2009	1,998 cc	130,000 km	Luxury	Available
1 Owner Only And Well Taken Care Of Regular Servicing And Maintenance! Low Genuine Mileage And Immaculate Bodywork And Interior, No Repairs Needed, Come And View To Believed, Another Pristine Car By O...									
Orchard Credit Pte Ltd									
Posted: 25-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota									
	Toyota Camry 2.0A		\$26,800	\$10,320 /yr	19-Jun-2009	1,998 cc	-	Luxury	Available
Elegant Silver, Spacious Sedan, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-house Loan Packages Available.									
Prime Motor & Leasing									
Posted: 25-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota									

Compare



Toyota Camry 2.4A G **\$28,500** \$12,460 /yr 16-Jun-2009 2,362 cc 142,000 km Luxury **Available**

100% Accident Free. Car In Excellent Conditions, No Repair Cost Needed. Call/SMS Now For Viewing Appointment

Think One Automobile & Trading

Posted: 25-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.4A **\$33,888** \$10,630 /yr 22-Dec-2009 2,362 cc - Luxury **Available**

Facelifted Unit. Cheapest In Town. 1 Owner. Full Service History By Borneo Motors. No Repair Or Touch Up Needed. Call For Viewing Now.

Posted: 23-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.0A **\$32,800** \$10,930 /yr 01-Dec-2009 1,998 cc - Luxury **Available**

Accident Free! Very Good Condition! No Repairs Needed! All Trade In Welcome, Major Bank And In House Loan Available! Night And Door Step Viewing Available! Hurry Call Our Friendly Staff To View And Di...

Posted: 23-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.0A **\$27,800** \$11,330 /yr 09-Jun-2009 1,998 cc - Luxury **Available**

Well Kept And Maintained By Previous Owner, Ideal For Short Term Useage, Most Popular Japanese Sedan With Comfortable Legroom, Trade In And Loan Available, Hurry Make An Appt To View This Unit Now.

Lay Auto Pte Ltd

Posted: 21-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.4A G **\$26,800** \$14,050 /yr 26-Feb-2009 2,362 cc 130,000 km Luxury **Available**

Reliable Japanese Luxury Sedan, Well Maintained, Excellent Condition! Minimum Down Payment With Bank Or In House Loan Available. Call For More Enquiries!

Posted: 16-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.0A **\$31,800** \$10,920 /yr 29-Oct-2009 1,998 cc 119,000 km Luxury **Available**

Low Mileage, Excellent Condition! View To Believe! Hurry! Trade In Welcome, Car Available In Showroom For Viewing Now. Contact For More Details.

Posted: 13-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.4A **\$24,800** \$11,180 /yr 19-Feb-2009 2,362 cc - Luxury **Available**

Low Deprecation At Only \$10k Per Year For A 2.4L Camry, Road Tax Renewed, Well Taken Care By Previous Family Owner, Regular Servicing Has Been Done To Ensure Reliability For This Camry, Perfect White P...

Wheeler Dealers LLP

Posted: 11-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.0A **\$25,800** \$9,720 /yr 11-Jun-2009 1,998 cc - Luxury **Available**

10% Downpayment. \$1,451/mth. Good Condition. Flexible Loan Package. Instant Approval, Ex Bankrupt Welcome. High Trade In.

Posted: 08-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.0A **\$21,800** \$8,970 /yr 23-Feb-2009 1,998 cc - Luxury **Available**

Luxurious Yet Fuel Efficient Sedan That Comes Standard With Enormous Boot And Spacious Interior For Your Utmost Comfort. Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awar...

Dickson Automobile

Posted: 05-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.4A G **\$23,777** \$10,470 /yr 24-Apr-2009 2,362 cc 90,126 km Luxury **Available**

Cheapest In Town. Car In Full Working Condition, View To Believe. Low Price, Best Condition. Wait No More. Call To View Now!

Posted: 04-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.4A **\$34,800** \$16,450 /yr 29-May-2009 2,362 cc - Luxury **Available**

Price To Go! Sold As It Is, Full Service Done By Borneo. Call Us For Viewing Appointment.

Posted: 24-Jan-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota

**Toyota Camry 2.0A****\$28,000**

\$11,980 /yr

21-May-2009

1,998 cc

152,500 km


Luxury

Available

100% Accident Free, Very Low Mileage Done! Very Well Maintained By Owner. View To Appreciate! Drive This Pristine Silver Exterior With Beige Camry Worry Free Now! Trade In Are Welcomed. Flexible Loans...

PREMIUM AD

Posted: 20-Jan-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota

**Toyota Camry 2.4A****\$24,700**

\$10,240 /yr

20-Mar-2009

2,362 cc

136,000 km

Luxury

Available

Beautifully Kept Interior/Engine/Body, Very Well Maintain. Lowest Depreciation In Market. In House Loan 10% Down Payment Avail. Balloon Scheme Monthly \$700 Only. View This Black Beauty Fast. 1 Year Wa...

Posted: 15-Jan-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota

**Toyota Camry 2.0A****\$32,000**

\$12,030 /yr

09-Sep-2009

1,998 cc

132,846 km

Luxury

Available

Very Well Maintained Car By Fussy Owner. Beautiful Exterior, Clean And Sweet Smelling Interior And Super Smooth Drive.

DIRECT OWNER

Posted: 12-Jan-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view **Expired ads**

« Back (1 2) Next »

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used TOYOTA CAMRY, TOYOTA CAMRY Singapore, used TOYOTA CAMRY Singapore, used TOYOTA CAMRY, used vehicles Singapore or even buy used TOYOTA CAMRY Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/02/2018 20:39
Date Of Accident	15/02/2018 09:30
Exact Location Of Accident	SIN MENG AVE TWDS BISHAN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR8708B
Insured/Policyholder	
Name Of Registered Owner	TAN PENG YIAM
NRIC No	S1549113B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81212655
Alternative Phone No	OFFICE-81212655
Vehicle Particulars	
Manufacturer	TOYOTA
Model	CAMRY 2.0 AUTO ABS AIRBAG
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3076671701
Cover Note Number	
Driver	
Name of Driver	TAN PENG YIAM
NRIC No	S1549113B
Date Of Birth	30/09/1962
Occupation	INDOOR
Date Of Driving Pass	23/05/1994
Driving Experience	23 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81212655
Fax Number	
Contact Number	OFFICE-81212655
EMail Address	NOEMAIL

Address BLK 504A YISHUN STREET 51
#04-84
Postcode 761504
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 4
Passenger 1
NAME: : -
GENDER: : FEMALE
Passenger 2
NAME: : -
GENDER: : FEMALE
Passenger 3
NAME: : -
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SH3388U
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver
NRIC/Passport Number
Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. My acceptance of this report to the insurers also hereby consent to the archiving of this report at the centre and to copies of the report being made available if/when so.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/ authority (such as the police) for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/ mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in the accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

24/

Policyholder's Signature
Date & Time

24/

Driver's Signature
If driver is not the policyholder
Date & Time

24/

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.

Accident Sketch Plan

SKETCH PLAN



Vehicle A is 1987 Honda Civic


Vehicle B is 1987 Honda Civic


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was travelling along the road and was stopped on the left lane. While I was travelling straight I was distracted and being aware that vehicle B was stationary, I was unable to stop in time and hit the vehicle B from behind.

DECLARATION

We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time


Driver's Signature
If driver is not the policyholder
Date & Time


Reporting Centre Person's Signature
Name
NRCCPIN No

MODERN AUTOMOTIVE SERVICES PTE LTD

E9 PREMIUM WOODLANDS
61 WOODLANDS INDUSTRIAL PARK E9 #01-23
SINGAPORE 757047

Tel : (65) 6368 1342

Fax : (65) 6368 3102

Hotline : (65) 8360 1313

Website : www.moderntyres.com.sg

Operation Hours : Mon - Sat (9am - 8pm)

Servicing - Repair - Tyre - Rim - Battery - Balancing & Alignment

Work Order: SJR8708B
Date 23.2.18 12:57

Toyota : Camry (South Africa) : 2001-06

Front : Left

Actual	BEFORE	Specified Range
-1°42'		-1°20' 0°10'
		1°28' 2°58'
0°03'		-0°05' 0°05'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°50'		-1°20' 0°10'
		1°28' 2°58'
0°50'		-0°05' 0°05'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-0°52'		
0°52'		-0°09' 0°09'

Rear : Left

Actual	BEFORE	Specified Range
-0°55'		-1°25' 0°05'
0°14'		0°05' 0°14'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°54'		-1°25' 0°05'
0°11'		0°05' 0°14'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
0°59'		
0°25'		0°09' 0°28'
0°02'		

**SMRT AUTOMOTIVE
SERVICES PTE LTD
60 WOODLANDS
INDUSTRIAL PARK E4
757705**

Claim Reference: MAC/FEB2018/001
Assessment Number: CTI10129
Version: SMRTAUTO/3
Date Calculated: 26/02/2018 03:33

Full Report - V1
Registration: SJR8708B
Printed: 26/02/2018 11:35

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Eng Hock Peh	Date of Incident:	15/02/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	MAC/FEB2018/001	Estimated Repair Time:	10 day(s)
Policy Number:	DMPCSN3076671701	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Camry
Sub Model:	BASE MODEL
Model Sheet Number:	YCA 01
Registration:	SJR8708B
Registration Month:	November
Registration Year:	2009
VIN Number:	MR053BK4107049767
Manufacture Year:	2009
Odometer:	145040
Colour:	Green
Engine Number:	1AZE149757
Fuel Level:	90%


Model Specs

FROM 12/2009	AUTO AIR CON
CHROME DOOR HANDLES	S/MOULDING CHROMED
MIRROR W/NDICATOR	2COMP GLASS ADHESIVE
RADIO WITH CD	REARVIEW CAMERA
FOG LAMPS	EXHAUST TRIM CHROMED
PARKING BRAKE FOOT	LEATHER SEATS
S-WHEEL RADIO CONT	ANTI THEFT ALARM
LEATHER/WOOD S-WHEEL	RR PARK DIST CONTROL
2.0 LTR 108 KW	4-SPEED AUTOMATIC
ELECT POWER STEERING	CRUISE CONTROL
TYRES 215/60 YR 16	WHEELS 6.5J X 16 ALU
VERSION THAILAND	PRODUCT THAILAND
PREPARE OFF VEHICLE	TWO COAT PEARL/MICA

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	Light Structural
Steering:	Vehicle Status on	Unroadworthy
	Inspection:	Mobile
Brakes Pedal Travel:	Date of Inspection:	18/01/2018
Place of Inspection:	Assessor	
Pre-Accident Damage:		
Tyres Condition:	Fair	
Tread Depth LHF:		Tread Depth RHF:
Tread Depth LHR:		Tread Depth RHR:
Damage Areas:		Direction of Impact:

SMRT AUTOMOTIVE SERVICES PTE LTD**Claim Reference: MAC/FEB2018/001****Full Report - V1****Assessment Number: CTI10129****Registration: SJR8708B****Version: SMRTAUTO/3****Printed: 26/02/2018 11:35****Date Calculated: 26/02/2018 03:33**

Primary Impact

Secondary Impact

Addresses**Cost Summary**

Total Labour	\$3,247.60
Total Paint/Material	\$300.23
Total Parts	\$9,515.67
Excess:	TBA
Grand Total Exc GST:	\$13,063.50
7 % GST:	\$914.45
Grand Total Inc GST:	\$13,977.95

Repair Information**LABOUR****Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR****Price/Dent = \$46.00/HR****Repair /**

Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	DIAGNOSIS WITHOUT CHASSIS JIG	2.0	9.20
NO NUMBER	CONVERT CHASSIS JIG	10.0	46.00
043233C	ADD: ADJUST FRONT TOE	1.0	4.60
043233	ALIGN VEHICLE CPL	12.0	55.20
043233D	ADJUST FRONT CAMBER (ADD/WORK)	5.0	23.00
043233F	ADD: ADJUST REAR TOE	2.0	9.20
M030ZAX	R + R L/F AXLE HALF (ADD/WORK)	11.0	50.60
NO NUMBER	R + R ENGINE WITH GEARBOX	4.0	18.40
B140	RENEW FRONT PANEL	22.0	101.20
NO NUMBER	RENEW R/R LOWER SIDEMEMBER	36.0	165.60
B170)	RENEW R/F SIDE MEMBER	23.0	105.80
B110	RENEW L/FRT WING	5.0	23.00
	(FRT BUMPER AND L/HEADLAMP ASSY REMOVED)		
B110	RENEW R/FRT WING	5.0	23.00
	(FRT BUMPER AND R/HEADLAMP ASSY REMOVED)		
B100	R + R LEFT SILL RAIL	3.0	13.80
B100	R + R RIGHT SILL RAIL	3.0	13.80
B020	RENEW FRONT BUMPER	15.0	69.00
	INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS		
B040	RENEW BOTH HEADLAMPS	7.0	32.20
	(BUMPER REMOVED)		
	INCLUDES: ADJUST HEADLAMPS		

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: MAC/FEB2018/001

Assessment Number: CTI10129

Version: SMRTAUTO/3

Date Calculated: 26/02/2018 03:33

Full Report - V1

Registration: SJR8708B

Printed: 26/02/2018 11:35

B070	RENEW BONNET	6.0	27.60
B080	R + R BONNET HINGES	1.0	4.60
530121)	R + R BONNET OPENER CABLE	2.0	9.20
190011	R + R BATTERY	3.0	13.80
851091)	R + R WASHER RESERVOIR	4.0	18.40
851061	R + R WASHER NOZZLES	2.0	9.20
B085)	R + R WATER BOX CLOSING PANEL	4.0	18.40
M010)	RENEW CONDENSER (REMOVED)	1.0	4.60
883401)	R + R AIR CONDITIONING COMPRESSOR	1.0	4.60
NO NUMBER	R + R AIR CONDITIONING PIPE	4.0	18.40
NO NUMBER	R + R AIR CONDITIONING PIPE	5.0	23.00
NO NUMBER	R + R AIR CONDITIONING HOSE	4.0	18.40
NO NUMBER	R + R ENGINE ROOM WIRING	19.0	87.40
NO NUMBER	R + R ENGINE WIRING	10.0	46.00
895011	R + R ENGINE CONTROL UNIT	3.0	13.80
NO NUMBER	R + R FAN RELAY	2.0	9.20
M010	R + R RADIATOR AND CONDENSER (FRONT BUMPER REMOVED)	16.0	73.60
	INCLUDES: BLEED COOLING SYSTEM		
M010)	RENEW RADIATOR	3.0	13.80
160111)	R + R LOWER RADIATOR HOSE	2.0	9.20
160101)	R + R UPPER RADIATOR HOSE	2.0	9.20
NO NUMBER	R + R ENGINE COVER	1.0	4.60
NO NUMBER	R + R AIR FILTER HOSE	1.0	4.60
160251)	R + R DRIVE BELT	2.0	9.20
271011)	R + R ALTERNATOR	2.0	9.20
444401)	R + R POWER STEERING	6.0	27.60
	INCLUDES: BLEED POWER STEERING		
420091)	R + R R/F WHEEL/TYRE	3.0	13.80
473011)	R + R L/FRT BRAKE DISC	1.0	4.60
473011A)	R + R FRONT BRAKE DISC/S	2.0	9.20
896081)	R + R R/F ABS SENSOR	1.0	4.60
NO NUMBER	R + R R/R AXLE CARRIER BRACKET	2.0	9.20
NN	LIQUID GAS SYSTEM R&R / NEW PARTS	10.0*	46.00
0250	VEHICLE TRANSPORT	20.0*	92.00
4475	DRAIN AND REFILL AIR CONDITIONING	30.0*	138.00
9732	REMOVE AND REFIT R/F AXLE HALF	40.0*	184.00
9790	AXLE REMOVED R/F AXLE HALF	40.0*	184.00
9947	ADJUST HEADLAMP	20.0*	92.00
9973	CARRY OUT TEST DRIVE	10.0*	46.00
1117	REPAIR L/F WHEELHOUSE CPL	30.0*	138.00
1118	REPAIR R/F WHEELHOUSE CPL	30.0*	138.00
1124	REPAIR R/F WHEELHOUSE	30.0*	138.00
9831	CHECK ENGINE	10.0*	46.00
9901	ALIGN W/OUT ADJUST COMPL VEH BEFORE REP	30.0*	138.00

LABOUR COST

Total Work Units	581.0	
Panel / Mechanical Labour	53.1HRS	\$2,442.60
Visual Alignment Labour	5.0HRS	\$230.00
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	58.1HRS	\$2,672.60
Paint Labour	12.5HRS	\$575.00

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: MAC/FEB2018/001

Assessment Number: CTI10129

Version: SMRTAUTO/3

Date Calculated: 26/02/2018 03:33

Full Report - V1

Registration: SJR8708B

Printed: 26/02/2018 11:35

Total Labour

70.6HRS

\$3,247.60

PAINT WORK

Guide Number Description

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

WU

Cost Price (\$)

- PREPARE OFF VEHICLE
- TWO COAT PEARL/MICA

471	BONNET NEW PART PAINTING	26.0
741	L/F WING NEW PART PAINTING	10.0
742	R/F WING NEW PART PAINTING	10.0
988	LOCK CARRIER STRUT SURFACE PAINT	4.0
1009	FRONT PANEL SURFACE PAINT	7.0
1208	R/F OUT S-MEMBER PNLSURFACE PAINT	5.0
1214	R/F S-MEMB RR REINF SURFACE PAINT	5.0
283	FRONT BUMPER NEW PART PAINT K1R	13.0
410	GRILLE NEW PART PAINT K1R	3.0
1117	L/F WHEELHOUSE CPL SURFACE PAINT	6.0
1118	R/F WHEELHOUSE CPL SURFACE PAINT	6.0

LABOUR COST - PAINT

TIME(PAINT)

95.0

Preparation Main Work Plastic

5.0

Preparation Main Work Metal

25.0

Preparation Work Multi Layer Paint

0.0

Total Work Units (10WU/HR)

125.0

Total Paintwork Labour

12.5HRS

\$575.00

MATERIAL COST - PAINT

Cost Price

New Part Painting

\$129.00

New Part Painting - Plastic K1R

\$68.39

Material-Constant Main Work Metal

\$28.60

Surface-/Blend Paint

\$65.24

Material-Const Main Work Plastic

\$9.00

Total Excluding Pearlescent Uplift

\$300.23

Pearlescent Uplift @ 0.0%

\$0.00

Total Paint Material Cost

\$300.23

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/06/2015	Bet.	Price (\$)
8391	1	AIR FILTER ASSY ✓ Deform.	17700 0H121	photo ? Δ	0%		225.00*
8389	1	AIR INTAKE HOSE X	17881 0H100		0%		60.00*
8375	1	AIR INTAKE HOSE ✓ Bt	17750 0H070		0%		90.00*
3011	1	BADGE "VVT-I" L ✓ NGC	75443 06260		0%		28.00*
3012	1	BADGE "VVT-I" R ✓ NEC	75443 06540		0%		28.00*
471	1	BONNET ✓ DT	53301 06110		0%		430.00*
527	1	BONNET FRONT SEAL ✓ NEC	53381 06060		0%		38.00*
481	1	BONNET INSULATION ✓ NEC	53341 06160	? X Δ	0%		180.00*
340	1	BUMPER SUPPORT ✓ DT	52021 06060		0%		150.00*
4481	1	COMPR/CONDENSER TUBE ?	88711 06280		0%		48.00*
4482	1	COND/EVAPORATOR PIPE ?	88710 06211		0%		95.00*
4465	1	CONDENSER ✓ DT	88460 06170		0%		380.00*
500	1	CONTROL CABLE ?	53630 06110		0%		45.00*
412	1	CTR BUMPER GRILLE ✓ CRK	53112 06120		0%		85.00*
9585	1	ENGINE COMP HARNESS X	82111 06S60		0%		0.00
9588	1	ENGINE HARNESS X	82121 06A73		0%		0.00

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: MAC/FEB2018/001

Assessment Number: CTI10129

Version: SMRTAUTO/3

Date Calculated: 26/02/2018 03:33

Full Report - V1

Registration: SJR8708B

Printed: 26/02/2018 11:35

7757	1	FAN RELAY 1 ✓ DMG	90987 02027	0%	76.47U
7758	1	FAN RELAY 2 x	90987 04004	0%	59.53U
283	1	FRONT BUMPER ✓ Deform	52119 06960	0%	260.00*
1000	1	FRONT GRILLE EMBLEM ✓ NEC Renew		0%	30.00*
257	1	FRONT NUMBER PLATE ✓ BT KNPL3		0%	35.00*
1009	1	FRONT PANEL ✓ BT	53201 06171	0%	380.00*
344	1	FRT BUMPER ABSORBER ✓ CRK	52611 06160	0%	75.00*
1000	1	FRT BUMPER TOW COVER ✓ cut Renew		0%	20.00*
260	1	FRT NO PLATE BRKT ✓ CRK	52114 06100	0%	65.00*
258	1	FRT NO PLATE REINF ✓ CRK	KNPL0	0%	15.00*
4485	1	FRT PIPE COMPR/COND ✓ BT	88715 06050	0%	35.00*
410	1	GRILLE ✓ CRK	53111 06280	0%	185.00*
7793	1	L/BLOWER FAN ?	16361 0H210	0%	55.00*
497	1	L/BONNET DAMPER x x x x	53450 0W090	0%	160.00*
475	1	L/BONNET HINGE x x x x	53420 06130	0%	35.00*
8781	1	L/ENGINE COVER x	51442 06110	0%	85.00*
637	1	L/F FOG LAMP CPL ?	81220 02121	0%	115.00*
317	1	L/F UPP BUMPER BRKT ?	52536 06090	0%	48.00*
741	1	L/F WING ✓ BT	53802 06140	0%	225.00*
7789	1	L/FAN MOTOR ?	16363 0H130	0%	180.00*
297	1	L/FOG LAMP COVER x x x x	52040 06080	0%	60.00*
9645	1	L/HORN ✓ DMG	86510 06110	0%	65.00*
7771	1	L/LWR RADIATOR BRKT x	16535 0H060	0%	0.00
1169	1	L/RADIATOR AIR GUIDE ✓ CRK	53294 06100	0%	55.00*
7769	1	L/UPP RADIATOR BRKT ?	16523 0H050	0%	40.00*
843	1	L/WING COVER PANEL x	53883 06030	0%	45.00*
561	1	LEFT HEADLAMP ASSY ?	81150 06530	0%	380.00*
9951	1	LIQUID GAS SYSTEM ✓ NEC	NO NUMBER	0%	60.00*
988	1	LOCK CARRIER STRUT ✓ DMG	53208 06040	0%	60.00*
493	1	LOWER BONNET LOCK ✓ Jm	53510 06101	0%	50.00*
7773	1	LWR RADIATOR HOSE ?	16572 0H100	0%	35.00*
7300	1	POWER STEERING CPL ?	44250 06310	0%	155.00*
7794	1	R/BLOWER FAN ?	16361 0H220	0%	55.00*
498	1	R/BONNET DAMPER ✓ DMG	53440 0W110	0%	160.00*
476	1	R/BONNET HINGE ✓ BT	53410 06130	0%	35.00*
7066	1	R/CARRIER JOINT x	43330 09580	0%	85.00*
7036	1	R/DRIVE SHAFT CPL x	43410 06590	0%	155.00*
8782	1	R/ENGINE COVER x	51441 06120	0%	85.00*
638	1	R/F FOG LAMP CPL ?	81210 02121	0%	115.00*
1208	1	R/F OUT S-MEMBER PNL x	57025 06030	0%	0.00
1214	1	R/F S-MEMB RR REINF x	57016 06120	0%	0.00
7272	1	R/F STABI ROD ✓ BT	48820 33070	0%	85.00*
7082	1	R/F STEERING KNUCKLE ✓ BT	43211 06210	0%	65.00*
318	1	R/F UPP BUMPER BRKT x	52535 06100	0%	48.00*
7202	1	R/F WHEEL ✓ cut	42611 06571	0%	450.00*
7118	1	R/F WHEEL BEARING ✓ BT	90369 T0007	0%	60.00*
7218	5	R/F WHEEL BOLT SET x	90942 01033	0%	30.00*
7132	1	R/F WHEEL HUB ✓ DMG	43502 06120	0%	85.00*
742	1	R/F WING ✓ BT	53801 06130	0%	225.00*
7790	1	R/FAN MOTOR ?	16363 0H140	0%	180.00*
298	1	R/FOG LAMP COVER ✓ CRK	52030 06080	0%	60.00*
9646	1	R/HORN ✓ DMG	86520 06100	0%	65.00*
1166	1	R/INN W-HOUSE COVER R	53736 06090	0%	55.00*
7054	1	R/LWR AXLE STEERING x	48068 33070	0%	145.00*

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: MAC/FEB2018/001
 Assessment Number: CTI10129
 Version: SMRTAUTO/3
 Date Calculated: 26/02/2018 03:33

Full Report - V1
 Registration: SJR8708B
 Printed: 26/02/2018 11:35

7772	1	R/LWR RADIATOR BRKT X	16535 0H060	0%	0.00
7026	1	R/R BUFFER ✓ NEC	52216 06080	0%	35.00*
7030	1	R/R CONTROL ARM BUSH ✓ NEC	52217 06060	0%	25.00*
7024	1	R/R FRONT AXLE BRKT X	51023 06020	0%	45.00*
1170	1	R/RADIATOR AIR GUIDE ✓ CRK	53293 06110	0%	55.00*
7770	1	R/UPP RADIATOR BRKT ✓ BT	16523 0H050	0%	40.00*
842	1	R/WHEELHOUSE SHELL X	53875 06081	0%	75.00*
844	1	R/WING COVER PANEL ?	53882 06030	0%	45.00*
768	1	R/WING MOULDING ?	53825 06040	0%	55.00*
7761	1	RADIATOR ✓ Leaking / ST	16400 0H250	0%	485.00*
7767	1	RADIATOR SHROUD ?	16711 0H170	0%	105.00*
562	1	RIGHT HEADLAMP ASSY ✓ CRK	81110 06530	0%	380.00*
413	2	SCREW ✓ NEC	53119 20120	0%	16.22U
7776	1	UPPER RADIATOR HOSE ?	16571 0H110	0%	35.00*
1444	1	WASHER CONT SENSOR ?	85397 33230	0%	62.08U
1436	1	WASHER CONTAINER ✓ Defect	85315 06160	0%	75.00*
1437	1	WASHER PUMP ?	85330 21010	0%	150.00*
1443	1	WASHER RESERVOIR CAP X	85386 60050	0%	15.00*

f: OEM Parts

g: Original

h: Secondhand

p: Parallel

x: Exchange

Sub Total

Mark Up From Cost

Sundry Parts

Total Parts

(5 %)

(Fixed)

\$8,967.30

\$448.37

\$100.00

\$9,515.67

THIS ASSESSMENT CONTAINS UNPRICED PARTS

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras

\$0.00

Final Calculation

Total Parts

\$9,515.67

Labour

Total Panel/Mechanical (814.00)

Total Paintwork (556.60)

Total Visual Alignment work (90)

\$2,442.60 1987.00

\$575.00 529

\$230.00 230

Total Labour

\$3,247.60

Total Paint/Material Costs

(277.21)

\$300.23 282.05

Grand Total Excludes GST

\$13,063.50

GST @ 7 %

\$914.45

Grand Total Includes GST

\$13,977.95

Assessment Notes

8 days.

Sebastian.
26/2/18.

- Lump Sum Repair.
- Question Mark Item
- Photo
- Photo After Paint
- EXCESS : \$250
- Revert
- 90036121

sebastianyeang@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

- Revert

Claim Reference: SNM18D00938C01
Assessment Number: CTI10129
Version: SMRTAUTO/4
Date Calculated: 01/03/2018 06:21

Full Report - V1
Registration: SJR8708B
Printed: 01/03/2018 14:21

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	MR LAU	Date of Incident:	15/02/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM18D00938C01	Estimated Repair Time:	10 day(s)
Policy Number:	DMPCSN3076671701	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Camry
Sub Model:	BASE MODEL
Model Sheet Number:	YCA 01
Registration:	SJR8708B
Registration Month:	November
Registration Year:	2009
VIN Number:	MR053BK4107049767
Manufacture Year:	2009
Odometer:	145040
Colour:	Green
Engine Number:	1AZE149757
Fuel Level:	90%



Model Specs

FROM 12/2009	AUTO AIR CON
CHROME DOOR HANDLES	S/MOULDING CHROMED
MIRROR W/NDICATOR	2COMP GLASS ADHESIVE
RADIO WITH CD	REARVIEW CAMERA
FOG LAMPS	EXHAUST TRIM CHROMED
PARKING BRAKE FOOT	LEATHER SEATS
S-WHEEL RADIO CONT	ANTI THEFT ALARM
LEATHER/WOOD S-WHEEL	RR PARK DIST CONTROL
2.0 LTR 108 KW	4-SPEED AUTOMATIC
ELECT POWER STEERING	CRUISE CONTROL
TYRES 215/60 YR 16	WHEELS 6.5J X 16 ALU
VERSION THAILAND	PRODUCT THAILAND
PREPARE OFF VEHICLE	TWO COAT PEARL/MICA


Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	Light Structural
Steering:	Vehicle Status on	Unroadworthy
	Inspection:	Mobile
Brakes Pedal Travel:	Date of Inspection:	18/01/2018
Place of Inspection:	Assessor	
Pre-Accident Damage:		
Tyres Condition:	Fair	
Tread Depth LHF:		Tread Depth RHF:
Tread Depth LHR:		Tread Depth RHR:
Damage Areas:		Direction of Impact:



Primary Impact
Secondary Impact



Addresses

Cost Summary

Total Labour	\$2,746.20
Total Paint/Material	\$282.05
Total Parts	\$8,247.76
Excess:	TBA
Grand Total Exc GST:	\$11,276.01
7 % GST:	\$789.32
Grand Total Inc GST:	\$12,065.33

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	DIAGNOSIS WITHOUT CHASSIS JIG	2.0	9.20
NO NUMBER	CONVERT CHASSIS JIG	10.0	46.00
043233C	ADD: ADJUST FRONT TOE	1.0	4.60
043233	ALIGN VEHICLE CPL	12.0	55.20
043233D	ADJUST FRONT CAMBER (ADD/WORK)	5.0	23.00
043233F	ADD: ADJUST REAR TOE	2.0	9.20
NO NUMBER	R + R ENGINE WITH GEARBOX	4.0	18.40
B140	RENEW FRONT PANEL	22.0	101.20
B110	RENEW L/FRT WING	5.0	23.00
	(FRT BUMPER AND L/HEADLAMP ASSY REMOVED)		
B110	RENEW R/FRT WING	5.0	23.00
	(FRT BUMPER AND R/HEADLAMP ASSY REMOVED)		
B100	R + R LEFT SILL RAIL	3.0	13.80
B100	R + R RIGHT SILL RAIL	3.0	13.80
B020	RENEW FRONT BUMPER	15.0	69.00
	INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS		
B040	RENEW BOTH HEADLAMPS	7.0	32.20
	(BUMPER REMOVED)		
	INCLUDES: ADJUST HEADLAMPS		
B070	RENEW BONNET	6.0	27.60
B080	R + R BONNET HINGES	1.0	4.60
530121)	R + R BONNET OPENER CABLE	2.0	9.20
190011	R + R BATTERY	3.0	13.80
851091)	R + R WASHER RESERVOIR	4.0	18.40

851061	R + R WASHER NOZZLES	2.0	9.20
B085)	R + R WATER BOX CLOSING PANEL	4.0	18.40
M010)	RENEW CONDENSER (REMOVED)	1.0	4.60
883401)	R + R AIR CONDITIONING COMPRESSOR	1.0	4.60
NO NUMBER	R + R AIR CONDITIONING PIPE	4.0	18.40
NO NUMBER	R + R AIR CONDITIONING PIPE	5.0	23.00
NO NUMBER	R + R AIR CONDITIONING HOSE	4.0	18.40
895011	R + R ENGINE CONTROL UNIT	3.0	13.80
NO NUMBER	R + R FAN RELAY	2.0	9.20
M010	R + R RADIATOR AND CONDENSER (FRONT BUMPER REMOVED) INCLUDES: BLEED COOLING SYSTEM	16.0	73.60
M010)	RENEW RADIATOR	3.0	13.80
160111)	R + R LOWER RADIATOR HOSE	2.0	9.20
160101)	R + R UPPER RADIATOR HOSE	2.0	9.20
NO NUMBER	R + R ENGINE COVER	1.0	4.60
NO NUMBER	R + R AIR FILTER HOSE	1.0	4.60
160251)	R + R DRIVE BELT	2.0	9.20
271011)	R + R ALTERNATOR	2.0	9.20
444401)	R + R POWER STEERING INCLUDES: BLEED POWER STEERING	6.0	27.60
420091)	R + R R/F WHEEL/TYRE	3.0	13.80
473011)	R + R L/FRT BRAKE DISC	1.0	4.60
473011A)	R + R FRONT BRAKE DISC/S	2.0	9.20
896081)	R + R R/F ABS SENSOR	1.0	4.60
NO NUMBER	R + R R/R AXLE CARRIER BRACKET	2.0	9.20
NN	LIQUID GAS SYSTEM R&R / NEW PARTS	10.0*	46.00
0250	VEHICLE TRANSPORT	20.0*	92.00
4475	DRAIN AND REFILL AIR CONDITIONING	30.0*	138.00
9732	REMOVE AND REFIT R/F AXLE HALF	40.0*	184.00
9790	AXLE REMOVED R/F AXLE HALF	40.0*	184.00
9947	ADJUST HEADLAMP	20.0*	92.00
9973	CARRY OUT TEST DRIVE	10.0*	46.00
1117	REPAIR L/F WHEELHOUSE CPL	30.0*	138.00
1118	REPAIR R/F WHEELHOUSE CPL	30.0*	138.00
1124	REPAIR R/F WHEELHOUSE	30.0*	138.00
9831	CHECK ENGINE	10.0*	46.00
9901	ALIGN W/OUT ADJUST COMPL VEH BEFORE REP	30.0*	138.00

LABOUR COST

Total Work Units	482.0	
Panel / Mechanical Labour	43.2HRS	\$1,987.20
Visual Alignment Labour	5.0HRS	\$230.00
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	48.2HRS	\$2,217.20
Paint Labour	11.5HRS	\$529.00
Total Labour	59.7HRS	\$2,746.20

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

Guide Number Description

WU

Cost Price (\$)

- PREPARE OFF VEHICLE

	- TWO COAT PEARL/MICA		
471	BONNET NEW PART PAINTING	26.0	
741	L/F WING NEW PART PAINTING	10.0	
742	R/F WING NEW PART PAINTING	10.0	
988	LOCK CARRIER STRUT SURFACE PAINT	4.0	
1009	FRONT PANEL SURFACE PAINT	7.0	
283	FRONT BUMPER NEW PART PAINT K1R	13.0	
410	GRILLE NEW PART PAINT K1R	3.0	
1117	L/F WHEELHOUSE CPL SURFACE PAINT	6.0	
1118	R/F WHEELHOUSE CPL SURFACE PAINT	6.0	
LABOUR COST - PAINT			
	TIME(PAINT)	85.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	115.0	
	Total Paintwork Labour	11.5HRS	\$529.00
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$129.00
	New Part Painting - Plastic K1R		\$68.39
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$47.06
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$282.05
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$282.05

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
8391	1	AIR FILTER ASSY	17700 0H121		0% 225.00*
8375	1	AIR INTAKE HOSE	17750 0H070		0% 90.00*
3011	1	BADGE "VVT-I" L	75443 06260		0% 28.00*
3012	1	BADGE "VVT-I" R	75443 06540		0% 28.00*
471	1	BONNET	53301 06110		0% 430.00*
527	1	BONNET FRONT SEAL	53381 06060		0% 38.00*
481	1	BONNET INSULATION	53341 06160		0% 180.00*
340	1	BUMPER SUPPORT	52021 06060		0% 150.00*
4481	1	COMPR/CONDENSER TUBE	88711 06280		0% 48.00*
4482	1	COND/EVAPORATOR PIPE	88710 06211		0% 95.00*
4465	1	CONDENSER	88460 06170		0% 380.00*
500	1	CONTROL CABLE	53630 06110		0% 45.00*
412	1	CTR BUMPER GRILLE	53112 06120		0% 85.00*
7757	1	FAN RELAY 1	90987 02027		0% 76.47U
283	1	FRONT BUMPER	52119 06960		0% 260.00*
1000	1	FRONT GRILLE EMBLEM	Renew		0% 30.00*
257	1	FRONT NUMBER PLATE	KNPL3		0% 35.00*
1009	1	FRONT PANEL	53201 06171		0% 380.00*
344	1	FRT BUMPER ABSORBER	52611 06160		0% 75.00*
1000	1	FRT BUMPER TOW COVER	Renew		0% 20.00*
260	1	FRT NO PLATE BRKT	52114 06100		0% 65.00*
258	1	FRT NO PLATE REINF	KNPL0		0% 15.00*
4485	1	FRT PIPE COMPR/COND	88715 06050		0% 35.00*

410	1	GRILLE	53111 06280	0%	185.00*
7793	1	L/BLOWER FAN	16361 0H210	0%	55.00*
475	1	L/BONNET HINGE	53420 06130	0%	35.00*
637	1	L/F FOG LAMP CPL	81220 02121	0%	115.00*
317	1	L/F UPP BUMPER BRKT	52536 06090	0%	48.00*
741	1	L/F WING	53802 06140	0%	225.00*
7789	1	L/FAN MOTOR	16363 0H130	0%	180.00*
9645	1	L/HORN	86510 06110	0%	65.00*
1169	1	L/RADIATOR AIR GUIDE	53294 06100	0%	55.00*
7769	1	L/UPP RADIATOR BRKT	16523 0H050	0%	40.00*
561	1	LEFT HEADLAMP ASSY	81150 06530	0%	380.00*
9951	1	LIQUID GAS SYSTEM	NO NUMBER	0%	60.00*
988	1	LOCK CARRIER STRUT	53208 06040	0%	60.00*
493	1	LOWER BONNET LOCK	53510 06101	0%	50.00*
7773	1	LWR RADIATOR HOSE	16572 0H100	0%	35.00*
7300	1	POWER STEERING CPL	44250 06310	0%	155.00*
7794	1	R/BLOWER FAN	16361 0H220	0%	55.00*
498	1	R/BONNET DAMPER	53440 0W110	0%	160.00*
476	1	R/BONNET HINGE	53410 06130	0%	35.00*
638	1	R/F FOG LAMP CPL	81210 02121	0%	115.00*
7272	1	R/F STABI ROD	48820 33070	0%	85.00*
7082	1	R/F STEERING KNUCKLE	43211 06210	0%	65.00*
7202	1	R/F WHEEL	42611 06571	0%	450.00*
7118	1	R/F WHEEL BEARING	90369 T0007	0%	60.00*
7132	1	R/F WHEEL HUB	43502 06120	0%	85.00*
742	1	R/F WING	53801 06130	0%	225.00*
7790	1	R/FAN MOTOR	16363 0H140	0%	180.00*
298	1	R/FOG LAMP COVER	52030 06080	0%	60.00*
9646	1	R/HORN	86520 06100	0%	65.00*
7026	1	R/R BUFFER	52216 06080	0%	35.00*
7030	1	R/R CONTROL ARM BUSH	52217 06060	0%	25.00*
1170	1	R/RADIATOR AIR GUIDE	53293 06110	0%	55.00*
7770	1	R/UPP RADIATOR BRKT	16523 0H050	0%	40.00*
844	1	R/WING COVER PANEL	53882 06030	0%	45.00*
768	1	R/WING MOULDING	53825 06040	0%	55.00*
7761	1	RADIATOR	16400 0H250	0%	485.00*
7767	1	RADIATOR SHROUD	16711 0H170	0%	105.00*
562	1	RIGHT HEADLAMP ASSY	81110 06530	0%	380.00*
413	2	SCREW	53119 20120	0%	16.22U
7776	1	UPPER RADIATOR HOSE	16571 0H110	0%	35.00*
1444	1	WASHER CONT SENSOR	85397 33230	0%	62.08U
1436	1	WASHER CONTAINER	85315 06160	0%	75.00*
1437	1	WASHER PUMP	85330 21010	0%	150.00*
f: OEM Parts		Sub Total			\$7,759.77
g: Original		Mark Up From Cost		(5 %)	\$387.99
h: Secondhand		Sundry Parts		(Fixed)	\$100.00
p: Parallel		Total Parts			\$8,247.76
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras

\$0.00

Final Calculation

Total Parts

\$8,247.76

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore
Claim Reference: SNM18D00938C01
Assessment Number: CTI10129
Version: SMRTAUTO/4
Date Calculated: 01/03/2018 06:21

Full Report - V1
Registration: SJR8708B
Printed: 01/03/2018 14:21

Labour		
Total Panel/Mechanical	\$1,987.20	
Total Paintwork	\$529.00	
Total Visual Alignment work	\$230.00	
Total Labour		\$2,746.20
Total Paint/Material Costs		\$282.05
Grand Total Excludes GST		\$11,276.01
GST @ 7 %		\$789.32
Grand Total Includes GST		\$12,065.33

Assessment Notes

**CHINA TAIPING
INSURANCE (S) PTE LTD
3 ANSON ROAD
#15-02 SPRINGLEAF
TOWER**

079909

China Taiping

Marking

Claim Reference: SNM18D00938C01
Assessment Number: CTI10129
Version: LKKAUTOC/2
Date Calculated: 02/03/2018 04:59

Full Report - V1
Registration: SJR8708B
Printed: 02/03/2018 13:00

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Eddie Sim	Date of Incident:	15/02/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM18D00938C01	Estimated Repair Time:	10 day(s)
Policy Number:	DMPCSN3076671701	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Camry
Sub Model:	BASE MODEL
Model Sheet Number:	YCA 01
Registration:	SJR8708B
Registration Month:	November
Registration Year:	2009
VIN Number:	MR053BK4107049767
Manufacture Year:	2009
Odometer:	145040
Colour:	Green
Engine Number:	1AZE149757
Fuel Level:	90%

Model Specs

FROM 12/2009	AUTO AIR CON
CHROME DOOR HANDLES	S/MOULDING CHROMED
MIRROR W/INDICATOR	2COMP GLASS ADHESIVE
RADIO WITH CD	REARVIEW CAMERA
FOG LAMPS	EXHAUST TRIM CHROMED
PARKING BRAKE FOOT	LEATHER SEATS
S-WHEEL RADIO CONT	ANTI THEFT ALARM
LEATHER/WOOD S-WHEEL	RR PARK DIST CONTROL
2.0 LTR 108 KW	4-SPEED AUTOMATIC
ELECT POWER STEERING	CRUISE CONTROL
TYRES 215/60 YR 16	WHEELS 6.5J X 16 ALU
VERSION THAILAND	PRODUCT THAILAND
PREPARE OFF VEHICLE	TWO COAT PEARL/MICA

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	Light Structural
Steering:	Vehicle Status on	Unroadworthy
	Inspection:	Mobile
Brakes Pedal Travel:	Date of Inspection:	18/01/2018
Place of Inspection:	Assessor	
Pre-Accident Damage:		
Tyres Condition:	Fair	
Tread Depth LHF:		
Tread Depth LHR:		
Damage Areas:	Tread Depth RHF:	
	Tread Depth RHR:	
	Direction of Impact:	

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: SNM18D00938C01

Assessment Number: CTI10129




Version: LKKAUTOC/2

Date Calculated: 02/03/2018 04:59

Full Report - V1

Registration: SJR8708B

Printed: 02/03/2018 13:00



Primary Impact
Secondary Impact

Addresses

Cost Summary

Total Labour	\$1,462.80
Total Paint/Material	\$277.21
Total Parts	\$5,619.85
Total of Additional Costs	\$35.00
Repair Cost Exc GST:	\$7,394.86
Overall Discount (0.0%):	- \$0.00
Excess:	-\$250.00
After Deduction -	
Grand Total Exc GST:	\$7,144.86
7 % GST:	\$500.14
Grand Total Inc GST:	\$7,645.00

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
043233C	ADD: ADJUST FRONT TOE	1.0	4.60
043233	ALIGN VEHICLE CPL	12.0	55.20
043233D	ADJUST FRONT CAMBER (ADD/WORK)	5.0	23.00
043233F	ADD: ADJUST REAR TOE	2.0	9.20
B100	R + R LEFT FRONT WING (FRT BUMPER AND L/HEADLAMP ASSY REMOVED)	4.0	18.40
B140	RENEW FRONT PANEL	22.0	101.20
B110	RENEW R/FRT WING (FRT BUMPER AND R/HEADLAMP ASSY REMOVED)	5.0	23.00
B100	R + R LEFT SILL RAIL	3.0	13.80
B100	R + R RIGHT SILL RAIL	3.0	13.80
B020	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS	15.0	69.00
B040)	RENEW R/HEADLAMP (REMOVED)	2.0	9.20
B040	R + R HEADLAMPS (BUMPER REMOVED)	4.0	18.40
B070	RENEW BONNET	6.0	27.60
B080	R + R BONNET HINGES	1.0	4.60
530121)	R + R BONNET OPENER CABLE	2.0	9.20
851061	R + R WASHER NOZZLES	2.0	9.20
B085)	R + R WATER BOX CLOSING PANEL	4.0	18.40

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: SNM18D00938C01

Assessment Number: CTI10129

Version: LKKAUTOC/2

Date Calculated: 02/03/2018 04:59

Full Report - V1

Registration: SJR8708B

Printed: 02/03/2018 13:00

M010)	RENEW CONDENSER (REMOVED)	1.0	4.60
NO NUMBER	R + R AIR CONDITIONING PIPE	4.0	18.40
NO NUMBER	R + R AIR CONDITIONING HOSE	4.0	18.40
895011	R + R ENGINE CONTROL UNIT	3.0	13.80
M010	R + R RADIATOR AND CONDENSER (FRONT BUMPER REMOVED)	16.0	73.60
	INCLUDES: BLEED COOLING SYSTEM		
M010)	RENEW RADIATOR	3.0	13.80
NO NUMBER	R + R ENGINE COVER	1.0	4.60
420091)	R + R R/F WHEEL/TYRE	3.0	13.80
0481	REMOVE&REFIT BONNET INSULATION	2.0*	9.20
4482	REMOVE&REFIT COND/EVAPORATOR PIPE	2.0*	9.20
7757	REMOVE&REFIT FAN RELAY 1	1.0*	4.60
7769	REMOVE&REFIT L/UPP RADIATOR BRKT	1.0*	4.60
7773	REMOVE&REFIT LWR RADIATOR HOSE	2.0*	9.20
7776	REMOVE&REFIT UPPER RADIATOR HOSE	2.0*	9.20
1001	REPAIR FRONT CROSSMEMBER	5.0*	23.00
1019	REPAIR L/F PANEL STRUT	3.0*	13.80
1021	REPAIR L/F RADIATOR BRACKET	5.0*	23.00
1027	REPAIR L/F PANEL REINF	3.0*	13.80
1117	REPAIR L/F WHEELHOUSE CPL	3.0*	13.80
1118	REPAIR R/F WHEELHOUSE CPL	10.0*	46.00
1124	REPAIR R/F WHEELHOUSE	30.0*	138.00
1436	CHECK WASHER CONTAINER		
1437	CHECK WASHER PUMP		
1444	CHECK WASHER CONT SENSOR		
7082	CHECK R/F STEERING KNUCKLE		
7118	CHECK R/F WHEEL BEARING		
7132	CHECK R/F WHEEL HUB		
7272	CHECK R/F STABI ROD		
7300	CHECK POWER STEERING CPL		
7310	CHECK R/F TIE ROD		
7312	CHECK R/TIE ROD BALL JOINT		

LABOUR COST

Total Work Units	197.0	
Panel / Mechanical Labour	17.7HRS	\$814.20
Visual Alignment Labour	2.0HRS	\$92.00
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	19.7HRS	\$906.20
Paint Labour	12.1HRS	\$556.60
Total Labour	31.8HRS	\$1,462.80

PAINT WORK

Guide Number	Description	Time Basis 10 WU = 1 HR. Price = \$46.00/HR	WU	Cost Price (\$)
	- PREPARE OFF VEHICLE			
	- TWO COAT PEARL/MICA			
471	BONNET NEW PART PAINTING		26.0	
742	R/F WING NEW PART PAINTING		10.0	
988	LOCK CARRIER STRUT SURFACE PAINT		4.0	
1009	FRONT PANEL SURFACE PAINT		7.0	

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: SNM18D00938C01

Assessment Number: CTI10129

Version: LKKAUTOC/2

Date Calculated: 02/03/2018 04:59

Full Report - V1

Registration: SJR8708B

Printed: 02/03/2018 13:00

283	FRONT BUMPER NEW PART PAINT K1R	13.0	
410	GRILLE NEW PART PAINT K1R	3.0	
741	L/F WING REPAIR PAINTING >50%	16.0	
1117	L/F WHEELHOUSE CPL SURFACE PAINT	6.0	
1118	R/F WHEELHOUSE CPL SURFACE PAINT	6.0	
LABOUR COST - PAINT			
	TIME(PAINT)	91.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	121.0	
	Total Paintwork Labour	12.1HRS	\$556.60
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$108.36
	New Part Painting - Plastic K1R		\$68.39
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$47.06
	Repair Painting		\$15.80
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$277.21
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$277.21

PARTS

					Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
260	1	FRT NO PLATE BRKT	52114 06100		0%	65.00*
283	1	FRONT BUMPER	52119 06960		0%	260.00*
298	1	R/FOG LAMP COVER	52030 06080		0%	60.00*
317	1	L/F UPP BUMPER BRKT	52536 06090		0%	48.00*
340	1	BUMPER SUPPORT	52021 06060		0%	150.00*
344	1	FRT BUMPER ABSORBER	52611 06160		0%	75.00*
410	1	GRILLE	53111 06280		0%	185.00*
412	1	CTR BUMPER GRILLE	53112 06120		0%	85.00*
471	1	BONNET	53301 06110		0%	430.00*
475	1	L/BONNET HINGE	53420 06130		0%	35.00*
476	1	R/BONNET HINGE	53410 06130		0%	35.00*
493	1	LOWER BONNET LOCK	53510 06101		0%	50.00*
498	1	R/BONNET DAMPER	53440 0W110		0%	160.00*
500	1	CONTROL CABLE	53630 06110		0%	45.00*
527	1	BONNET FRONT SEAL	53381 06060		0%	38.00*
562	1	RIGHT HEADLAMP ASSY	81110 06530		0%	380.00*
638	1	R/F FOG LAMP CPL	81210 02121		0%	115.00*
742	1	R/F WING	53801 06130		0%	225.00*
768	1	R/WING MOULDING	53825 06040		0%	55.00*
844	1	R/WING COVER PANEL	53882 06030		0%	45.00*
988	1	LOCK CARRIER STRUT	53208 06040		0%	60.00*
1009	1	FRONT PANEL	53201 06171		0%	380.00*
1170	1	R/RADIATOR AIR GUIDE	53293 06110		0%	55.00*
3012	1	BADGE "VVT-I" R	75443 06540		0%	28.00*
4465	1	CONDENSER	88460 06170		0%	380.00*
4481	1	COMPR/CONDENSER TUBE	88711 06280		0%	48.00*
4485	1	FRT PIPE COMPR/COND	88715 06050		0%	35.00*

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: SNM18D00938C01

Assessment Number: CTI10129

Version: LKKAUTOC/2

Date Calculated: 02/03/2018 04:59

Full Report - V1

Registration: SJR8708B

Printed: 02/03/2018 13:00

7202	1	R/F WHEEL	42611 06571	0%	450.00*
7761	1	RADIATOR	16400 0H250	0%	485.00*
7767	1	RADIATOR SHROUD	16711 0H170	0%	105.00*
7770	1	R/UPP RADIATOR BRKT	16523 0H050	0%	40.00*
7789	1	L/FAN MOTOR	16363 0H130	0%	180.00*
7790	1	R/FAN MOTOR	16363 0H140	0%	180.00*
7793	1	L/BLOWER FAN	16361 0H210	0%	55.00*
7794	1	R/BLOWER FAN	16361 0H220	0%	55.00*
9645	1	L/HORN	86510 06110	0%	65.00*
9646	1	R/HORN	86520 06100	0%	65.00*
1000	1	FRONT GRILLE EMBLEM	Renew	0%	30.00*
1000	1	FRT BUMPER TOW COVER	Renew	0%	20.00*

f: OEM Parts

g: Original

h: Secondhand

p: Parallel

x: Exchange

Sub Total

Mark Up From Cost

Sundry Parts

Total Parts

(5 %)

(Fixed)

\$5,257.00

\$262.85

\$100.00

\$5,619.85

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description

FRY NO. PLATE

SPECIALIST

Betterment

0%

Total Extras

Price

\$35.00

\$35.00

Final Calculation

Total Parts

\$5,619.85

Labour

Total Panel/Mechanical

\$814.20

Total Paintwork

\$556.60

Total Visual Alignment work

\$92.00

Total Labour

\$1,462.80

Additional Costs

Corr Prot Materials External

\$0.00

Corr Prot Materials Internal

\$0.00

Cost of Specialist

\$35.00

Total of Additional Costs

\$35.00

Total Paint/Material Costs

\$277.21

Repair Costs Excludes GST

→ \$7,394.86

Deductions

Deduction for Excess (Fixed)

-\$250.00

Total Deductions

-\$250.00

Grand Total Excludes GST (After Deduction)

\$7,144.86

GST @ 7 %

\$500.14

Grand Total Includes GST (After Deduction)

\$7,645.00

Assessment Notes

7,394.86

-20% = 5,915.89

45 5,900/-