

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180

Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944

Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E**26 FEB 2018**

Estimate No. : **b1 46026**
Date Estimated : **23/02/2018**
Prepared By : **Kevin Leong Wai Kit**

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Zhao Xiaoming
52 Newton Road
#09-06

Singapore 307992**- ACCOUNT - 158**

Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLL2078H	5G65774	17/02/2017	X1 sDrive20i	0

DESCRIPTION

To replace rear right door, rear right wheel arch cover &
all attachments cause by accident

VALUE

~~850~~ 2,580.00

~~885~~ Painting on rear right door & rear left side panel

~~796~~ 1,770.00

To transfer lock mechanism from old to new door including
conduct checks on new door power window system for proper
function. (1 door).

~~X~~ 531.00

To check electrical wiring systems for proper function.

~~150~~ 177.00

To carry out body cavity preservation.
(Per panel).

~~X~~ 118.00

Sundries.

~~40~~ 80.00

Total Labour 1: **5,226.00**

DESCRIPTION

RR RH DOOR
RR RH INNER DOOR CHANNEL SEAL
Cover, colum
RR RH DOOR WINDOW FRAME COVER (ALU)
RR RH DOOR OUTER CHANNEL COVER (ALU)
REAR DOOR SEALING TAPE ENTRANCE
REAR RH WHEEL ARCH TRIM

QTY PRIC

1 1,168.60
1 66.10
1 48.15
1 59.75
1 126.30
1 34.80
1 147.55

VALUE

~~R~~ 1,168.60
~~X~~ 66.10
~~X~~ 48.15
~~X~~ 59.75
~~X~~ 126.30
~~X~~ 34.80
~~sur~~ 147.55

Total Parts : **1,651.25**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46026
Date Estimated : 23/02/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLL2078H	5G65774	17/02/2017	X1 sDrive20i	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 09/08/18 21410 Excess S\$ _____

Surveyor's Name Rafael Sign _____

Surveyor's Tel 9006068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

Labour 1	:	5,226.00
Parts	:	1,651.25
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	481.41
Grand Total	:	7,358.66

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **