



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2013 HONDA NC700XD HONXXX (FBH7128D)

Date of Loss

19 February 2018

Time of Loss

6.20

Loss Description

FBH7128D (INSD) C/W SKM9709G (TP)

Comment

Workshop Details

Total Rebate Amount

947

Nett Loss Amount

\$14,053.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

17/05/2018



Days of work completion *

80



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

FBH7128D

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

03/09/2013



Mileage

65243

Age of Vehicle

4

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2013

ASSESSMENT INFO...

2013

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

SIA TIONG MENG

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... HONDA NC700XD

ASSESSMENT INFO... HONDA

CATEGORY Model

POLICY INFORMAT... HONXXX

ASSESSMENT INFO... NC700XD

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... JH2RC63AXDK600385

CATEGORY Date of Birth

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... JH2RC63AXDK600385

CATEGORY Engine No

POLICY INFORMAT... RC61E5208346

ASSESSMENT INFO... RC61E5208346

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 670

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 15000

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI... Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S7329163A

POST SURVEY INF...

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Detailed Assessment

Inspection Date *

01/03/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

750

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

120/70ZR17

Condition of Vehicle at time of survey

General condition

-- none --



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

-- none --



Tyre Condition

Spare wheel

Rear Tyre Size

160/60R17

Front left side

BRIDGESTONE6mm

Front right side

Rear left side

BRIDGESTONE6mm

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Save

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			FRONT MUDGUARD			Cracked	295		10		265.5	Review
		2	1			FRONT MUDGUARD BRACKET COMP			Serviceable	0	0	0	0	0	Deny
		3	1			FRONT WHEEL AXLE			Cut	115		10		103.5	Review
		4	1			FRONT BRAKE DISK			Bent	390		10		351	Review
		5	2			STEERING STEM BEARING			Damaged	45		10		81	Review
		6	1			FRONT LEFT FORK ASSEMBLY			Bent	1085		10		976.5	Review
		7	1			FRONT RIGHT FORK ASSEMBLY			Cut	1085		10		976.5	Review
		8	1			STEERING HEAD CROWN			Bent	430		10		387	Review
		9	1			STEERING STEM UNDERBRACKET			Bent	440		10		396	Review
		10	1			WINDSHIELD			Damaged	185		10		166.5	Review
		11	2			WINDSHIELD SUPPORT BRACKET			Serviceable	0	0	0	0	0	Deny
		12	1			IU BRACKET			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		13	1			LEFT CLUTCH LEVER			Cut	75		10		67.5	Review
		14	1			BRAKE LEVER			Cut	75		10		67.5	Review
		15	1			RIGHT BALANCER			Damaged	65		10		58.5	Review
		16	1			LEFT BALANCER			Cut	65		10		58.5	Review
		17	1			LEFT VIEW MIRROR			Cut	165		10		148.5	Review
		18	1			RIGHT VIEW MIRROR			Cut	165		10		148.5	Review
		19	1			HANDLE BAR			Bent	245		10		220.5	Review
		20	1			RIGHT FRONT SIGNAL			Cut	165		10		148.5	Review
		21	1			LEFT FRONT SIGNAL			Damaged	165		10		148.5	Review
		22	1			FUEL TANK COVER			Cut	395		10		355.5	Review
		23	1			FUEL TANK FRONT INNER BLACK COVER			Serviceable	0	0	0	0	0	Deny
		24	1			FUEL TANK FRONT RIGHT COVER			Cut	395		10		355.5	Review
		25	1			RIGHT BODY FAIRING			Cut	495		10		445.5	Review
		26	1			HONDA WING DECAL			Necessary	55		10		49.5	Review
		27	1			LOWER RIGHT COVER			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		28	1			BELLY PAN			Cut	335		10		301.5	Review
		29	1			LOWER LEFT COVER			Serviceable	0	0	0	0	0	Deny
		30	1			RADIATOR ASSY			Damaged	795		10		715.5	Review
		31	1			LEFT CRASH BAR			Cut	275		10		247.5	Review
		32	1			RIGHT CRASH BAR			Cracked	275		10		247.5	Review
		33	1			GEAR PEDAL TIE ROD			Bent	95		10		85.5	Review
		34	1			GEAR PEDAL ASSEMBLY			Bent	185		10		166.5	Review
		35	1			BRAKE PEDAL			Bent	155		10		139.5	Review
		36	1			RIGHT FRONT FOOTREST			Cut	115		10		103.5	Review
		37	1			LEFT FRONT FOOTREST			Serviceable	0	0	0	0	0	Deny
		38	1			MAINSTAND ASSY			Serviceable	0	0	0	0	0	Deny
		39	1			SIDE STAND ASSY			Serviceable	0	0	0	0	0	Deny
		40	1			LEFT REAR FOOTREST			Serviceable	0	0	0	0	0	Deny
		41	1			LEFT FOOTREST HOLDER			Serviceable	0	0	0	0	0	Deny
		42	1			RIGHT REAR FOOTREST			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		43	1			RIGHT FOOTREST HOLDER			Damaged	375		10		337.5	Review
		44	1			LEFT SIDE COVER			Serviceable	0	0	0	0	0	Deny
		45	1			RIGHT SIDE COVER			Serviceable	0	0	0	0	0	Deny
		46	1			REAR TAIL COVER ASSY UPPER			Serviceable	0	0	0	0	0	Deny
		47	1			REAR TAIL COVER ASSY LOWER			Repair	0	0	0	0	0	Deny
		48	1			REAR LEFT SIGNAL			Serviceable	0	0	0	0	0	Deny
		49	1			REAR RIGHT SIGNAL			Serviceable	0	0	0	0	0	Deny
		50	1			EXHAUST COMP			Cut	1880		10		1692	Review

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RE
		1		TOWING CHARGES	60	0	0	Reviewing		
		2		REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS	300	0	0	Reviewing		
		3		BALANCING FRONT WHEEL RIM	80	0	0	Reviewing		
		4		TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES	100	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RE
		5		RESET METER	80	0	0	Reviewing		
		6		TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	200	0	0	Reviewing		
		7		SPRAY PAINTING	350	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS OF
REPAIR : 3
DAYS

Reviewing



2

FRONT
SPORT RIM

Reviewing

995

CUT



3

ERP IU

Deny

0

NOT NECESSARY



4

BOX
BRACKET

Deny

0

NOT NECESSARY



5

TOP CASE

Reviewing

495

CUT



6

HEADLAMP
ASSY (DISC
10%)

Reviewing

423

CRACKED
(SUPPLEMENTARY)



7

METER
BRACKET
(DISC 10%)

Reviewing

265.5

BENT
(SUPPLEMENTARY)



	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		8	HEADLIGHT COVER (DISC 10%)	Reviewing	139.5	CRACKED (SUPPLEMENTARY)	
		9	LEFT FAIRING WHITE	Deny	0	NOT NECESSARY	
		10	HEADLAMP BRACKET - 2PCS (DISC 10%)	Reviewing	400.5	BENT (SUPPLEMENTARY)	
		11	RIGHT FAIRING WHITE (DISC 10%)	Reviewing	342	CUT (SUPPLEMENTARY)	
		12	RIGHT SILVER FAIRING (DISC 10%)	Reviewing	207	SCRATCHED (SUPPLEMENTARY)	
		13	LEFT BODY FAIRING (DISC 10%)	Reviewing	445.5	DEFORMED (SUPPLEMENTARY)	
		14	LEFT SILVER FAIRING	Deny	0	NOT NECESSARY	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		15	HONDA WING DECAL	Deny	0	NOT NECESSARY	
		16	BEAK LOWER COVER (DISC 10%)	Reviewing	175.5	MISSING (SUPPLEMENTARY)	
		17	UPPER METER COVER (DISC 10%)	Reviewing	178.2	BENT (SUPPLEMENTARY)	
		18	HORN-2PCS (DISC 10%)	Reviewing	108	DAMAGED (SUPPLEMENTARY)	
		19	RIGHT REAR HANDLE	Deny	0	REPAIR	
		20	THROTTLE GRIP (DISC 10%)	Reviewing	36	CUT (SUPPLEMENTARY)	
		21	BODY FRAME POWDER COAT	Deny	0	NOT NECESSARY	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		22	MUDGUARD BRACE (DISC 10%)	Reviewing	85.5	CUT (SUPPLEMENTARY)	
		23	BELLY PAN BRACKET (DISC 10%)	Reviewing	67.5	DISTORTED (SUPPLEMENTARY)	
		24	ENGINE COVER RIGHT (DISC 10%)	Reviewing	522	CUT (SUPPLEMENTARY)	
		25	ENGINE COVER GASKET (DISC 10%)	Reviewing	67.5	NECESSARY (SUPPLEMENTARY)	
		26	BODY FRAME POWDER COAT	Deny	0	REPEATED	
		27	ENGINE OIL - 3PCS	Deny	0	SERVICEABLE	

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$15,385.70

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,170.00	\$1,170.00
Spare Parts	\$10,012.50	\$10,012.50
Miscellaneous	\$4,953.20	\$4,953.20
Excess	-\$750.00	-\$750.00

Submit for Review

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	FINAL LUMP SUM	Reviewing	10000		

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$9,250.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Miscellaneous	\$10,000.00	\$10,000.00
Excess	-\$750.00	-\$750.00

Submit for Review