

INS. CASE OWNER:

CC 6/LPC1800

LKK:

IDAC:

Surveyor:

marcus

DOI:

ASSIGNMENT

27/7/18

Date / Time:

27/7/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJS 54776

Name of Insured:

TAN HENRY HENRY

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

27/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

JUSTIN TAN JUN HAN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

27/18/18/0505020435

Policy No.:

6770501547

Make / Model:

HONDA

Place of Accident:

SEMPANG EXIT TWO TAMPINES

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SEA 68762



INSRS:

WSP:

Tel:

Liability:

RMKS:

Fastech



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

| Date / Time | STAGE                             | DATE / PIC                          |
|-------------|-----------------------------------|-------------------------------------|
| 27/7/18     | Non-Reporting ltr (1st):          |                                     |
| 27/7/18     | Non-Reporting ltr (2nd):          |                                     |
| 27/7/18     | Non-Reporting ltr (Final):        |                                     |
| 27/7/18     | Notification ltr (if non-pickup): |                                     |
| 27/7/18     | Call OI:                          |                                     |
| 27/7/18     | After call ltr to OI:             |                                     |
| 27/7/18     | Documentation Check List:         | Handler Typist                      |
| 27/7/18     | Notification ltr (if non-pickup): | <input type="checkbox"/>            |
| 27/7/18     | After call ltr to OI:             | <input type="checkbox"/>            |
| 27/7/18     | Authorisation To Act:             | <input checked="" type="checkbox"/> |
| 27/7/18     | Release Voucher:                  | <input checked="" type="checkbox"/> |
| 27/7/18     | Final Repair Bill:                | <input checked="" type="checkbox"/> |
| 27/7/18     | Car Rental Invoice:               | <input type="checkbox"/>            |
| 27/7/18     | Towing Invoice:                   | <input type="checkbox"/>            |
| 27/7/18     | LTA / GIA:                        | <input checked="" type="checkbox"/> |
| 27/7/18     | Medical Bill:                     | <input type="checkbox"/>            |
| 27/7/18     | PIR:                              | <input type="checkbox"/>            |
| 27/7/18     | Mandate/Reject Instruction:       | <input checked="" type="checkbox"/> |
| 27/7/18     | LOD:                              | <input checked="" type="checkbox"/> |
| 27/7/18     | Payment Breakdown Form:           | <input type="checkbox"/>            |
| 27/7/18     | Post-Repair Photos:               | <input type="checkbox"/>            |
| 27/7/18     | Others:                           | <input type="checkbox"/>            |

|                                                                                                                                           |                           |                              |
|-------------------------------------------------------------------------------------------------------------------------------------------|---------------------------|------------------------------|
| <b>PRELIMINARY ADVICE</b>                                                                                                                 | Date/Time:                | Sent By:                     |
|                                                                                                                                           | 04.04.18                  |                              |
| <b>FINALIZATION</b>                                                                                                                       | Date/Time:                | Confirm with:                |
| Repair Cost:                                                                                                                              | SS 9,000.00 (9 days)      | Reduction: 65 %              |
| <b>FINAL SETTLEMENT</b>                                                                                                                   | Date/Time:                | Confirm with:                |
| Final Liability:                                                                                                                          | % 100 (Agreed / Assessed) | BOLA S/N No.: 28             |
| Repair Cost:                                                                                                                              | SS 9,000.00               |                              |
| Loss of Rental (LOR):                                                                                                                     | SS - (days)               |                              |
| Loss of Use (LOU):                                                                                                                        | SS 600.00 x 10 days       |                              |
| Loss of Income (LOI):                                                                                                                     | SS - (S x days)           |                              |
| LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> | [Tick only one]           |                              |
| GIA/LTA Search                                                                                                                            | SS 2.00                   |                              |
| Medical:                                                                                                                                  | SS -                      |                              |
| Disbursement:                                                                                                                             | SS -                      | (e.g. Tow/ Independent)      |
| Legal Cost                                                                                                                                | SS -                      |                              |
| <b>Total:</b>                                                                                                                             | SS 10,252.00              | Global Sum SS: -             |
| <b>FINAL PAYMENT</b>                                                                                                                      | Date/Time:                | Confirm with:                |
| Payee 1:                                                                                                                                  | SS 10,252.00              | Name 1: FASTECH AUTO PTE LTD |
| Payee 2: (Strike if N.A.)                                                                                                                 | SS -                      | Name 2: -                    |
| Payee 3: (Strike if N.A.)                                                                                                                 | SS -                      | Name 3: -                    |

RECEIVED 21 MAY 2018

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value:

IDAC Accident Report

GIA / PR Seen:

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No.

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / STD A/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*L7A24497*  
*3yrs 1mlc. Def 9500 net 11503*  
*have 612 dnf*

*26/3/18 2/5 @ 9000 confirmed with Alan*

MV: \$36,000.00 (Cost)

LTA: \$24,494.00 (Cost)

Nett: \$11,503.00 (Cost)

(Red: \$16,443.08 / 65%)

Date/Time. File Pass to?

☐

Preli. Report

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1)

Date/Time. File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                           |                            |            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|----------------------------|------------|-------------------------------------------------------------------------------------|
| LONPAC INSURANCE BHD                                                                                                                   |                                                                                           | Ref : CC6/LPC18003742/Ukb3 |            |                                                                                     |
| 300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555                                                                              |                                                                                           | Date : 27-02-2018          |            |  |
|                                                                                                                                        |                                                                                           | Code : LPC2                |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                           |                            |            |                                                                                     |
| Insured Veh.                                                                                                                           | SJS 5477G                                                                                 | Veh. Inspected             | SKA 6825L  |                                                                                     |
| Policy No.                                                                                                                             |                                                                                           | Coverage (\$)              | 0.00       |                                                                                     |
| Claim No.                                                                                                                              |                                                                                           | Excess (\$)                | 0.00       |                                                                                     |
| Assign From                                                                                                                            |                                                                                           | Assign Date                | 27/02/2018 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                           |                            |            |                                                                                     |
| Make & Model                                                                                                                           |                                                                                           | c.c                        | 0          |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                                    | Year of Reg.               |            |                                                                                     |
| Chassis No.                                                                                                                            |                                                                                           | Colour                     |            |                                                                                     |
| Odometer                                                                                                                               | -                                                                                         | Steering                   |            |                                                                                     |
| Brakes                                                                                                                                 |                                                                                           | Modification               |            |                                                                                     |
| General                                                                                                                                |                                                                                           |                            |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                           |                            |            |                                                                                     |
|                                                                                                                                        | Size                                                                                      | Make                       | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                         |                                                                                           |                            | mm         |                                                                                     |
| L/H Front Tyre                                                                                                                         |                                                                                           |                            | mm         |                                                                                     |
| R/H Rear Tyre                                                                                                                          |                                                                                           |                            | mm         |                                                                                     |
| L/H Rear Tyre                                                                                                                          |                                                                                           |                            | mm         |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                           |                            |            |                                                                                     |
|                                                                                                                                        |                                                                                           |                            |            |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                           |                            |            |                                                                                     |
| Accident Date                                                                                                                          | 27/02/2018                                                                                | Inspection Date            |            |                                                                                     |
| Survey held at                                                                                                                         | FASTECH AUTO PTE LTD<br>1 KAKI BUKIT AVENUE 6<br>#01-46/48/50 AUTOBAY<br>SINGAPORE 417883 |                            |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                           |                            |            |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                           |                            |            |                                                                                     |

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No:67452063/67467158 Fax No:67458520

not Allocated  
2/5 = 9000  
947.

VEH: SKA6825L

| QTY  | PARTICULAR                           | AMOUNT             |
|------|--------------------------------------|--------------------|
| 1PCS | BOOTLID                              | 100/3uc \$685.10 ✓ |
| 1PCS | BOOTLID REAR LOGO                    | neu \$38.80 ✓      |
| 1PCS | BOOTLID 'CITY' EMBLEM                | neu \$35.20 ✓      |
| 1PCS | BOOTLID 'I-VTEC' EMBLEM              | neu \$36.50 ✓      |
| 1PCS | BOOTLID OUTER HANDLE 288.60          | CRG \$366.20 ✓     |
| 1PCS | BOOTLID INNER LOCK 192.30            | twi \$245.30 ✓     |
| 1PCS | BOOTLID LOCK STRIKER                 | 11 \$66.80 X       |
| 2PCS | BOOTLID HINGES @\$101.00             | 11 \$202.00 X      |
| 1PCS | BOOTLID WEATHERSTRIP                 | twi \$166.30 ✓     |
| 1PCS | BOOTLID KEY CYCLINDER                | Dye \$245.30 ✓     |
| 1PCS | REAR BUMPER                          | D15 \$585.20 ✓     |
| 2PCS | REAR BUMPER SIDE HOLDERS @\$25.50    | 3uf \$51.00 ✓      |
| 1SET | REAR BUMPER CLIPS                    | neu \$39.00 ✓      |
| 1PCS | REAR EXHAUST                         | 1 \$688.20 X       |
| 2PCS | REAR EXHAUST MOUNTINGS @\$45.00      | 11 \$90.00 X       |
| 1PCS | REAR END PANEL                       | 3.6.00 \$445.10 ✓  |
| 1PCS | REAR END PANEL TOP GARNISH           | twi \$221.30 ✓     |
| 1PCS | REAR FLOOR PANEL                     | 1 \$1,066.30 X     |
| 1PCS | REAR FLOOR PANEL TOP BOARD 184.50    | 71-1 \$428.30 ✓    |
| 2PCS | TAILLAMPS @\$382.30                  | CRG \$764.60 ✓     |
| 2PCS | TAILLAMP HOUSING PANELS @\$285.20    | 0/500 \$570.40 X   |
| 2PCS | REAR FENDERS @\$843.59               | 1 \$1,687.18 X     |
| 2PCS | REAR FENDER INNER TRIMS @\$262.50    | 11 \$525.00 X      |
| 1PCS | REAR WINDSCREEN MOULDING             | 11 \$82.30 X       |
| 1PCS | BONNET 645.20                        | 10/3uc \$866.20 ✓  |
| 1PCS | BONNET RUBBER 66.50                  | neu \$83.40 ✓      |
| 1PCS | BONNET LOCK 125.00                   | twi \$268.30 ✓     |
| 2PCS | BONNET HINGES @\$85.00               | 11 \$170.00 X      |
| 1PCS | FRONT BUMPER 522.01                  | 10/12 \$645.20 ✓   |
| 2PCS | FRONT BUMPER SIDE RETAINERS @\$30.50 | 3uf \$61.00 ✓      |
| 1SET | FRONT BUMPER CLIPS                   | neu \$50.00 ✓      |
| 1PCS | FRONT BUMPER REINFORCEMENT 273.20    | 3uf \$345.20 ✓     |
| 2PCS | FRONT BUMPER BRACKETS @\$68.50       | 3uf \$137.00 ✓     |
| 1PCS | RADIATOR GRILLE                      | CRG \$389.20 ✓     |
| 1PCS | RADIATOR GRILLE 'H' LOGO             | neu \$35.50 ✓      |

(29%)

|      |                         |                     |     |             |   |
|------|-------------------------|---------------------|-----|-------------|---|
| 2PCS | HEADLAMPS @\$845.20     | 485.10 x 2 = 970.20 | one | \$1,690.40  | ✓ |
| 1PCS | FRONT SUPPORT PANEL     |                     | sub | \$663.50    | ✓ |
| 1PCS | AIRCON CONDENSER        |                     | sub | \$923.40    | ✓ |
| 1PCS | RADIATOR ASSY           |                     | 11  | \$1,088.20  | x |
| 1PCS | RADIATOR FAN MOTOR      |                     | 11  | \$455.20    | x |
| 2PCS | FRONT FENDERS @\$645.00 |                     | 11  | \$1,290.00  | x |
|      |                         |                     |     | \$18,493.08 |   |

(20%)  
9125.71  
7300.28

|        |                              |  |     |          |     |
|--------|------------------------------|--|-----|----------|-----|
| S.NETT |                              |  |     |          |     |
| 1SET   | REAR BUMPER REVERSE SENSOR   |  | sub | \$280.00 | 200 |
| 1PCS   | REAR LICENCE PLATE W/HOLDER  |  | sub | \$50.00  | 40  |
| 1PCS   | REAR END PANEL SEALANT       |  | sub | \$50.00  | ✓   |
| 1SET   | REAR FLOOR PANEL INSULATOR   |  | 11  | \$280.00 | x   |
| 1PCS   | FRONT LICENCE PLATE W/HOLDER |  | sub | \$50.00  | 40  |
| 1BOL   | RADIATOR COOLANT             |  | 11  | \$50.00  | x   |

|                                              |            |            |
|----------------------------------------------|------------|------------|
| TO CHECK WIRING                              | \$80.00    | 30         |
| TO DISMENTLE & REPLACING REVERSE SENSOR      | \$80.00    | 50         |
| TO TRANSFER BOOTLID MECHANISM                | \$100.00   | 60         |
| TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTERY | \$150.00   | 80         |
| TO DISMENTLE & REFIX REAR EXHAUST            | \$100.00   | 60         |
| TO DISMENTLE & REFIX REAR WINDSCREEN         | 11         | \$150.00 x |
| TO DISMENTLE & REFIX PETROL TANK             | 11         | \$100.00 x |
| TO SPRAY RUST PROOFING                       | \$180.00   | 100        |
| TO REFILL AIR CON GAS                        | \$150.00   | 100        |
| LABOUR FOR PANEL BEATING & REPLACING PARTS   | \$2,800.00 | 1400       |
| TO PUTTY & SPRAY PAINTING                    | \$2,500.00 | 1800       |

TOTAL \$25,643.08

11310.26

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Shu Pei (LKKAUTO)**

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Thursday, 1 March 2018 8:50 AM  
**To:** Shu Pei (LKKAUTO)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Direct Settlement - Accident Involving SJS5477G (OI : LPC - TBA) AND SKA6825L (TP : LKK REF -CC6/LPC18003742/Ukb3 ) on 27.02.2018  
**Attachments:** 01032018084802.pdf

Our Ref : 17/18/18/VP05/020435

Dear Shu Pei,

We attached a copy of insured's GIA report for your attention.

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]  
**Sent:** Wednesday, 28 February, 2018 6:19 PM  
**To:** GERALD POH WEE BIN; ONG LI LI; ERIC WOO JUN KIAT  
**Cc:** MT\_Claim\_SG; Admin A; Hsiao Tong (LKKAUTO); Zaini (LKK Auto)  
**Subject:** Direct Settlement - Accident Involving SJS5477G (OI : LPC - TBA) AND SKA6825L (TP : LKK REF - CC6/LPC18003742/Ukb3 ) on 27.02.2018

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SKA 6825L at M/s Fastech Auto Pte Ltd.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:  
- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet

Our case handler in-charge is Zaini and he can be contacted at DID: 6841-2132.

Thank you.

Best Regards,

**Shu Pei** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [shupe@lkkauto.com](mailto:shupe@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Vic (LKKAUTO)

---

**From:** Vic (LKKAUTO)  
**Sent:** Tuesday, 8 May, 2018 11:35 AM  
**To:** jason@fastechauto.com.sg  
**Cc:** Admin A; Vic (LKKAUTO); Bevan Lim (LKK Auto)  
**Subject:** Your Ref: SKA 6825L ACIDENT INVOLVING VEHICLES SJS 5477G / SKA 6825L / OTHERS ON 27/02/2018 LKK REF CC6/LPC18003742/Uhb3  
**Attachments:** DV.pdf

Your Ref: SKA 6825L  
Our Ref: CC6/LPC18003742/Uhb3

WITHOUT PREJUDICE

Dear Jason,

ACIDENT INVOLVING VEHICLES SJS 5477G / SKA 6825L / OTHERS ON 27/02/2018

We refer to the subject matter and we confirmed in receipt of your LOD.

On a without prejudice basis and purely for an amicable settlement on a without admission of liability to our Insured's part, we have our principal's mandate and we offer settlement as below:

|                              |                     |
|------------------------------|---------------------|
| Cost of Repair (w/gst)       | \$ 9,630.00         |
| Loss of Use (\$60 x 10 days) | \$ 600.00           |
| GIA Search Fee               | \$ 2.00             |
| <b>TOTAL</b>                 | <b>\$ 10,232.00</b> |

If agreeable, kindly let the owner sign the attached DV and forward to us(LKK) the **original signed copy (hard copy)** for payment processing.

The above amount is to be made payable to **FASTECH AUTO PTE LTD.**

Thank you.

*"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."*


Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicapeh@lkkauto.com](mailto:vicapeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                           |                              |            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|------------------------------|------------|-------------------------------------------------------------------------------------|
| LONPAC INSURANCE BHD                                                                                                                   |                                                                                           | Ref : CC6/LPC18003742/Uhb3s2 |            |                                                                                     |
| 300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555                                                                              |                                                                                           | Date : 21-05-2018            |            |  |
|                                                                                                                                        |                                                                                           | Code : LPC2                  |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                           |                              |            |                                                                                     |
| Insured Veh.                                                                                                                           | SJS 5477G                                                                                 | Veh. Inspected               | SKA 6825L  |                                                                                     |
| Policy No.                                                                                                                             | Z17VP05015421                                                                             | Coverage (\$)                | 0.00       |                                                                                     |
| Claim No.                                                                                                                              | 17/18/18/VP05/020435                                                                      | Excess (\$)                  | 0.00       |                                                                                     |
| Assign From                                                                                                                            |                                                                                           | Assign Date                  | 27/02/2018 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                           |                              |            |                                                                                     |
| Make & Model                                                                                                                           | HONDA CITY (M)                                                                            | c.c                          | 1497       |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                                    | Year of Reg.                 | 2011       |                                                                                     |
| Chassis No.                                                                                                                            | MRHGM25509P020044                                                                         | Colour                       | BLUE       |                                                                                     |
| Odometer                                                                                                                               | 104488                                                                                    | Steering                     | IN ORDER   |                                                                                     |
| Brakes                                                                                                                                 | IN ORDER                                                                                  | Modification                 | SPORTS RIM |                                                                                     |
| General                                                                                                                                | GOOD                                                                                      |                              |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                           |                              |            |                                                                                     |
|                                                                                                                                        | Size                                                                                      | Make                         | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                         | 185/60R15                                                                                 | FALKEN                       | 6 mm       |                                                                                     |
| L/H Front Tyre                                                                                                                         | 185/60R15                                                                                 | FALKEN                       | 6 mm       |                                                                                     |
| R/H Rear Tyre                                                                                                                          | 185/60R15                                                                                 | FALKEN                       | 6 mm       |                                                                                     |
| L/H Rear Tyre                                                                                                                          | 185/60R15                                                                                 | FALKEN                       | 6 mm       |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                           |                              |            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.                                                                           |                                                                                           |                              |            |                                                                                     |
| DAMAGES SEE DETAILS.                                                                                                                   |                                                                                           |                              |            |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                           |                              |            |                                                                                     |
| Accident Date                                                                                                                          | 27/02/2018                                                                                | Inspection Date              | 27/02/2018 |                                                                                     |
| Survey held at                                                                                                                         | FASTECH AUTO PTE LTD<br>1 KAKI BUKIT AVENUE 6<br>#01-48/48/50 AUTOBAY<br>SINGAPORE 417883 |                              |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                           |                              |            |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                           |                              |            |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                           |                              |            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                           | <b>9 Working Days</b>        |            |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 6825L

| Qty | Description of Parts               | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b> |                      |                           |                   |
| 1   | BOOTLID                            | DENTED / BUCKLED     | 685.10                    | 685.10            |
| 1   | BOOTLID REAR LOGO                  | NECESSARY            | 38.80                     | 38.80             |
| 1   | BOOTLID 'CITY' EMBLEM              | NECESSARY            | 35.20                     | 35.20             |
| 1   | BOOTLID 'I-VTEC' EMBLEM            | NECESSARY            | 36.50                     | 36.50             |
| 1   | BOOTLID OUTER HANDLE               | CRACKED              | 366.20                    | 288.60            |
| 1   | BOOTLID INNER LOCK                 | TWISTED              | 245.30                    | 192.30            |
| 1   | BOOTLID LOCK STRIKER               | NOT NECESSARY        | 66.80                     | -                 |
| 2   | BOOTLID HINGES @ \$101.00          | NOT NECESSARY        | 202.00                    | -                 |
| 1   | BOOTLID WEATHERSTRIP               | TWISTED              | 166.30                    | 166.30            |
| 1   | BOOTLID KEY CYLINDER               | DAMAGED              | 245.30                    | 245.30            |
| 1   | REAR BUMPER                        | DISTORTED            | 585.20                    | 585.20            |
| 2   | REAR BUMPER SIDE HOLDERS @ \$25.50 | BENT                 | 51.00                     | 51.00             |
| 1   | SET REAR BUMPER CLIPS              | NECESSARY            | 39.00                     | 39.00             |
| 1   | REAR EXHAUST                       | TO REPAIR SEE LABOUR | 688.20                    | -                 |
| 2   | REAR EXHAUST MOUNTINGS @ \$45.00   | NOT NECESSARY        | 90.00                     | -                 |
| 1   | REAR END PANEL                     | BADLY DENTED         | 445.10                    | 445.10            |
| 1   | REAR END PANEL TOP GARNISH         | TWISTED              | 221.30                    | 221.30            |
| 1   | REAR FLOOR PANEL                   | TO REPAIR SEE LABOUR | 1,066.30                  | -                 |
| 1   | REAR FLOOR PANEL TOP BOARD         | TORN                 | 428.30                    | 184.50            |
| 2   | TAILLAMPS @ \$382.30               | CRACKED              | 764.60                    | 764.60            |
| 2   | TAILLAMP HOUSING PANELS @ \$285.20 | O/S DENTED           | 570.40                    | 285.20            |
| 2   | REAR FENDERS @ \$843.59            | TO REPAIR SEE LABOUR | 1,687.18                  | -                 |
| 2   | REAR FENDER INNER TRIMS @ \$262.50 | NOT NECESSARY        | 525.00                    | -                 |
| 1   | REAR WINDSCREEN MOULDING           | NOT NECESSARY        | 82.30                     | -                 |
| 1   | BONNET                             | DENTED / BUCKLED     | 866.20                    | 645.20            |
| 1   | BONNET RUBBER                      | NECESSARY            | 83.40                     | 66.50             |
| 1   | BONNET LOCK                        | TWISTED              | 268.30                    | 125.00            |

Report Ref No. CC6/LPC18003742/Uhb3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                           | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------------------|----------------------|---------------------------|-------------------|
| 2   | BONNET HINGES @ \$85.00                        | NOT NECESSARY        | 170.00                    | -                 |
| 1   | FRONT BUMPER                                   | DENTED / DEFORMED    | 645.20                    | 522.01            |
| 2   | FRONT BUMPER SIDE RETAINERS @ \$30.50          | BENT                 | 61.00                     | 61.00             |
| 1   | SET FRONT BUMPER CLIPS                         | NECESSARY            | 50.00                     | 50.00             |
| 1   | FRONT BUMPER REINFORCEMENT                     | BENT                 | 345.20                    | 273.20            |
| 2   | FRONT BUMPER BRACKETS @ \$68.50                | BENT                 | 137.00                    | 137.00            |
| 1   | RADIATOR GRILLE                                | CRACKED              | 389.20                    | 389.20            |
| 1   | RADIATOR GRILLE 'H' LOGO                       | NECESSARY            | 35.50                     | 35.50             |
| 2   | HEADLAMPS @ \$845.20                           | CRACKED              | 1,690.40                  | 970.20            |
| 1   | FRONT SUPPORT PANEL                            | BENT                 | 663.50                    | 663.50            |
| 1   | AIRCON CONDENSER                               | BENT                 | 923.40                    | 923.40            |
| 1   | RADIATOR ASSY                                  | NOT NECESSARY        | 1,088.20                  | -                 |
| 1   | RADIATOR FAN MOTOR                             | NOT NECESSARY        | 455.20                    | -                 |
| 2   | FRONT FENDERS @ \$645.00                       | TO REPAIR SEE LABOUR | 1,290.00                  | -                 |
|     | LESS 20% DISCOUNT                              |                      | -                         | -1,825.14         |
|     |                                                |                      | 18,493.08                 | 7,300.57          |
|     | <b>SPECIAL NETT ITEMS</b>                      |                      |                           |                   |
| 1   | SET REAR BUMPER REVERSE SENSOR (SN)            | SHORTED              | 280.00                    | 200.00            |
| 1   | REAR LICENCE PLATE W/HOLDER (SN)               | BENT                 | 50.00                     | 40.00             |
| 1   | REAR END PANEL SEALANT (SN)                    | NECESSARY            | 50.00                     | 50.00             |
| 1   | SET REAR FLOOR PANEL INSULATOR (SN)            | NOT NECESSARY        | 280.00                    | -                 |
| 1   | FRONT LICENCE PLATE W/HOLDER (SN)              | BENT                 | 50.00                     | 40.00             |
| 1   | BOL RADIATOR COOLANT (SN)                      | NOT NECESSARY        | 50.00                     | -                 |
|     |                                                |                      | 760.00                    | 330.00            |
|     | <b>LABOUR</b>                                  |                      |                           |                   |
|     | TO CHECK WIRING.                               |                      | 80.00                     | 30.00             |
|     | TO DISMANTLE & REPLACING REVERSE SENSOR.       |                      | 80.00                     | 50.00             |
|     | TO TRANSFER BOOTLID MECHANISM.                 |                      | 100.00                    | 60.00             |
|     | TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY. |                      | 150.00                    | 80.00             |
|     | TO DISMANTLE & REFIX REAR EXHAUST.             |                      | 100.00                    | 60.00             |
|     | TO DISMANTLE & REFIX REAR WINDSCREEN.          | NOT NECESSARY        | 150.00                    | -                 |

Report Ref No. CC6/LPC18003742/Uhb3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty                                                                  | Description of Parts                                                                                                                   | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|----------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|                                                                      | TO DISMANTLE & REFIX PETROL TANK.                                                                                                      | NOT NECESSARY | 100.00                    | -                 |
|                                                                      | TO SPRAY RUST PROOFING.                                                                                                                |               | 180.00                    | 100.00            |
|                                                                      | TO REFILL AIR CON GAS.                                                                                                                 |               | 150.00                    | 100.00            |
|                                                                      | LABOUR FOR PANEL BEATING & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR EXHAUST, REAR FLOOR PANEL, REAR FENDERS AND FRONT FENDERS. |               | 2,800.00                  | 1,400.00          |
|                                                                      | TO PUTTY & SPRAY PAINTING.                                                                                                             |               | 2,500.00                  | 1,800.00          |
|                                                                      |                                                                                                                                        |               | 6,390.00                  | 3,680.00          |
| GRAND TOTAL                                                          |                                                                                                                                        |               | 25,643.08                 | 11,310.57         |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) |                                                                                                                                        |               |                           | 9,000.00          |

Report Ref No. CC6/LPC18003742/Uhb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.