

REC. BY:

REF: CS3 / AXA18003746 / Wbez

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Stacey Ng

of

AXA

Date/Time:

26/02/2018 4:12pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJK 2695E

Insured:

SHD 9997J

at Workshop m/s

Teamwork

Tel:

of

53 Ubi Ave 1 #01-24

Policy No:

P16 80520

Claim No:

C0471112

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16-07-2018

CA / REV / REP. / REV 24 HRS WP

28-07-2018

H.O.D. Endorsement:

Date/Time:

27/2/2018 10:01am

Person Contacted:

Chris

Vehicle IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SJK 2695E - X.
	Dismantle: 2/3/2018
	After repair: 7/3/2018



## ...CLAIM SUBFOLDER...(New Assignment)

Incomplete Estimation

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Feb 2018		26 Feb 2018 16:12				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

<b>CLAIM SUBFOLDER DETAILS</b>		[Created by insurer]	
Insured:	<b>TRANS-CAB SERVICES PTE LTD</b>		
Main Claimant:	<b>SUNG YOUNG HOON, ID: G5592764U</b>		
Vehicle Reg. No.:	<b>SJK2695E</b>	Date of Loss:	16/02/2018 15:00 - :59
Claim Type:	<b>TP / C0471112</b>	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	<b>SHD9797J</b>	Policy No. (Claimant):	
		Excess:	\$5,000.00
Repairer:	<b>Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475</b>		
Handling Insurer:	<b>AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Stacey Ng - 6880 4351]</b>		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/03/2018]</b>		
Driver/Custodian (Insured):	<b>NG LIP YAH (54 / Male), NRIC: S1590767C, Tel: +6590299103</b>		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>AXA_SG (26/02/2018): WP / New TP Assignment - C0471112/P1680520</li> </ul>			
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

10-01 am @ 27/2/18  
 vehicle in  
 person @ chris  
 sur @ Bryan

**Enquire Transfer Fee****Vehicle Details**

Vehicle No.: SJK2695E  
 Vehicle Type: P10 - Passenger Motor Car  
 Vehicle Attachment 1: No Attachment  
 Vehicle Scheme: Normal  
 Vehicle Make: NISSAN  
 Vehicle Model: TEANA 2.0L CVT ABS D/AIRBAG 2WD  
 Chassis No.: JN1BDUJ32Z0000442  
 Propellant: Petrol  
 Engine No.: MR20677155A  
 Engine Capacity: 1997 cc  
 Maximum Power Output: 100.0 kW ( 134 bhp)  
 :  
 Maximum Laden Weight: 1900 kg  
 :  
 Unladen Weight: 1450 kg  
 Year Of Manufacture: 2008  
 Original Registration Date: 14 Oct 2008  
 Lifespan Expiry Date: -  
 COE Category: E - Open Category  
 Quota Premium: \$15,661.00  
 COE Expiry Date: 13 Oct 2018  
 Road Tax Expiry Date: 13 Oct 2018  
 PARF Eligibility Expiry Date: 13 Oct 2018  
 Inspection Due Date: 13 Oct 2019  
 Intended Transfer Date: 12 Apr 2018  
 CO2 Emission: -  
 CO Emission: -  
 HC Emission: -  
 NOx Emission: -  
 PM Emission: -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

**Amount Payable**

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Total Amount Payable:</b>			<b>25.00</b>

You may print this page for reference.

OK

Print

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Foreign Identification Number

Owner ID:

2764U

### Vehicle Details

Vehicle No.:

SJK2695E

Vehicle to be Exported:

Yes

Intended De-registration Date:

12 Apr 2018

Vehicle Make:

NISSAN

Vehicle Model:

TEANA 2.0L CVT ABS D/AIRBAG 2WD

Primary Colour:

Black

Manufacturing Year:

2008

Engine No.:

MR20677155A

Chassis No.:

JN1BDUJ32Z0000442

Maximum Power Output:

100.0 kW (134 bhp)

Open Market Value:

\$25,376.00

Original Registration Date:

14 Oct 2008

First Registration Date:

14 Oct 2008

Transfer Count:

1

Actual ARF Paid:

\$25,376.00

### Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

13 Oct 2018

PARF Rebate Amount:

\$12,688.00

### Intended COE Rebate Details

COE Expiry Date:

13 Oct 2018

COE Category:

E - Open Category

COE Period(Years):

10

QP Paid:

\$15,661.00

COE Rebate Amount:

\$779.00

Total Rebate Amount:

\$13,467.00

The information contained herein is correct as at 12 Apr 2018

OK

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	21/02/2018 16:08
Date Of Accident	16/02/2018 15:00
Exact Location Of Accident	PIE TWDS JURONG AT THOMSON FLYOVER (BEFORE STEVEN)
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK2695E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SUNG YOUNG HOON
Passport No/FIN	G5592764U
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97526046
Alternative Phone No	OFFICE-97526046

#### Vehicle Particulars

Manufacturer	NISSAN
Model	TEANA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

#### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA066413
Cover Note Number	

#### Driver

Name of Driver	SUNG YOUNG HOON
Passport No/FIN	G5592764U
Date Of Birth	26/11/1965
Occupation	INDOOR
Date Of Driving Pass	27/03/2002
Driving Experience	15 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97526046
Fax Number	
Contact Number	OFFICE-97526046
Email Address	NOEMAIL

Address -  
 Postcode -  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

AHEAD OF MY VEHICLE SLOW DOWN AND STOP DUE TO HEAVY TRAFFIC. SO I FOLLOWED AND STOP WITHOUT ANY CONTACT TO THE FRONT VEHICLE. OUT OF SUDDEN, I FELT A HEAVY IMPACT ON MY REAR PORTION. AFTER COMING OUT FROM MY VEHICLE, I REALISED THERE IS A TOTAL 4 VEHICLES INVOLVED.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SHD9797J  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Vehicle Category TAXI  
 Name of Driver NG LIP YAH  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number UNKNOWN

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE C

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 3**

Vehicle Registration Number

SJJ3934P

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE D

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

*[Signature]*  
 Policyholder's Signature / Date & Time

*[Signature]*  
 Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

**Sketch Plan**



Describe Circumstances of the Accident

Ahead of my vehicle, I slow down and stop  
due to heavy traffic, so I also follow and  
stop without any contact to the front vehicle.  
Out of sudden, I feel a heavy impact on my  
rear portion. After coming out from my vehicle,  
I realize there is total 4 vehicle involve.

*Champ*

Declaration

We declare the foregoing particulars are true in every respect.

*Champ*  
Policyholder's Signature / Date &  
Time

*Champ*  
Driver's Signature (if driver is not the policyholder) / Date  
& Time

Witnessed by Reporting Centre  
Personnel

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Incomplete Estimation

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Feb 2018		26 Feb 2018 16:12 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>TRANS-CAB SERVICES PTE LTD</b> , Co. Reg. No.: -								
Main Claimant:	<b>SUNG YOUNG HOON</b> , ID: G5592764U								
Vehicle Reg. No.:	<b>SJK2695E</b>	Date of Loss:	16/02/2018 15:00 - :59 [112 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / C0471112</b>	Policy/Cover Note No.:	P1680520 (Third Party Only)						
Vehicle Reg. No. (Insured):	<b>SHD9797J</b>	Policy No. (Claimant):							
		Excess:	S\$5,000.00						
Repairer:	<b>Teamwork Garage Pte Ltd (HQ)</b> 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475								
Handling Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288 ... [Handled by <b>Stacey Ng</b> - 6880 4351]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Teo Cheng Ming Wilson</b> ] ... [Final Rpt due 07/03/2018]								
Driver/Custodian (Insured):	NG LIP YAH (54 / Male), NRIC: S1590767C, Tel: +6590299103								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• AXA_SG (26/02/2018): <b>WP / New TP Assignment - C0471112/P1680520</b>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

### Claim Documents

**\*SJK2695E (C0471112)**  
**[SHD9797J]**  
**TP**  
**SUNG YOUNG HOON**  
**Feb 16 2018 3:00PM**  
**[TRANS-CAB SERVICES PTE LTD]**  
**Teamwork Garage Pte Ltd**

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)
View [View in Browser](#)

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail Print
1	22/02/18 08:53	EMAIL_ABS		Load PDF
2	22/02/18 08:53	SDB2988D GIA_ABS		Load PDF
3	22/02/18 08:53	SHD9797J INS GIA_ABS		Load PDF
4	22/02/18 08:53	SJJ3934P GIA_ABS		Load PDF
5	22/02/18 08:53	SURVEY LIST_ABS		Load PDF
6	26/02/18 16:12	Email reply from teamwork		Load TIF

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AXA18003746/WBE2

Date: 18/04/2018

#### REFERENCE

Handling Insurer: AXA Insurance Pte Ltd	Policy No:	P1680520	
Claimant Vehicle No : SJK2695E	Insured Vehicle No :	SHD9797J	
Date of Loss: 16/02/2018	Nature of Claim:	TP	Claim No: C0471112

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJK2695E</b>	Engine No:	MR20677155A
Make & Model:	NISSAN TEANA, 2.0 (A)	Chassis No:	JN1BDUJ32Z0000442
Reg. Date:	14/10/2008 (Man. Year: 2008)	Odometer:	136428 km
Colour:	Black		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 2 mm	Rear Left Side:	Michelin 3 mm
Front Right Side:	Michelin 2 mm	Rear Right Side:	Michelin 3 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	26/02/2018	
Date Inspected:	28/02/2018 Inspected At:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	0.0 days	

**Adjuster:** Teo Cheng Ming Wilson

**Manager:** CATHERINE CHONG KAI LING

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG                      Version: 1.0 (Last Synchronised: 18 Apr 2018)  
**Parts:**                      143                      NISSAN TEANA 2.0 (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:**                      Repairer's                      (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SJK2695E)  
**Validity:**                      These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >