

Surveyor

From (Person):

Rasul
Gerald Poh

ASSIGNMENT (Office)

of LPC

Date/Time: 26/2/18 @ 5.29pm

Estimated Cost:

Bill to:

OD IP WS/TPRES/OD RES/EVA/INV/MV7CS

To Inspect Vehicle No:

SKA9465Y

Insured:

at Workshop m/s:

Mova Automotive

Tel:

02723892 / 97762311

of No. 22 Jalan Kilang # 07-01

Policy No:

Claim No:

17/18/18/vp05/020421

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/02/2018

15 Fan Yang Road

CA / REV REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9.46am @ 27/2/18

Person Contacted:

Annie

Vehicle IN/OUT

Date/Time	Action/Instruction
	(<input checked="" type="checkbox"/>) Estimate
	SKA 9465Y - CCG/LPC18003644/AW43 D.O.A: 22/2/18
28/2/18	Revert by merimen, pending repair cost from repairer
1/3/18	@ 4.40pm Samuel call up said they are unable to repair within the Nett Value
2/3/18	@ 8.30am Informed Gerald vehicle recommended TL

5/3/18	@ 2.53pm Samuel said they are able to repair at LS \$15K
5/3/18	Revert by merimen, repairer asking LS \$15K
6/3/18	Recd appraised \$13,428.50 from Mr Chew by merimen
7/3/18	@ 9.05am Check with Gerald insured top up \$1571.50
7/3/18	@ 4.54pm Suzanne said Gerald has informed them to proceed repair, OI Top up \$1571.50
4/5/18	@ 1.22pm Samuel said they have submitted \$13,428.50
11/5/18	LS \$15,000 - (Recd 31,874.78, 68%)

RECEIVED 11 MAY 2018

Signature: *Rasul*

2011/4

ASSIGNMENT

Vehicle: SKA 94654
Type: M/Cycle/Buy Van/Lorry/Taxi/Prime Mover
Track/Trailer:
Make: Jaguar XF 3.0 V6
Colour: BLACK
So. Reading: 148478
Eng No:
Chassis: S4JA C0569 BFR 97086
Gear: Good 5 Foot Burnt
Steering: Good 5 Jammed Leaked Burnt or
Brake: Good 5 Jammed Leaked Burnt or
Mod: NH 5 STD A/R or
Tyre Size: R 245/45 ZR18
R

Estimated Cost:
QD / TP / WS / TP RES / OD RES / EVA / INV / MV:
To inspect Vehicle No: 90616581
at Workshop via:
of:
Insured:
Policy No:
Claims No:
Sum Insured: Excess:
Client's Record:
Make of Van:

(Policy Condition)
Remarks: The van had commenced its repair at the time of inspection.

NS	OS

Est. or Market Value: 66k-
IDAO Accident Report: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res: Yes or No
Lift Sum: % 3 Val: Yes or No
CA / REV / REP. / 24 HRS
Date: Person Contacted: Vehicle IN / OUT

Front: 6 mm 6 mm
R. Bal: 6 mm 6 mm
L. Bal: 6 mm 6 mm
D. O.A: 22/02/18 mm 27/02/18 mm
Survey held at: MANA (PY)
Des. of Damages: 5 Rear OS NS UC Roofed or
The UIC / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction
2/3/18 Rasul Revert vehicle TL by merimen
2/3/18 Submit uneconomical TL
5/3/18 @10spn Gerald call up want us to revert LS \$15k
RECEIVED 02 MAR 2018

Date Time File Pass of: : Preli. Report
 : Final Report
Date Time File Return of:
11/5- typist
Report Format: merimen
Lump Sum: LS \$15000/2
Days Of Repair: 8
Resurvey No. of Trip: 1
Add Fee:
Steered:
Tires:
Tech:
Rep:
36x15=540
170+540=710
710x20%=142
710+142=852
50
50
53
1005+10=1015

Survey Department Check List (Case Handler)

Reference No. : CS/LPC/18003TH8/RH013
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form					
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 23/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/20:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS/LPC18003748/R1vd3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 27-02-2018	
		Code : LPC2	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SKA 9465Y
Policy No.		Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020421	Excess (\$)	0.00
Assign From	MERIMEN (GERALD POH)	Assign Date	27/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	22/02/2018	Inspection Date	27/02/2018
Survey held at	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Feb 2018 Sendback Est	26 Feb 2018 17:20 S\$46,874.78	26 Feb 2018 17:59 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	YONG KAR MOH, ID: S7188011G, Tel: +6590112816, Email: MICHAEL@IBN.COM		
Vehicle Reg. No.:	SKA9465Y	Date of Loss:	22/02/2018 09:00 - :59
Claim Type:	OD / 17/18/18/VP05/020421	Policy/Cover Note No.:	N/A (Comprehensive)
		Excess:	S\$0.00
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) No. 22 Jalan Kilang, #07-01, Mova Building, 159419 Bukit Merah - Tel: 62723892/64763333		
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/03/2018]		
Driver/Custodian:	YONG KAR MOH (46 / Male), NRIC: S7188011G, Tel: +6590112816		
Adj Asg. Remarks:	SURVEY & REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS View All

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

SKA9465Y (17/18/18/VP05/020421)

OD

Feb 22 2018 9:00AM

[YONG KAR MOH]

Mova Automotive Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From Lonpac Insurance Bhd (HQ) (LONPAC_HQ), sent on **06/03/2018 18:31 PM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$13428.50) - SKA9465Y - Claim Handler: Gerald Poh

Approved:13428.50.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd 300 Beach Road #17-04/07 The Concourse Singapore 199555	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Gerald Poh	Date: 05 Mar 2018
<u>Preliminary Advice</u>	

Vehicle No	: SKA9465Y	Accident Date	: 22/02/2018
Make	: JAGUAR XF	Policy No.	: N/A
Assignment Date	: 26/02/2018	Excess	: S\$0.00
Date of Inspection	: 27/02/2018	Est. Duration of Repair	: 8.00
Inspection At	: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) NO. 22 JALAN KILANG, #07-01, MOVA BUILDING SINGAPORE 159419		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	46,874.78
Revised Amount	:S\$	41,292.03
Check Items (Estimated)	:S\$	5,162.05
Total	:S\$	46,454.08

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	54,143.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,857.00

Remarks

<input type="checkbox"/>	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
<input type="checkbox"/>	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
<input checked="" type="checkbox"/>	Other comments :Repairer asking for Lump Sum \$15,000/-

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gerald Poh

Date: 02 Mar 2018

Preliminary Advice

Vehicle No	: SKA9465Y	Accident Date	: 22/02/2018
Make	: JAGUAR XF	Policy No.	: N/A
Assignment Date	: 26/02/2018	Excess	: S\$0.00
Date of Inspection	: 27/02/2018	Est. Duration of Repair	: 0
Inspection At	: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) NO. 22 JALAN KILANG, #07-01, MOVA BUILDING SINGAPORE 159419		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	46,874.78
Revised Amount	:S\$	41,292.03
Check Items (Estimated)	:S\$	5,162.05
Total	:S\$	46,454.08

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	54,143.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,857.00

Remarks

() The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

(X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd 300 Beach Road #17-04/07 The Concourse Singapore 199555	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Gerald Poh	Date: 28 Feb 2018
<u>Preliminary Advice</u>	

Vehicle No	: SKA9465Y	Accident Date	: 22/02/2018
Make	: JAGUAR XF	Policy No.	: N/A
Assignment Date	: 26/02/2018	Excess	: S\$0.00
Date of Inspection	: 27/02/2018	Est. Duration of Repair	: 8.00
Inspection At	: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) NO. 22 JALAN KILANG, #07-01, MOVA BUILDING SINGAPORE 159419		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	46,874.78
Revised Amount	:S\$	41,292.03
Check Items (Estimated)	:S\$	5,162.05
Total	:S\$	46,454.08

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	54,143.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,857.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING REPAIR COST FROM REPAIRER

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 8011G

Vehicle Details

Vehicle No.: SKA9465Y
Vehicle to be Exported: Yes
Intended De-registration Date: 23 Feb 2018
Vehicle Make: JAGUAR
Vehicle Model: XF 3.0 V6 LUXURY AT ABS D/AB HID 2WD 4DR
Primary Colour: Black
Manufacturing Year: 2010
Engine No.: 591404333FC
Chassis No.: SAJAC05D9BFR97086
Maximum Power Output: 175.0 kW (234 bhp)
Open Market Value: \$56,697.00
Original Registration Date: 15 Apr 2011
First Registration Date: 15 Apr 2011
Transfer Count: 2
Actual ARF Paid: \$56,697.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 14 Apr 2021
PARF Rebate Amount: \$36,853.00

2/23/2018

PARF/COE Rebate Enquiry

Intended COE Rebate Details

COE Expiry Date:	14 Apr 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$55,001.00
COE Rebate Amount:	\$17,290.00
Total Rebate Amount:	\$54,143.00

The information contained herein is correct as at 23 Feb 2018

OK

66,000
54,143

11,857

11k

Jaguar XF 3.0A Luxury

Price	\$65,800
Reg date	19-Apr-2011
Manufactured	2010
Mileage	130,000 km
Transmission	Auto
Engine Capacity	2,967 cc
Road Tax	\$2,348 per year
Power	175.0 kW (234 bhp)
Curb Weight	1,735 kg
Features	Superb 3.0L V6 Engine Producing 234 BHP, 6 Speeds Transmission With Paddle Shifters, SRS Airbags, ABS, DSC, Cruise Control, Bi Xenon Headlamps.
Accessories	Rain Sensors, 140W Audio System With In Dash Single CD Player. Bluetooth, Dual Digital Climatic AC Control, Push Start/Stop, Multi Steering Control.
Description	Classic, Elegant And Sporty White Jaguar XF 3.0 For Sale! Clean Interior And Original Paint. Well Taken Care By Previous Owner. Serviced Regularly By Previous Owner. No Accidents. The Only White Unit And The Cheapest In The Market. View To Believe! Call Now For A Non Obligatory Discussion. Loan Can Be Arranged! Trade In Welcome!
COE	\$59,073
OMV	\$52,020
ARF	\$52,020
Depreciation	\$12,630 / year
No. of owners	2
Type of Vehicle	Luxury Sedan
Availability	Available

Seller Information

Company	Just Paper Motoring	
	» dealer's pricelist » 35 vehs sold 10 vehs available	
Address	176 Sin Ming Drive #05-14	
Location	Sin Ming Autocare	
Office No	64574192	
Contact Person(s)	Joseph	86851212



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/02/2018 09:42
Date Of Accident	22/02/2018 09:10
Exact Location Of Accident	CTE TOLLROAD AFTER AMK EXIT 11
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA9465Y
Insured/Policyholder	
Name Of Registered Owner	YONG KAR MOH
NRIC No	S7188011G
Email Address	MICHAEL@IBN.COM
Mobile Phone No	(LOCAL) +65-90112816
Alternative Phone No	OFFICE-90112816

Vehicle Particulars

Manufacturer	JAGUAR
Model	XF-3.0 V6 LUXURY (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO

Policy Number

Cover Note Number

Driver

Name of Driver	YONG KAR MOH
NRIC No	S7188011G
Date Of Birth	25/09/1971
Occupation	INDOOR
Date Of Driving Pass	12/03/2013
Driving Experience	4 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90112816
Fax Number	
Contact Number	OFFICE-90112816
Email Address	MICHAEL@IBN.COM

Address	770 BEDOK RESERVOIR RD #08-01
Postcode	479250
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE791A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SKA 94654 ACCIDENT DATE & TIME: 22/2/18 9.10am
CONTACT NUMBER: +65 90112816 E-MAIL ADDRESS: michael@ibn.com
LOCATION: Along CTE Toll road after Ang Mo Kio Exit 11

I accidentally hit on the front vehicle (truck Nissan GBE T91A) during the traffic jam

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION

Please state: ☒ Claim Own Policy ☐ Claim Third Party ☒ Claim OD/TP at other workshop ☐ Reporting Only

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder Signature _____
Date & Time: _____

Driver's Signature: _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 3

Annex D

NOTICE OF REPORTING

This is to confirm that Yong Kar Moh, NRIC/FIN S7188011G, has reported to the Police a non-injury traffic accident which occurred at Along CTE toll road after Ang Mo Kio exit 11 on 22/02/2018 at 0910 am involving the following vehicles: SKA9465Y and GBE791A

2 If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Rank/Name of Issuing Officer: Sgt T140176 Leow Su Ling

Date: 22/02/2018 Time: 1156hrs

S/D Ref: 27

Police Post/Unit : QUEENSTOWN POLICE CENTRE

Original - to be issued to informant

Queenstown
Neighbourhood Police Centre
No 3 Queensway #01-03
Singapore 149073



Sketch Plan Pg. 4



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

	EFFECTIVE DATE
Class 2B Motorcycles <= 300 cc	12 Mar 2013
Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles <= 2500kg	12 Mar 2013



NP 428A



2/26/2018

Estimate Report



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing in New/Used Cars, Hire Purchase & Insurance



INSURER:

Lonpac Insurance Bhd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	N/A	Date of Loss:	22/02/2018
Vehicle Reg. No.:	SKA9465Y	Driveable?	
Driver Age/Info:	46 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	YONG KAR MOH	Contact No:	+6590112816
Driver:	YONG KAR MOH		
Make/Model:	JAGUAR XF, 3.0 V6 LUXURY (A)	Vehicle Reg. Date:	15/04/2011
Vehicle Colour:	BLACK	Chassis No:	SAJAC05D9BFR97086
Engine No:	591404333FC		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	18		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	44,434.78
Miscellaneous Items	0.00
Labour	2,440.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	46,874.78
+ GST 7.00% (S\$)	3,281.23
Nett Amount (S\$)	50,156.01

This claim is handled by: SAMUEL

Generated using Merimen e-Claims Internet Estimation & Adjusting System

2/26/2018

Estimate Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Feb 2018)
 Parts: 143 JAGUAR XF 3.0 V6 LUXURY (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SKA9465Y)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET	0.00	0.00	*2,925.00 F
2	1		*BONNET INSULATOR	0.00	0.00	*320.00 F
3	15		*BONNET INSULATOR CLIPS	0.00	0.00	*82.50 F
4	1		*BONNET SAFETY HANDLE	0.00	0.00	*80.00 F
5	4		*AIRBAG IMPACT SENSOR	0.00	0.00	*600.00 F
6	1		*FRONT GRILLE	0.00	0.00	*1,092.00 F
7	1		*FRONT GRILLE LOGO	0.00	0.00	*280.00 F
8	1		*FRONT BUMPER	0.00	0.00	*1,989.00 F
9	1		*FRONT BUMPER WASHER JET COVER RH	0.00	0.00	*115.00 F
10	1		*FRONT BUMPER WASHER JET RH	0.00	0.00	*230.00 F
11	1		*FRONT BUMPER SPONGE	0.00	0.00	*390.00 F
12	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*667.00 F
13	1		*HEADLAMP LH	0.00	0.00	*3,800.00 F
14	1		*HEADLAMP RH	0.00	0.00	*3,800.00 F
15	1		*FRONT SUPPORT PANEL	0.00	0.00	*1,115.00 F
16	1		*FRONT SUPPORT PANEL TOP GARNISH	0.00	0.00	*210.00 F
17	1		*RADIATOR AIR GUIDE UPPER	0.00	0.00	*210.00 F
18	1		*RADIATOR AIR GUIDE LOWER	0.00	0.00	*210.00 F
19	1		*A/C CONDENSER	0.00	0.00	*1,400.00 F
20	1		*RADIATOR	0.00	0.00	*1,500.00 F
21	1		*DASHBOARD	0.00	0.00	*4,000.00 F
22	1		*AIRBAG DRIVER	0.00	0.00	*5,840.00 F
23	1		*AIRBAG ROTARY COUPLING	0.00	0.00	*1,200.00 F
24	1		*AIRBAG PASSENGER	0.00	0.00	*3,980.00 F
25	1		*AIRBAG ECU	0.00	0.00	*2,450.00 F
26	1		*FRONT NUMBER PLATE	0	0.00	*35.00 FS
27	1		*RADIATOR COOLANT	0.00	0.00	*35.00 F
28	1		*TOWING CHARGE	0.00	0.00	*70.00 F

F=Franchise part. S=SpecNet.

Sub Total (\$\$) 38,643.50
 + Margin on L,N Items 15.00% (\$\$) 5,791.28
 Total Parts (\$\$) 44,434.78

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

2/26/2018

Estimate Report

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK AND STRAIGHTEN FRONT CHASSIS LH & RH.REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. TO REALIGN ALL CONNECTION	New	750 850.00
2	TO SPRAY PAINT ON BONNET, FRONT BUMPER LH & RH	New	700 850.00
3	REMOVE AND REPLACE A/C CONDENSER, A/C PIPE, A/C HOSE AND RADIATOR	New	XMY00? 140.00
4	TO REMOVE AND REPLACE DASHBOARD PANEL, AIRBAG DRIVER, AIR BAG PASSENGER AND AIR BAG ECU	New	250 300.00
5	TO COMPUTER DIAGNOSE AND REPROGRAMME AFTER REPAIR	New	200 300.00
Gross Labour Cost (\$\$)			2,440.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Resul

Up 20010068

8 days

L/S

27/02/18 @ 1030

EXCESS: 0

REVERT

Resurvey after repair

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Feb 2018	26 Feb 2018	26 Feb 2018	\$15,000.00	\$15,000.00		Pending for Survey Report
	Sendback Est	17:20 \$46,874.78	17:59 Edit Adj Rpt	Edit Estimates	View Rpt		Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	YONG KAR MOH, ID: S7188011G, Tel: +6590112816, Email: MICHAEL@IBN.COM								
Vehicle Reg. No.:	SKA9465Y	Date of Loss:	22/02/2018 09:00 - :59 [82 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 17/18/18/VP05/020421	Policy/Cover Note No.:	N/A (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333								
Handling Insurer:	Lompac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 07/03/2018]								
Driver/Custodian:	YONG KAR MOH (46 / Male), NRIC: S7188011G, Tel: +6590112816								
Adj Asg. Remarks:	SURVEY & REVERT								
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
• LONPAC_HQ (06/03/2018): Alert - Adj Mandate Approved (S\$13428.50) - SKA9465Y - Claim Handler: Gerald Poh									
ALL ASSOCIATED TASKS									
		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKA9465Y (17/18/18/VP05/020421)

OD

Feb 22 2018 9:00AM

[YONG KAR MOH]

Mova Automotive Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

1 per page


























☒

Assessment Reports			Thumbnail	Print
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)		
1	26/02/18 17:20	Repairer Estimates		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		
1	28/02/18 15:19	Adjuster Immediate Advice		Load HTM
2	02/03/18 09:30	Adjuster Immediate Advice		Load HTM
3	05/03/18 14:59	Adjuster Immediate Advice		Load HTM

3 per page

☒

Photos/Images			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
2	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
3	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
4	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
5	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
6	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
7	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
8	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
9	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
10	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
11	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
12	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
13	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
14	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
15	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
16	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
17	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
18	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
19	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
20	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
21	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
22	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
23	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
24	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
25	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
26	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
27	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
28	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
29	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
30	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
31	28/02/18 08:00	General View		<input checked="" type="checkbox"/>
32	28/02/18 08:00	General View		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
33	28/02/18 08:00	General View	 Load JPG	<input checked="" type="checkbox"/>
34	28/02/18 08:00	General View	 Load JPG	<input checked="" type="checkbox"/>
35	28/02/18 08:00	General View	 Load JPG	<input checked="" type="checkbox"/>
36	28/02/18 08:00	General View	 Load JPG	<input checked="" type="checkbox"/>
37	28/02/18 08:00	General View	 Load JPG	<input checked="" type="checkbox"/>
38	28/02/18 08:00	General View	 Load JPG	<input checked="" type="checkbox"/>
39	28/02/18 08:00	General View	 Load JPG	<input checked="" type="checkbox"/>
40	28/02/18 08:00	General View	 Load JPG	<input checked="" type="checkbox"/>
41	28/02/18 08:00	General View	 Load JPG	<input checked="" type="checkbox"/>
42	28/02/18 08:00	General View	 Load JPG	<input checked="" type="checkbox"/>
43	28/02/18 08:00	General View	 Load JPG	<input checked="" type="checkbox"/>
44	28/02/18 08:00	General View	 Load JPG	<input checked="" type="checkbox"/>
45	28/02/18 08:00	General View	 Load JPG	<input checked="" type="checkbox"/>
46	28/02/18 08:00	General View	 Load JPG	<input checked="" type="checkbox"/>
47	28/02/18 08:00	General View	 Load JPG	<input checked="" type="checkbox"/>
48	28/02/18 08:00	General View	 Load JPG	<input checked="" type="checkbox"/>
49	09/05/18 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	09/05/18 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	09/05/18 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	09/05/18 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	09/05/18 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	26/02/18 17:19	Driver's Driving License	 Load PDF	
2	26/02/18 17:19	E-filed GIA report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/02/18 07:59	MARK ESTIMATE	 Load PDF	
2	02/03/18 09:56	Log card (if available)	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	23/02/18 10:25	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	23/02/18 10:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	23/02/18 10:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	23/02/18 10:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	23/02/18 10:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	23/02/18 10:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	23/02/18 10:25	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	23/02/18 10:02	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC18003748/R1VD3E2

Date: 18/05/2018

REFERENCE

Insured/Claimant: YONG KAR MOH Policy No: N/A
Date of Loss: 22/02/2018 Nature of Claim: OD Claim No: 17/18/18/VP05/020421

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA9465Y**
Make & Model: JAGUAR XF, 3.0 V6 LUXURY (A) Engine No: 591404333FC
Reg. Date: 15/04/2011 (Man. Year: 2010) Chassis No: SAJAC05D9BFR97086
Colour: Black Odometer: 148478 km
Engine Capacity: 2967 cc
Market Value/New Car Price: S\$66,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/45Z R18 Rear Tyre Size: 245/45Z R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	44,434.78	39,392.03	5,042.75	11.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,440.00	1,900.00	540.00	22.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,874.78	41,292.03	5,582.75	11.91
Approved Total (Overridden) (S\$)		15,000.00		
- Top-Up Amount (S\$)	0.00	1,571.50	-1,571.50	
(S\$)	46,874.78	13,428.50	33,446.28	71.35
+ GST 7.00/7.00% (S\$)	3,281.23	940.00	2,341.23	71.35
Nett Amount (S\$)	50,156.01	14,368.50	35,787.51	71.35

INSPECTION

Date of Assignment: 26/02/2018 Present Location:
Date Inspected: 27/02/2018 Inspected At:

Mova Automotive Pte Ltd (Bukit Merah)
No. 22 Jalan Kilang, #07-01, Mova Building
Singapore 159419

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$66,000.00
OMV : \$56,697.00
PARF Rebate (1) : \$36,853.00
Quota Premium Paid : \$55,001.00
COE Rebate (2) : \$17,290.00
Total Rebate (1) + (2) = : \$54,143.00

The total amount incurred will be Market Value \$66,000.00 minus Total Rebate \$54,143.00 = \$11,857.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 May 2018)
Parts: 143	JAGUAR XF 3.0 V6 LUXURY (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA9465Y)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	2,925.00 F	*2,925.00 F
2	1		*BONNET INSULATOR	Deformed	320.00 F	*320.00 F
3	15		*BONNET INSULATOR CLIPS	Necessary	82.50 F	*82.50 F
4	1		*BONNET SAFETY HANDLE	Bent	80.00 F	*80.00 F
5	4		*AIRBAG IMPACT SENSOR	Activated	600.00 F	*600.00 F
6	1		*FRONT GRILLE	Broken	1,092.00 F	*1,092.00 F
7	1		*FRONT GRILLE LOGO	Missing	280.00 F	*280.00 F
8	1		*FRONT BUMPER	Torn	1,989.00 F	*1,989.00 F
9	1		*FRONT BUMPER WASHER JET COVER RH	Serviceable	115.00 F	*- F
10	1		*FRONT BUMPER WASHER JET RH	Serviceable	230.00 F	*- F
11	1		*FRONT BUMPER SPONGE	Cut	390.00 F	*390.00 F
12	1		*FRONT BUMPER REINFORCEMENT	Serviceable	667.00 F	*- F
13	1		*HEADLAMP LH	Cracked	3,800.00 F	*3,800.00 F
14	1		*HEADLAMP RH	Cracked	3,800.00 F	*3,800.00 F
15	1		*FRONT SUPPORT PANEL	Bent	1,115.00 F	*1,115.00 F
16	1		*FRONT SUPPORT PANEL TOP GARNISH	Cracked	210.00 F	*210.00 F
17	1		*RADIATOR AIR GUIDE UPPER	Serviceable	210.00 F	*- F
18	1		*RADIATOR AIR GUIDE LOWER	Serviceable	210.00 F	*- F
19	1		*A/C CONDENSER	Serviceable	1,400.00 F	*- F
20	1		*RADIATOR	Serviceable	1,500.00 F	*- F
21	1		*DASHBOARD	Torn	4,000.00 F	*4,000.00 F
22	1		*AIRBAG DRIVER	Activated	5,840.00 F	*5,840.00 F
23	1		*AIRBAG ROTARY COUPLING	Activated	1,200.00 F	*1,200.00 F
24	1		*AIRBAG PASSENGER	Activated	3,980.00 F	*3,980.00 F
25	1		*AIRBAG ECU	Activated	2,450.00 F	*2,450.00 F
26	1		*FRONT NUMBER PLATE	Scratched	35.00 FS	*35.00 FS
27	1		*RADIATOR COOLANT	Not Necessary	35.00 F	*- F
28	1		*TOWING CHARGE		88.00 F	*70.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	38,643.50	34,258.50
+ Margin on L,N Items 15.00/15.00% (S\$)	5,791.28	5,133.53
Total Parts (S\$)	44,434.78	39,392.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK AND STRAIGHTEN FRONT CHASSIS LH & RH.REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. TO REALIGN ALL CONNECTION	New	850.00	750.00
2	TO SPRAY PAINT ON BONNET, FRONT BUMPER LH & RH	New	850.00	700.00
3	REMOVE AND REPLACE A/C CONDENSER, A/C PIPE, A/C HOSE AND RADIATOR	New	140.00	0.00
4	TO REMOVE AND REPLACE DASHBOARD PANEL, AIRBAG DRIVER, AIR BAG PASSENGER AND AIR BAG ECU	New	300.00	250.00
5	TO COMPUTER DIAGNOSE AND REPROGRAMME AFTER REPAIR	New	300.00	200.00
Gross Labour Cost (S\$)			2,440.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >