

ASS. REC. BY:

REF:

CS3/SPF18003751/Tlvd389

Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Abdul Rahman

of

SPF

Date/Time:

26/02/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 27984

Insured:

QX 61X

at Workshop m/s

Han Car Repairs

Tel:

62710275

of

B/k 1001, Bkt Merah Lane 3 # 01-49

Policy No:

Claim No:

AEMD/105/009/2018/017

Sum Insured:

Excess:

Make of Veh:

D.O.A.

31/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

1wp

H.O.D. Endorsement:

Date/Time:

11:00am 27/2/18

Person Contacted:

tina

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLF 27984 - X
	QX 61X - X
14/6/18	Submit LS \$ 3300, 4 days

— — —

200

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

CS3 | SPF 1800 3751 | Tivd3

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By:

VERON

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION			Ref : CS3/SPF18003751/T1vd3	
ACCIDENT CLAIM SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333			Date : 27-02-2018 Code : SPF	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	QX 61X	Veh. Inspected	SLF 2798U	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/1009/2018/017	Excess (\$)	0.00	
Assign From	ABDUL RAHMAN	Assign Date	27/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	31/01/2018	Inspection Date	27/02/2018	
Survey held at	HAN CAR REPAIRS BLK 1001 #01-49 BUKIT MERAH LANE 3 ALEXANDRA VILLAGE SINGAPORE 159718			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : SLF2798U

Our Ref : AEMD/105/009/2018/017

Date : 26 February 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir/Madam,

ACCIDENT ON 31 JANUARY 2018 INVOLVING POLICE VEHICLE QX61X AND OTHER VEHICLE SLF2798U

We refer to the above matter.

- 2 Please arrange for a Pre-Repair Inspection of vehicle no. SLF2798U at M/s Han Car Repairs of Blk 1001 Bukit Merah Lane 3 #01-49, Singapore 159718.
- 3 Estimates were not provided by the workshop.
- 4 For appointment, please contact Ms Susan at HP: 97777266 / DID: 62710275.
- 5 Thank you.

Yours faithfully,

Abdul Rahman
Accident Claims Officer
for ASST DIRECTOR

cc : KSCGP Juris LLP Ref: SLF2798U/HC/sy/ms Via Fax: 65383708 (FYI, pls)

A FORCE FOR THE NATION

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/02/2018 17:08
Date Of Accident	31/01/2018 15:10
Exact Location Of Accident	BLK 28 OLD POLICE ACADEMY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF2798U
Insured/Policyholder	
Name Of Registered Owner	NG SHI WEI
NRIC No	S8333200Z
Email Address	NGSHIWEI7@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97503949
Alternative Phone No	OTHERS-97503949

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 HYBRID X (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA243617
Cover Note Number	20/08/2017 - 19/08/2018

Driver

Name of Driver	NG SHI WEI
NRIC No	S8333200Z
Date Of Birth	25/10/1983
Occupation	INDOOR
Date Of Driving Pass	12/05/2004
Driving Experience	13 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97503949
Fax Number	
Contact Number	OTHERS-97503949
EMail Address	NGSHIWEI7@GMAIL.COM

49
225/45K18

Address	BLK 8 TANJONG PAGAR PLAZA #18-105
Postcode	080008
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG POLICE DIVISIONAL HQ ('J' DIVISION)
Police Station Address	ROAD: NO. 2 JURONG WEST AVENUE 5 , POSTCODE: 649482 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7910000 - FAX NO: 68965649
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE POLICE REPORT & SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX61X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	MUHD SAIFUDDIN ZULLFATTH
NRIC/Passport Number	S8925485Z
Contact Number	98324316
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 1/2/18
2:13pm


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

Date of accident: 31/1/18 Time: 1510hrs Location: Blk 28 Old Police Academy
 My Vehicle A: SLF2798U Vehicle B: QX61X Vehicle C: -

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car was parked stationary at 1330hrs on 31/1/18 with hand brake on.

At around 1530hrs I was informed a police car has hit my stationary vehicle. Thereafter, I exchange particulars with the driver of QX61X. Please see detail in Police Report.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop:

Email address:

& myself:

Email address:

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 1/2/18

1410hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Officer's Signature

Name:

NRIC/FIN No.:

veh. SLF 2798 U

DOI. 27.2.18

1. Tailgate	- dt	909.60
2. Tailgate windscreen sealant	- nec	50.00
" " moulding	- nec	160.00
3. Tailgate emblem 'HYBRID'	- nec	56.20
4. Tailgate emblem 'VEZEL'	- nec	56.20
" weatherstrip	-	135.00
5. Tailgate 'H' logo	- nec	35.00
" keyless sensor	- ?	80.00
6. Rear bumper	- dt	721.70
@ 456.00		
7. Rear tail lamp x 2	- dm	913.60
8. Rear corner garnish	- dm	149.50 x 2
		299
9. Rear end panel top garnish	- dm	86.40
10. Tailgate outer garnish	- dm	245.10
" lock	-	170.00
11. Rear bumper lower diffuser	- scr - R	250 (S/N)
" sensor	-	45.00
12. Set rear bumper lower diffuser clips	- nec	

less 20%

~~3417.80~~
~~683.56~~
~~2734.24~~

1. To dismantle/refit tailgate fittings / ancillary accessories
2. To dismantle/refit tailgate glass
3. To supply /rust proofing /resal tuff coating treatment to resprayed/replaced/repainted panel
4. To respray affected areas - 2 panels
5. Labour charge - panel beating, repairing of affected areas


14/6/18

60.00

120.00

60.00

400.00

600.00

6 To conduct electrical check,
replace reverse sensors, module,
rewiring, etc

50.00

Total

4024.24


14/6/18

4/5 3200/2

Labour 4 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref: CS3/SPF18003751/T1vd3s2

ACCIDENT CLAIM SECTION(SINGAPORE POLICE Date: 20-06-2018
FORCE)1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMYSINGAPORE 298333



ATTN: ABDUL RAHMAN

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 61X	Veh. Inspected	SLF 2798U
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/1009/2018/017	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	26/02/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL 1.5X HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU31203879	Colour	BLACK
Odometer	020686 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45R18	GOODYEAR	6 mm
L/H Front Tyre	225/45R18	GOODYEAR	6 mm
R/H Rear Tyre	225/45R18	GOODYEAR	6 mm
L/H Rear Tyre	225/45R18	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/01/2018	Inspect Date / Time	27/02/2018 (12:40 PM)
Survey held at	HAN CAR REPAIRS BLK 1001 #01-49 BUKIT MERAH LANE 3 ALEXANDRA VILLAGE SINGAPORE 159718		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

OPINION ON REPAIR COST FOR VEHICLE NO. SLF 2798U

Qty	Description of Parts	Condition	Recommended (\$)
REPLACEMENT OF PARTS			
1	TAILGATE	DENTED	909.60
1	TAILGATE WINDSCREEN SEALANT	NECESSARY	50.00
1	TAILGATE WINDSCREEN MOULDING	NECESSARY	160.00
1	TAILGATE EMBLEM 'HYBRID'	NECESSARY	56.20
1	TAILGATE EMBLEM 'VEZEL'	NECESSARY	56.20
1	TAILGATE WEATHERSTRIP	* CHECK	-
1	TAILGATE 'H' LOGO	NECESSARY	35.00
1	TAILGATE KEYLESS SENSOR	* CHECK	-
1	REAR BUMPER	DENTED	721.70
2	REAR TAILLAMP @ \$456.80	DAMAGED	913.60
2	REAR CORNER GARNISH @ \$149.50	DAMAGED	299.00
1	REAR END PANEL TOP GARNISH	DAMAGED	86.40
1	TAILGATE OUTER GARNISH	DAMAGED	245.10
1	TAILGATE LOCK	* CHECK	-
1	REAR BUMPER LOWER DIFFUSER (NPA)	TO REPAIR SEE LABOUR	-
1	SET REAR BUMPER LOWER DIFFUSER CLIPS	NECESSARY	45.00
	LESS 20% DISCOUNT		-715.56
			2,862.24
SPECIAL NETT ITEMS			
1	REAR BUMPER SENSOR (SN)	* CHECK	-
			-
LABOUR			
	TO DISMANTLE / REFIT TAILGATE FITTINGS / ANCILLARY ACCESSORIES.		60.00
	TO DISMANTLE / REFIT TAILGATE GLASS.		120.00
	TO SUPPLY RUST PROOFING / RESEAL TUFF COATING TREATMENT TO RESPRAYED / REPLACED / REPAIRED PANEL.		60.00
	TO RESPRAY AFFECTED AREAS - 2 PANELS.		400.00
	LABOUR CHARGE - PANEL BEATING, REPAIRING OF AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR BUMPER LOWER DIFFUSER.		600.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Recommended (\$)
	TO CONDUCT ELECTRICAL CHECK, REPLACE REVERSE SENSORS, MODULE, REWIRING, ETC.		50.00
			1,290.00
	GRAND TOTAL		4,152.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)(EXCLUDE CHECK ITEMS S\$566.00 NETT)			3,300.00

Report Ref No. CS3/SPF18003751/T1vd3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.