

REF: MSLG

ASSIGNMENT

Date: 28.02.2018

Veh No: PA 9850J

Yr Regn: 7/12/2010

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Coaster Super LWB 4009

Colour: White A/O: Insured / Std / NI / NA

Sp. Reading: 582056 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JT GEP 538606000208

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size F: 215/75R17.5 Mic

R: " " Pirelli

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 23/2/18 D.O.I. 28/2/18

Survey held at RUS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

TP RES / OD RES / EVA / INV / MV

Vehicle No: PA 9850J

Workshop m/s: RVS Allied Global

8 Woodlands Ind Park E3

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

11am - 12pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time : Action / Instruction

RECEIVED 28 FEB 2018

Date/Time: File Pass to?

☐ : Preli. Report☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: —

Survey Fee

200

Transportation

Add Fee: ☐ Site Insp \$☐ Interview \$☐ Technician \$☐ Weekend \$

Photos

Chart

10

Report Format:

Lump Sum / I.B.I. \$

TP 4050 3700/-