

ASS. REC. BY: Adrian May chua REF: CS/FCI18003776/Agd3MV Special Information

Surveyor: rws ASSIGNMENT (Office) FCI Date/Time: 27/2/18 @ 9-42am

From (Person): May chua of FCI

Estimated Cost: _____ Bill to: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SIG 75432 Insured: SHB 6640H

at Workshop m/s: MG Solution Tel: 67444165

of 23 Kaki Bkt Ave 4 #02-03

Policy No: D-18088936MFSH Claim No: D18001415MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 14/02/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' H.O.D. Endorsement: _____

Date/Time: 1:33pm @ 27/2/18 Person Contacted: Ms. Heng Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SIG 75432 - NA LINC18003041/h-4 D.O.A: 14/2/18
	SHB 6640H - NA LINC18003041/h-4 D.O.A: 14/2/18
01/7/17 @	10:21am informed May chua, we are pending estimate from repairers.
04/5/18 @	2:50pm revised to May chua by email.
	US \$3400, 5 days (red \$5277.12, b17.)

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: ✓ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

R/Bal. 00 mm R/Bal. 00 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 27/02/18

Survey held at MG Solution

Des. of Damages: Frt / Rear ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP 1st Cap.
	MV : 13K
	PV : 9.5K
	Nett : 3.5K

RECEIVED 04 MAY 2018

Date/Time, File Pass to? ☐ : Preli. Report

11/04/18 Adrian ☐ : Final Report

Date/Time, File Return to? _____

2) _____

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee: 160

Transportation: 50

Photo: 35

Other: _____

Report Format: TP

Lump Sum / I.B.K. (\$) 3400

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Invs (\$) ☐ Weekend (\$)

TOTAL: 295



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FC118003778/Aqd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 27-02-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 6640H	Veh. Inspected	SJG 7543Z
Policy No.		Coverage (\$)	0.00
Claim No.	D18001415MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	27/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/02/2018	Inspection Date	27/02/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	15-02-2018	Our Ref No. D18001415MFSH
Accident Date	14-02-2018	Claim Type. Third Party
Insured Vehicle	SHB6640H	Third Party Vehicle. SJG7543Z
Survey Location	23 KAKI BUKIT AVE 4 AAS KAKI BUKIT CENTRE#02-03	
Contact Person.	HENG YOKE HONG(MS)	
Contact No.	67444165/ 0	Fax No. 67444604
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MG SOLUTION PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235071)



PRI Documents



Close



PRI Header Details

Claim No	D18001415MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & MG SOLU
Workshop Name	MG SOLUTION PTE LTD (Contact Person : HENG YOE HONG(MS))	Survey Location & Contact Details	23 KAKI BUKIT AVE 4 AAS KAKI BUKIT CENTRE#02-03 Mobile: 0 , Phone: 67444165 , Fax: 67444604 EmailId: MG3SOLUTION@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHB6640H	TP Vehicle No	SJG7543Z
PRI Recieved Date	26-02-2018 08:50:09 PM	Surveyor Appointed Date	27-02-2018 09:41:46 AM	Surveyor Accept Date	27-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	27-02-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 4 May 2018 2:54 PM
To: 'Claim Workflow System'; assignments
Cc: 'MAYCHUA@MSFIRSTCAPITAL.COM.SG'; SUR
Subject: RE: SURVEY ASSESSMENT - D18001415MFSH/1
Attachments: CSFC18003778Aqd3.pdf

Dear May,

Enclosed herewith preliminary advice of SJG 7543Z.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 1 March 2018 10:21 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001415MFSH/1

Dear May,

Please be informed that we have inspected the vehicle SJG 7543Z on 27/02/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 27 February 2018 1:34 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001415MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001415MFSH

Date: 04 May 2018

Our Ref: CS/FCI18003778/Aqd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJG 7543Z

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/02/2018 at the premises of M/s MG SOLUTION, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>8,677.12</u>
Revised Estimate Amount	: S\$ <u>3,400.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the o/s portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 1 March 2018 10:21 AM
To: 'Claim Workflow System'; assignments
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001415MFSH/1

Dear May,

Please be informed that we have inspected the vehicle SJG 7543Z on 27/02/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 27 February 2018 1:34 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001415MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 27 February 2018 9:42 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001415MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/02/2018 12:01
Date Of Accident	14/02/2018 08:30
Exact Location Of Accident	JUNC OF FINLAYSON GREEN & RAFFLES QUAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJG7543Z
Insured/Policyholder	
Name Of Registered Owner	PINNACLE RENTAL PTE. LTD.
Co Reg No	201634825C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90665340

Vehicle Particulars

Manufacturer	HONDA
Model	CITY
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5087371903-01
Cover Note Number	-

Driver

Name of Driver	DESMOND HO SEE FONG
NRIC No	S1654443D
Date Of Birth	25/07/1964
Occupation	OUTDOOR
Date Of Driving Pass	13/04/1982
Driving Experience	35 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90702808
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 889B TAMPINES AVE 8 #14-512
Postcode 522869
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : RAUNAQ NANWANI
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name GEYLANG N.P.C
Police Station Address ROAD: 132 PAYA LEBAR ROAD , POSTCODE: 409014 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO POLICE REPORT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

Details of Witness 1

Name RAUNAQ NANWANI
Phone Number 82275114
Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHB6640H
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver TEO AH SAI

NRIC/Passport Number	S0715642A
Contact Number	96725540
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

DETAILS OF INJURED PERSON 1

Name	DESMOND HO SEE FONG
Approximate Age	
Injuries Sustain	NECK & RIGHT SHOULDER
Injured person in which vehicle?	SJG7543Z
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Goose Bay

A = 225 45422

B = 248 66404

Finlayson Green

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to Police Report



Holder's Signature
Date & Time:

are true in every respect.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Recording Centre Personnel's Signature
Name:
NRQ/IN No.:



SINGAPORE POLICE FORCE



T/20180214/2036

Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8486999

1 of 4

Report No: T/20180214/2036

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/02/2018 11:11	Video Report No.:	Station Diary No.: 37
--	-------------------	--------------------------

Informant's Particulars

Name of Informant: DESMOND HO SEE FONG			Address: APT BLK 869B TAMPINES AVENUE 8 #14-512 SINGAPORE 522869		
ID Type / ID No.: NRIC NO / S1854443D			Contact No.: Home/Office: Mobile: 90702808		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 53	Date of Birth: 25/07/1964	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Uber			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 14/02/2018 08:30	Type of Location:
Location: Along Road 1 FINLAYSON GREEN				
Junction of Finlayson Green turning into Raffles Quay.				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHB6640H	Taxi					1
SJG7543Z	Car					1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180214/2036

Police Station Of Origin:
Gaylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8488999

2 of 4

Report No: T/20180214/2036

CONTINUATION OF REPORT

Driver			
Name	TEO AH SAI	ID No.	S0715842A
Related Vehicle	SHB8640H (Taxi)	Contact No.	96725540
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	DESMOND HO SEE FONG	ID No.	S1654443D
Related Vehicle	SJG7543Z (Car)	Contact No.	90702808
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	RAUNAQ NANWANI	ID No.	NIL
Related Vehicle	SJG7543Z (Car)	Contact No.	82275114
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 14/02/2018, at about 0830hrs, I was driving my silver colored Honda car bearing licence plate SJG7543Z, on Finlayson Green turning right into raffles quay. I was on transit with one passenger by the name of Mr Raunaq (H/P: 8227 5114) to 1 Raffles Quay. I was driving on the lane in which I could either go straight or turn right. Traffic light turned green in my favor and I was in motion about to turn right when I felt an impact on the right side of my car. I then realized that a blue colored taxi bearing licence plate SHB8640H had actually collided into my side mirror. I then went down to make a check.

I then realized that the taxi had actually drove straight when the lane is for turning right only and subsequently, hit onto my right mirror. We both then shifted our vehicles to the side of the road and exchanged particulars and took photos of our vehicles. The said driver mentioned that he was on the lane meant for going straight and argued with me that he was not at fault and that his lane discipline was



SINGAPORE
POLICE FORCE



T/20180214/2035

Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8486999

3 of 4

Report No. T/20180214/2035

CONTINUATION OF REPORT

correct.

I then made a check with my passenger and he informed that he is fine. I asked whether he could be my witness to this accident and he informed that he is willing to become my witness and told me his contact details.

I would like to declare that I do not have an in-built car camera but I noticed that the taxi has one.

After the incident, I felt uncomfortable in my neck and right shoulder region, and I sought medical assistance from Gallilee Clinic and was given a 3 days Medical Leave (MC no. 66786).



**SINGAPORE
POLICE FORCE**



T/20180214/2038

Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8486999

4 of 4

Report No: T/20180214/2038

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Staff Sgt LUQMAN MOHD MANSOR

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

SSI KASMAWATI BTE SAMIAN

Contact No.: 65476179

Signature Of Informant:

Date/Time:

14/02/2018 11:11

Classification Of Case:

Authentication Stamp

NP188



SINGAPORE
POLICE FORCE

SIGNATURE

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4825C
Vehicle Details	
Vehicle No.:	SJG7543Z
Vehicle to be Exported:	Yes
Intended De-registration Date:	27 Feb 2018
Vehicle Make:	HONDA
Vehicle Model:	CITY VTEC CVT
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	L15A16800197
Chassis No.:	MRHGD86508P040068
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$17,931.00
Original Registration Date:	15 Jul 2008
First Registration Date:	15 Jul 2008
Transfer Count:	2
Actual ARF Paid:	\$17,931.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jul 2018
PARF Rebate Amount:	\$8,965.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jul 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,685.00
COE Rebate Amount:	\$557.00
Total Rebate Amount:	\$9,522.00

The information contained herein is correct as at 27 Feb 2018

OK



Enjoy up to
\$188 OFF handsets!



honda city

Price Range ▾

Depreciation ▾

2008 ▾

Vehicle Type ▾



Advanced Search

Used Car Comparison

— Comparing 3 Vehicles —

Honda City 1.5A LX



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Honda City 1.5M LX



Add to Shortlist

Honda City 1.5M LX



Add to Shortlist



Use search bar above to add to compare.

CAR DETAILS

Price	\$15,555	\$15,000	\$15,500	-
Instalment	\$1,388	\$1,339	\$1,232	-
Registration Date	13-Nov-2008	18-Nov-2008	16-Dec-2008	-
Manufactured	2008	2008	2008	-
Mileage	145,637 km	-	167,588 km	-
Transmission	Auto	Manual	Manual	-
Engine Cap	1,497 cc	1,497 cc	1,497 cc	-
Road Tax	\$684 /yr	\$684 /yr	\$684 /yr	-
Power	88.0 kW (118 bhp)	88.0 kW (118 bhp)	88.0 kW (118 bhp)	-
Curb Weight	1,150 kg	1,110 kg	1,110 kg	-
Features	Original Condition.	Honda 1.5L I-VTEC 16 Valves Responsive Yet Fuel Efficient, ABS, 2 x SRS Airbags, 5 Speed Manual Transmission, Front And Rear Disc Brake	Fuel Efficient 1.5L DOHC I-VTEC 4 Cylinders 16 Valves Engine, 5 Speed Manual Transmission, 4 Disc ABS, Airbags, Immobiliser Remote Key.	-
Accessories	Factory Fitted Interior.	Audio System, Retractable Side Mirrors With Indicator, Fog Lamps, Solar Films,	Factory Fitted Audio Sound System, Leather Upholstery, Side Mirrors With Indicator, Fog Lamps, Reverse Sensors, 16" Sports Rims With Michelin Tyres.	-
Description	(Japanese Sedan At \$591 Per Month!) Ideal For Short Term Usage. 9 Months To Be Driven. Drive And Get Back \$9731 PARF Value And \$500 Body Value At End Of COE, Total Return \$10,231. Value For Money, Cheaper Than Rental. (Viewing Available Daily By Appointment.)	Good For First Time Driver Or Short Term Usage! Civic Look Alike But Is A Honda City 1.5LX Manual! You Be Paying 1.5cc Road Tax! Low Insurance! Manual Petrol Consumption! Most Importantly Lowest Pricing! Lower Monthly Depreciation! High Arf \$18460! Come View And We Discuss Further Thanks!	High PARF \$9,230. Low Maintenance Costs. Very Well Kept. In-House Loan. Please Call Us For More Details.	-
COE	\$13,801	\$13,801	\$7,721	-
OMV	\$19,462	\$18,460	\$18,460	-
ARF	\$19,462	\$18,460	\$18,460	-
Depreciation	\$8,240 /yr	\$8,010 /yr	\$7,860 /yr	-
No. of Owners	2	5	3	-
Type of Vehicle	Sedan	Sedan	Sedan	-
Category	PARF Car, Premium Ad Car	PARF Car	PARF Car	-
Availability	Available	Available	Available	-

SELLER INFORMATION

Seller	Sincere Motoring Pte Ltd	ValueCars Auto Traders	Sino Credit Pte Ltd	-
--------	--------------------------	------------------------	---------------------	---

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: FIRST CAPITAL	DATE	: 26/02/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJG7543Z		
MODEL	: HONDA CITY 1.5		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>			
DATE	: 14-Feb-18		
TIME	: 08:30HRS		
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BONNET	1	\$ 540.90	\$ 540.90
2	FRONT DOOR SIDE MIRROR ASSY RH	1	\$ 560.90	\$ 560.90
3	FRONT BUMPER	1	\$ 470.30	\$ 470.30
4	FRONT BUMPER SIDE RETAINER RH	1	\$ 62.40	\$ 62.40
5	HEADLAMP RH	1	\$ 612.00	\$ 612.00
6	HEADLAMP LOWER BRACKET RH	1	\$ 58.50	\$ 58.50
7	FRONT FENDER RH	1	\$ 450.30	\$ 450.30
8	FRONT FENDER COWLING RH	1	\$ 97.90	\$ 97.90
9	SUPPORT PANEL	1	\$ 633.00	\$ 633.00
10	FRONT KNUCKLE ARM RH	1	\$ 412.00	\$ 412.00
11	FRONT KNUCKLE BEARING RH	1	\$ 255.30	\$ 255.30
12	FRONT WHEEL HUP RH	1	\$ 278.10	\$ 278.10
13	FRONT SHOCK ABSORBER RH	1	\$ 422.20	\$ 422.20
14	FRONT LOWER ARM RH	1	\$ 342.60	\$ 342.60

TOTAL PRICE \$ 5,196.40

LESS 20% \$ 1,039.28

SUB TOTAL PRICE \$ 4,157.12

3234.90

2587.92

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP <i>new</i>	1	\$ 20.00	\$ 20.00
2	FRONT FENDER SEALANT RH <i>new</i>	1	\$ 80.00	\$ 80.00
3	FRONT FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 20.00	\$ 20.00
4	FRONT WHEEL RIM RH <i>hit</i>	1	\$ 300.00	\$ 300.00
5	FRONT WHEEL TYRE RH <i>new</i>	1	\$ 650.00	\$ 650.00
		340	TOTAL	\$ 1,070.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	500	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	500	
3	TUFF COAT	\$ 250.00	X.	
4	WIRING CHECK	\$ 180.00	30	
5	REFOCUS HEADLAMP BEAM	\$ 150.00	X	
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 550.00	220	
7	FOUR WHEEL ALIGNMENT	\$ 120.00	80	
		TOTAL 1330	\$3,450.00	

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,227.12
TOTAL LABOUR COST : \$ 3,450.00
TOTAL REPAIR COST : \$ 8,677.12

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
NO OF DAYS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj total: 4257.9
27/02/18. f/s: 3-4K.
h/s 05 days.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003778/Aqd3q2	
36 ROBINSON ROAD #16-01 CITY HOUSES SINGAPORE 068877		Date : 09-05-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 6640H	Veh. Inspected	SJG 7543Z
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18001415MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	27/02/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA CITY	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MRHGD86508PD040068	Colour	SILVER
Odometer	159044	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/50 R15	BOTO	6 mm
L/H Front Tyre	195/50 R15	BOTO	6 mm
R/H Rear Tyre	195/50 R15	BOTO	6 mm
L/H Rear Tyre	195/50 R15	BOTO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/02/2018	Inspection Date	27/02/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJG 7543Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BONNET	NOT NECESSARY	540.90	-
1	FRONT DOOR SIDE MIRROR ASSY RH	CRACKED	560.90	560.90
1	FRONT BUMPER	DEFORMED	470.30	470.30
1	FRONT BUMPER SIDE RETAINER RH	NECESSARY	62.40	32.00
1	HEADLAMP RH	CRACKED	612.00	442.20
1	HEADLAMP LOWER BRACKER RH	NOT NECESSARY	58.50	-
1	FRONT FENDER RH	DENTED	450.30	450.30
1	FRONT FENDER COWLING RH	DEFORMED	97.90	97.90
1	SUPPORT PANEL	TO REPAIR SEE LABOUR	633.00	-
1	FRONT KNUCKLE ARM RH	BENT	412.00	341.00
1	FRONT KNUCKLE BEARING RH	NECESSARY	255.30	106.00
1	FRONT WHEEL HUP RH	DAMAGED	278.10	185.00
1	FRONT SHOCK ABSORBER RH	BENT	422.20	262.30
1	FRONT LOWER ARM RH	BENT	342.60	287.00
	LESS 20% DISCOUNT		-1,039.28	-646.98
			4,157.12	2,587.92
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	FRONT FENDER SEALANT RH (SN)	NOT NECESSARY	80.00	-
1	SET FRONT FENDER COWLING CLIP (SN)	NECESSARY	20.00	20.00
1	FRONT WHEEL RIM RH (SN)	CUT	300.00	300.00
1	FRONT WHEEL TYRE RH (SN)	NOT NECESSARY	650.00	-
			1,070.00	340.00
<u>LABOUR</u>				
	PANEL BEATING ,REMOVING AND REPLACING PARTS .INCLUSIVE OF THE REPAIR OF SUPPORT PANEL .		1,200.00	500.00
	SPRAY PAINTING TO AFFECTED AREA.		1,000.00	500.00
	TUFF COAT.	NOT NECESSARY	250.00	-
	WIRING CHECK .		180.00	30.00

Report Ref No. CS/FCI18003778/Aqd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REFOCUS HEADLAMP BEAM	NOT NECESSARY	150.00	-
	REMOVE AND REFIX FRONT UNDERCARRIAGE :		550.00	220.00
	FOUR WHEEL ALIGNMENT		120.00	80.00
			3,450.00	1,330.00
GRAND TOTAL			8,677.12	4,257.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,400.00

Report Ref No. CS/FCI18003778/Aqd3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.