





# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18003798/K1tb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 27-02-2018



189556

Code: INC4

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJD 3446M	Veh. Inspected	SHA 7760T
Policy No.	5097970294	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	27/02/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	25/02/2018	Inspection Date	27/02/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

TP Claims against NTUC Income: Follow-Through Survey

Date: 5/3/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	-	SMRT BUSES LTD	SMB 3529H	FV 3043U	11/12/2018	16:15	\$ 3,858.03	\$ 2,550.00
2	MT/0983770-002	COMFORT TRANSPORTATION PTE LTD	SHC 8339K	FY 5545J	25/2/2018	2:25	\$ 6,898.96	\$ 4,100.00
3	MT/0984758-001	COMFORT TRANSPORTATION PTE LTD	SHC 3155G	GBG 1237S	22/2/2018	14:40	\$ 2,549.36	\$ 1,400.00
4	MT/0980882-004	COMFORT TRANSPORTATION PTE LTD	SHD 3132S	GBC 3328X	3/2/2018	7:55	\$ 3,503.26	\$ 1,348.21
5	MT/0984276-002	COMFORT TRANSPORTATION PTE LTD	SHC 746X	SLR 7216L	28/2/2018	2:00	TOTAL LOSS	TOTAL LOSS
6	MT/0984762-001	SMRT BUSES LTD	SG 5452J	SKQ 3494T	5/1/2018	13:22	\$ 8,131.29	\$ 7,161.29
7	MT/0984765-001	SMRT BUSES LTD	SMB 336S	SHD 1237L	27/1/2018	18:30	\$ 2,990.00	\$ 700.00
8	MT/0979197-002	SMRT BUSES LTD	TIB 1116B	GBD 5665D	23/1/2018	10:05	\$ 3,964.77	\$ 3,000.00
9	MT/0983952-002	COMFORT TRANSPORTATION PTE LTD	SHB 6713G	SLA 46X	26/2/2018	6:05	\$ 6,740.80	\$ 4,950.00
10	NOT INSURED	COMFORT TRANSPORTATION PTE LTD	SHA 6973C	FBB 4102D	23/2/2018	17:15	\$ 1,250.48	\$ 600.00
11	MT/0983501-002	CITY CAB PTE LTD	SHA 9243G	PC 4246B	23/2/2018	18:05	\$ 2,681.58	\$ 2,400.00
12	MT/0984783-001	CITY CAB PTE LTD	SHB 4736D	FBL 7388Z	22/2/2018	12:30	\$ 2,487.18	\$ 950.48
13	MT/0982510-002	COMFORT TRANSPORTATION PTE LTD	SH 6763A	SJP 3496E	13/2/2018	22:00	\$ 2,324.08	\$ 1,295.76
14	MT/0984221-001	CITY CAB PTE LTD	SHC 926T	SDX 6942T	18/2/2018	16:50	\$ 3,181.90	\$ 1,400.00
15	MT/0984099-001	COMFORT TRANSPORTATION PTE LTD	SHA 4722Z	SJR 294E	16/2/2018	16:40	\$ 5,637.20	\$ 2,237.52
16	MT/0984101-001	COMFORT TRANSPORTATION PTE LTD	SHC 3372X	SLU 1543R	18/2/2018	5:35	\$ 4,132.08	\$ 560.00
17	MT/0984790-001	CITY CAB PTE LTD	SHC 7866L	SLP 4518X	18/2/2018	17:50	\$ 1,375.12	\$ 660.00
18	MT/0983617-002	COMFORT TRANSPORTATION PTE LTD	SH9111L	SHC 6770K	24/2/2018	22:50	\$ 2,605.10	\$ 975.48
19	MT/0983513-002	COMFORT TRANSPORTATION PTE LTD	SH A 3341X	SIL 7579U	24/2/2018	14:05	\$ 6,414.38	\$ 1,200.00
20	MT/0972860-002	COMFORT TRANSPORTATION PTE LTD	SMB 3141S	GBE 9185R	4/12/2017	14:25	\$ 6,153.67	\$ 6,090.67
21	MT/0983749-002	COMFORT TRANSPORTATION PTE LTD	SHA 7760T	SJD 3446M	25/2/2018	22:15	\$ 6,759.82	\$ 1,850.00

eBaoTech

GeneralClaim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.  Date of Accident   
Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5097970294	JONATHAN TAN LIN KIAT	S8947510D	GPC	drivo CLASSIC	SJD3446M	SJD3446M	06/02/2018	05/02/2019

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO. 305120104

CUSTOMER  
COMFORT TRANSPORTATION PTE LTD  
7010045  
CUSTOMER NO.  
383 SIN MING DRIVE  
ADDRESS  
Singapore SINGAPORE 575717  
65508755  
L. (R) (O)  
(P)

REGN NO.	SHA7760T	MILEAGE
MAKE	HYUNDAI	FUEL
MODEL	I-40	DATE/TIME IN
YR OF MANU	18.06.2015	TARGET DATE
CHASSIS CODE	KMHLB41UMFU069582	COMPLETION DATE/TIME

SCOUNT CARD NO.

JOB DESCRIPTION

Accident Date: 25.02.2018  
NATURE: 3P 25.02.2018

S/NO	LABOR CODE	DESCRIPTION
		NTUC - taxi Rear Right damage
		LKK/fal mi -

CHECKED & PASSED OUT BY:

SERVICE ADVISOR		CUSTOMER'S SIGNATURE	
Acknowledgement Slip		Exit Pass	
Name: LARRY		Vehicle No.: SHA7760T	
No.: SHA7760T			
Vehicle No.:			
Name of Service Advisor		Date	
Signature/Date		To be kept by Security Guard	
To be returned to Service Reception upon collection			

Larry Ng

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/02/2018 16:00
Date Of Accident	25/02/2018 22:15
Exact Location Of Accident	PIE TWDS CHANGI AIRPORT NEAR JLN EUNOS EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA7760T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	CHO WAI CHING
NRIC No	S1512892E
Date Of Birth	10/11/1961
Occupation	OUTDOOR
Date Of Driving Pass	21/03/1983
Driving Experience	34 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 118 CORPORATION DRIVE #01-462
Postcode	610118
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : - GENDER: : MALE
Passenger 2	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	JURONG WEST N.P.C
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO POLICE REPORT :T/20180226/2011

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJD3446M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JONATHAN TAN
NRIC/Passport Number	S8947510D
Contact Number	81264362
Address	
Postcode	

Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	FRT
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKX9736U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	NO CONTACT
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	CHO WAI CHING
Approximate Age	56
Injuries Sustain	PAIN TO SHOULDER, NECK AND BACK. ON 5 DAYS MC.
Injured person in which vehicle?	SHA7760T
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	



**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO REG. NO. 199303821R


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police

Report:

T/20180226/2011

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO REG NO. 199303821R

Policyholder's Signature

Date & Time:

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20180226/2011

1 of 3

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

Report No. T/20180226/2011

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/02/2018 03:04		Vide Report No.: G/20180225/0241		Station Diary No.: 11	
<b>Informant's Particulars</b>					
Name of Informant: CHO WAI CHING			Address: APT BLK 118 CORPORATION DRIVE #01-462 SINGAPORE 610118		
ID Type / ID No.: NRIC NO / S1512892E			Contact No.: Home/Office: Mobile: 82331176		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 56	Date of Birth: 10/11/1961	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,3,4		Date of Expiry:

## General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 25/02/2018 22:15	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY				
Near Jln Eunox exit				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHA7760T	Car				Slightly Damaged	1
SJD3446M	Car				Slightly Damaged	1
SKX9736U	Car				No Damage	0



**SINGAPORE  
POLICE FORCE**



T/20180226/2011

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

2 of 3

Report No. T/20180226/2011

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHO WAI CHING	ID No.	S1512892E
Related Vehicle	SHA7760T (Car)	Contact No.	82331176
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	26/02/2018	Date Discharge	26/02/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Name			
Name	JONATHAN TAN	ID No.	S8947510D
Related Vehicle	SJD3446M (Car)	Contact No.	81264362
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

**Brief Details.**

On 25/2/18, around 2215hrs, I was travelling along PIE towards Changi in my vehicle V1) SHA7760T. Subsequently, there was an accident ahead and I came to a stop as all the vehicles in front of me had done so. Subsequently, another vehicle V2) SJD3446M collided into the rear of V1. As a result, my shoulder, neck and back are in pain. I then exchanged particulars with the driver of V2. Traffic police and ambulance attended to me. I am lodging this report for insurance claims purposes.



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999



T/20180226/2011

3 of 3

Report No. T/20180226/2011

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
J /  
Staff Sgt MUHAMMAD ZHARIF BIN ZAINUQIN

Signature Of Interpreter:  
Not applicable







Officer In Charge Of Case:  
TP / GIT /  
Staff Sgt LEE GUANG HUI  
Contact No.: 65476138

 Authentication Stamp NP 388 Signature: _____ Singapore Police Force	SN 126
--	--------



Signature Of Informant:

Date/Time:  
26/02/2018 03:04

Classification Of Case:







## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHA7760T

MAKE : HYUNDAI

MODEL : i40

Date: 27.02.2018

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Rear Bumper			\$ 603.60
1	Rear Bumper Side Bracket- RH			\$ 49.00
10	Rear Bumper Clip 10 pcs @ \$2.20			\$ 22.00
1	Rear Bumper Sponge			\$ 143.40
1	Rear Bumper Reinforcement			\$ 504.35
1	Rear Bumper Under Cover			\$ 225.00
1	Exhaust Silencer - RH			\$ 954.00
1	Exhaust Pipe Centre			\$ 1,150.30
1	Rear Bumper Reflector - RH			\$ 32.00
1	Tail Lamp 1/4 Panel			\$ 97.90
1	Rear Panel			\$ 592.30
1	Rear Panel Garnish			\$ 57.70
1	Rear Panel Lower			\$ 495.50
1	Boot Lid			\$ 1,681.40
1	Boot Lid 'H' emblem			\$ 27.20
1	Boot Lid CRDI emblem			\$ 41.00
1	Boot Lid i40 emblem			\$ 41.00
SUB TOTAL				\$ 6,717.65
LESS 20%				1,343.53
DISCOUNTED TOTAL				\$ 5,374.12
1	Rear Bumper Reverse Sensor			\$ 135.70 <b>Nett</b>
1	Rear Bumper Rubber Mat			\$ 50.00 <b>Nett</b>
1	Boot Lid Comfort Logo			\$ 15.00 <b>Nett</b>
1	Boot Lid Tel No. Logo			\$ 15.00 <b>Nett</b>
				\$ 215.70
<b>Labour Charge</b>				
1	Panel Beating			\$ 400.00
1	Spray Painting Charge			\$ 600.00
1	Wiring Charge			\$ 50.00
1	R/Refix Reverse Sensor			\$ 120.00
1	R/Refix Exhaust			\$ 120.00
TOTAL LABOUR				\$ 1,170.00
ESTIMATE TOTAL				\$ 6,759.82

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date: 27/2/18

Signature: [Signature]

300

180

50.00

120.00

120.00

After Repair

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



# COMFORTDELGRO ENGINEERING

Our Job Ref No . 305120104

Date : 2. Mar. 2018

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHA7760T

Date of Accident: 25.02.2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SJD3446M

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost \$1,850.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : Larry Ng

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature :

Name : K. G. L.

Date : 2/3/18

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham escribe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18003798/K1tbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 09-03-2018



Code: INC4

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SJD 3446M	Veh. Inspected	SHA 7760T
Policy No.	5097970294	Coverage (\$)	0.00
Claim No.	MT/0983749-002	Excess (\$)	0.00
Assign From		Assign Date	27/02/2018

**2. Vehicle Particulars & Condition**

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KMHLB41UMFU069582	Colour	BLUE
Odometer	400188	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	7 mm
L/H Front Tyre	205/60 R16	HANKOOK	7 mm
R/H Rear Tyre	205/60 R16	HANKOOK	7 mm
L/H Rear Tyre	205/60 R16	HANKOOK	7 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

**5. General Information**

Accident Date	25/02/2018	Inspection Date	27/02/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>3 Working Days</b>
-------------------------------------	-----------------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7760T**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DEFORMED	603.60	603.60
1	REAR BUMPER SIDE BRACKET-RH	SERVICEABLE	49.00	-
10	REAR BUMPER CLIP @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE	TORN	143.40	143.40
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	504.35	-
1	REAR BUMPER UNDER COVER	CRACKED	225.00	225.00
1	EXHAUST SILENCER-RH	BENT	954.00	954.00
1	EXHAUST PIPE CENTRE	TO REPAIR	1,150.30	-
1	REAR BUMPER REFLECTOR-RH	CRACKED	32.00	32.00
1	TAIL LAMP 1/4 PANEL	SERVICEABLE	97.90	-
1	REAR PANEL	TO REPAIR	592.30	-
1	REAR PANEL GARNISH	SERVICEABLE	57.70	-
1	REAR PANEL LOWER	TO REPAIR	495.50	-
1	BOOT LID	SERVICEABLE	1,681.40	-
1	BOOT LID "H" EMBLEM	NOT NECESSARY	27.20	-
1	BOOT LID CRDI EMBLEM	NOT NECESSARY	41.00	-
1	BOOT LID I40 EMBLEM	NOT NECESSARY	41.00	-
	LESS 20% DISCOUNT		-1,343.53	-396.00
			5,374.12	1,584.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	BOOT LID COMFORT LOGO (SN)	NOT NECESSARY	15.00	-
1	BOOT LID TEL NO LOGO (SN)	NOT NECESSARY	15.00	-
			215.70	185.70
<b><u>LABOUR</u></b>				
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		690.00	400.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		600.00	180.00
			1,290.00	580.00

Report Ref No. NS/INC18003798/K1tbn2

GRAND TOTAL		6,879.82	2,349.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,850.00

Report Ref No. NS/INC18003798/K1tbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.