

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Date: \_\_\_\_\_

CD / TP / WS / TP RES / CD RES / EVA / INV / MV


To inspect Vehicle No: \_\_\_\_\_  
 at Workshop no/s: \_\_\_\_\_  
 of: \_\_\_\_\_

Insured: **SG 6853 K**  
 Policy No: **5030046046 - 09 11-07-17 - 100718**  
 Claims No: **MT/0981716-002**

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at this time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: **SG 5494M** Yr Regn: **5/10/17**

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Volvo B9TL** CC: **9364**

Colour: **Green** A/C: Insured / Std / Nil / NA

Sp. Reading: **17531** T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: **YV384P9284A 182957**

Gen. Cond: Good / **Fair** / Poor / Burnt

Steering: **Order** / Jammed / Leaked / Burnt or

Brake: **Order** / Jammed / Leaked / Burnt or

Mod: **Nil** / S/Rim / STD A/Rim or

Tyre Size: F: **275/70 R22.5**

R: **11**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Bridgestone**

Front

R/Bal: 6 mm

L/Bal: 6 mm

D.O.A. 8/2/18

Survey held at **SHUT.**

Rear

R/Bal: 6 mm

L/Bal: 6 mm

D.O.I. 19/2/18

Des. of Damages: Frt / Rear / O/S / **NS** / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time / Action/Instruction

**SG 5494M - X**

**SG 6853K - NA / LIP18002653 / 24**

**DUA: 080218**

Confirm **\$1590**, 2 days  
 Red: **\$337**, 17%.

RECEIVED 04 APR 2018

*[Signature]*  
**6/4/2018**

Date/Time, File Pass to?

☐ : Prelim. Report

1)

☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

\$ + RS. \$

Phone:

Cover:

TOTAL

**160**

Report Format:

Lump Sum / I.B.L: **\$1590**

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18003811/Srb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 27-02-2018  
189556



Code: INC4

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJG 6853K	Veh. Inspected	SG 5494M
Policy No.	5030046046-09	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	19/02/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	09/02/2018	Inspection Date	19/02/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

TP Claims against NTUC Income: Follow-Through Survey

Date : 04/04/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/0984098-002	SMRT TAXIS PTE LTD	SHB 5366G	SKA 7181D	28/02/2018	\$ 7,797.23	\$ 2,550.00
2	MT/0988982-001	SMRT TAXIS PTE LTD	SHC 4926S	SIK 1772Y	19/03/2018	\$ 2,842.70	\$ 550.00
3	MT/0988428-002	COMFORTDELGRO	SHA 4969D	SCE 4477U	02/04/2018	\$ 1,303.30	\$ 480.00
4	MT/0988889-002	COMFORTDELGRO	SH 6484E	SIG 4840K	31/03/2018	\$ 2,381.58	\$ 1,050.00
5	MT/0984196-002	SMRT TAXIS PTE LTD	SHC 4004C	GU 9556K	01/03/2018	\$ 10,777.84	\$ 3,750.00
6	MT/0987457-002	SMRT TAXIS PTE LTD	SHB 5197C	SLK 4501U	16/03/2018	\$ 5,230.50	\$ 920.00
7	MT/0981513-002	SMRT BUS	SMB 5057P	SLU 2644B	06/02/2018	\$ 1,540.00	\$ 700.00
8	MT/0981716-002	SMRT BUS	SG 5494M	SIG 6853K	08/02/2018	\$ 1,927.00	\$ 1,590.00
9	MT/0985967-002	SMRT TAXIS PTE LTD	SHF 7E	SIM 542R	13/03/2018	\$ 12,384.10	\$ 4,284.50

Claim received from LKK Auto

eBaoTech

General Claim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.  Date of Accident

Vehicle No. (For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5030046046-09	LIEW WAI KHEONG	52550037G	GPC	drive CLASSIC	SJG6853K	SJG6853K	11/07/2017	10/07/2018

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	09/02/2018 16:19
Date Of Accident	08/02/2018 13:20
Exact Location Of Accident	ALONG YISHUN RING RD AFTER BS:59571
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SG5494M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64823888
<b>Vehicle Particulars</b>	
Manufacturer	MERCEDES-BENZ
Model	BUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
<b>Insurance Company</b>	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-17087563MFBP
Cover Note Number	
<b>Driver</b>	
Name of Driver	LIM TSE CHIANG
NRIC No	G8121278W
Date Of Birth	09/01/1988
Occupation	OUTDOOR
Date Of Driving Pass	03/10/2014
Driving Experience	3 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address NOADDRESS

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 40

### Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER] YISHUN NORTH N.P.C

Was notice of intended Prosecution given? NO

If Yes, against whom?

### Circumstances of Accident

POLICE REPORT NO: T/20180208/2099

### Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJG6853K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver LIEW KAI XIANG

NRIC/Passport Number

Contact Number 91885840

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

Bus 02/18/7018

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

police report T/20180208/2099

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

*[Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





**SINGAPORE  
POLICE FORCE**



T/20180208/2099

1 of 3

Police Station Of Origin:  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768827  
Tel No: 1800-8529999

Report No. T/20180208/2099

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 08/02/2018 15:33		Vide Report No.: F/20180208/0152		Station Diary No.: 92	
<b>Informant's Particulars</b>					
Name of Informant: LIM TSE CHIANG			Address: 6 Ang Mo Kio Street 62 SINGAPORE 569140		
ID Type / ID No.: FIN NO / G8121278W			Contact No.: Home/Office: Mobile: 84978772		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 30	Date of Birth: 09/01/1988	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Bus driver			Driving Licence Information: Class: 2B,3,4A		Date of Expiry:

**General Information of the Accident**

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 08/02/2018 13:15	Type of Location: Straight Road
Location: Along Road 1 YISHUN RING ROAD  IN FRONT OF NORTH BROOKS SECONDARY SCHOOL				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 50 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SG5494M	Bus/Coach/Minibus	VOLVO		Green	Slightly Damaged	40
SJG6853K	Car			Black	Slightly Damaged	0

**Details of Person Involved**

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL		



**SINGAPORE  
POLICE FORCE**



T/20180208/2099

2 of 3

Police Station Of Origin:  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768827  
Tel No: 1800-8529999

Report No. T/20180208/2099

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	LIM TSE CHIANG	ID No.	G8121278W
Related Vehicle	SG5494M (Bus/Coach/Minibus)	Contact No.	84978772
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3,4A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	LIEW KAI XIANG	ID No.	S8945654A
Related Vehicle	SJG6853K (Car)	Contact No.	91885840
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 8.2.18 at about 1315hrs, I was driving SMRT bus service 807 bearing registration number SG5494M. I have about 40 passengers at that time. I was along Yishun Ring Road in front of North Brooks Secondary school. After leaving the bus stop near to the scene, I observed that there was a vehicle (Black Honda Stream) parking by the side of the road ahead of me. After moving off about a few meters away from the bus stop, suddenly the black Honda Stream registration SJG6853K rolled back wards and collided onto the front of my company vehicle.

I observed that there was a slight uphill where the said Honda Stream was parked. I have not enough space or time to avoid it from colliding into the front of my company vehicle. I came down to check and later discovered that the Honda Stream was involved in a road traffic accident with a blue Toyota van registration number GT5913U before it was parked at the side of the road. The van driver is one, Poh Leung Hin S1699445F Tel: 96883155. I am not sure what causes the Honda Stream to roll back wards but it could be possibly due to handbrake not pulled up on the uphill road. There was traffic police at the scene and advised me to lodge a police report vide F/20180208/0152 under IO Zaid. I've made a check with my passengers and there were no casualties in my company bus. I wish to state that the driver of the Honda Stream Liew Kai Xiang was inside his vehicle at the time it collided onto my company bus.



**SINGAPORE  
POLICE FORCE**



T/20180208/2099

3 of 3

Report No. T/20180208/2099

Police Station Of Origin:  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768827  
Tel No: 1800-8529999

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Staff Sgt GHAZALI BIN IBRAHIM

Signature Of Informant:

*[Handwritten Signature]*

Signature Of Interpreter:

Not applicable

Date/Time:

08/02/2018 15:33

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt NOR FAIZAL BIN YAHYA

Contact No.: 65476202

Classification Of Case:

Authentication Stamp

NP168



Signature:

*[Handwritten Signature]*

SN 085

**Singapore Police Force**

## Sketch Plan Pg. 6

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 2292D

### Vehicle Details

Vehicle No.: SG5494M

Vehicle to be Exported: No

Intended De-registration Date: 20 Feb 2018

Vehicle Make: VOLVO

Vehicle Model: B9TL 9.4L AUTO TURBO ABS

Primary Colour: Multi-Colour

Manufacturing Year: 2016

Engine No.: D9195896

Chassis No.: YV3S4P928HA182757

Maximum Power Output: -

Open Market Value: \$505,887.00

Original Registration Date: 05 Oct 2017

First Registration Date: 05 Oct 2017

Transfer Count: 0

Actual ARF Paid: \$0.00

### Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Rebate Amount: \$0.00

**Total Rebate Amount: \$0.00**


The information contained herein is correct as at 20 Feb 2018

OK

## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG5494M  
Ref. No : BUS/02/18/7018  
Reg. Date : 05/10/2017  
Vehicle Type : DOUBLE DECK  
Make : VOLVO  
Model : Volvo B9TL DD  
Name of Driver : Lim Tse Chiang  
Type of Accident : SIDE SWIPE  
Date / Time of Accident : 08/02/2018 01:22:00 PM  
Accident Reported Date / Time : 09/02/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : IDAC  
Vehicle is Towed Back? : No  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024094770  
Special Instruction to ARC, if any :  
SG5494M - LEFT REAR PORTION  
SJG6853K (TP) - INSURED WITH NTUC  
Prepared Date : 12/02/2018 12:46:29 PM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Sebastian  
22/2/18

- Part by past repair  
- Photo Before & After Paint

*[Signature]*  
28/2/18

Chassis No : YV3S4P928HA182757

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

### Summary of Repair Estimates

Quotation from ARC Adjusted by Surveyor, if applicable

Total Labour Charges : 1,325.00 0.00

Total Spray Painting Charges : 602.00 0.00

Total Material Charges : 0.00 0.00

Other Charges : 0.00 0.00

**TOTAL : 1,927.00 0.00**

**Lum Sum Total : 0.00 0.00**

No. of Repair Days : 3.00 0.00

Prepared / Adjusted By :

Arc / Surveyor Sing Off Date : 27/02/2018 09:52:39 AM

01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 27/02/2018 09:52:39 AM

### Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :

Quotation Date : Invoice Date :

Invoice Amount : Prepared Date :



**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	1,325.00	0.00 1070
<b>Total Labour</b>	<b>1,325.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	602.00	0.00 500
<b>Total Spray Painting &amp; Panel Beating</b>	<b>602.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
TOTAL MATERIALS										
TOTAL MATERIALS(Discounted)								0.00	0.00	


Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

## SMRT Accident Vehicle Repair Estimates

**Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre**

Reg. No : SG5494M  
 Ref. No : BUS/02/18/7018  
 Reg. Date : 12/02/2018  
 Vehicle Type : DOUBLE DECK  
 Make : VOLVO  
 Model : Volvo B9TL DD  
 Name of Driver : Lim Tse Chiang  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 08/02/2018 01:22:00 PM  
 Accident Reported Date / Time : 09/02/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : IDAC  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No :  
 Special Instruction to ARC,if any :





SG5494M - LEFT REAR PORTION  
 SJG6853K (TP) - INSURED WITH NTUC

Prepared Date : 12/02/2018 12:46:29 PM

## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG5494M  
 Ref. No : BUS/02/18/7018  
 Reg. Date : 05/10/2017  
 Vehicle Type : DOUBLE DECK  
 Make : VOLVO  
 Model : Volvo B9TL DD  
 Name of Driver : Lim Tse Chiang  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 08/02/2018 01:22:00 PM  
 Accident Reported Date / Time : 09/02/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : IDAC  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time : 01/01/2000  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024094770  
 Special Instruction to ARC,if any :  
 SG5494M - LEFT REAR PORTION  
 SJG6853K (TP) - INSURED WITH NTUC  
 Prepared Date : 12/02/2018 12:46:29 PM



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : YV3S4P928HA182757

Mileage

0

Work Shop :

Repair Completed Date / Time :

01/01/2000

**Summary of Repair Estimates****Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges : 1,325.00

1,090.00

Total Spray Painting Charges : 602.00

500.00

Total Material Charges : 0.00

0.00

Other Charges : 0.00

0.00

**TOTAL : 1,927.00****1,590.00****Lum Sum Total : 0.00****0.00**

No. of Repair Days : 3.00

2.00

Prepared / Adjusted By :

SEBASTIAN -LKK

Arc / Surveyor Sign Off Date : 27/02/2018 09:52:39 AM

03/03/2018 02:40:21 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 27/02/2018 09:52:39 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

## Section D - Details of Repair Estimates

### Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	1,325.00	1,090.00 /
<b>Total Labour</b>	<b>1,325.00</b>	<b>1,090.00</b>

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	602.00	500.00 /
<b>Total Spray Painting &amp; Panel Beating</b>	<b>602.00</b>	<b>500.00</b>

### Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

$$\begin{array}{r} 1090 \\ + 500 \\ \hline 1590 \end{array}$$

Sebastian  
13/3/18

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
<b>TOTAL MATERIALS</b>										
<b>TOTAL MATERIALS(Discounted)</b>								<b>0.00</b>	<b>0.00</b>	

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18003811/Srbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 10-04-2018  
189556



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJG 6853K	Veh. Inspected	SG 5494M
Policy No.	5030046046-09	Coverage (\$)	0.00
Claim No.	MT/0981716-002	Excess (\$)	0.00
Assign From		Assign Date	19/02/2018

### 2. Vehicle Particulars & Condition

Make & Model	VOLVO B9TL	c.c	9364
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	YV3S4P928HA182757	Colour	GREEN
Odometer	17531	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	6 mm
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	6 mm
R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	6/6 mm
L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	6/6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	08/02/2018	Inspection Date	19/02/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------





# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 5494M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TO REPAIR LH REAR PORTION.		1,325.00	1,090.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		602.00	500.00
			1,927.00	1,590.00
	GRAND TOTAL		1,927.00	1,590.00
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,590.00

Report Ref No. NS/INC18003811/Srbn2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.