

ASS. REC. BY:

REF:

TMI / CC3 / TMI18003823 / Kqb02

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_  
of Trans Cab

Insured: SKA 8756P

Policy No. MD003041

Claims No. M1800953

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 1/2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHC 5382D Yr Regn: 10, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Perant Latitude c.c. 1995

Colour N. White / Red A/C: Insured / Std / NI / NA

Sp. Reading 477275 T/Radio: Insured / Std / NI / NA

Eng No: \_\_\_\_\_

C/No: VFI AB215AUC 279801

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Giti 215/60R16

R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 13/2/18

Survey held at \_\_\_\_\_

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 20/2/18

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or N/S Frt

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/2 File pass to Caroline Denise  
11 By @ 2600 (Red @ 36784.95, 93%)  
SHC 5382D - CC3 / TMI 17002068 / Kw0342  
SKA 8756P - X

OCA: 310100H

28/2/18 @ 4.17pm Email GIA report & estimate to Shirley.

RECEIVED 01 MAR 2018

Date/Time, File Pass to?

: Prel. Report

: Final Report

Date/Time, File Return to?

Days Of Repair: 2 1/2

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee

Transportation:

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Report Format: MER-V

Lump Sum / I.B.I. (\$ 2600)

\$ - RS - \$

Photos

Others

TOTAL

250
10
260



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
TOKIO MARINE INSURANCE SINGAPORE LTD		Ref : CC3/TMI18003823/Kqb	
20 MCCALLUM STREET #09-01 TOKIO MARINE CENTRESINGAPORE 069046		Date : 27-02-2018	
		Code : TMI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SKA 8756P	Veh. Inspected	SHC 5382D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/02/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	13/02/2018	Inspection Date	20/02/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## Survey Department Check List (Case Handler)

SHC 53820

Reference No. : 003/TMI/8003823/K96  
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin** ( John ): Case handler to make sure all information created by the assignment team are **ACCURATE**.

**(1) Office Assign Form**

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	✓			
C Customer Code	✓			
N Assign From				
C Assign Date	✓			
C Veh No (Inspected)	✓			
C Veh No (Insured)				
C D.O.A	✓			
C Policy No	✓			
C Claim No	✓			
C Insurance Authorisation (CA /REV/REP)				
C Report Type	✓			
C Weekend Charges				
N Survey held at/Repairer	✓			
C Excess				

**Surveyor** ( Kenneth ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

	Y-Date	N-Date	Y-Date	N-Date
C Vehicle No	✓			
C Regn Month/Year	✓			
N Vehicle Type	✓			
N Make & Model	✓			
C Engine Capacity. (C.C)	✓			
N Colour	✓			
C Odometer. (Sp.Reading)	✓			
C Chassis No	✓			
N General Condition	✓			
N Steering	✓			
N Brake	✓			
N Modification (Modi)	✓			
C Tyre Size	✓			
N Tyre Make	✓			
C Tyre Balance	✓			
C Date of Inspection	✓			
N Survey held	✓			
N Des.of Damages	✓			

**(2) System - (Views/Merimen)**

C Damaged Vehicle Photographs Uploaded	✓			
--	---	--	--	--

**(3) Workshop Estimate/Assignment Form**

N ALL Parts condition	✓			
C Market Value for OD cases				
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C Days of repair	✓			
C Finalised Amount				
C Re-inspection Cases to Finalize within 5 Days				

**(4) System - (Views/Merimen)**

C Resurvey photo Uploaded				
---------------------------	--	--	--	--

Check By: John 01/3/18  
 Case Handler Date

\*C: Critical \*N: Non-Critical

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 28 February 2018 4:17 PM  
**To:** Too Joon Hwa  
**Cc:** Priscilla Tan; SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 13/02/2018, SHC 5382D (TP VEHICLE), SKA 8756P (OI VEHICLE)  
**Attachments:** SHC5382 PR.pdf; SHC5382 GIA.pdf; SHC5382 EST.pdf

Dear Shirley,

Please be informed that we had inspected the vehicle SHC 5382D M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 20/02/2018.

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5382D
Vehicle to be Exported:	Yes
Intended De-registration Date:	14 Feb 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002103
Chassis No.:	VF1ABL15AUC279861
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	21 Oct 2014
First Registration Date:	21 Oct 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Oct 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

COE Expiry Date:	20 Oct 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,938.00
COE Rebate Amount:	\$29,816.00
<b>Total Rebate Amount:</b>	<b>\$39,189.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 Feb 2018

OK

**SINGAPORE ACCIDENT STATEMENT**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report	14/02/2018 08:52
Date Of Accident	13/02/2018 13:30
Exact Location Of Accident	SEMBAWANG ROAD TOWARDS CANBERRA ROAD
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	SHC5382D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

**Vehicle Particulars**

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

**Insurance Company**

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

**Driver**

Name of Driver	GOH CHUN KIANG
NRIC No	S0197311H
Date Of Birth	26/09/1949
Occupation	OUTDOOR
Date Of Driving Pass	19/12/1985
Driving Experience	32 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98181597
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 299A TAMPINES STREET 22 #04-604
Postcode	521299
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TOA PAYOH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	<b>ROAD:</b> 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING , <b>POSTCODE:</b> 319194 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-2519999 - <b>FAX NO:</b> 63548749
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20180213/2129

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKA8756P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name GOH CHUN KIANG

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHC5382D

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

Grid area for sketch plan. Handwritten text: *pls see attach police report*

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Lined area for describing accident circumstances. Handwritten text: *pls see attach police report*

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180213/2129

1 of 3

Report No. T/20180213/2129

Police Station Of Origin:  
Toa Payoh N.P.C  
93 Toa Payoh Central #01-02 Toa Payoh  
Community Building SINGAPORE 319194  
Tel No: 1800-2519999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 13/02/2018 17:54	Vide Report No.:	Station Diary No.: 126
--	------------------	---------------------------

Informant's Particulars			
Name of Informant: GOH CHUN KIANG		Address: APT BLK 299A TAMPINES STREET 22 #04-604 SINGAPORE 521299	
ID Type / ID No.: NRIC NO / S0197311H		Contact No.:	Mobile: 98181597
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 68	Date of Birth: 26/09/1949	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 13/02/2018 13:30	Type of Location: Straight Road
Location: Along Road 1 SEMBAWANG ROAD  towards Canberra Road, merging traffic				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC5382D	Car	RENAULT	LATITUDE 2.0L DCI AUTO D/AB 4DR	Red	Slightly Damaged	1
SKA8756P	Car	HYUNDAI	NFSONATA 2.0	Black	Slightly Damaged	0

POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180213/2129

2 of 3

Report No. T/20180213/2129

Police Station Of Origin:  
Toa Payoh N.P.C  
93 Toa Payoh Central #01-02 Toa Payoh  
Community Building SINGAPORE 319194  
Tel No: 1800-2519999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	GOH CHUN KIANG	ID No.	S0197311H
Related Vehicle	SHC5382D (Car)	Contact No.	98181597
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	13/02/2018	Date Discharge	13/02/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight

**Brief Details.**

On 13/2/18 at about 1.30pm, I was driving my taxi (SHC5382D) along Sembawang Road towards Canberra Road, where there was road work being done in the middle lane. As such, instead of 3 lanes, there were only 2 lanes, with a merging lane after the road work. While going straight before the road works, I felt an impact on my front left part of vehicle. I then discovered that I have been hit from the side by another vehicle (SKA8756P). After the collision, the driver continued on, but pulled over after I honked at him. Before we could exchange particulars, he drove off.  
No police or ambulance was called, but I went to Mount Alvernia Hospital to make a check as I felt some pain on my neck. I was given 3 days of medical leave.



SINGAPORE  
POLICE FORCE



T/20180213/2129

3 of 3


Report No. T/20180213/2129

Police Station Of Origin:  
Toa Payoh N.P.C  
93 Toa Payoh Central #01-02 Toa Payoh  
Community Building SINGAPORE 319194  
Tel No: 1800-2519999

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan



IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
E /  
Sgt 2 NURUL NADIAH BINTE MOHAMED SARIFF

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / HRT /  
Sr Staff Sgt ESTHER CHONG  
Contact 65474885 SN 168

Authentication Stamp  
NP168

SIGNATURE

Signature Of Informant:

Date/Time:  
13/02/2018 17:54

Classification Of Case:

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.2 ANG MO KIO ST63 SINGAPORE 569111  
 TEL NO. 6287 6666 FAX NO. 6257 1330  
 CO/GST REG NO. 201019626G  
**SHC5382D -**

**AAD1802-147**

*Not Authorized*  
*1/1 Rm & 2600/*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :

**SHC 5382D - CANDY**  
 VF1ABL15AUC279861  
 RENAULT  
 LATITUDE  
 13.02.2018  
**TOKIO**

PART		LIST
1	1	BUMPER COVER FRT \$ <i>Bu/nd</i> 1,259.42 ✓
2	1	BUMPER ABSORBER FRT \$ <i>Sn</i> 394.68 X
3	1	BUMPER BEAM FRT \$ <i>R</i> 914.08 X
4	1	BUMPER SPOILER FRT \$ <i>Sn</i> 181.75 X
5	1	BUMPER GRILLE LOWER FRT \$ <i>Sn</i> 266.80 X
6	1	BUMPER FOG LAMP GRILLE LH \$ <i>Sn</i> 207.22 X
7	1	BUMPER RETAINER FRT LH \$ <i>D, /</i> 151.41 ✓
8	1	BUMPER BRACKET FRT LH \$ <i>R</i> 181.75 X
9	1	HEADLAMP LH \$ <i>Sn</i> 1,184.43 X
10	1	HEADLAMP PANEL FRT LH \$ <i>R</i> 152.15 X
11	1	FENDER PANEL FRT LH \$ <i>B,</i> 783.83 ✓
12	1	FENDER INSULATOR LH \$ <i>Sn</i> 130.84
13	1	FENDER BRACKET FRT LH \$ <i>R</i> 34.14
14	1	WHEELARCH FRT LH \$ <i>Sn</i> 278.84
15	1	AIR CLEANER LOWER \$ <i>Sn</i> 352.64
16	1	AIR CLEANER HOSE \$ <i>Sn</i> 76.14
17	1	RADAITOR GRILLE \$ <i>Sn</i> 1,707.78
18	1	RADAITOR GRILLE BADGE 'RENAULT' \$ <i>Sn</i> 173.36
19	1	RADAITOR GRILLE FRAME \$ <i>Sn</i> 1,353.75
20	1	FRAME FULL SUPPORT PANEL \$ <i>Sn</i> 615.90
21	1	FRAME FULL SUPPORT BRACKET \$ <i>R</i> 89.79
22	1	BONNET \$ <i>R</i> 1,941.63 X
23	1	BONNET HINGE LH \$ <i>R</i> 348.31
24	1	BONNET HINGE RH \$ <i>R</i> 348.31
25	1	WHEEL HOUSING PANEL FRT LH \$ <i>R</i> 5,173.47
26	1	LOWER ARM LH \$ <i>Sn</i> 685.76
27	1	KUNCKLE ARM LH \$ <i>Sn</i> 846.98
28	1	ABSORBER FRT LH \$ <i>Sn</i> 360.54
48	1	AIR CLEANER LOWER \$ <i>Sn</i> 271.26
49	1	AIR CLEANER HOSE \$ <i>Sn</i> 76.14
51	1	AUTO COMPUTER \$ <i>Sn</i> 5,032.17
52	1	STEERING PUMP ELECTRIC \$ <i>Sn</i> 2,306.90
29	1	DOOR PANEL FRT LH \$ <i>R</i> 2,844.66
30	1	DOOR MIRROR LH \$ <i>Sn</i> 1,483.40

**TRANS-CAB AUTO SERVICES PTE LTD**

**AAD1802-147**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5382D -**

31	1	DOOR MIRROR GLASS LH	\$	<i>Sm</i> 148.20 X
32	1	DOOR MIRROR BACK COVER LH	\$	<i>Sm</i> 218.46 X
33	1	ROCKER PANEL OUTER LH	\$	<i>R</i> 987.49 X

<b>TOTAL</b>	\$	<u>33,564.39</u>
<b>10%</b>	\$	<u>3,356.44</u>
	\$	<u>30,207.95</u>

**Special Nett**

1	1SET	WHEELARCH CLIP FRT LH	\$	<i>nn</i> 66.00 X
2	1SET	FRONT BUMPER CLIP	\$	<i>nn</i> 66.00 ✓
3	1	RIM LH FRT	\$	<i>Sm</i> 385.00 X
4	1	TYRE LH FRT	\$	<i>Sm</i> 330.00 X
5	1	DOOR STICKER "Trans-cab"	\$	<i>nn</i> 80.00 <i>60sm</i>
6	1	DOOR STICKER "Classic"	\$	<i>nn</i> 30.00 <i>15sm</i>
7	1	DOOR STICKER "6555-3333"	\$	<i>nn</i> 80.00 X
8	1	FENDER ADVERTISEMENT STICKER FRT LH	\$	<i>nn</i> 300.00 X
9	1	DOOR ADVERTISEMENT STICKER FRT LH	\$	<i>nn</i> 300.00 X

<b>TOTAL</b>	\$	<u>1,637.00</u>
<b>TOTAL PARTS</b>	\$	<u>31,844.95</u>

To Check Electrical Lighting Concerned.	\$	170.00 <i>15L</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00 <i>660L</i>
Putty and spray painting of the affected portion.	\$	3,000.00 <i>400L</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	220.00 <i>60L</i>
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X

**TRANS-CAB AUTO SERVICES PTE LTD**

**AAD1802-147**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5382D -**

Towing fees	\$	<i>na</i> 120.00 <i>X</i>
To rust-proofing of the affected areas.	\$	170.00 <i>3d</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>na</i> 380.00 <i>X</i>

<b>TOTAL</b>	<b>\$</b>	<b>7,540.00</b>
<b>Over All Total</b>	<b>\$</b>	<b>39,384.95</b>

**(PARTS BY PARTS) Repair Days**

**10-Days**

*2 1/2 days*

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18003823/KQBN2

Date: 05/03/2018

#### REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MD003041
Claimant Vehicle No :	SHC5382D	Insured Vehicle No :	SKA8756P
Date of Loss:	13/02/2018	Nature of Claim:	TP <span style="float: right;">Claim No: M1800953</span>

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5382D	Engine No:	M9R8839C002103
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC279861
Reg. Date:	21/10/2014 (Man. Year: 2014)	Odometer:	477275 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 9 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Falken 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,844.94	2,116.19	29,728.75	93.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,540.00	1,165.00	6,375.00	84.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>39,384.94</b>	<b>3,281.19</b>	<b>36,103.75</b>	<b>91.67</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
(S\$)	39,384.94	2,600.00	36,784.94	93.40
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,756.95</b>	<b>182.00</b>	<b>2,574.95</b>	<b>93.40</b>
<b>Nett Amount (S\$)</b>	<b>42,141.89</b>	<b>2,782.00</b>	<b>39,359.89</b>	<b>93.40</b>

#### INSPECTION

Date of Assignment:	01/03/2018	
Date Inspected:	20/02/2018 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.5 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

## Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 05 Mar 2018)
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SHC5382D)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled/Dented	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
3	1		*BUMPER BEAM FRT	Repair	914.08 FL	*- FL
4	1		*BUMPER SPOILER FRT	Serviceable	181.75 FL	*- FL
5	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL
6	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.22 FL	*- FL
7	1		*BUMPER RETAINER FRT LH	Distorted	151.41 FL	*151.41 FL
8	1		*BUMPER BRACKET FRT LH	Repair	181.75 FL	*- FL
9	1		*HEADLAMP LH	Serviceable	1,184.43 FL	*- FL
10	1		*HEADLAMP PANEL FRT LH	Repair	152.15 FL	*- FL
11	1		*FENDER PANEL FRT LH	Bent	783.83 FL	*783.83 FL
12	1		*FENDER INSULATOR LH	Serviceable	130.84 FL	*- FL
13	1		*FENDER BRACKET FRT LH	Repair	34.14 FL	*- FL
14	1		*WHEELARCH FRT LH	Serviceable	278.84 FL	*- FL
15	1		*AIR CLEANER LOWER	Serviceable	352.64 FL	*- FL
16	1		*AIR CLEANER HOSE	Serviceable	76.14 FL	*- FL
17	1		*RADIATOR GRILLE	Serviceable	1,707.78 FL	*- FL
18	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	173.36 FL	*- FL
19	1		*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	*- FL
20	1		*FRAME FULL SUPPORT PANEL	Serviceable	615.90 FL	*- FL
21	1		*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	*- FL
22	1		*BONNET	Repair	1,941.63 FL	*- FL
23	1		*BONNET HINGE LH	Repair	348.31 FL	*- FL
24	1		*BONNET HINGE RH	Repair	348.31 FL	*- FL
25	1		*WHEEL HOUSING PANEL FRT LH	Repair	5,173.47 FL	*- FL
26	1		*LOWER ARM LH	Serviceable	685.76 FL	*- FL
27	1		*KNUCKLE ARM LH	Serviceable	846.98 FL	*- FL
28	1		*ABSORBER FRT LH	Serviceable	360.54 FL	*- FL
29	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
30	1		*AIR CLEANER HOSE	Serviceable	76.14 FL	*- FL
31	1		*AUTO COMPUTER	Serviceable	5,032.17 FL	*- FL
32	1		*STEERING PUMP ELECTRIC	Serviceable	2,306.90 FL	*- FL
33	1		*DOOR PANEL FRT LH	Repair	2,844.66 FL	*- FL
34	1		*DOOR MIRROR LH	Serviceable	1,483.40 FL	*- FL
35	1		*DOOR MIRROR GLASS LH	Serviceable	148.20 FL	*- FL
36	1		*DOOR MIRROR BACK COVER LH	Serviceable	218.46 FL	*- FL
37	1		*ROCKER PANEL OUTER LH	Repair	987.49 FL	*- FL
38	1		*SET WHEELARCH CLIP FRT LH	Not Necessary	66.00 FS	*- FS
39	1		*SET FRONT BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
40	1		*RIM LH FRT	Serviceable	385.00 FS	*- FS
41	1		*TYRE LH FRT	Serviceable	330.00 FS	*- FS
42	1		*DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
43	1		*DOOR STICKER CLASSIC	Necessary	30.00 FS	*15.00 FS
44	1		*DOOR STICKER 6555-3333	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
45	1		*FENDER ADVERTISEMENT STICKER FRT LH	Not Necessary	300.00 FS	*- FS	
46	1		*DOOR ADVERTISEMENT STICKER FRT LH	Not Necessary	300.00 FS	*- FS	
					<b>Sub Total (\$\$)</b>	<b>35,201.38</b>	<b>2,335.66</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>3,356.44</b>	<b>219.47</b>
					<b>Total Parts (\$\$)</b>	<b>31,844.94</b>	<b>2,116.19</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,800.00	660.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	400.00
4	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	-
5	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	-
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
7	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	-
8	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
9	TOWING FEES	New	120.00	-
10	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
11	TO DISMANTLE AND REFIT FRONT END SUSPENSION,UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING	New	380.00	-
<b>Gross Labour Cost (\$\$)</b>			<b>7,540.00</b>	<b>1,165.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >