

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18003827/Sqbn2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 15-03-2018	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJD 5334P	Veh. Inspected	SHC 4532U	
Policy No.	5083195710-01	Coverage (\$)	0.00	
Claim No.	MT/0982721-002	Excess (\$)	0.00	
Assign From		Assign Date	23/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	CHRYSLER C300	c.c	2987	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	1C3C96CM4AY102199	Colour	BLACK	
Odometer	915140	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R18	PIRELLI	6 mm	
L/H Front Tyre	225/60 R18	PIRELLI	6 mm	
R/H Rear Tyre	225/60 R18	PIRELLI	6 mm	
L/H Rear Tyre	225/60 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/02/2018	Inspection Date	23/02/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		