Surveyor: mirmen

REF: III

ASSIGNMENT

From: Date: 28022018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFZ 1811L

at Workshop m/s Ah Lim Motor

of Blk 10 AMK Ind Park 2A

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: $9k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SFZ1811L Yr Regn: 05 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Fit c.c 1339

Colour M. Black A/C: Insured / Std / NI / NA

Sp.Reading 181922 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GE6 1087114

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/50R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	4 mm	R/Bal.	3 mm
L/Bal.	6 mm	L/Bal.	3 mm
D.O.A.	27/2/18	D.O.I.	28/2/18

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or & Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	1/3 file pass to Carmine

Date/Time. File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee: ☐ Site Insp ($) ___$ - PS ___$

☐ Interview ($) Photos

☐ Tech. Invs ($) Others

☐ Weekend ($)

TOTAL

Report Format :

Lump Sum / I.B.I: ($)