

Tanpik

REF: AXA

ASSIGNMENT

2018 July

2003 Sep

From Date 28/2/18

Estimated Cost

OD TP / NS / TP RES / OD RES / EVA / INV / MV

To inspect vehicle No GW6692J
at Workshop / Mile Sin Sheng Engineering
or 3 teeh park Crescent

Insured

Policy No

Claims No

Sum Insured Excess

Client's Record

Make of Ven

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☒
NS	O/S

Est. or Market Value: 15K

DAD Accident Report Consistent? : Yes or No

GIA / PR Seen Consistent? : Yes or No

Est. Repairs days Res: Yes or No

Lim Sum % G Val: Yes or No

OA / REV / REP / 24 HRS 1up

Date Person Contacted

Vehicle IN / OUT

Date Time Action / Instruction
Email wls repair limit \$2500

Van No

GW6692J

Type: M/Cat M/Cycle Bus/Lorry Taxi Prime Mover

Truck Trailer

Make: Mikiishi L300

2477

Colour: White

AC Insured Std N/A

Se Reading: 468751

TP Insured Std N/A

Eng No

C No

JMAJNP15V4A 000 336

Gen Cond: Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: H / S Rim / STD A/Rim or

Tyre Size

F

R

185/R14

BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUM

TOYO / YOKO or

Anstone

Front

Rear

R.Ba

R.Ba

L.Ba

L.Ba

D.O.A

D.O

Survey taken

Sin Sheng

Des. of Damages: Rear / O/S / N/A / L/O / Roof/ or

The U/C / Chassis frame / Body Structure affected due to collision

Date Time File Pass to

☐

: Prelim. Report

☐

: Final Report

Date Time File Return to

Days Of Repair

Resurvey No. of Trip

Surveys Fee

Transportation

Add Fee

☐
☐
☐
☐
☐

Site Fee

Site Fee

Site Fee

Site Fee

Report Form

Report Form