

ASS. REC. BY:

REF:

C3/FCL18003889 Ntb 9/1

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Cus Lureng Jaw

of

FCL

Date/Time: 27/02/2018 12:22pm

Estimated Cost:

Bill to:

OD / IF / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SKS 4201E

Insured:

SHA 218P

at Workshop m/s

Kah Mylar

Tel:

6511 5687

of

15 Ubi Rd 4

Policy No:

Claim No:

D18001640MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 22/02/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

02032018 @ 9am

H.O.D. Endorsement:

Date/Time:

28/02/2018 11:08am

Person Contacted:

Liew

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKS 4201E - x
	SHA 218P - C3 / FCL18003889 / KJwb3
12/3/18	- 3:25pm Revert via email

Date: 10/02/18

FCI

ASSIGNMENT

Date 2/3/18
 Estimated Cost
 SO (P) WS TR RES / CO RES / EVA / INV / MV
 To Inspect Vehicle No SKS4201E
 At Vehicle No Kah Motor
 At 15 Ubi Road 4
 Insured
 Policy No
 Claims No
 Sum Insured Excess
 Claims Record
 Make of Van Liew
 9am @ owner meeting

NS	OG

Policy Condition
 Remark: The van had commenced its repair at the time of inspection.
 Est. of Market Value
 C/L Accident Report Consistent? Yes or No
 C/L Acc Sec Consistent? Yes or No
 Est. Repair 4 days Res? Yes or No
 Lim Sum 1.8M Res? Yes or No
 CA / REV / REP / 24 HRS lwp
 Date Person Contacted

SKS4201E 415
 CAI
 Honda mobilio ORC 1497
 orange
 47359
 MR HDD 4870FP000049
 195/55R16 6Y
 SS / SUN / EXNOVA / BY / FS / LISA / MID / CHSL / PR / SLV
 TOYO / YOKO
 Falken
 7
 7
 22/2/18
 2/3/18
 N/S Ref.
 The UIC / Chassis Frame / Body Structure affected out of collision

20/3/18 confirmed final of 3154.51 mls MR (Red: 1089.60:25)

RECEIVED 27 MAR 2018

Days Time File Pass
 JTB Typist
 Days Time File Pass
 Preli. Report
 Final Report
 Days Of Repair 4
 Resurvey No. of Trip 1
 Add Fee
 3154.51
 135
 50
 50
 43
 278



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18003889/Utb

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 28-02-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 218P	Veh. Inspected	SKS 4201E
Policy No.		Coverage (\$)	0.00
Claim No.	D18001640MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	27/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/02/2018	Inspection Date	02/03/2018
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	26-02-2018	Our Ref No. D18001640MFSH
Accident Date	22-02-2018	Claim Type. Third Party
Insured Vehicle	SHA0218P	Third Party Vehicle. SKS4201E
Survey Location	15 UBI ROAD 4	
Contact Person.	TW LIEW	
Contact No.	67480770/0	Fax No. 65145687
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO SDN BHD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235358)



PRI Documents



Close



PRI Header Details

Claim No	D18001640MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & KA
Workshop Name	KAH MOTOR CO SDN BHD (Contact Person : TW LIEW)	Survey Location & Contact Details	15 UBI ROAD 4 Mobile: 0 , Phone: 67480770 , Fax: 6514568 EmailId: TWLIEW@HONDA.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA0218P	TP Vehicle No	SKS421
PRI Recieved Date	26-02-2018 10:07:23 PM	Surveyor Appointed Date	27-02-2018 12:22:20 PM	Surveyor Accept Date	28-02-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	28-02-2018	Upload Survey Report *:	
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	----------------------

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 12 March 2018 3:25 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001640MFSH/1
Attachments: PRELI ADVISED SKS 4201E.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SKS 4201E**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 28 February 2018 3:37 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001640MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 27 February, 2018 12:22 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001640MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001640MFSH

Date: 12/3/2018

Our Ref: CS/FCI18003889/Utb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKS 4201E

Please be informed that we had conducted the inspection of the abovementioned vehicle on 2/3/2018 at the premises of M/s Kah Motor, and have the following to report: -

Workshop Estimate Amount	: S\$ <u>4,244.11</u>
Revised Estimate Amount	: S\$ <u>3,074.51</u>
"Check" Items Amount	: S\$ <u>129.60</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the n/s front.

Comments/ Present Status:
Damages Consistent.

Yours faithfully
Marcus
Automotive Assessor



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/02/2018 14:42
Date Of Accident	22/02/2018 23:15
Exact Location Of Accident	BEDOK RESERVOIR ROAD CP ENTRANCE OF BLK 631
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS4201E
Insured/Policyholder	
Name Of Registered Owner	SITI SALMI BINTE MUBARI
NRIC No	S8320733G
Email Address	SAMIMUBARI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91504840
Alternative Phone No	OTHERS-NOPHONE
Vehicle Particulars	
Manufacturer	HONDA
Model	MOBILIO-1.5 RS LUXE (A)
Exact Purpose for which vehicle was being used at time of accident	DRIVING HOME
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	18-MW003410-R02
Cover Note Number	
Driver	
Name of Driver	MOHAMMAD ZAID BIN MUBARI
NRIC No	S7917289H
Date Of Birth	24/05/1979
Occupation	INDOOR
Date Of Driving Pass	22/11/1997
Driving Experience	20 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94598230
Fax Number	
Contact Number	
Email Address	ZAIDM79@YAHOO.COM

Address	BLK 144, BEDOK RESERVOIR ROAD #02-1593
Postcode	470144
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	RELATIVE
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHMENT REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA218P
Vehicle Make/Model/Colour	TOYOTA // YELLOW
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	MOHD SHARIFF
NRIC/Passport Number	S1841662Z
Contact Number	82888991
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Vehicle No SZS 42016**SKETCH PLAN**

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan


Please continue in Annex E

Vehicle No SKS4201E

Annex E

Describe Circumstances of the Accident

I, Mohammad Said, was driving along Bedok Reservoir Road, Road outside Sunco Heights. It is a 2-lane (one way directional) road. I was on the right lane, driving at speed less than 50 km/h. A taxi, SHA 218P, driven by Mr Mohd Shariff is driving on the left side of the Bedok Reservoir Road. After my car was approximately a few metres diagonally from his taxi. After passing Sunco Heights car park entrance. His taxi made an abrupt immediate turn right wanting to go into the right hand side carpark entrance to block 631. I did an emergency brake but did not manage to stop in time and did a side swipe on the taxi right door. My car had scratches, dents and the bumper torn and dislodge. It happened exactly at the carpark entrance to block 631 bedok reservoir Road. We took pictures and move the car to the side and exchange particulars.



Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 0733G

Vehicle Details

Vehicle No.: 5K54201E

Vehicle to be Exported: No

Intended De-registration Date: 05 Mar 2018

Vehicle Make: HONDA

Vehicle Model: MOBILIO SV 1.5 CVT

Primary Colour: Orange

Manufacturing Year: 2015

Engine No.: L15Z12100058

Chassis No.: MRHDD4870FP000049

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$19,587.00

Original Registration Date: 14 Apr 2015

First Registration Date: 14 Apr 2015

Transfer Count: 0

Actual ARF Paid: \$14,587.00

OPC Cash Rebate Details

OPC Cash Rebate Eligibility: No

OPC Cash Rebate Eligibility
Expiry Date: -

OPC Cash Rebate Amount: -

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 13 Apr 2025

PARF Rebate Amount: \$10,940.00

Intended COE Rebate Details

COE Expiry Date: 13 Apr 2025

COE Category: A - Car up to 1600cc & 97kW
(130bhp)

COE Period(Years): 10

QP Paid: \$47,700.00

COE Rebate Amount: \$33,893.00

Total Rebate Amount: \$44,833.00

The information contained herein is correct as at 05 Mar 2018

OK



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Not Authorised
Mark
telephoto photography
2/3/18
4dy.

QUALIFICATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: MS FIRST CAPITAL INSURANCE	Document No.	: SQT18000809	Page	1
	36 ROBINSON ROAD	Date	: 24. Feb 2018		
	#16-01 CITY HOUSE	Customer No.	: WZF002		
	SINGAPORE 068877	Svc Advisor	: LIEW THYE WEI		
Registration No	: SKS4201E	Engine No	: L15Z12100058		
Chassis No	: MRHDD4870FP000049	Date Time	: 24. Feb 2018 11:38:15 AM		
Model	: MOBILIO YM 2015	Surveyor Name	:		
Owner's Name	: SITI SALMI BINTE MUBARI	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 22/2/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: SITI SALMI BINTE MUBARI						
	OWNER INSURER: TOKIO MARINE						
	ACC DATE: 22/02/18						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: MS FIRST CAPITAL INSURANCE						
	TP VEH: SHA218P						
BO-NUM-SEAL	SEAL NUMBER PLATE	<i>nu</i> 1	80.00	✓	80.00	5.60	85.60
			Sum Ext. Service		<u>80.00</u>	<u>5.60</u>	<u>85.60</u>
BO-NUM-COMP-OPC-S	NUMBER PLATE WITH CASING-OPC-S	<i>nu</i> 1	45.00	✓	45.00	3.15	48.15
60261-TRD-T10ZZ	PANELL FR.FENDER	<i>70/cu</i> 1	270.60	✓ 25	202.95	14.21	217.16
74150-TE7-K90	FENDERL FR INNER	<i>11</i> 1	76.80	✓ 25	57.60	4.03	61.63
91501-TG2-K01	CLIPINNER FENDER	<i>nu</i> 9	0.30	✓ 25	2.02	0.14	2.16
71101-TE7-K90ZZ	FACEFR.BUMPER	<i>Dis/To</i> 1	459.80	✓ 25	344.85	24.14	368.99
71103-TE7-K91	GRILLE ASSYFR.BUMPER LOWER	<i>11</i> 1	96.00	✓ 25	72.00	5.04	77.04
91505-S9A-003	CLIP ABUMPER	<i>net</i> 6	3.90	✓ 25	17.55	1.23	18.78
71109-TE7-K91	GARNISHL FR.FOGLIGHT	<i>Sc</i> 1	63.30	✓ 25	47.47	3.32	50.79
71198-TG1-T01	SPACERL FR.BUMPER SIDE	<i>but</i> 1	10.40	✓ 25	7.80	0.55	8.35
91505-TG1-T01	CLIP ABUMPER	<i>nu</i> 4	6.10	✓ 25	18.30	1.28	19.58
91506-TG1-T01	CLIP BBUMPER	<i>nu</i> 4	6.10	✓ 25	18.30	1.28	19.58
33150-TE7-K91	HEADLIGHT ASSYL	<i>One</i> 1	1093.70	✓ 25	820.27	57.42	877.69
			Sum Item		<u>1654.11</u>	<u>115.79</u>	<u>1,769.90</u>
BOSUN	SUNDRIES	<i>nu</i> 1	30.00	✓ 10	30.00	2.10	32.10
BML011	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	80.00	✓	80.00	5.60	85.60
BKFE11R	REMOVE & RENEW FR L FENDER & FRT BUMPER	1	1200.00	✓ 560	1200.00	84.00	1284.00



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance. Call 96203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SKS4201E
Chassis No : MRHDD4870FP000049
Model : MOBILIO YM 2015
Owner's Name : SITI SALMI BINTE MUBARI
Ins Policy No. :
Date of Accident : 22/2/2018

Document No. : SQT18000809 Page 2
Date : 24. Feb 2018
Customer No. : WZF002
Svc Advisor : LIEW THYE WEI
Engine No : L15Z12100058
Date | Time : 24. Feb 2018 11:38:15 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1200.00	900	1200.00	84.00	1284.00
	450			Sum Labor	2510.00	175.70	2,685.70

Survey By _____
Date & Time _____
Excess _____
Status _____
Signature _____

Total Amount 4,244.11 297.09 4,541.20
Total (Inclusive of GST) **4,541.20**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Printed on 24/2/2018 12:10:26 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408851 Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

18/03/2018

Page 1/1

SERVICE PRE-INVOICE

Attn: Marcus (L.k.k.)

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

4 days

Customer: WZF002 / MS FIRST CAPITAL
 Chassis No: MRHDD4870FP000049
 License No: SKS4201E
 Mileage: 47511
 Engine No: L15Z12100058

Document No: SVO18012878
 Printed By: TWLIEW
 Order Date: 5. March 2018
 Order Time: 12:23:02 PM
 Service Advisor: LIEW THYE WEI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount Includ Amount	GST
	TP DIRECT SETTLEMENT (J/NO: 70065) OWNER: SITI SALMI BINTE MUBARI OWNER INSURER: TOKIO MARINE ACC DATE: 22/02/18 SURVEYED BY: MARCUS DATE: 2/3/18 REF NO: D18001640MFSH TP INSURER: MS FIRST CAPITAL INSURANCE TP VEH: SHA218P						
BO-NUM-COMP-OPC-L	NUMBER PLATE WITH CASING-OPC-L	1	45.00		45.00	3.15	48.15
60261-TRD-T10ZZ	PANELL.FR.FENDER	1	270.80	25	202.95	14.21	217.16
91501-TG2-K01	CLIPINNER FENDER	8	0.30	25	2.02	0.14	2.16
71101-TE7-K90ZZ	FACEFR.BUMPER	1	459.80	25	344.85	24.14	368.99
91505-S9A-003	CLIP ABUMPER	6	3.90	25	17.55	1.23	18.78
71109-TE7-K91	GARNISHL.FR.FOGLIGHT	1	63.30	25	47.47	3.32	50.79
71198-TG1-T01	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
91505-TG1-T01	CLIP ABUMPER	4	6.10	25	18.30	1.28	19.58
91508-TG1-T01	CLIP BBUMPER	4	6.10	25	18.30	1.28	19.58
33150-TE7-K91	HEADLIGHT ASSYL	1	1,093.70	25	820.27	57.42	877.69
	SUM PARTS:				1,524.81	108.72	1,631.23
BOSUN	0672	1	10.00		10.00	0.70	10.70
	SUNDRIES						
BML01I	EXT-YJ	1	80.00		80.00	5.60	85.60
	INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)						
BKFE11R	EXT-YJ	1	560.00		560.00	39.20	599.20
	REMOVE & RENEW FR L FENDER & FRT BUMPER						
BP02R	EXT-YBH	1	900.00		900.00	63.00	963.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(2P)						
	SUM LABOUR:				1,550.00	108.50	1,658.50
BO-NUM-SEAL	SEAL NUMBER PLATE.	1	80.00		80.00	5.60	85.60
	SUM EXT SERVICE:				80.00	5.60	85.60
	TOTAL SGD				3,154.51	220.82	3,375.33
	Total Payable (SGD)						3,375.33

GST Amount is calculated from individual line(s)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18003889/Utbq2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 28-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 218P	Veh. Inspected	SKS 4201E
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18001640MFSH	Excess (\$)	0.00
Assign From	LURENE JAW	Assign Date	27/02/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA MOBILIO (A)	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MRHDD4870FP000049	Colour	ORANGE
Odometer	47359	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R16	GOODYEAR	7 mm
L/H Front Tyre	195/55 R16	GOODYEAR	7 mm
R/H Rear Tyre	195/55 R16	FALKEN	7 mm
L/H Rear Tyre	195/55 R16	FALKEN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/02/2018	Inspection Date	02/03/2018
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 4201E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SEAL NUMBER PLATE (SN)	NECESSARY	80.00	80.00
1	NUMBER PLATE WITH CASING-OPC-S (SN)	NECESSARY	45.00	45.00
1	PANEL FR.FENDER (SN)	DENTED / CRACKED	202.95	202.95
1	FENDERL.FR.INNER (SN)	NOT NECESSARY	57.60	-
9	CLIPINNER FENDER (SN)	NECESSARY	2.02	2.02
1	FACEFR .BUMPER (SN)	DISTORTED / TORN	344.85	344.85
1	GRILLE ASSYFR.BUMPER LOWER (SN)	NOT NECESSARY	72.00	-
6	CLIP ABUMPER (SN)	NECESSARY	17.55	17.55
1	GARNISHL.FR.FOGLIGHT (SN)	SCRATCHED	47.47	47.47
1	SPACERL.FR.BUMPER SIDE (SN)	BENT	7.80	7.80
4	CLIP BUMPER (SN)	NECESSARY	18.30	18.30
4	CLIP BUMPER (SN)	NECESSARY	18.30	18.30
1	HEADLIGHT ASSYL (SN)	CRACKED	820.27	820.27
1	SUNDRIES (SN)	NECESSARY	30.00	10.00
			1,764.11	1,614.51
LABOUR				
INSPECT FR LIGHTING MECHANISMS & FOCUS.			80.00	80.00
REMOVE & RENEW FR L FENDER & FRT BUMPER .			1,200.00	560.00
SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.			1,200.00	900.00
			2,480.00	1,540.00
GRAND TOTAL			4,244.11	3,154.51
RECOMMENDED COST OF REPAIRS				3,154.51

Report Ref No. CS/FCI18003889/Utbq2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.