

ASS. REC. BY:

REF: CS3 / GA118003890 / T1b

range 8 days

Special Instruction:

Surveyor:

Tawhid

ASSIGNMENT (Office)

From (Person):

Rachel Tan

of

GAL

Date/Time:

28/07/2018 923am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

56C 5589L

Insured:

FBB 5981B

at Workshop m/s

Miracle Works

Tel:

9647 2568

of

48 Toh Guan Rd East #04-126

Policy No:

Claim No:

CLM0MVM00000176

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12.02.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

01-03-2018 @ after 2pm

H.O.D. Endorsement:

Date/Time:

28/07/2018 1145am

Person Contacted:

Nicole

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	56C 5589L - CCS / A1740801819 / UDN
	FBB 5981B - X
	Dismantle: 5/3/2018
	After repair: 5/3/2018

Tanpin

GAI

ASSIGNMENT

01E 2021 Jan.

Date: 01/03/2018

SGC 5589L

2006 Jan

Estimated Cost:

OD TP WS TP RES / OD RES / EVA / INV / MY

To inspect vehicle No: SGC 5589L

at Workshop: Miracle works

at: 18, Toh Guan Rd East #04-126

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

Claims Record:

After 2pm

Make of Vehicle:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NS	OS

Ball or Market Value:

IDAO Accident Report: Consistent? : Yes or No

GIA / RP Seen: Consistent? : Yes or No

Est. Repairs: days Rep: Yes or No

Sum Sum: \$ 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'up'

Date: Person Contacted:

Vehicle IN / OUT

Engine:

Transmission: 5 Speed Manual

Track / Traction:

Make:

1.4 Picanto

1086

Colour:

Yellow

So/Reading:

190967

Eng No:

KNAB A2 4326 T254486

CNO:

Gen Cond: Good Fair Poor Burnt

Steering: Intact Jammed Leaked Burnt or

Brake: Intact Jammed Leaked Burnt or

Mod: N/A STD A/R

Tyre Size:

185 / 55 R15

BS / DUN / EXNOVA / G / FS / LZA / MIC / HTSL / PR / SUM

TOYO / YOKO: Fallen

Front:

Rear:

R.Ba:

0

R.Ba:

6

L.Ba:

6

L.Ba:

6

C.O.A:

C.O.A:

Survey needed:

Miracle works

Des of Damages: Fr Rear OS NS UC Rock/Scr

Rear n/c

The U/C / Chassis/frame Body Structure affected due to collision

Date / Time Action / Instruction

* Repair Estimate : S\$ 6500 - 7500

* 3-4 days

RECEIVED 16 MAY 2018

Date/Time File Passed:

☐ Prelim Report
☐ Final Report

Days Of Repair:

4

Date/Time File Returned:

Resurvey No. of Trip:

2

Report Form:

PR2

Sum Sum:

Add Fee:

☐ Grease
☐ Wash
☐ Paint
☐ Sealant

Survey Fee:

100

100

Catherine Chong (LKK Auto)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Wednesday, 28 February, 2018 9:23 AM
To: Lheny
Cc: winnie@yoga-legal.com; LKK Assignments
Subject: RE: CLMOMVM000000176 - SGC5589L v FBB5981B (GA) on 12 Feb 18

Without Prejudice

Dear Lheny
We will arrange for LKK to conduct pre-repair inspection.

Dear LKK
Please accept assignment to conduct inspection.

Thank you

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Lheny [mailto:lheny@yoga-legal.com]
Sent: Wednesday, February 28, 2018 9:22 AM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: winnie@yoga-legal.com
Subject: RE: CLMOMVM000000176 - SGC5589L v FBB5981B (GA) on 12 Feb 18

WITHOUT PREJUDICE

Dear Sirs

We refer to your email on the even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you choose a surveyor from our list of surveyors as appended below:-

1. Winson Goh
2. Amas Ong Poh Meng
3. Ong Ah Keng, Kent

Please be informed that if we do not hear from you **within 2 working days** from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors you will be deemed to have agreed to the any of the above motor surveyors as a "single joint expert".

We will accordingly inform you who the "single joint expert" is to facilitate your conduct of a pre-repair survey.

Best regards,

Lheny

M/s C YOGARAJAH LLC
883 North Bridge Road
#19-05 Southbank
Singapore 198785

Tel: 6292 5838
Fax: 6292 5938

Email: lheny@yoga-legal.com

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Wednesday, 28 February, 2018 9:19 AM
To: Lheny
Subject: CLMOMVM000000176 - SGC5589L v FBB5981B (GA) on 12 Feb 18

Without Prejudice

Dear Lheny

We received your letter dated 27 Feb 2018. We append the following list of our panel surveyors:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. L.B.S. Automotive Appraisal Pte Ltd
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants
6. JP KNIGHTS PTE LTD

Kindly let us know which SJE is selected and furnish the estimates for the survey to be carried out.

Regards,

Rachel Tan, Executive | P. +65 6804 7846 | Rachel.tan@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190

This email transmission, including any attachments, is intended solely for the addressee named above, and may contain confidential or privileged information. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this e-mail is prohibited. If you have received this e-mail in error, please notify the sender immediately by reply email and destroy the message and its attachments.



Moody's
A1 (Good)
Affirmed June 15, 2015

Standard & Poor's
A+ (Strong)
Affirmed March 2, 2016

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Catherine Chong (LKK Auto)

From: Lheny <lheny@yoga-legal.com>
Sent: Wednesday, 28 February, 2018 9:31 AM
To: 'Catherine Chong (LKK Auto)'; 'Tan, Rachel'
Cc: winnie@yoga-legal.com; 'LKK Assignments'
Subject: RE: CLMOMVM000000176 - SGC5589L v FBB5981B (GA) on 12 Feb 18

WITHOUT PREJUDICE

Dear Catherine

Please be informed that our client's vehicle can be inspected at:

M/s. Miracle Works Pte Ltd
48 Toh Guan Road East
#04 – 126 Enterprise Hub
Singapore 608586
Nicole (82045858 / 96472568 / 6385 5262)
Fax no : 6515 5434

*28/2/2018 @ 11:45am
Nicole veh not in*

Best regards,

Lheny

M/s C YOGARAJAH LLC
883 North Bridge Road
#19-05 Southbank
Singapore 198785

Tel: 6292 5838
Fax: 6292 5938

Email: lheny@yoga-legal.com

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 28 February, 2018 9:27 AM
To: 'Tan, Rachel'; 'Lheny'
Cc: winnie@yoga-legal.com; 'LKK Assignments'
Subject: RE: CLMOMVM000000176 - SGC5589L v FBB5981B (GA) on 12 Feb 18

Dear Rachel,

Thank you for the assignment.

Dear Lheny,

Kindly provide us the workshop detail.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8253M
Vehicle Details	
Vehicle No.:	SGC5589L
Vehicle to be Exported:	No
Intended De-registration Date:	02 Mar 2018
Vehicle Make:	KIA
Vehicle Model:	PICANTO 1.1M
Primary Colour:	Yellow
Manufacturing Year:	2005
Engine No.:	G4HG5064599
Chassis No.:	KNABA24326T254486
Maximum Power Output:	47.1 kW (63 bhp)
Open Market Value:	\$7,713.00
Original Registration Date:	19 Jan 2006
First Registration Date:	19 Jan 2006
Transfer Count:	5
Actual ARF Paid:	\$8,485.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jan 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$28,317.00
COE Rebate Amount:	\$16,289.00
Total Rebate Amount:	\$16,289.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 02 Mar 2018

OK



kia picanto

Price Range

Depreciation

> 10 year(s) of

Vehicle Type

Search

Advanced Search

Home » Used Cars » Maaz Global Trading » Kia Picanto 1.1A (COE till 12/2021)

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Commercial Vehicle



Kia Picanto 1.1A (COE till 12/2021)

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$24,900	?
Depreciation	\$6,540 /yr	?
Reg Date	21-Dec-2006 (3yrs 9mths 18days COE left)	?
Manufactured	2006	?
Mileage	106,000 km (9.5k /yr)	?
Transmission	Auto	?
Engine Cap	1,086 cc	?
Road Tax	\$530 /yr	?
Power	47.1 kW (63 bhp) View specs of the Kia Picanto (2005-2010)	?
Curb Weight	872 kg	?
Features	Responsive 1.1L Engine. Auto Transmission. Knockdown Rear Seats. Powerful Aircon. Low Fuel Consumption.	?
Accessories	Sports Rims, Leather Seats, Audio System, Foldable Rear Seats, Solar Films.	?
Description	\$0 Down. Current Paper \$20619. Bank And In House Loan Available, Fast And Easy Approval, Low Mileage, Excellent Condition, Well Kept By Previous Owner, Trade In Welcome.	?
COE	\$25,636	?
OMV	\$8,365	?
ARF	\$4,568	?
Dereg Value	\$19,511 as of today (change)	?
No. of Owners	4	?
Type of Veh	Hatchback	?
Category	COE Car, Low Mileage Car	?
Availability	Available	?

Add to Shortlist

Add to Compare

Add a Note

Posted on: 18-Feb-2018 | Last Updated on: 28-Feb-2018

Tags: Kia Picanto, 2006 Kia Picanto, Kia, Picanto, Used Kia

Upfront Payment

» more Financial Info

Transfer Fee	\$25	?
Down Payment	\$7,470 (change)	Maximum 70% Loan ?
1st Instalment	\$442	?
Total Upfront Payment	\$7,937 (excluding insurance)	?

Estimates based on 70% loan at 3.75% interest rate. Check with seller for exact figure.



Location Map

Seller Information

Company	Maaz Global Trading » dealer's pricelist » 17 vehs sold 10 vehs available
Address	18 Kaki Bukit Road 3 #02-16 Search cars nearby this location
Location	Entrepreneur Business Centre
Office No	67420467
Contact Person(s)	Azizah 85809141 Aziz 85333365 Ah Or 81647599

Useful Services



Make sure of this car condition with STA Evaluation.

Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.

Free Valuation



Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/02/2018 15:33
Date Of Accident	12/02/2018 17:50
Exact Location Of Accident	ALONG PIE BEFORE EXIT JLN BAHAR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGC5589L
Insured/Policyholder	
Name Of Registered Owner	TENGAI ENGINEERING & HARDWARE PTE LTD
Co Reg No	199908253M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67486188

Vehicle Particulars

Manufacturer	KIA
Model	PICANTO-1.1 (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA013548
Cover Note Number	

Driver

Name of Driver	SOH CHIN ANN
NRIC No	S7342882C
Date Of Birth	28/11/1973
Occupation	OUTDOOR
Date Of Driving Pass	15/10/2010
Driving Experience	7 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85775488
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	37, KALLANG PUDDING ROAD, #01-12, TONG LEE BUILDING BLOCK B,
Postcode	349315
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 12/02/2018 AT ABOUT 1750 HRS. WHILE I WAS TRAVELLING ON EXTREME RIGHT LANE ALONG PIE BEFORE EXIT JLN BAHAR. IN FRONT VEHICLE APPLY BRAKE. I THEN APPLY BRAKE ALSO. SUDDENLY I FEEL AN IMPACT FROM MY REAR. I NOTICED THAT MY VEHICLE HAVE COLLIDED BY A MOTORCYCLE (FBB5981B)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBB5981B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	SHERMAN TAN WEI FONG
NRIC/Passport Number	S9232831G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders;



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAY'S TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

GIA-01/2013 Sketch Plan Form 1_1/13

SKETCH PLAN



A - SGCS589L

B - FBB5981B

Along PIE Before Exit Jln Bahar
(Towards Changi)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to circumstances

DECLARATION

I/We declare the foregoing particulars are true in every respect.



[Handwritten signature]

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

- ☐ Claim own policy
- ☐ Claim third party
- ☒ Claim OD TP at other works hop
- ☐ For record purpose

Policy No. GA013548

Insurer AXA

Veh. No. SGCS589L

[Handwritten signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
GREAT AMERICAN INSURANCE COMPANY		Ref: CS3/GAI18003890/T1be2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date: 17-05-2018		
		Code: GAI		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	FBB 5981B	Veh. Inspected	SGC 5589L	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVM000000176	Excess (\$)	0.00	
Assign From	RACHEL TAN	Assign Date	28/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA PICANTO	c.c	1086	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	KNABA24326T254486	Colour	YELLOW	
Odometer	190967 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R15	FALKEN	6 mm	
L/H Front Tyre	185/55 R15	FALKEN	6 mm	
R/H Rear Tyre	185/55 R15	FALKEN	6 mm	
L/H Rear Tyre	185/55 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
5. General Information				
Accident Date	12/02/2018	Inspect Date / Time	01/03/2018 (12:40 AM)	
Survey held at	MIRACLE WORKZ PTE LTD 48 TOH GUAN ROAD EAST #04-126 ENTERPRISE HUB SINGAPORE 608586			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,500-\$7,500				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

Report Ref No. CS3/GAI18003890/T1be2

Inspected By



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.