


Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

26 FEB 2018

Estimate No. : **b1 46039**
Date Estimated : **26/02/2018**
Prepared By : **Kevin Leong Wai Kit**

Page No. : 1 of 1

- ESTIMATE REPAIR FOR -
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
	WC08833		520iA	0

DESCRIPTION

To repair on front bumper assembly & replace necessary attachments on front bumper cause by attachments.

✓ **850** ~~1,700.00~~

Painting on front bumper assembly

✓ **934** ~~1,088.00~~

To check electrical wiring systems at the front section for proper function

✓ **150** ~~177.00~~

To supply front emboss number plate. (*frame only*)

35 price? ~~83.00~~

Sundries.

✓ **40.00**

Total Labour 1: **3,038.00**

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time **28/02/18 09:20** Excess S\$ _____

Surveyor's Name **RASUL** Sign _____

Surveyor's Tel **90010068** Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ F.M.L. Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend **3 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	3,038.00
Parts	:	0.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	212.66
Grand Total	:	3,250.66

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **