

ASS. REC. BY:

REF: CS/MSC18003904/Avbnz

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

Merimen

From (Person): Lionel Tan

of MSTH

Date/Time: 27/02/2018 2:28pm

Estimated Cost:

Bill to:

OD / ~~TD~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFS 7739K

Insured:

SKS 8861Z

at Workshop m/s

Leang Automotive

Tel: 9028 6516

of

Blk 1 Kaki Bukit Ave 6 #01-68

Policy No:

MSD/VPCP/17-001108

Claim No:

MSC/V/18-000242

Sum Insured:

Excess:

Make of Veh:

D.O.A.

08022018

(Client's Record)

01-03-2018

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

28/2/2018 12:14pm

Person Contacted:

Leang

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SFS 7739K - X

SKS 8861Z - X

2/3/18

Informed Lionel pending est from repairer by merimen

11/4/18

Adrian confirmed LS \$2500 (Real 2470, 50%)

12/4/18

Send preli revised by merimen

12/4/18

Simon on leave

MS1G

ASSIGNMENT

From: _____ Date: 11/3/18

Estimate No: _____

OD: TP / WS / TP RES / CD RES / EVA / INV / MV

To: SFS 7739K

at: Leong Automotive

or: Blk 1, Kaki Blk + Ave 6 # 01-68

Insured: _____

Policy No: _____

Claim No: _____

Sum Insured: _____ Excess: _____

Client's Report: _____

Name of Vn: _____

NS	OS

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Sal. or Market Value: _____

QAC Accident Form: _____ Consistent? : Yes or No

Q/A PP Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Rep: Yes or No

LMT Sum: _____ % Given: Yes or No

QA / REV / REP. / 24 HRS wp

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Date / Time Action / Instruction

TP MS1G.

MV: 37K

PV: 28.1K

Nett: 8.9K.

RECEIVED 12 APR 2018.

Date / Time File Pass:

☐

Prel. Report

☐

Final Report

Date / Time File Return:

12/4 - typist

Record Format

merimen

As For Sum: _____

LS \$2500p

Veh No: SFS7739K Reg: 2011 May

Type: M/Cat M/Cycle Bus/Van/Long Taxi Prime/Mover

Truck Trailer:

Name: Citroen DS3 1598

Color: Blue H/C Insured: NO

So. Facing: 153471 T/Fac Insured: NO

Eng No: VF75A5FS9BW511074

C/V:

Gear: Cont 5000 Rev Peak BurntSteering: Inter Jammed Leaked BurntBrake: Inter Jammed Leaked BurntMod: NR SP STD APR OKTyre Size: 205/45R17R: 205/45R17

BS / DUN / EXYOVA / GY / FS / LIZ / MIC / OHTSU / PIR / SUM

TOYO / YOKO: Nexen

Front:

R/Ba: 06L/Ba: 06

C/OA: _____

Survey Report: Leong AutoDes. of Damages: Fr Rear OS NS UC RoofedFront o/s

The U/C / Chassis/frame Body Structure affected due to collision

Days Of Repair: 4Resurvey No. of Trip: 1

Add. Fee:

☐
Ste. Fee: 0
☐
Inter. Fee: 0
☐
Rep. Fee: 0
☐
As. Fee: 0

Survey Fee

Transportation

As. Fee

As. Fee

As. Fee

As. Fee

200
10

210

Survey Department Check List (Case Handler)

Reference No. : CS/MSG/8603904/Avb
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 12/4/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18003904/Avb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 28-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKS 8861Z	Veh. Inspected	SFS 7739K
Policy No.	MSD/VPCP/17-001108	Coverage (\$)	0.00
Claim No.	MSC/V/18/000242	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	27/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	08/02/2018	Inspection Date	01/03/2018
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 12 Apr 2018

Preliminary Advice

Insured Vehicle No	: SKS8861Z	Accident Date	: 08/02/2018
TP Vehicle No	: SFS7739K	Assignment Date	: 27/02/2018
Make	: CITROEN DS3	Est. Duration of Repair	: 4.00
Date of Inspection	: 01/03/2018		
Inspection At	: LEANG AUTOMOTIVE - KAKI BUKIT (HQ) AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6 #01-68 SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,970.00
Revised Amount	:S\$	2,500.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Feb 2018		27 Feb 2018 14:28 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	WONG SEOW HONG, ID: S7518611H, Tel: +6598337441, Email: SEOWHONG@HOTMAIL.COM		
Main Claimant:	YAP SHU SZE CANDY, ID: S7705871J		
Vehicle Reg. No.:	SFS7739K	Date of Loss:	08/02/2018 13:00 - :59
Claim Type:	TP / MSC/V/18-000242	Policy/Cover Note No.:	MSD/VPCP/17-001108 (Comprehensive) Coverage: 13/05/2017 - 12/05/2018
Vehicle Reg. No. (Insured):	SKS8861Z	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Leang Automotive - Kaki Bukit (HQ) AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6 #01-68, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/02/2018]		
Driver/Custodian (Insured):	WONG SEOW HONG (42 / Female), NRIC: S7518611H, Tel: +6598337441		
Adj Asg. Remarks:	Please appoint MR ADRIAN LING to conduct the survey . Kindly contact the workshop directly @ 9028 6516		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

28/02/2018 @ 12:14pm
Mr Leang v2h Not in

01/03/2018

View Sent Message

This mail is associated with :

***SFS7739K (MSC/V/18-000242)**
[SKS8861Z]

TP

YAP SHU SZE CANDY

Feb 8 2018 1:00PM

[WONG SEOW HONG]

Leang Automotive - Kaki Bukit

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **02/03/2018 10:02 AM.**
To MSIG_LTTP
Subject **PENDING ESTIMATE FROM REPAIRER**

Dear Lionel,

Please be informed that we have inspected the vehicle SFS 7739K on 1/3/2018.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

SELL YOUR CAR BY BIDDING
HIGHEST SELLING PRICE GUARANTEED!
OR GET \$100 CASH!



Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Year Coe Renewal Toyota Vios 1.5A



\$2500 Downpayment Monthly
 From \$580 Onwards. Lowest
 3.68%PA 100% GV Credit Pte Ltd StarAd



Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

3 vehicles

Citroen DS3

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Citroen DS3		Any	Any	2011	Any	Any	Any	Available
	Citroen DS3	1.6A VTI	\$34,800	\$8,900 /yr	13-Jan-2011	1,598 cc	-	Hatchback	Available
CNY Promo! Free STA Evaluation! Limited Time Only! Cheapest In The Market! 1 Lady Owner Only! 100% To Be The Head Turner On The Road! 100% Fully Serviced By C&C Buy With A Peace Of Mind! In Perfect C... ST Carz Pte Ltd Posted: 27-Feb-2018 Tags: 2011 Citroen DS3, Citroen DS3, Citroen, DS3, Used Citroen									
	Citroen DS3	1.6A VTI	\$34,000	\$8,630 /yr	13-Jan-2011	1,598 cc	76,000 km	Hatchback	Available
The Best Value In The Market! 100% Accident Free, Fully Serviced By C&C And In Very Good Condition By Careful Owner. Car Always Parked Under Shelter. Direct Seller. Posted: 09-Feb-2018 Tags: 2011 Citroen DS3, Citroen DS3, Citroen, DS3, Used Citroen									
	Citroen DS3	1.6A VTI	\$43,800	\$8,830 /yr	09-Dec-2011	1,598 cc	87,000 km	Hatchback	Available
Cheapest In The Market, 1 Owner, Fully Maintained By Agent! Low Mileage Done At 14,000Km Yearly, One Year Additional Warranty, Beautiful Blue On Black Interior, Mint Condition, Well Maintained, Trade ... Posted: 28-Feb-2018 Tags: 2011 Citroen DS3, Citroen DS3, Citroen, DS3, Used Citroen									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Citroen DS3, Citroen DS3 Singapore, used Citroen DS3 Singapore, used Citroen DS3, used vehicles Singapore or even buy used Citroen DS3 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5871J
Vehicle Details	
Vehicle No.:	SFS7739K
Vehicle to be Exported:	Yes
Intended De-registration Date:	01 Mar 2018
Vehicle Make:	CITROEN
Vehicle Model:	DS3 1.6 VTI AT ABS D/AIRBAG 2WD 3DR
Primary Colour:	Blue
Secondary Colour:	White
Manufacturing Year:	2011
Engine No.:	10FHCK1087594
Chassis No.:	VF7SA5FS9BW511274
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$20,979.00
Original Registration Date:	26 May 2011
First Registration Date:	26 May 2011
Transfer Count:	0
Actual ARF Paid:	\$20,979.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 May 2021
PARF Rebate Amount:	\$13,636.00
Intended COE Rebate Details	
COE Expiry Date:	25 May 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$44,790.00
COE Rebate Amount:	\$14,472.00
Total Rebate Amount:	\$28,108.00

The information contained herein is correct as at 01 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 08/02/2018 17:31
Date Of Accident 08/02/2018 13:30
Exact Location Of Accident PASIR PANJANG (MAPLE TREE BUSINESS CITY ROUNDABOUT)
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SFS7739K
Insured/Policyholder
Name Of Registered Owner YAP SHU SZE CANDY
NRIC No S7705871J
Email Address YAP.SHUSZE@GMAIL.COM
Mobile Phone No (LOCAL) +65-81981677
Alternative Phone No OFFICE-81981677
Vehicle Particulars
Manufacturer CITROEN
Model DS3
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 2100259671
Cover Note Number
Driver
Name of Driver YAP SHU SZE CANDY
NRIC No S7705871J
Date Of Birth 28/02/1977
Occupation INDOOR
Date Of Driving Pass 09/11/1998
Driving Experience 19 YEARS AND 2 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-81981677
Fax Number
Contact Number OFFICE-81981677
Email Address YAP.SHUSZE@GMAIL.COM

BLK 172 BEDOK SOUTH ROAD #02-423

Address 460172
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

I WAS DRIVING ALONG ROUND ABOUT. VEHICLE B FROM INNER RIGHT SUDDENLY MAKE A LEFT TURN AND HIT ONTO MY FRONT LEFT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKS8861Z
Vehicle Make/Model/Colour
Details Of Properties VEHICLE B
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

X 
 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan #3 Pg. 1



SKETCH PLAN

REFER TO ATTACHED

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

WAS DRIVING ALONG ROUND-ABOUT, VEHICLE B FROM INNER
RIGHT SUDDENLY MAKE A LEFT TURN AND HIT ONTO MY
FRONT LEFT.

DECLARATION

I/we declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ST57239K . 200 May

Date

No.

Citroen DS3 1598.

VF7SASF9BW S11274

Front Bumper tom

1180 /

Front Bumper Clips. new

30 /

Front Bumper Side Holder x2 RH 2yd.

~~65x2=130~~ 65

Front Bumper Fog Lamp RH. New

375 x

Front Bumper Signal Lamp RH. Graded

252 /

Headlamp RH. ut

956 ✓

Front RH Fender. Repair

569. x

Front RH Fender Inner Shield New

135 x

Front RH Fender Inner Shield Clips. New

25 x

Logo New

68 /

Panel Beating.

600 350

Spray Painting.

~~600~~ 450

Wiring.

~~50~~ 30

4970

hist 2551

Labour 830

Tens 10/ 2295.90

Total 3125.90

H/S 25K.

048pays

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003904/AVBN2

Date: 13/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VPCP/17-001108
Claimant Vehicle No :	SFS7739K	Insured Vehicle No :	SKS8861Z
Date of Loss:	08/02/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000242

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFS7739K	Engine No:	10FHCK1087594
Make & Model:	CITROEN DS3, 1.6 VTi (A)	Chassis No:	VF7SA5FS9BW511274
Reg. Date:	26/05/2011 (Man. Year: 2011)	Odometer:	153471 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45R17	Rear Tyre Size:	205/45R17
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,720.00	2,295.90	1,424.10	38.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	830.00	420.00	33.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,970.00	3,125.90	1,844.10	37.10
Approved Total (Overridden) (S\$)		2,500.00		
Nett Amount (S\$)	4,970.00	2,500.00	2,470.00	49.70

INSPECTION

Date of Assignment:	27/02/2018	
Date Inspected:	01/03/2018	Inspected At:
		Leang Automotive - Kaki Bukit (HQ)
		AUTOBAY @ KAKI BUKIT 1 KAKI
		BUKIT AVE 6 #01-68
		Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Apr 2018)
Parts: 144	CITROEN DS3 1.6 VTI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFS7739K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,180.00 F	*1,180.00 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	1		*FRONT BUMPER SIDE HOLDERS	O/s Damaged	130.00 F	*65.00 FL
4	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	375.00 F	*- FL
5	1		*FRONT BUMPER SIGNAL LAMP RH	Cracked	252.00 F	*252.00 FL
6	1		*HEADLAMP RH	Cut	956.00 F	*956.00 FL
7	1		*FRONT RH FENDER	Repair	569.00 F	*- FL
8	1		*FRONT RH FENDER INNER SHIELD	Not Necessary	135.00 F	*- FL
9	1		*FRONT RH FENDER INNER SHIELD CLIPS	Not Necessary	25.00 F	*- FL
10	1		*LOGO	Necessary	68.00 F	*68.00 FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	3,720.00	2,551.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	255.10
Total Parts (\$\$)	3,720.00	2,295.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	350.00
2	SPRAY PAINTING	New	600.00	450.00
3	WIRING	New	50.00	30.00
Gross Labour Cost (\$\$)			1,250.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >