

ASS. REC. BY:

REF: CS/ICS18003911/Krbnz

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Janice Goh

of ICS

Date/Time: 28/02/2018 12:06pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 9277T

Insured: SLH 2667D

at Workshop m/s Trans Cab

Tel:

of No. 2 AMK St 63

Policy No:

Claim No:

DMPC 1800080H

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 25/02/2018

CA / REV / REP. / REV 24 HRS 'WPI'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 9277T - CCL/AXA16019865/Vegsgg Dat: 17.10.16
	SLH 2667D - X



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS/ICS18003911/Krb

7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

Date : 28-02-2018



Code : ICS

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLH 2667D	Veh. Inspected	SHD 9277T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JANICE GOH	Assign Date	28/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/02/2018	Inspection Date	28/02/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Thursday, 8 March, 2018 8:46 AM
To: Catherine Chong (LKK Auto); ECICS Claims
Cc: 'SUR'; assignments@lkkauto.com
Subject: RE: ARRANGE FOR SURVEY SHD9277T

Dear Catherine

Our claim no is DMPC1800080H.
Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

**Please bear with us should we take longer to response as we are currently experiencing a high volume of claims.
Thank you for your kind patience and understanding.**

-----Original Message-----

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 7 March, 2018 4:38 PM
To: ECICS Claims
Cc: 'SUR'; assignments@lkkauto.com
Subject: RE: ARRANGE FOR SURVEY SHD9277T

Dear Janice,

Kindly provide us the claim number.

Best Regards,
Catherine Chong | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 28 February, 2018 1:02 PM
To: 'ECICS Claims' <claims@ecics.com.sg>
Cc: 'SUR' <sur@lkkauto.com>; assignments@lkkauto.com
Subject: RE: ARRANGE FOR SURVEY SHD9277T

Catherine Chong (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Wednesday, 28 February, 2018 12:05 PM
To: Candy Kong; assignments
Cc: ECICS Claims
Subject: RE: ARRANGE FOR SURVEY SHD9277T
Attachments: img-228090946-0001.pdf

Without Prejudice

Dear Candy

Thank you for your email.
We will appoint LKK for the PRI.

Kenneth

Aside to LKK

Please assist to arrange for TP PRI.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims.
Thank you for your kind patience and understanding.****

-----Original Message-----

From: Candy Kong [mailto:candy.kong@transcab.com.sg]
Sent: Wednesday, 28 February, 2018 9:13 AM
To: ECICS Claims
Subject: ARRANGE FOR SURVEY SHD9277T

Dear all ,

PLS ARRANGE LKK AUTO CONSULTANTS PTE LTD TO SURVEY.

Please arrange for survey as below :

SLH2667D - 25.02.2018 at 1230Hrs - SHD9277T

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

Thks & Rdgs
Candy Kong
Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

[ECICS Facebook] [ECICS Twitter] [ECICS Limited]

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD9277T
Vehicle to be Exported:	Yes
Intended De-registration Date:	27 Feb 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	Z20S1445324K
Chassis No.:	KL1LA69RJBB066352
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$13,811.00
Original Registration Date:	16 Dec 2011
First Registration Date:	16 Dec 2011
Transfer Count:	0
Actual ARF Paid:	\$13,811.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Dec 2019
PARF Rebate Amount:	\$8,977.00
Intended COE Rebate Details	

COE Expiry Date:	15 Dec 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
QP Paid:	\$39,041.00
COE Rebate Amount:	\$8,777.00
Total Rebate Amount:	\$17,754.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 27 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/02/2018 13:48
Date Of Accident	25/02/2018 12:30
Exact Location Of Accident	WOODLANDS STREET 12
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9277T
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	HARI SINGH S/O GERNAIL SINGH
NRIC No	S1348376J
Date Of Birth	03/03/1959
Occupation	OUTDOOR
Date Of Driving Pass	13/03/2002
Driving Experience	15 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84062385
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 409 BUKIT BATOK WEST AVE 4
 #11-168
 Postcode 650409
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-4849999 - FAX NO: 62181399
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20180227/2077

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLH2667D
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

NIL

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Clay
Driver's Signature
(If driver is not the policyholder)
Date & Time:

andy
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180227/2077

1 of 3

Report No. T/20180227/2077

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/02/2018 13:33	Vide Report No.:	Station Diary No.: 44
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: HARI SINGH S/O GERNAIL SINGH		Address: APT BLK 409 BUKIT BATOK WEST AVENUE 4 #11-168 SINGAPORE 650409	
ID Type / ID No.: NRIC NO / S1348376J		Contact No.:	Mobile: 84062385
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 58	Date of Birth: 03/03/1959	Type of Informant: Vehicle Owner
Race: Sikh		Language:	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3,4	Date of Expiry:

General Information of the Accident				
Type of Accident: Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 25/02/2018 12:30	Type of Location:	
Location: WOODLANDS STREET 12 Marsiling Mall driveway				
Weather: Sunny		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control:	Traffic Volume: Light	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHD9277T	Car			Red	Seriously Damaged	0
SLH2667D	Car			Red		0

Details of Person Involved	
Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180227/2077

2 of 3

Report No. T/20180227/2077

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

CONTINUATION OF REPORT

Vehicle Owner			
Name	HARI SINGH S/O GERNAIL SINGH	ID No.	S1348376J
Related Vehicle	NIL	Contact No.	84062385
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 25/02/2018, at around 1230hrs, I parked my vehicle at the driveway (two-way lane) of Masiling Mall and left the vehicle to get a drink. When you return, I realized that my vehicle has been damaged with dent and scratches on the right side of my vehicle. The vehicle that caused the damage (vehicle B) was nowhere to be seen at the point in time. A passerby approached me and showed me a photo of vehicle B he took earlier on. The photo showed the back view of vehicle B, including the license plate and the car color, which is red in color. I left the place soon after to lodge a report at a Neighborhood Police Centre.

I am this report for recording and claiming purposes.

POLICE REPORT Pg. 1



SINGAPORE
POLICE FORCE



T/20180227/2077

3 of 3

Report No. T/20180227/2077


Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 KOH JIA JUN <i>[Signature]</i>	Signature Of Informant: <i>[Signature]</i>
Signature Of Interpreter: Not applicable	Date/Time: 27/02/2018 13:33
Officer In Charge Of Case: TP / HRT / SI TAN LEE HWANG DAWN Contact No.: 65476215	Classification Of Case:
Authentication Stamp NP168 	

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9277T -

AAD1802-267

NOT Authored
21 Sep \$ 27502

Vehicle No.:	SHD 9277T - CANDY
Chassis No.:	KL1LA69RJBB066352
Date of Accident :	25.02.2018
Vehicle Make:	CHEVROLET
Vehicle Model:	CHEVROLET EPICA 2.0
Third Party Insurer :	<i>ECIS</i>

		PART		LIST	
1	1	Front Bumper	\$	<i>Sm</i> 1,202.00	<i>X</i>
2	1	Front Bumper Lower Absorber	\$	<i>Sm</i> 180.00	
3	1	Front Bumper Reinforcement	\$	<i>R</i> 356.00	
4	1	Front Bumper side support RH	\$	<i>Sm</i> 76.20	
5	1	Front Bumper side support LH	\$	<i>Sm</i> 76.20	
6	1	Front Bumper Retainer RH	\$	<i>Sm</i> 102.00	
7	1	Front Bumper Retainer LH	\$	<i>Sm</i> 102.00	
8	1	Front Bumper Lower Grille	\$	<i>Sm</i> 78.00	
9	1	Front Bumper Lower Stiffener	\$	<i>R</i> 134.37	
10	1	Front Bumper Bracket RH	\$	<i>R</i> 10.00	
11	1	Front Bumper Bracket LH	\$	<i>R</i> 10.00	
12	1	Front Bumper Fog Lamp Outer Cover RH	\$	<i>Sm</i> 32.40	
13	1	Headlamp RH	\$	<i>Sm</i> 816.00	
14	1	Windscreen Washer Tank - Filler Neck	\$	<i>Sm</i> 4.80	
15	1	Windscreen Washer Tank (Reservoir A-W/Shield)	\$	<i>Sm</i> 62.00	
16	1	Windscreen Washer Tank Motor (Pump Wswa)	\$	<i>Sm</i> 51.00	
17	1	TANK, WIPER HOSE	\$	<i>Sm</i> 21.00	
18	1	Front Fender RH	\$	<i>R</i> 837.60	
19	1	Front Fender Liner RH	\$	<i>Sm</i> 47.00	
20	1	Front Door RH	\$	<i>R</i> 1,133.00 ✓	
21	1	Front Door Outer Moulding RH	\$	<i>Sm</i> 220.00	<i>X</i>
22	1	Front Door Outer Handle RH	\$	<i>Sm</i> 125.00	
23	1	Front Door Handle Support RH	\$	<i>Sm</i> 3.00	
24	1	Front Door Outer handle inner seal RH	\$	<i>Sm</i> 89.15	
25	1	Front Door Outer key lock RH	\$	<i>Sm</i> 25.00	
26	1	Front Door Hinge Upper RH	\$	<i>R</i> 65.00	
27	1	Front Door Hinge Lower RH	\$	<i>R</i> 65.00	
28	1	Front Door Check / Arrestor RH	\$	<i>Sm</i> 67.50	
29	1	Front Door Weatherstrip RH	\$	<i>Sm</i> 138.79	
30	1	Front Side View Mirror RH	\$	<i>R</i> 939.00	

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-267

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9277T -

31	1	Side Rocker Panel Garnish RH	\$	R	236.40 X
32	1	Side Rocker Panel Outer RH	\$	R	433.26 X
33	1	Rear Door RH	\$	B	1,133.00 ✓
34	1	Rear Door check / arrestor RH	\$	Sn	65.00
35	1	Rear Door lock striker / latch RH	\$	R	120.00
36	1	Rear Door outer weatherstrip moulding RH	\$	Sn	85.00
37	1	Rear Door outer handle RH	\$	Sn	60.00
38	1	Rear Door outer handle - rubber seal RH	\$	Sn	25.00
39	1	Rear Door inner opening handle RH	\$	Sn	45.50
40	1	Rear Fender RH	\$	R	1,145.00
41	1	Rear Fender Inner Cowling RH	\$	Sn	76.60
42	1	Rear Tail Lamp RH	\$	Sn	479.30
43	1	Rear Bumper	\$	Sn	1,202.00
44	1	Rear Bumper Side Retainer RH	\$	Sn	68.76
45	1	Rear Bumper Reflectors RH	\$	Sn	119.74

TOTAL	\$	12,363.57
10%	\$	1,236.36
	\$	11,127.21

Special Nett

1	4	Front Bumper Fastener Clip	\$	nn	24.00 X
2	1 Set	Front Fender Liner Clip	\$	nn	30.00 X
3	1 Set	Rear Bumper Parking Sensor	\$	nn	300.00 X
4	1 Set	Rear Bumper Fastener Clip	\$	nn	30.00 X
5	1 Set	Rear Fender Liner Clip	\$	nn	30.00 X
6	1	Door Sticker "Trans-cab"	\$	nn	80.00 bosn
7	1	Door Sticker "6555-3333"	\$	nn	80.00 bosn
8	1set	Side Rocker Panel Garnish Clip RH	\$	nn	60.00
9	1	Front Tyre RH	\$	Sn	360.00
10	1	Front Wheel Rim RH	\$	Sn	254.00
11	1	Hub Cup Rim Front RH	\$	Sn	35.00
12	1	Rear Tyre RH	\$	Sn	360.00
13	1	Rear Wheel Rim RH	\$	Sn	254.00
14	1	Hub Cup Rim RR RH	\$	Sn	35.00

TOTAL	\$	1,932.00
TOTAL PARTS	\$	13,059.21

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-267

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9277T -

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,700.00 <i>50d</i>
To Rust-Proofing Of The Affected Areas.	\$	220.00 <i>60d</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
Putty and Spray Painting Of The Affected Portion.	\$	2,800.00 <i>60d</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>20d</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
Towing fees	\$	<i>nn</i> 120.00 <i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 <i>120d</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 <i>X</i>
	TOTAL	<u>\$ 6,740.00</u>
	Over All Total	<u>\$ 19,799.21</u>

REPAIR DAYS~~10-DAYS~~*3days*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS/ICS18003911/Krbn2

7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

Date : 08-03-2018



Code : ICS

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLH 2667D	Veh. Inspected	SHD 9277T
Policy No.		Coverage (\$)	0.00
Claim No.	DMPC1800080H	Excess (\$)	0.00
Assign From	JANICE GOH	Assign Date	28/02/2018

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET EPICA (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	KL1LA69RJBB066352	Colour	WHITE / RED
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	8 mm
L/H Front Tyre	195/65 R15	WEST LAKE	8 mm
R/H Rear Tyre	195/65 R15	FALKEN	7 mm
L/H Rear Tyre	195/65 R15	FALKEN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/02/2018	Inspection Date	28/02/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9277T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	SERVICEABLE	1,202.00	-
1	FRONT BUMPER LOWER ABSORBER	SERVICEABLE	180.00	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	356.00	-
1	FRONT BUMPER SIDE SUPPORT RH	SERVICEABLE	76.20	-
1	FRONT BUMPER SIDE SUPPORT LH	SERVICEABLE	76.20	-
1	FRONT BUMPER RETAINER RH	SERVICEABLE	102.00	-
1	FRONT BUMPER RETAINER LH	SERVICEABLE	102.00	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	78.00	-
1	FRONT BUMPER LOWER STIFFENER	TO REPAIR SEE LABOUR	134.37	-
1	FRONT BUMPER BRACKET RH	TO REPAIR SEE LABOUR	10.00	-
1	FRONT BUMPER BRACKET LH	TO REPAIR SEE LABOUR	10.00	-
1	FRONT BUMPER FOG LAMP OUTER COVER RH	SERVICEABLE	32.40	-
1	HEADLAMP RH	SERVICEABLE	816.00	-
1	WINDSCREEN WASHER TANK-FILLER NECK	SERVICEABLE	4.80	-
1	WINDSCREEN WASHER TANK (RESERVOIR A-W/SHIELD)	SERVICEABLE	62.00	-
1	WINDSCREEN WASHER TANK MOTOR (PUMP WSWA)	SERVICEABLE	51.00	-
1	TANK,WIPER HOSE	SERVICEABLE	21.00	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	837.60	-
1	FRONT FENDER LINER RH	SERVICEABLE	47.00	-
1	FRONT DOOR RH	BENT	1,133.00	1,133.00
1	FRONT DOOR OUTER MOULDING RH	SERVICEABLE	220.00	-
1	FRONT DOOR OUTER HANDLE RH	SERVICEABLE	125.00	-
1	FRONT DOOR HANDLE SUPPORT RH	SERVICEABLE	3.00	-
1	FRONT DOOR OUTER HANDLE INNER SEAL RH	SERVICEABLE	89.15	-
1	FRONT DOOR OUTER KEY LOCK RH	SERVICEABLE	25.00	-
1	FRONT DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	65.00	-
1	FRONT DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	65.00	-
1	FRONT DOOR CHECK/ARRESTOR RH	SERVICEABLE	67.50	-
1	FRONT DOOR WEATHERSTRIP RH	SERVICEABLE	138.79	-

Report Ref No. CS/ICS18003911/Krbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SIDE VIEW MIRROR RH	SERVICEABLE	939.00	-
1	SIDE ROCKER PANEL GARNISH RH	TO REPAIR SEE LABOUR	236.40	-
1	SIDE ROCKER PANEL OUTER RH	TO REPAIR SEE LABOUR	433.26	-
1	REAR DOOR RH	BENT	1,133.00	1,133.00
1	REAR DOOR CHECK/ARRESTOR RH	SERVICEABLE	65.00	-
1	REAR DOOR LOCK STRIKER/LATCH RH	TO REPAIR SEE LABOUR	120.00	-
1	REAR DOOR OUTER WEATHERSTRIP MOULDING RH	SERVICEABLE	85.00	-
1	REAR DOOR OUTER HANDLE RH	SERVICEABLE	60.00	-
1	REAR DOOR OUTER HANDLE-RUBBER SEAL RH	SERVICEABLE	25.00	-
1	REAR DOOR INNER OPENING HANDLE RH	SERVICEABLE	45.50	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER COWLING RH	SERVICEABLE	76.60	-
1	REAR TAIL LAMP RH	SERVICEABLE	479.30	-
1	REAR BUMPER	SERVICEABLE	1,202.00	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	68.76	-
1	REAR BUMPER REFLECTORS RH	SERVICEABLE	119.74	-
	LESS 10% DISCOUNT		-1,236.36	-226.60
			11,127.21	2,039.40
	<u>SPECIAL NETT ITEMS</u>			
4	FRONT BUMPER FASTENER CLIP (SN)	NOT NECESSARY	24.00	-
1	SET FRONT FENDER LINER CLIP (SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER PARKING SENSOR (SN)	NOT NECESSARY	300.00	-
1	SET REAR BUMPER FASTENER CLIP (SN)	NOT NECESSARY	30.00	-
1	SET REAR FENDER LINER CLIP (SN)	NOT NECESSARY	30.00	-
1	DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	DOOR STICKER "6555-3333" (SN)	NECESSARY	80.00	60.00
1	SET SIDE ROCKER PANEL GARNISH CLIP RH (SN)	NOT NECESSARY	60.00	-
1	FRONT TYRE RH (SN)	SERVICEABLE	360.00	-
1	FRONT WHEEL RIM RH (SN)	SERVICEABLE	254.00	-
1	HUB CUP RIM FRONT RH (SN)	SERVICEABLE	35.00	-
1	REAR TYRE RH (SN)	SERVICEABLE	360.00	-
1	REAR WHEEL RIM RH (SN)	SERVICEABLE	254.00	-

Report Ref No. CS/ICS18003911/Krbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HUB CUP RIM RR RH (SN)	SERVICEABLE	35.00	-
			1,932.00	120.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT,FRONT BUMPER LOWER STIFFENER,FRONT BUMPER BRACKET RH,FRONT BUMPER BRACKET LH,FRONT FENDER RH,FRONT DOOR HINGE UPPER RH,FRONT DOOR HINGE LOWER RH,SIDE ROCKER PANEL GARNISH RH,SIDE ROCKER PANEL OUTER RH,REAR DOOR LOCK STRIKER/LATCH RH AND REAR FENDER RH.		2,700.00	500.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		220.00	60.00
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,800.00	600.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	120.00
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			6,740.00	1,300.00
	GRAND TOTAL		19,799.21	3,459.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,750.00

Report Ref No. CS/ICS18003911/Krbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.