

INSURER

INS. CASE OWNER:

Smtm

CC 6/AIG1800

3910, Aebn

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

1/7/18

Date / Time:

28/1/18

Registered in Merimen:

28/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLW 2448R

Name of Insured:

TAN WEI NIAN

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

28/1/18

Is driver the owner?

( YES / NO )

Nature of Accident:

Claim No.:

05566406850

Policy No.:

150001674

Make / Model:

Audi

Place of Accident:

KPE INMVEL

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

4/7/18

SLW 2448R

STP 37318

SLK 7562X



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

modern

TP



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

2/7/18  
HSE

- NO OI GIA, SENT OUT 1ST LETTER.

5/3/18 4:10pm

CALLED OI CONFIRMED ACCIDENT. OI INVOLVED IN BOTH C.C OI  
OPS 7TH VEH. INFORM TP CLAIM AGREED TO SETTLE AND MAKE  
AGREED NCD ISSUE.

Email WSP LIABILITY CLEAR.

2/5/18 FILE PASS TO TYPST TO PREPARE REPORT.

RECEIVED 22 MAR 2018

RECEIVED 21 MAY 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st): 2/3/18

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 7 MAR 9/3/18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:-

FINALIZATION

Date/Time: 2/3/18

Confirm with: GHM

Confirm by: LSP

Repair Cost:

SS10,000

( 12 days)

Reduction:

44 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 1-5-18

Confirm with: MEI

Email ☒ Call ☐

Final Liability:

SS 100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 0%

Repair Cost:

SS10,100.00

8 VEH C.C OI TM

Loss of Rental (LOR):

SS 1,400.00

( 14 days)

x 100

Loss of Use (LOU):

SS -

(\$

x

days)

Loss of Income (LOI):

SS -

(\$

x

days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS7-49

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

+ 820 + 100

Total:

SS12,107.49

Global Sum SS:

FINAL PAYMENT

Date/Time: 1-5-18

Confirm with: MEI

Email ☒ Call ☐

Payee 1:

SS12,107.49

Name 1:

MODERN AUTOMOTIVE PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Lump Sum / I.B.I: (\$



Weekend (\$

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                 |                            |            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|----------------------------|------------|-------------------------------------------------------------------------------------|
| AIG ASIA PACIFIC INSURANCE PTE LTD                                                                                                     |                                                                                 | Ref : CC6/AIG18003916/Aeb3 |            |                                                                                     |
| 78 SHENTON WAY #08-16<br>CHARTIS BUILDING<br>SINGAPORE 079120                                                                          |                                                                                 | Date : 28-02-2018          |            |  |
|                                                                                                                                        |                                                                                 | Code : AIG                 |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                 |                            |            |                                                                                     |
| Insured Veh.                                                                                                                           | SLW 2448R                                                                       | Veh. Inspected             | SJZ 3731Z  |                                                                                     |
| Policy No.                                                                                                                             |                                                                                 | Coverage (\$)              | 0.00       |                                                                                     |
| Claim No.                                                                                                                              |                                                                                 | Excess (\$)                | 0.00       |                                                                                     |
| Assign From                                                                                                                            |                                                                                 | Assign Date                | 28/02/2018 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                 |                            |            |                                                                                     |
| Make & Model                                                                                                                           |                                                                                 | c.c                        | 0          |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                          | Year of Reg.               |            |                                                                                     |
| Chassis No.                                                                                                                            |                                                                                 | Colour                     |            |                                                                                     |
| Odometer                                                                                                                               | -                                                                               | Steering                   |            |                                                                                     |
| Brakes                                                                                                                                 |                                                                                 | Modification               |            |                                                                                     |
| General                                                                                                                                |                                                                                 |                            |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                 |                            |            |                                                                                     |
|                                                                                                                                        | Size                                                                            | Make                       | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                         |                                                                                 |                            | mm         |                                                                                     |
| L/H Front Tyre                                                                                                                         |                                                                                 |                            | mm         |                                                                                     |
| R/H Rear Tyre                                                                                                                          |                                                                                 |                            | mm         |                                                                                     |
| L/H Rear Tyre                                                                                                                          |                                                                                 |                            | mm         |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                 |                            |            |                                                                                     |
|                                                                                                                                        |                                                                                 |                            |            |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                 |                            |            |                                                                                     |
| Accident Date                                                                                                                          | 28/02/2018                                                                      | Inspection Date            |            |                                                                                     |
| Survey held at                                                                                                                         | MODERN AUTOMOTIVE PTE LTD<br>BLK 3023A UBI ROAD 1<br>#01-61<br>SINGAPORE 408717 |                            |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                 |                            |            |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                 |                            |            |                                                                                     |

MODERN AUTOMOTIVE PTE LTD  
BLK 3023A UBI ROAD 1 # 01-61  
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747-6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building  
78 Shenton Way #07-16  
Singapore 079120  
Tel : 6419 - 3000  
Fax : 6835 - 7416

Asher

Quotation  
DATE : 27.02.2018  
VEH NO : SJZ3731Z  
MODEL : Toyota Altis  
D O A : 28.02.2018  
YR REF : SLW2448R

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJZ3731Z (Toyota Altis)

| Item      | Description                                               | Qty   | Amt        |
|-----------|-----------------------------------------------------------|-------|------------|
| <u>NO</u> | <u>LIST ITEMS</u>                                         |       |            |
| 1         | Front Bumper <i>distorted</i>                             | 1     | 439.20 ✓   |
| 2         | Front Bumper Clips <i>new</i>                             | 1 set | 30.00 ✓    |
| 3         | Front Bumper Side Holder <i>new</i>                       | 2     | 121.40 ✓   |
| 4         | Front Bumper Reinforcement <i>but</i>                     | 1     | 339.70 ✓   |
| 5         | Front Bumper Logo <i>new</i>                              | 1     | 32.80 ✓    |
| 6         | Front Bumper Grille (Upper) <i>cracked</i>                | 1     | 298.80 ✓   |
| 7         | Front Bumper Grille (Lower) <i>peeled</i>                 | 1     | 106.50 ✓   |
| 8         | Front Bumper Undercover <i>form</i>                       | 1     | 262.20 ✓   |
| 9         | Front Bumper Undercover Clips <i>new</i>                  | 1 set | 30.00 ✓    |
| 10        | Headlamp <i>cracked</i>                                   | 2     | 982.20 ✓   |
| 11        | Front <del>Bumper</del> <sup>Brace</sup> Panel <i>but</i> | 1     | 113.10 ✓   |
| 12        | Front Support Panel <i>Buckled</i>                        | 1     | 699.90 ✓   |
| 13        | Bonnet <i>tear</i>                                        | 1     | 942.20 +   |
| 14        | Bonnet Lock <i>new</i>                                    | 1     | 128.60 x   |
| 15        | Air Con Condenser <i>distorted</i>                        | 1     | 1,299.40 ✓ |
| 16        | Radiator <i>distorted</i>                                 | 1     | 1,681.90 ✓ |
| 17        | Radiator Top Cover <i>2</i>                               | 1     | 193.40 ✓   |
| 18        | Radiator Fan Cowling                                      | 1     | 223.40 ✓   |
| 19        | Radiator Fan Blade <i>new</i>                             | 1     | 96.10 ✓    |
| 20        | Radiator Fan Motor <i>new</i>                             | 1     | 248.70 ✓   |
| 21        | Air Con Suction Pipe <i>3 new</i>                         | 1     | 341.60 +   |
| 22        | Air Con Discharge Pipe                                    | 1     | 395.80 +   |
| 23        | Rear Bumper <i>distorted</i>                              | 1     | 476.20 ✓   |
| 24        | Rear Bumper Clips <i>new</i>                              | 1 set | 30.00 ✓    |
| 25        | Rear Bumper Side Holder <i>new</i>                        | 2     | 114.00 ✓   |
| 26        | Rear Bumper Reflector <i>new</i>                          | 2     | 138.40 x   |
| 27        | Rear Bumper Sponge <i>cracked</i>                         | 1     | 80.90 ✓    |

RE: ESTIMATE FOR ACCIDENT REPAIR S.JZ3731Z (Toyota Altis)

|    |                                                |       |          |
|----|------------------------------------------------|-------|----------|
| 28 | Rear Bumper Reinforcement Rod <i>dent</i>      | 1     | 152.60 ✓ |
| 29 | Rear Bumper Impact Bracket <i>dent</i>         | 2     | 171.20 ✓ |
| 30 | Taillamp <i>at</i>                             | 2     | 684.00 ✓ |
| 31 | Rear End Panel <i>dent</i>                     | 1     | 532.80 ✓ |
| 32 | Rear End Panel Top Garnish <i>dent</i>         | 1     | 192.70 ✓ |
| 33 | Bootlid <i>dent</i>                            | 1     | 680.00 ✓ |
| 34 | Bootlid Lock <i>dent</i>                       | 1     | 121.50 ✓ |
| 35 | Bootlid Weatherstripe <i>at</i>                | 1     | 185.50 ✓ |
| 36 | Bootlid Hinge <i>dent</i>                      | 2     | 144.00 ✓ |
| 37 | Bootlid Reflector <i>dent</i>                  | 2     | 321.40 ✓ |
| 38 | Bootlid Inner Trim                             | 1     | 172.10 ✓ |
| 39 | Bootlid Inner Trim Clips <i>at</i>             | 1 set | 30.00 ✓  |
| 40 | Toyota Logo                                    | 1     | 52.00 ✓  |
| 41 | 1.6 Emblem <i>dent</i>                         | 1     | 46.00 ✓  |
| 42 | Corolla Wording <i>dent</i>                    | 1     | 48.00 ✓  |
| 43 | Altis Wording <i>dent</i>                      | 1     | 48.00 ✓  |
| 44 | Spare Tyre Panel <i>dent</i>                   | 1     | 752.60 ✓ |
| 45 | Spare Tyre Panel Top Board <i>dent</i>         | 1     | 359.20 ✓ |
| 46 | Rear Fender Inner Trim Board <i>dent</i>       | 2     | 677.40 ✓ |
| 47 | Rear Fender Inner Trim Board Clips <i>dent</i> | 1 set | 60.00 ✓  |
| 48 | Rear Exhaust Pipe <i>dent</i>                  | 1     | 792.10 ✓ |
| 49 | Rear Exhaust Mounting <i>dent</i>              | 1     | 42.00 ✓  |

11250.81  
8A101 set

Less 25%

16,111.50  
(4,027.88)  
\$ 12,083.63

S/NET ITEMS

|   |                                       |             |
|---|---------------------------------------|-------------|
| 1 | Front Number Plate <i>dent</i>        | \$ 30.00 ✓  |
| 2 | Front Number Plate Holder <i>dent</i> | \$ 30.00 ✓  |
| 3 | Rear Number Plate <i>dent</i>         | \$ 30.00 ✓  |
| 4 | Rear Number Plate Holder <i>dent</i>  | \$ 30.00 ✓  |
| 5 | Reverse Sensor <i>dent</i>            | \$ 280.00 ✓ |
| 6 | Taillamp Sponge Gasket <i>dent</i>    | \$ 40.00 ✓  |
| 7 | Rear End Panel Sealant <i>dent</i>    | \$ 60.00 ✓  |

Total Parts

\$ 12,583.63

LABOUR CHARGE

|   |                                                                 |               |
|---|-----------------------------------------------------------------|---------------|
| 1 | To knocking & pull out front & rear portion & renew above parts | \$ 2,400.00 ✓ |
| 2 | To putty & spray up paint works                                 | \$ 1,800.00 ✓ |
| 3 | To check wiring                                                 | \$ 100.00 ✓   |
| 4 | To remove condenser, radiator & to re-gas                       | \$ 180.00 ✓   |

RE: ESTIMATE FOR ACCIDENT REPAIR SJZ3731Z (Toyota Altis)

|              |                              |    |                      |
|--------------|------------------------------|----|----------------------|
| 5            | To remove reverse sensor     | \$ | <del>100.00</del> 50 |
| 6            | To remove upholstery         | \$ | <del>150.00</del> 60 |
| 7            | To underseal                 | \$ | <del>150.00</del> 60 |
| 8            | To remove exhaust pipe       | \$ | <del>150.00</del> 80 |
| 9            | To transfer bootlid fittings | \$ | <del>150.00</del> 40 |
| Total Labour |                              | \$ | 5,180.00             |
| Grand Total  |                              | \$ | <b>17,763.63</b>     |

GST Will be reflected in the final bills

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 12,508.10  
e/s: 10K.  
12 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Enquire PARF/COE Rebate for Registered Vehicle

|                                |                          |
|--------------------------------|--------------------------|
| Vehicle Owner Particulars      |                          |
| Owner ID Type:                 | Singapore NRIC           |
| Owner ID:                      | 6112D                    |
| Vehicle Details                |                          |
| Vehicle No.:                   | SJZ3731Z                 |
| Vehicle to be Exported:        | Yes                      |
| Intended De-registration Date: | 01 Mar 2018              |
| Vehicle Make:                  | TOYOTA                   |
| Vehicle Model:                 | COROLLA ALTIS 1.6 AUTO   |
| Primary Colour:                | Blue                     |
| Manufacturing Year:            | 2008                     |
| Engine No.:                    | 3ZZ4848648               |
| Chassis No.:                   | MR053ZEE106134307        |
| Maximum Power Output:          | 80.0 kW (107 bhp)        |
| Open Market Value:             | \$16,167.00              |
| Original Registration Date:    | 11 Dec 2008              |
| First Registration Date:       | 11 Dec 2008              |
| Transfer Count:                | 2                        |
| Actual ARF Paid:               | \$16,167.00              |
| Intended PARF Rebate Details   |                          |
| PARF Eligibility:              | Yes                      |
| PARF Eligibility Expiry Date:  | 10 Dec 2018              |
| PARF Rebate Amount:            | \$8,083.00               |
| Intended COE Rebate Details    |                          |
| COE Expiry Date:               | 10 Dec 2018              |
| COE Category:                  | A - Car (1600cc & below) |
| COE Period(Years):             | 10                       |
| QP Paid:                       | \$2.00                   |
| COE Rebate Amount:             | \$0.00                   |
| Total Rebate Amount:           | \$8,083.00               |

The information contained herein is correct as at 01 Mar 2018

OK

Altis Price Range Depreciation 2008 Vehicle Type

Advanced Search

## Used Car Comparison

--- Comparing 3 Vehicles ---

Toyota Corolla Altis 1.6A

Toyota Corolla Altis 1.6A

Toyota Corolla Altis 1.6A



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Add to Shortlist

Add to Shortlist

Use search bar above to set to compare.

### CAR DETAILS

|                   |                                                                                          |                             |                                                                                                                                                               |
|-------------------|------------------------------------------------------------------------------------------|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Price             | \$17,588                                                                                 | \$18,000                    | \$15,800                                                                                                                                                      |
| Instalment        | \$1,570                                                                                  | \$1,431                     | \$2,239                                                                                                                                                       |
| Registration Date | 10-Nov-2008                                                                              | 11-Dec-2008                 | 25-Aug-2008                                                                                                                                                   |
| Manufactured      | 2008                                                                                     | 2008                        | 2008                                                                                                                                                          |
| Mileage           | -                                                                                        | 313,200 km                  | 110,000 km                                                                                                                                                    |
| Transmission      | Auto                                                                                     | Auto                        | Auto                                                                                                                                                          |
| Engine Cap        | 1,598 cc                                                                                 | 1,598 cc                    | 1,598 cc                                                                                                                                                      |
| Road Tax          | \$742 /yr                                                                                | \$742 /yr                   | \$742 /yr                                                                                                                                                     |
| Power             | 80.0 kW (107 bhp)                                                                        | 80.0 kW (107 bhp)           | 80.0 kW (107 bhp)                                                                                                                                             |
| Curb Weight       | 1,195 kg                                                                                 | 1,195 kg                    | 1,195 kg                                                                                                                                                      |
| Features          | -                                                                                        | 95% Good Engine Very Good.  | 1.6L VVT-i DOHC Engine, Responsive Auto Transmission, Disc Brake, Dual Airbags, Auto Climatic Aircon, Retractable Side Mirrors With Indicators.               |
| Accessories       | -                                                                                        | -                           | Upholstery Leather Seats, Sports Rims, Knockdown Rear Seats, Factory Fitted Audio System With Audio Steering Control, Reverse Sensors, Solar Film.            |
| Description       | Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only. |                             | Superb Condition, Elegant White Colour, No Repairs Required, Well Kept, Reliable Model, Fuel Economical, Well Taken Care By Previous Owner. Price Negotiable. |
| COE               | \$10,455                                                                                 | \$7,721                     | \$13,289                                                                                                                                                      |
| OMV               | \$16,084                                                                                 | \$16,084                    | \$16,777                                                                                                                                                      |
| ARF               | \$16,084                                                                                 | \$16,084                    | \$16,777                                                                                                                                                      |
| Depreciation      | \$13,770 /yr                                                                             | \$12,800 /yr                | -                                                                                                                                                             |
| No. of Owners     | 1                                                                                        | 2                           | 3                                                                                                                                                             |
| Type of Vehicle   | Sedan                                                                                    | Sedan                       | Sedan                                                                                                                                                         |
| Category          | PARF Car                                                                                 | PARF Car, Direct Owner Sale | PARF Car                                                                                                                                                      |
| Availability      | Available                                                                                | Available                   | Available                                                                                                                                                     |

### SELLER INFORMATION

|               |                           |              |                               |
|---------------|---------------------------|--------------|-------------------------------|
| Seller        | Boeki Auto & Marine       | Direct Owner | WSYC Pte Ltd                  |
| Address       | 176 Sin Ming Drive #02-15 | -            | 1 Bukit Batok Crescent #02-39 |
| Office Number | 65549390                  | -            | 66358117                      |

## Asher Sng (LKKAUTO)

---

**From:** Asher Sng (LKKAUTO)  
**Sent:** Monday, 5 March 2018 12:34 PM  
**To:** Shu Pei (LKKAUTO); Chin  
**Cc:** Admin A; Vic (LKKAUTO)  
**Subject:** RE: TP Claim SJZ3731Z & SLW2448R (AIG) \*\*\*\*\*LKK REF:CC6/AIG18003916/Aeb3

WITHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents for us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shu Pei (LKKAUTO)  
**Sent:** Wednesday, 28 February 2018 5:57 PM  
**To:** Chin <[chin@modernautomotive.com.sg](mailto:chin@modernautomotive.com.sg)>  
**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Asher Sng (LKKAUTO) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>; Vic (LKKAUTO) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>  
**Subject:** RE: TP Claim SJZ3731Z & SLW2448R (AIG) \*\*\*\*\*LKK REF:CC6/AIG18003916/Aeb3

Dear Grace,

Thank you for your email.

Please be informed that we are currently **pending for our insured's report.**

Kindly note that for liability, claim negotiation and settlement, please contact Asher at 6841 6051.

Our respective case handler will look into the matter and revert to you in due course.

Thank you

*To check availability of the case handler, you may contact the undersigned.*

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chin [<mailto:chin@modernautomotive.com.sg>]

**Sent:** Wednesday, 28 February 2018 4:57 PM

**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** Re: TP Claim SJZ3731Z & SLW2448R (AIG)

Dear Sir

We refer to the above matter.

Kindly advise liability of the accident.

Your Insured: SLW2448R

Our Insured: SJZ3731Z

DOA: 28.02.2018

We enclosed herewith our client report for your perusal.

Please reply asap.

Thank you

Regards,

Grace Chin

Modern Automotive Pte Ltd

Blk 3023-A, Ubi Road 1 #01-61

Singapore 408717

Tel: 6748 4422

Fax: 6747 6720

## MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 #01 - 61

SINGAPORE 408717

GST REG. NO : 200501102H

TEL : 6748-4422/ 6745-4422 FAX : 6-747- 6720

Email: chin@modernautomotive.com.sg

Your Ref : SLW2448R

Our Ref : SJZ3731Z

Date : 21.03.2018

The Claims Manager

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78, Shenton Way #07-16

Singapore 079120

Tel : 6-419-300 Fax : 6-415-3727

Attn : The Motor Claim Dept

RE : ACCIDENT INVOLVING SJZ3731Z & SLW2448R ON 28.02.2018  
ALONG KPE TOWARDS CITY

---


We refer to the above matter.

We have been authorized by our client Mr Toh Shi Ming Darius to make claim against your insured vehicle No. SLW2448R in respect of the above accident for the following :

|                                  |                         |
|----------------------------------|-------------------------|
| Repair Cost                      | \$ 10,700.00 (Incl GST) |
| Loss of rental (\$120 x 14 days) | \$ 1,680.00             |
| Search fee                       | \$ 7.49                 |
| Total :                          | <u>\$ 12,387.49</u>     |

Enclosed herewith a copy each of the supporting documents for your perusal.  
Kindly process the above and remit the payment to us asap

Yours faithfully

  
\_\_\_\_\_  
Modern Automotive Pte Ltd

## Asher Sng (LKKAUTO)

---

**From:** Asher Sng (LKKAUTO)  
**Sent:** Thursday, 19 April 2018 2:56 PM  
**To:** Syed-Yusoff, Saliha  
**Cc:** Vic (LKKAUTO)  
**Subject:** [MANDATE REQUEST] ACCIDENT ON 28/02/2018 INVOLVING SLW 2448R (OI) & SJZ 3731Z (TP)

Your ref : **0556642068SG**  
Our ref : CC6/AIG18003916/Aeb3

Dear Sirs,

### **ACCIDENT ON 28/02/2018 INVOLVING SLW 2448R (OI) & SJZ 3731Z (TP)**

We refer to the above matter.

The said chain collision involved 3 vehicles whereby our insured was the 2nd vehicle.

In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) maybe affected.

We seek your approval to offer repairer " **MODERN AUTOMOTIVE PTE LTD**" at **\$ 12,107.49 (all-in)**.

The summary is as follows: -

|                                    | Amount Claimed      | Amount Revised               |
|------------------------------------|---------------------|------------------------------|
| 1. Cost of Repairs (with GST)      | \$ 19,007.07        | \$ 10,700.00                 |
| 2. Loss of Rental (14days x \$120) | \$ 1,680.00         | \$ 1,400.00 (14days x \$100) |
| 3. LTA Search Fee                  | \$ 7.49             | \$ 7.49                      |
| <b>Total</b>                       | <b>\$ 20,694.56</b> | <b>\$ 12,107.49</b>          |

**For your approval in merimen please.**

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Print Received Message

This mail is associated with :

**\*SJZ3731Z (0556642068SG)  
[SLW2448R]**

TP  
TOH SHI MING DARIUS  
Feb 28 2018 9:00AM  
[TAN WEI NIAN]  
Modern Automotive Pte Ltd

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 04/05/2018 11:00 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$12107.49) - SJZ3731Z - Claim Handler: Syed-Yusoff, Saliha

Approved:12107.49:approved TPPD settlement @ \$12,107.49 [COR- \$10,700 LOR-\$1,400.00]

**Asher Sng (LKKAuto)**

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Friday, 9 March 2018 2:33 PM  
**To:** 'WEI\_NIAN@HOTMAIL.COM'  
**Subject:** ACCIDENT INVOLVING SLW 2448R AND SJZ 3731Z / OTHERS ON 28/02/2018



Auto  
Consultants  
Pte Ltd

---

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG18003916/Aeb3

09 MAR 2018

**TAN WEI NIAN**

Dear Sir/Madam,

**ACCIDENT INVOLVING SLW 2448R AND SJZ 3731Z / OTHERS ON 28/02/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

Asher  
Case Handler  
DID: 6841 6051  
FAX: 6741 4108  
Email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

# LETTER OF AUTHORIZATION

Date: 28/2/18

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

SJZ 37312 & SLW2448R

ON 28/2/18 ALONG KPE towards city

.....  
This letter is to authorize MODERN AUTOMOTIVE PTE LTD at Block 3023A, Ubi Road 1, #01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, MODERN AUTOMOTIVE PTE LTD has my/our authority to decide on my/our behalf whether to accept any offer of settlement from the third party insurers. I/we also agreed that all payments include Loss of Use to make in favour of MODERN AUTOMOTIVE PTE LTD.

MODERN AUTOMOTIVE PTE LTD is also authorized to sign all the required documents include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully



.....  
Signature of Owner

Toh Shi Ming Darius

Name / NRIC S8636112D

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **MODERN AUTOMOTIVE PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$10,700.00** (Repair Cost), **S\$1,400.00** (Loss of Use/Rental), **S\$7.49** (Disbursement) for vehicle no. **SJZ 3731Z** that was damaged pursuant to the accident which occurred on **28/02/2018** (date) along **KPE TOWARDS CITY** (location) involving vehicle no/s **SLW 2448R**.

This is pursuant to the inspection conducted on **01/03/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **TOH SHI MING DARIUS** ("the third party claimant") of vehicle no. **SJZ 3731Z** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SJZ 3731Z** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 11 (day) of MAY (month) 2018 (year)



**LWP**

Signed by appointed surveyor



Signed by "the workshop" (with chop)

# MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01-58 / 61 SINGAPORE 408717  
TEL : 67474422, 67454422 FAX : 67476720  
GST REG. NO : 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY #07-16  
SINGAPORE 079120

Attention : Motor Claim Department  
Contact : 6415-3727 6419-3000

Tax Invoice : TP001165

Date : 21/03/2018  
Vehicle Num. : SJZ 3731Z  
Make/Model : TOYOTA ALTIS-2008  
Chassis/Eng# :  
Accident Date : 28/02/2018  
Claim No. :  
Reference : CC6/AIG18003916/Aeb3  
Policy No. :

| S/N | Quantity | Particular                | Unit Price | Amount S\$ |
|-----|----------|---------------------------|------------|------------|
|     |          | LABOUR :                  |            |            |
|     |          | ACCIDENT REPAIR (LUMPSUM) |            | 10,000.00  |
|     |          | Labour Total S\$ :        |            | 10,000.00  |

|                  |           |
|------------------|-----------|
| Total S\$ :      | 10,000.00 |
| GST @ 7% S\$ :   | 700.00    |
| Amount Due S\$ : | 10,700.00 |
|                  | =====     |

  
MODERN AUTOMOTIVE PTE LTD



## DAWN ENTERPRISES

21 SELETAR WEST FARMWAY 1  
SINGAPORE 798125  
TEL: 6383 2661 FAX: 6484 2836  
REG. NO. 430058/00D

No. 19138

Date, 14/2/18

### OFFICIAL RECEIPT

Received from Darius Tay Shi Ming

the sum of Dollars One thousand six hundred eighty  
only

being Payment Of SRH 4862 C (28/2/18 - 14/3/18)

DAWN ENTERPRISES

\$ 1680/-  
Cash/Cheque No.



# DAWN ENTERPRISES

21 Seletar West Farmway 1  
Singapore 798125  
Tel: 63832661 Fax: 64842836  
Reg No.430058/00D

TP SJZ37312

Nº 34593

## RENTAL AGREEMENT

DATE 28/2/18

### HIRER'S PARTICULARS

Name DARIUS TOH Shi Ming  
Address 524C Pasir Ris St. 51  
#09-603  
5513524  
I/C or Passport No. 86261120 Country \_\_\_\_\_  
Occupation \_\_\_\_\_  
Date of Birth \_\_\_\_\_ Age \_\_\_\_\_  
Driving Licence No. \_\_\_\_\_ Date Passed \_\_\_\_\_  
Tel: (HP) 83225337 (Residence) \_\_\_\_\_

### DRIVER'S PARTICULARS

Name DARIUS TOH  
Address \_\_\_\_\_  
I/C or Passport No. \_\_\_\_\_ Country \_\_\_\_\_  
Occupation \_\_\_\_\_  
Date of Birth \_\_\_\_\_ Age \_\_\_\_\_  
Driving Licence No. \_\_\_\_\_ Date Passed \_\_\_\_\_  
Tel: (Office) \_\_\_\_\_ (Residence) \_\_\_\_\_

### IMPORTANT NOTES:

- No Insurance Coverage if the driver is below 21 years old or less than 2 years driving licence.
- This vehicle is licensed to carry 2000 passengers only.
- Hirer is liable to pay first \$ 2000 as excess on all claims any accident plus loss of earning while damaged vehicle is under repair.
- For usage to Malaysia subject to higher excess all claims of S\$5,000.00 and different rental rate.
- Please notify our office should there be any accident involving this hired vehicle within 24 hrs.
- No refund will be given for vehicle returns early.
- No refund will be given for petrol left in vehicle.
- Hirer is liable to pay all parking fee and traffic summonses.
- Vehicles to be return during office hour only.
- No Service on Public Holiday and Sunday.

### CHARGES

|                                |           |           |
|--------------------------------|-----------|-----------|
| Day at \$120.00                | per days  | \$1680.00 |
| Day at \$                      | per week  |           |
| Day at \$                      | per month |           |
| TOTAL AMOUNT                   |           | \$1680.00 |
| AMOUNT PAID                    |           | \$1680.00 |
| BALANCE DUE                    |           |           |
| Days Extension From            | To        |           |
| Amount Deposit (refundable) \$ |           |           |

### SCHEDULE

SK H4863C

### MODEL

T/A/H

| Date    | Time   | Mileage |
|---------|--------|---------|
| 28/2/18 | 3.30pm |         |
| 14/3/18 |        |         |

FROM

28/2/18

TO

14/3/18

I/we have read and understood the terms and conditions above and hereby agreed to abide

Hirer's Signature

Driver/Gurantor's Signature

DAWN ENTERPRISES

Thank you



Minder Kaur has successfully logged out.  
Your last login date and time was 28 Feb 2018, 14:36:17.  
To return to ONE.MOTORING, please click [here](#)  
For security reasons, please **CLEAR YOUR CACHE** after each session.

SJZ 37312

Session Transaction History

| S/No. | Asset Type | Asset ID | Asset Owner ID | Transaction Type                                  | Transaction Amount(S\$) | Log Date/Time          |
|-------|------------|----------|----------------|---------------------------------------------------|-------------------------|------------------------|
| 1     | Vehicle    | SLW2448R | -              | 18.19 Enquire Veh Owner Info (Others) by Law Firm | 7.49                    | 28 Feb 2018 / 14:38:52 |
| 2     | -          | -        | -              | 20.14 Change Password for VRL User Account        | -                       | 28 Feb 2018 / 14:37:06 |

Enquire Vehicle & Owner Information ( Vehicle No. SLW2448R As At 28 Feb 2018 / 09:00:00 )

Law Firm Search Details

Search Reason:

Insurance claim in relation to traffic accident  
MODERN AUTOMOTIVE

Law Firm Case No.:

Current Owner Details

Owner ID Type:

Singapore NRIC

Owner ID:

S8849279Z

Owner Name:

TAN WEI NIAN

Registered Address Type:

Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.:

7

Registered Street Name:

SENGKANG EAST AVENUE

Registered Unit No.:

# 02 - 24

Registered Building Name:

-

Registered Postal Code:

544741

Current Vehicle Details

Vehicle No.:

SLW2448R

Make Description/Model:

AUDI / A3 SEDAN 1.0 TFSI S TRONIC (LED)

Insurance Company Name:

AIG ASIA PACIFIC INSURANCE PTE. LTD.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

## CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt                                               | Adj Submitted                                   | Ins Auth'ed | Status                                                          |
|------|-----------------------------------------|---------------|---------------------------------------------------|-------------------------------------------------------|-------------------------------------------------|-------------|-----------------------------------------------------------------|
| Main | 28 Feb 2018<br><a href="#">Edit Reg</a> |               | 01 Mar 2018 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$10,000.00</b><br><a href="#">Edit Estimates</a> | <b>S\$10,000.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                                                                                                                               | Reference                                                                                                                                         | Claim Details          | Documents                                                                     | Show All |         |             |              |            |       |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|-------------------------------------------------------------------------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>                                                                                                                            |                                                                                                                                                   |                        |                                                                               |          |         |             |              |            |       |
| Insured:                                                                                                                                                                                                           | <b>TAN WEI NIAN</b> , ID: S8849279Z                                                                                                               |                        |                                                                               |          |         |             |              |            |       |
| Main Claimant:                                                                                                                                                                                                     | <b>TOH SHI MING DARIUS</b> , ID: S8636112D                                                                                                        |                        |                                                                               |          |         |             |              |            |       |
| Vehicle Reg. No.:                                                                                                                                                                                                  | <b>SJZ3731Z</b>                                                                                                                                   | Date of Loss:          | 28/02/2018 09:00 - :59<br>[110 Months and 17 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:                                                                                                                                                                                                        | <b>TP / 0556642068SG</b>                                                                                                                          | Policy/Cover Note No.: | 1800008874                                                                    |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):                                                                                                                                                                                        | <b>SLW2448R</b>                                                                                                                                   | Policy No. (Claimant): | GA062548/1                                                                    |          |         |             |              |            |       |
|                                                                                                                                                                                                                    |                                                                                                                                                   | Excess:                |                                                                               |          |         |             |              |            |       |
| Repairer:                                                                                                                                                                                                          | <b>Modern Automotive Pte Ltd (HQ)</b> Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422                              |                        |                                                                               |          |         |             |              |            |       |
| Handling Insurer:                                                                                                                                                                                                  | <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Syed-Yusoff, Saliha</b> ] Saliha.Syed-Yusoff@aig.com |                        |                                                                               |          |         |             |              |            |       |
| Claimant's Insurer:                                                                                                                                                                                                | <b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288                                                                                                |                        |                                                                               |          |         |             |              |            |       |
| Adjuster:                                                                                                                                                                                                          | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... [Final Rpt due 09/03/2018]                     |                        |                                                                               |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>                                                                                      |                                                                                                                                                   |                        |                                                                               |          |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>AIG_SG_EXPRESS (04/05/2018): Alert - Adj Mandate Approved (S\$12107.49) - SJZ3731Z - Claim Handler: Syed-Yusof...</li> <li>AIG_SG (01/03/2018): No OI GIA Report</li> </ul> |                                                                                                                                                   |                        |                                                                               |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>                                      |                                                                                                                                                   |                        |                                                                               |          |         |             |              |            |       |
| Due Date                                                                                                                                                                                                           | Priority                                                                                                                                          | Type                   | Task Group                                                                    | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                                                                                                        |                                                                                                                                                   |                        |                                                                               |          |         |             |              |            |       |

## Claim Documents

\*SJZ3731Z (0556642068SG)  
[SLW2448R]  
TP  
TOH SHI MING DARIUS  
Feb 28 2018 9:00AM  
[TAN WEI NIAN]  
Modern Automotive Pte Ltd

|                         |                 |  |                                                                            |  |  |                    |  |  |              |  |  |              |  |  |            |          |                                     |                 |  |  |
|-------------------------|-----------------|--|----------------------------------------------------------------------------|--|--|--------------------|--|--|--------------|--|--|--------------|--|--|------------|----------|-------------------------------------|-----------------|--|--|
| Upload Documents        |                 |  | Upload Photos                                                              |  |  | Compose New Letter |  |  | Upload Video |  |  | Upload Audio |  |  | View       |          |                                     | View in Browser |  |  |
| Letters/Correspondences |                 |  |                                                                            |  |  |                    |  |  |              |  |  |              |  |  | 1 per page |          | <input checked="" type="checkbox"/> |                 |  |  |
| No                      | Finalized On    |  | LKK Auto Consultants Pte Ltd (HQ)                                          |  |  |                    |  |  |              |  |  |              |  |  | Thumbnail  |          | Print                               |                 |  |  |
| 1                       | (Draft)         |  | Third Party Express Settlement – Payment Breakdown                         |  |  |                    |  |  |              |  |  |              |  |  | 1          | Edit     |                                     |                 |  |  |
| Assessment Reports      |                 |  |                                                                            |  |  |                    |  |  |              |  |  |              |  |  | 1 per page |          | <input checked="" type="checkbox"/> |                 |  |  |
| No                      | Finalized On    |  | AIG Asia Pacific Insurance Pte. Ltd. (SG)                                  |  |  |                    |  |  |              |  |  |              |  |  | Thumbnail  |          | Print                               |                 |  |  |
| 1                       | 02/03/18 15:07  |  | Accident Statement<br>From: SC – Reg. No: SLW2448R, Claimant: TAN WEI NIAN |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load HTM |                                     |                 |  |  |
| Photos/Images           |                 |  |                                                                            |  |  |                    |  |  |              |  |  |              |  |  | 3 per page |          | <input checked="" type="checkbox"/> |                 |  |  |
| No                      | Relabel/Reorder |  | LKK Auto Consultants Pte Ltd (HQ)                                          |  |  |                    |  |  |              |  |  |              |  |  | Thumbnail  |          | Print                               |                 |  |  |
| 1                       | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 2                       | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 3                       | 20/03/18 19:29  |  | Chassis Number                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 4                       | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 5                       | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 6                       | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 7                       | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 8                       | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 9                       | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 10                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 11                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 12                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 13                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 14                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 15                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 16                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 17                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 18                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 19                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 20                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 21                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 22                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 23                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 24                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 25                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 26                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 27                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 28                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 29                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |
| 30                      | 20/03/18 19:29  |  | General View                                                               |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG | <input checked="" type="checkbox"/> |                 |  |  |

| Letters/Correspondences |                |                                   | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|-------------------------|----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                      | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 31                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 32                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 33                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 34                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 35                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 36                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 37                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 38                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 39                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 40                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 41                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 42                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 43                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 44                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 45                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 46                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 47                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 48                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 49                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 50                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 51                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 52                      | 20/03/18 19:29 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 53                      | 20/03/18 19:29 | General View                      |  Load JPG  | <input checked="" type="checkbox"/> |
| 54                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 55                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 56                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 57                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 58                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 59                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 60                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 61                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 62                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 63                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 64                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 65                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 66                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 67                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 68                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 69                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 70                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 71                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 72                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 73                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 74                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 75                      | 20/03/18 19:29 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 76                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 77                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 78                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 79                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 80                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |

| Letters/Correspondences |                |                                   | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|-------------------------|----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                      | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 81                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 82                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 83                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 84                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 85                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 86                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 87                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 88                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 89                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 90                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 91                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 92                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 93                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 94                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 95                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 96                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 97                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 98                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 99                      | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 100                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 101                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 102                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG  | <input checked="" type="checkbox"/> |
| 103                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 104                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 105                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 106                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 107                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 108                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 109                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 110                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 111                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 112                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 113                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 114                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 115                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 116                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 117                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 118                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 119                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 120                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 121                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 122                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 123                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 124                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 125                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 126                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 127                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 128                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 129                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 130                     | 20/03/18 19:30 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |

| Letters/Correspondences |                 |                                   | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|-------------------------|-----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                      | Finalized On    | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 131                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 132                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 133                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 134                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 135                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 136                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 137                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 138                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 139                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 140                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 141                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 142                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 143                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 144                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 145                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 146                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 147                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 148                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 149                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 150                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 151                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 152                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG  | <input checked="" type="checkbox"/> |
| 153                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 154                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 155                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 156                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 157                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 158                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 159                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 160                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 161                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 162                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 163                     | 20/03/18 19:30  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation           |                 |                                   | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
| No                      | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 1                       | 28/02/18 17:38  | TP GIA REPORT                     |  Load PDF |                                     |
| 2                       | 02/03/18 10:32  | Non reporting letter              |  Load PDF |                                     |
| 3                       | 09/03/18 14:39  | LETTER TO OI                      |  Load PDF |                                     |
| 4                       | 16/04/18 12:46  | LTA SEARCH                        |  Load PDF |                                     |
| 5                       | 16/04/18 12:46  | RENTAL RECEIPT                    |  Load PDF |                                     |
| 6                       | 22/05/18 10:04  | WORKSHOP INVOICE                  |  Load PDF |                                     |
| 7                       | 22/05/18 10:04  | AUTHORISATION TO ACT FORM         |  Load PDF |                                     |
| 8                       | 22/05/18 10:04  | Release Voucher                   |  Load PDF |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                          | Reset | Save | Print |
|----------------------------------------------|-------|------|-------|
| There are no document checklists configured. |       |      |       |

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

|                   |                     |        |                      |
|-------------------|---------------------|--------|----------------------|
| Vehicle No:       | SLW2448R (Insd veh) | Model: | TOYOTA COROLLA ALTIS |
|                   | SJZ3731Z (TP veh)   |        | 1.6 (A)              |
| Date of Accident: | 28/02/2018          |        |                      |

|                       |      |                              |                                        |      |
|-----------------------|------|------------------------------|----------------------------------------|------|
| Global Sum Settlement | :    | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |      |
| Repair Estimate       | : \$ | 19,007.07                    |                                        |      |
| Final Repair Cost     | : \$ | 10,700.00                    |                                        |      |
| Loss of Use           | : \$ | days at \$0.00 per day       |                                        |      |
| Rental (if any)       | : \$ | 1,400.00                     | 14                                     | days |
| LTA / GIA Search Fee  | : \$ | 7.49                         |                                        |      |
| Others:               | : \$ | 0.00                         |                                        |      |
|                       | : \$ |                              |                                        |      |
| Final Settlement Sum  | : \$ | 12,107.49                    |                                        |      |

**Is Third Party Workshop GIA Registered?**    ☐ YES    ☒ NO    (Kindly indicate below)

**A) For Non GIA Registered Workshop:**    Agreed Liability \_\_\_\_\_ 100 \_\_\_\_\_ (%)

**B) For GIA Registered Workshop:**    BOLA Applicable: Yes/ No    BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%)    Assessed Liability (\*): \_\_\_\_\_ 0 \_\_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

| Payment Instruction: Payee's Breakdown |                           |      |           |
|----------------------------------------|---------------------------|------|-----------|
| 1)                                     | Modern Automotive Pte Ltd | : \$ | 12,107.49 |
| 2)                                     |                           | : \$ |           |
| 3)                                     |                           | : \$ |           |
| 4)                                     |                           | : \$ |           |

JOANNE LEE KHANG MIN

22 May  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18003916/AEB3Q2

Date: 22/05/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800008874  
**Claimant Vehicle No :** SJZ3731Z **Insured Vehicle No :** SLW2448R  
 Date of Loss: 28/02/2018 Nature of Claim: TP Claim No: 0556642068SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJZ3731Z**  
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4848648  
 Reg. Date: 11/12/2008 (Man. Year: 2008) Chassis No: MR053ZEE106134307  
 Colour: Blue Odometer: 158745 km  
 Engine Capacity: 1598 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm  
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                                   | Repairer's       | Adjuster's       | Difference      | Diff %       |
|--------------------------------------------------|------------------|------------------|-----------------|--------------|
| Parts                                            | 12,583.62        | 8,830.35         | 3,753.27        | 29.83        |
| Miscellaneous Items                              | 0.00             | 0.00             | 0.00            |              |
| Labour                                           | 5,180.00         | 3,680.00         | 1,500.00        | 28.96        |
| Paintwork Labour                                 | 0.00             | 0.00             | 0.00            |              |
| Towing                                           | 0.00             | 0.00             | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>              | <b>17,763.62</b> | <b>12,510.35</b> | <b>5,253.27</b> | <b>29.57</b> |
| <b>Approved Total (Overridden) (S\$)</b>         |                  | <b>10,000.00</b> |                 |              |
| (S\$)                                            | 17,763.62        | 10,000.00        | 7,763.62        | 43.71        |
| <b>+ GST 7.00/7.00% (S\$)</b>                    | <b>1,243.45</b>  | <b>700.00</b>    | <b>543.45</b>   | <b>43.71</b> |
| <b>Nett Amount (S\$)</b>                         | <b>19,007.07</b> | <b>10,700.00</b> | <b>8,307.07</b> | <b>43.71</b> |
| <b>+ Car Rental (14.0 x S\$100.00/day) (S\$)</b> |                  | <b>1,400.00</b>  |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                    |                  | <b>7.49</b>      |                 |              |
| <b>Nett Liability (S\$)</b>                      |                  | <b>12,107.49</b> |                 |              |

### INSPECTION

Date of Assignment: 01/03/2018  
 Date Inspected: 01/03/2018 Inspected At: Modern Automotive Pte Ltd (HQ)  
 Blk 3023A Ubi Road 1, #01-61 & #01-58  
 Singapore 408717

Estimated Period of Repair: 12.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                             | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                           | Distorted     | 439.20 FL   | *439.20 FL   |
| 2   | 1   |          | *SET FRONT BUMPER CLIPS                 | Necessary     | 30.00 FL    | *30.00 FL    |
| 3   | 2   |          | *FRONT BUMPER SIDE HOLDER               | Necessary     | 121.40 FL   | *121.40 FL   |
| 4   | 1   |          | *FRONT BUMPER REINFORCEMENT             | Bent          | 339.70 FL   | *339.70 FL   |
| 5   | 1   |          | *FRONT BUMPER NOZZLE                    | Necessary     | 32.80 FL    | *32.80 FL    |
| 6   | 1   |          | *FRONT BUMPER GRILLE (UPPER)            | Cracked       | 298.80 FL   | *298.80 FL   |
| 7   | 1   |          | *FRONT BUMPER GRILLE (LOWER)            | Deformed      | 106.50 FL   | *106.50 FL   |
| 8   | 1   |          | *FRONT BUMPER UNDERCOVER                | Torn          | 262.20 FL   | *262.20 FL   |
| 9   | 1   |          | *SET FRONT BUMPER UNDERCOVER CLIPS      | Necessary     | 30.00 FL    | *30.00 FL    |
| 10  | 2   |          | *HEADLAMP                               | Cracked       | 982.20 FL   | *982.20 FL   |
| 11  | 1   |          | *FRONT BRACE PANEL                      | Bent          | 113.10 FL   | *113.10 FL   |
| 12  | 1   |          | *FRONT SUPPORT PANEL                    | Buckled       | 699.90 FL   | *699.90 FL   |
| 13  | 1   |          | *BONNET                                 | Repair        | 942.20 FL   | *- FL        |
| 14  | 1   |          | *BONNET LOCK                            | Not Necessary | 128.60 FL   | *- FL        |
| 15  | 1   |          | *AIR CON CONDENSER                      | Dented        | 1,299.40 FL | *1,299.40 FL |
| 16  | 1   |          | *RADIATOR                               | Dented        | 1,681.90 FL | *1,681.90 FL |
| 17  | 1   |          | *RADIATOR TOP COVER                     | Not Necessary | 193.40 FL   | *- FL        |
| 18  | 1   |          | *RADIATOR FAN COWLING                   | Not Necessary | 223.40 FL   | *- FL        |
| 19  | 1   |          | *RADIATOR FAN BLADE                     | Not Necessary | 96.10 FL    | *- FL        |
| 20  | 1   |          | *RADIATOR FAN MOTOR                     | Not Necessary | 248.70 FL   | *- FL        |
| 21  | 1   |          | *AIR CON SUCTION PIPE                   | Not Necessary | 341.60 FL   | *- FL        |
| 22  | 1   |          | *AIR CON DISCHARGE PIPE                 | Not Necessary | 395.80 FL   | *- FL        |
| 23  | 1   |          | *REAR BUMPER                            | Deformed      | 476.20 FL   | *476.20 FL   |
| 24  | 1   |          | *SET REAR BUMPER CLIPS                  | Necessary     | 30.00 FL    | *30.00 FL    |
| 25  | 2   |          | *REAR BUMPER SIDE HOLDER                | Necessary     | 114.00 FL   | *114.00 FL   |
| 26  | 2   |          | *REAR BUMPER REFLECTOR                  | Not Necessary | 138.40 FL   | *- FL        |
| 27  | 1   |          | *REAR BUMPER SPONGE                     | Cracked       | 80.90 FL    | *80.90 FL    |
| 28  | 1   |          | *REAR BUMPER REINFORCEMENT ROD          | Bent          | 152.60 FL   | *152.60 FL   |
| 29  | 2   |          | *REAR BUMPER IMPACT BRACKET             | Dented        | 171.20 FL   | *171.20 FL   |
| 30  | 2   |          | *TAILLAMP                               | Cut           | 684.00 FL   | *684.00 FL   |
| 31  | 1   |          | *REAR END PANEL                         | Dented        | 532.80 FL   | *532.80 FL   |
| 32  | 1   |          | *REAR END PANEL TOP GARNISH             | Deformed      | 192.70 FL   | *192.70 FL   |
| 33  | 1   |          | *BOOTLID                                | Buckled       | 680.00 FL   | *680.00 FL   |
| 34  | 1   |          | *BOOTLID LOCK                           | Damaged       | 121.50 FL   | *121.50 FL   |
| 35  | 1   |          | *BOOTLID WEATHERSTIPE                   | Cut           | 185.50 FL   | *185.50 FL   |
| 36  | 2   |          | *BOOTLID HINGE                          | Not Necessary | 144.00 FL   | *- FL        |
| 37  | 2   |          | *BOOTLID REFLECTOR                      | Not Necessary | 321.40 FL   | *- FL        |
| 38  | 1   |          | *BOOTLID INNER TRIM                     | Not Necessary | 172.10 FL   | *- FL        |
| 39  | 1   |          | *SET BOOTLID INNER TRIM CLIPS           | Necessary     | 30.00 FL    | *30.00 FL    |
| 40  | 1   |          | *TOYOTA LOGO                            | Necessary     | 52.00 FL    | *52.00 FL    |
| 41  | 1   |          | *1.6 EMBLEM                             | Necessary     | 46.00 FL    | *46.00 FL    |
| 42  | 1   |          | *COROLLA WORDING                        | Necessary     | 48.00 FL    | *48.00 FL    |
| 43  | 1   |          | *ALTIS WORDING                          | Necessary     | 48.00 FL    | *48.00 FL    |
| 44  | 1   |          | *SPARE TYRE PANEL                       | Repair        | 752.60 FL   | *- FL        |
| 45  | 1   |          | *SPARE TYRE PANEL TOP BOARD             | Torn          | 359.20 FL   | *359.20 FL   |
| 46  | 2   |          | *REAR FENDER INNER TRIM BOARD           | Not Necessary | 677.40 FL   | *- FL        |
| 47  | 1   |          | *SET REAR FENDER INNER TRIM BOARD CLIPS | Necessary     | 60.00 FL    | *60.00 FL    |
| 48  | 1   |          | *REAR EXHAUST PIPE                      | Bent          | 792.10 FL   | *792.10 FL   |
| 49  | 1   |          | *REAR EXHAUST MOUNTING                  | Not Necessary | 42.00 FL    | *- FL        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                | Condition     | Repairer's | Amount     |
|-----|-----|----------|----------------------------|---------------|------------|------------|
| 50  | 1   |          | *FRONT NUMBER PLATE        | Cracked       | 30.00 FS   | *30.00 FS  |
| 51  | 1   |          | *FRONT NUMBER PLATE HOLDER | Cracked       | 30.00 FS   | *30.00 FS  |
| 52  | 1   |          | *REAR NUMBER PLATE         | Not Necessary | 30.00 FS   | *- FS      |
| 53  | 1   |          | *REAR NUMBER PLATE HOLDER  | Not Necessary | 30.00 FS   | *- FS      |
| 54  | 1   |          | *REVERSE SENSOR            | Damaged       | 280.00 FS  | *200.00 FS |
| 55  | 1   |          | *TAILLAMP SPONGE GASKET    | Necessary     | 40.00 FS   | *40.00 FS  |
| 56  | 1   |          | *REAR END PANEL SEALANT    | Necessary     | 60.00 FS   | *60.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                  |
|------------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$\$)</b>                                    | <b>16,611.50</b> | <b>11,653.80</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | <b>4,027.88</b>  | <b>2,823.45</b>  |
| <b>Total Parts (\$\$)</b>                                  | <b>12,583.62</b> | <b>8,830.35</b>  |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                                                     | Lab.Type | Repairer's      | Amount          |
|-------------------------|-----------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>     |                                                                 |          |                 |                 |
| 1                       | TO KNOCKING & PULL OUT FRONT & REAR PORTION & RENEW ABOVE PARTS | New      | 2,400.00        | 1,600.00        |
| 2                       | TO PUTTY & SPRAT UP PAINT WORKS                                 | New      | 1,800.00        | 1,600.00        |
| 3                       | TO CHECK WIRING                                                 | New      | 100.00          | 60.00           |
| 4                       | TO REMOVE CONDENSER ,RADIATOR & TO RE-GAS                       | New      | 180.00          | 120.00          |
| 5                       | TO REMOVE REVERSE SENSOR                                        | New      | 100.00          | 50.00           |
| 6                       | TO REMOVE UPHOLSTERY                                            | New      | 150.00          | 60.00           |
| 7                       | TO UNDERSEAL                                                    | New      | 150.00          | 60.00           |
| 8                       | TO REMOVE EXHAUST PIPE                                          | New      | 150.00          | 80.00           |
| 9                       | TO TRANSFER BOOTLID FITTINGS                                    | New      | 150.00          | 50.00           |
| Gross Labour Cost (S\$) |                                                                 |          | <b>5,180.00</b> | <b>3,680.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >