

ASS. REC. BY:

REF:

CS/MSG18003918 / 84 bed

Special Instruction:

Surveyor

Meehan

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSLH

Date/Time:

27/02/2018 8:45am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SVJ 1302

Insured:

S 8662TE

at Workshop m/s

Performanc

Tel:

6319 0174

of

303 Alexandra Rd

Policy No:

A388 35919TMP

Claim No:

550671

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/02/2018

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time:

28-02-2018 11:49am

Person Contacted:

Caroline

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SVJ 1302 - X

S 8662TE - X

12/04/18

@ 15:02 p.m. revised to Irene Tan Gek Ing via meehan.

labour - 1974/- (Red: 2667.45; 57%)

confirm with caroline.

ASSIGNMENT

From: _____ Date: **10/04/2018**
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SJV 130Z**
 at Workshop m/s: **Performance**
 of: **303 Alexander Rd**
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: **Merina**
 (Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: **Yes** or No
 GIA / PR Seen: _____ Consistent?: **Yes** or No
 Est. Repairs: _____ days Res.: **Yes** or No
 Lum Sum: _____ % 3 Val.: **Yes** or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: **IN / OUT**

N/S	O/S

Veh No: **SJV 130Z** Yr Regn: **15/12/2017**
 Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or**
 Make: **Bmw 116D** c.c. **1496**
 Colour: **Grey** A/C: **Insured / Std / NI / NA**
 Sp. Reading: **4586** T/Radio: **Insured / Std / NI / NA**
 Eng/No: _____
 C/No: **W341V720805G87226**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or
 Brake: **In order** / Jammed / Leaked / Burnt or
 Modi: **Nil** / S/Rim / STD A/Rim or
 Tyre Size: F: **205/55R16**
 R: **"**
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or **Pirelli**

Front	Rear
R/Bal. 7 mm	R/Bal. 7 mm
L/Bal. 7 mm	L/Bal. 7 mm
D.O.A. 25/2/18	D.O.I. 10/4/18

 Survey held at **Performance motor**
 Des. of Damages: **Frnt N/S** / Rear / O/S / N/S / UIC / Rooftop or
 The **UIC / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
<p>RECEIVED 23 AUG 2018</p> <p style="text-align: right;"> 23/8/2018 </p>	

Date/Time. File Pass to? : Preli. Report
 1) **23/8 Typist** : Final Report
 Date/Time. File Return to?
 2) _____

Days Of Repair: **3**
 Resurvey No. of Trip: _____

Report Format: **TP**
 Lump Sum / I.B.I. (\$) **1974**

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee: **200**
 Transportation: _____
 Photos: _____
 Others: **10**
 TOTAL: **210**

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Feb 2018		27 Feb 2018 08:45 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	NGUYEN HOANG HAI, ID: G1467438T		
Main Claimant:	MELANIE MEI LAN NG, ID: S7281208E		
Vehicle Reg. No.:	SJV130Z	Date of Loss:	25/02/2018 13:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	28835919TMP (Third Party Only) Coverage: 07/10/2016 - 06/04/2018
Vehicle Reg. No. (Insured):	S8662TE	Policy No. (Claimant):	
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/02/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

9.15am
xms

280218@ 11.49am

Caroline veh not in

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 12 Apr 2018

Preliminary Advice

Insured Vehicle No	: S8662TE	Accident Date	: 25/02/2018
TP Vehicle No	: SJV130Z	Assignment Date	: 27/02/2018
Make	: BMW 116I	Est. Duration of Repair	: 3 days
Date of Inspection	: 10/04/2018		
Inspection At	: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,641.45
Revised Amount	:S\$	1,934.00
Check Items (Estimated)	:S\$	80.00
Total	:S\$	2,014.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/02/2018 13:27
Date Of Accident	25/02/2018 13:55
Exact Location Of Accident	CARPARK IN THE CLEMANTI MALL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV130Z
Insured/Policyholder	
Name Of Registered Owner	MELANIE MEI LAN NG
NRIC No	S7281208E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97299205
Alternative Phone No	OFFICE-65012424

Vehicle Particulars

Manufacturer	BMW
Model	116D
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	NOATAVAIL
Cover Note Number	

Driver

Name of Driver	MELANIE MEI LAN NG
NRIC No	S7281208E
Date Of Birth	01/03/1972
Occupation	INDOOR
Date Of Driving Pass	11/11/2000
Driving Experience	17 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97299205
Fax Number	
Contact Number	OFFICE-65012424
EMail Address	NOEMAIL

Address	44 TAMAN WARNA
Postcode	276376
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	S8662TE
Vehicle Make/Model/Colour	LEXUS WHITE ES300
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NGUYEN HOANG HAI
NRIC/Passport Number	G1467438T
Contact Number	
Address	EMBASSY OF THE SOCIALIST REPUBLIC OF VIETNAM
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


26 FEB 2010

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

26 FEB 2010

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was parked in a car park lot in Clementi mall. As I finished my shopping with my daughters and went to the car park at about 1:53 pm, I saw the other vehicle S8662TE diagonally across the car park road and hit my front bumper on the left. His car S8662TE hit the front of my stationary parked car.

He informed me that his car lost control and hit my car.

A man in the car park tried to push the car (S8662TE) and it further slide into my car due to the slope.

I had to reverse my car further in the car lot to avoid further damage.


His car cannot be moved and they needed to get road side assistance to remove the car.

Meanwhile his car blocks the road in the car park. The mall security had to block and direct traffic.

All this was also captured in the mall CCTV.

DECLARATION

I/We declare the foregoing particulars are true in every respect.




Policyholder's Signature

Date & Time:
26 FEB 2010

Driver's Signature
(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

26 FEB 2010

Performance Motors Limited


A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SJR (Low)
3/4 10am
10/4 10am



GST REG. NO : M2 - 0020081 - X

ESTIMATE

26 FEB 2018

Estimate No. : **b1 46042** Page No. : 1 of 2
Date Estimated : **26/02/2018**
Prepared By : **Merina Chia San San**

- ESTIMATE REPAIR FOR -

Melanie Mei Lan Ng
44 Taman Warna

Singapore 276376

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJV130Z	5G87226	15/12/2017	116d	0

DESCRIPTION

To replace front bumper including attachments etc and to knock out dented area caused by accident

850 1,790.00

To paint front bumper

934 1,038.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

Sundries.

40? 80.00

Total Labour 1: **2,995.00**

DESCRIPTION

CLAMP *x nn*
FRT BUMPER TOP MOUNT *x nn*
LH CLOSED GRID (BASIS) *x nn*
IMPACT ABSORNER TOP *x gan*
FRT BUMPER LH INSERT *x gan*
FRT BUMPER RH INSERT *x gan*
FRT BUMPER PANEL PRIMED *R*
SET PDC HOLDER FRONT *x*
EMBLEM GROMMET *x*
FRT BUMPER LOWER MOUNT *x*
PLAQUE 82MM *x*
DECOUPLING RING PDC TORQUE CONVERTE *x*
(DG) ADHESIVE SET K6 *x*

QTY	PRIC	VALUE
1	3.20	3.20
1	361.65	361.65
1	93.20	93.20
1	42.45	42.45
1	32.15	32.15
1	32.15	32.15
1	786.20	786.20
1	23.10	23.10
2	0.80	1.60
1	128.00	128.00
1	69.50	69.50
4	5.05	20.20
1	53.05	53.05

Total Parts : **1,646.45**



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46042
Date Estimated : 26/02/2018
Prepared By : Merina Chia San San

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJV130Z	5G87226	15/12/2017	116d	0

3 days.

Sebastian.
10/4/18

- Part by part repair.
- Photo After Paint
90036121

sebastianyeang@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4621.05

Labour 1	:	2,995.00
Parts	:	1,646.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	324.90
Grand Total	:	<u>4,966.35</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46042
Date Estimated : 26/02/2018
Prepared By : Merina Chia San San

Page No. :

REPAIR FOR -
Melanie Mei Lan Ng
44 Taman Warna

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 276376

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE		
SJV130Z	5G87226	15/12/2017	116d	0		
DESCRIPTION					ORIGINAL PRICE	DISC. % NETT
To make good the front bumper include removing attachments to facilitate repairs and knocking out dents caused by the accident					850.00	850.00
To spray paint front bumper					934.00	934.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.					150.00	150.00
Sundries.					40.00	40.00
DESCRIPTION					UNIT PRICE	QTY DISC. % NETT

SUPPLEMENTARY ITEMS

Total Labour :	1,974.00
Total Parts :	
Total Labour & Parts :	1,974.00
Deduction for Excess :	
Total Repair Costs less Excess:	1,974.00
GST @7%:	138.18
Grand Total :	2,112.18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Feb 2018		27 Feb 2018 08:45 Edit Adj Rpt	S\$1,974.00 Edit Estimates	S\$1,974.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	NGUYEN HOANG HAI , ID: G1467438T								
Main Claimant:	MELANIE MEI LAN NG , ID: S7281208E								
Vehicle Reg. No.:	SJV130Z	Date of Loss:	25/02/2018 13:00 - :59 [2 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 550671	Policy/Cover Note No.:	A28835919TMP (Third Party Only) Coverage: 07/10/2016 - 06/04/2018						
Vehicle Reg. No. (Insured):	S8662TE	Policy No. (Claimant):							
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 29/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/> View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJV130Z (550671)**
[S8662TE]
TP
MELANIE MEI LAN NG
Feb 25 2018 1:00PM
[NGUYEN HOANG HAI]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/04/18 15:02	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
2	28/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
3	28/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
4	28/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
5	28/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
6	28/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
7	28/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
8	28/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
9	28/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
10	28/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
11	28/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
12	28/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
13	28/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
14	28/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
15	28/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
16	28/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/02/18 08:45	TP estimate	Load PDF	<input type="checkbox"/>
2	27/02/18 08:45	OI GIA REPORT.	Load PDF	<input type="checkbox"/>
3	27/02/18 08:45	TP GIA REPORT	Load PDF	<input type="checkbox"/>
4	27/02/18 08:45	Email from TP agree SJE	Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003918/STBE2
Date: 24/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28835919TMP
Claimant Vehicle No : SJV130Z	Insured Vehicle No :	S8662TE
Date of Loss: 25/02/2018	Nature of Claim:	TP
		Claim No: 550671

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV130Z		
Make & Model:	BMW 116i, 1.6 ABS D/AIRBAG 2WD 5DR HID DSC (A)	Engine No:	34565093B37D15A
Reg. Date:	15/12/2017 (Man. Year: 2017)	Chassis No:	WBA1V720805G87226
Colour:	Grey	Odometer:	4586 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,726.45	40.00	1,686.45	97.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,915.00	1,934.00	981.00	33.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,641.45	1,974.00	2,667.45	57.47
+ GST 7.00/7.00% (S\$)	324.90	138.18	186.72	57.47
Nett Amount (S\$)	4,966.35	2,112.18	2,854.17	57.47

INSPECTION

Date of Assignment:	27/02/2018	
Date Inspected:	10/04/2018	Inspected At: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	3.0 days	

Adjuster: Muhammad Nazril Bin Abdullah

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2018)
Parts: 144	BMW 116I 1.6 ABS D/AIRBAG 2WD 5DR HID DSC (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV130Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*40.00 FS
2	1		*CLAMP	Not Necessary	3.20 FS	*- FS
3	1		*FRT BUMPER TOP MOUNT	Not Necessary	361.65 FS	*- FS
4	1		*LH CLOSED GRID (BASIS)	Not Necessary	93.20 FS	*- FS
5	1		*IMPACT ABSORBER TOP	Not Necessary	42.45 FS	*- FS
6	1		*FRT BUMPER LH INSERT	Not Necessary	32.15 FS	*- FS
7	1		*FRT BUMPER RH INSERT	Not Necessary	32.15 FS	*- FS
8	1		*FRT BUMPER PANEL PRIMED	Repair	786.20 FS	*- FS
9	1		*SET PDC HOLDER FRONT	Not Necessary	23.10 FS	*- FS
10	2		*EMBLEM GROMMET	Not Necessary	1.60 FS	*- FS
11	1		*FRT BUMPER LOWER MOUNT	Not Necessary	128.00 FS	*- FS
12	1		*PLAQUE 82MM	Not Necessary	69.50 FS	*- FS
13	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.20 FS	*- FS
14	1		*(DG) ADHESIVE SET K6	Not Necessary	53.05 FS	*- FS
Total Parts (\$\$)					1,726.45	40.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER INCLUDING ATTACHMENTS ETC AND TO KNOCK OUT DENTED AREA CAUSED BY ACCIDENT	New	1,700.00	850.00
2	TO PAINT FRONT BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
			Gross Labour Cost (\$\$)	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >