

22/03/2012

PR2

ASS. REC. BY:

REF:

CS3 AXA 16005512

GAB

Special Instruction:

Survivor:

Guo Rong

ASSIGNMENT (Office)

From (Person):

Tan Wan Cong

of

AXA

Date/Time: 26-02-2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YM 6966R

Insured:

SKA 61036

at Workshop m/s

Twinkl Automotive

Tel:

84820051

of

Blk 2 Kaki Bukit Ave 2 # 01-17/18

Policy No:

GA 053644

Claim No:

C0376814

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10/5/2016

CA / REV / REP. / REV 24 HRS

rev

2/5/2016 @ 10am (owner waiting)

2/4/2016 @ after 10am

H.O.D. Endorsement:

Date/Time: 2/3/2016

Person Contacted:

MASON

Vehicle IN / OUT

Date/Time

Action/Instruction (*) Estimate


YM 6966R - *

SKA 61036 - KA / JNC / 15005275 / F

DIA 11/5/2016

2/4/2016 4:27pm

Send email to Flossie Ang

 6/3/2018

\$5250 . 5 Days.
(Red \$6150, 5420)

URGENT

RECEIVED 07 MAR 2018

Survey Department Check List (Case Handler)

Reference No. : *C33/AXA/602552-696-1*

Policy Type: OD / *TP* / TP RES / TL / EVA

Case Handler

Typist

Admin (*Cathy*): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	<input checked="" type="checkbox"/>			
C Customer Code	<input checked="" type="checkbox"/>			
N Assign From	<input checked="" type="checkbox"/>			
C Assign Date	<input checked="" type="checkbox"/>			
C Veh No (Inspected)	<input checked="" type="checkbox"/>			
C Veh No (Insured)	<input checked="" type="checkbox"/>			
C D.O.A	<input checked="" type="checkbox"/>			
C Policy No	<input checked="" type="checkbox"/>			
C Claim No	<input checked="" type="checkbox"/>			
C Insurance Authorisation (CA /REV/REP)	<input checked="" type="checkbox"/>			
C Report Type	<input checked="" type="checkbox"/>			
C Weekend Charges	<input checked="" type="checkbox"/>			
N Survey held at/Repairer	<input checked="" type="checkbox"/>			
C Excess				

Surveyor (*Guo Qiang*): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C Vehicle No				
C Regn Month/Year				
N Vehicle Type				
N Make & Model				
C Engine Capacity. (C.C)				
N Colour				
C Odometer. (Sp.Reading)				
C Chassis No				
N General Condition				
N Steering				
N Brake				
N Modification (Modi)				
C Tyre Size				
N Tyre Make				
C Tyre Balance				
C Date of Inspection				
N Survey held				
N Des.of Damages				

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded				
--	--	--	--	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition	<input checked="" type="checkbox"/>			
C Market Value for OD cases				
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)	<input checked="" type="checkbox"/>			
C Days of repair				
C Finalised Amount				
C Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C Resurvey photo Uploaded				
---------------------------	--	--	--	--

Check By: *[Signature]*

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS3/AXA16005512/Gqb-1

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 28-02-2018



Code : AXA2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKA 6103L	Veh. Inspected	YM 5966R
Policy No.		Coverage (\$)	0.00
Claim No.	C0376814	Excess (\$)	0.00
Assign From	MERIMEN (TAN WANCONG)	Assign Date	26/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/03/2016	Inspection Date	28/02/2018
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(Pending for Payment)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Mar 2016		24 Mar 2016 16:35		15 Apr 2016 11:24 S\$0.00 (S\$107.00)		Pending for Payment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ZAMAKHAIR BIN BUJANG, ID: S7910773E, Tel: +6590612079, Email: DSASSMGT@GMAIL.COM		
Main Claimant:	MAJESTIC MACHINERY MOVER PTE LTD		
Vehicle Reg. No.:	YM5966R	Date of Loss:	10/03/2016 13:00 - :59
Claim Type:	TP / C0375644	Policy/Cover Note No.:	GA053844 (Comprehensive)
Vehicle Reg. No. (Insured):	SKA6103L	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Tan Wancong - 68804832]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 05/04/2016]		
Driver/Custodian (Insured):	ZAMAKHAIR BIN BUJANG (36), NRIC: S7910773E, Tel: +6590612079		
Insurer's Solicitor:	SEAH ONG & PARTNERS LLP (HQ) - Tel: 65365369 ... Incoming Assignment		

ASSOCIATED MAIL RECEIVED

View All | Compose Case Mail

- AXA_SG (26/02/2018): Please conduct Paper survey urgently
- AXA_SG (01/06/2016): C0375644 - PLEASE TAKE NOTE ON CHANGE OF CLAIM NUMBER.
- AXA_SG (24/03/2016): New TP Assignment - C0376814/GA053844

ALL ASSOCIATED TASKS

View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths

Agents for Trade Marks

(Incorporated with limited liability)

Unique Entity Number: 200721148H

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI D'O MUNIANDY
SEGA PARAM
TIWARY ANURADHA
ONG BOCK KEE
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
TAN YINGXIAN SELWYN

✓Head Office:
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Branch:
490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490
Branch:
133 New Bridge Road
#10-03 Chinatown Point
Singapore 059413

HEAD OFFICE:

TEL : (65) 65342811 (Hunting)
FAX : (65) 65356802 (General)

E-MAIL: annatan@visionlawllc.com

61093245

BRANCH

TEL : (65) 63580703
TEL : (65) 65330868

BRANCH

TEL : (65) 65342811 (Hunting)
TEL : (65) 65330869

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to HEAD OFFICE for this

Our Ref : AKN-atv-Ins-T140-103266-17

Your Ref : SKA 6103 L

Date: 13 July 2017

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Attn: Motor Claims Department

ZAMAKHAIR BIN BUANG

Apt Blk 561 Choa Chu Kang North
#02-98
Singapore 680561

WITHOUT PREJUDICE
BY HAND

CERTIFICATE OF POSTING
[For your information only]

Dear Sir,

CLAIMANT : MAJESTIC MACHINERY MOVER PTE LTD

ACCIDENT INVOLVING YM 5966 R & SKA 6103 L ON 10-MAR-2016 AT JUNCTION OF LOYANG AVENUE AND NEW LOYANG LINK AT ABOUT 1335HOURS

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on 10-MAR-2016 AT JUNCTION OF LOYANG AVENUE AND NEW LOYANG LINK AT ABOUT 1335HOURS involving our client's vehicle registration number YM 5966 R and vehicle registration number SKA 6103 L driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

01.	Cost of Repair	\$12,198.00
02.	Loss of Use for 7 days at \$300.00 per day	\$ 2,100.00
03.	Additional 2 days loss of use for pre repair	\$ 600.00
04.	Survey report fees	\$ 896.00
05.	Towing fees	\$ 100.00
06.	GIA & LTA search / report fees	\$ 42.35
07.	Cost Contribution (at this stage)	\$ 2,675.00
08.	Disbursements (at this stage)	\$ 50.00

TOTAL \$18,661.35

.../2 to be continued next page

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.



VISION LAW LLC

Advocates & Solicitors

Page 2

Our Ref : AKN-atv-Ins-T140-103266-17
Your Ref : SKA 6103 L

Date: 13 July 2017

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Department

ZAMAKHAIR BIN BUJANG

Apt Blk 561 Choa Chu Kang North 6

#02-98

Singapore 680561

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA report lodged by driver of YM 5966 R;
 - (b) LTANet Search;
 - (c) Certificate of Insurance;
 - (d) Registration Card;
 - (e) Towing receipt;
 - (f) Final Repair Bill;
 - (g) Surveyor's report & invoice; and
 - (h) **72 coloured photographs** depicting the damages to motor vehicle YM 5966 R.
- (P.S:- Original photographs will be sent to insurance co. only)

The demand herein is in respect of our client's claim for damages pertaining to his motor vehicle and any settlement following or subsequent to this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully



(HEAD OFFICE)

Enc. (By PDX Only)

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/03/2016 16:35
Date Of Accident	10/03/2016 13:35
Exact Location Of Accident	LOYANG AVE / NEW LOYANG LINK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YM5966R
Insured/Policyholder	
Name Of Registered Owner	MAJESTIC MACHINERY MOVER PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-NOPHONE
Vehicle Particulars	
Manufacturer	HINO
Model	FD8JPKA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Commercial Vehicle
Insurance Company	
Name of Insurance Company	ERGO Insurance Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMCV15S022508
Cover Note Number	
Driver	
Name of Driver	CHUA HIANG SENG
NRIC No	S0924755F
Date Of Birth	30/08/1948
Occupation	Indoor
Date Of Driving Pass	01/11/1980
Driving Experience	35 Years And 4 Months
Gender	Male
Mobile Number	(Local) +65-96269914
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 123 HOUGANG AVE 1 #07-1410
 Postcode 1953
 Was driver an employee of the Insured's Company Yes
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident Collision- Head to Side
 Weather Conditions Clear
 Road Surface Dry

Other Information

Was any foreign vehicle involved in this accident? No
 Was any body injured in the Accident? No
 Was any other material or property damaged? Yes
 Was there any video captured by Car Camera? No
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? No
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? No
 If Yes, against whom?

Circumstances of Accident

I WAS TRAVELING ALONG LOYANG AVE. WHEN APPROACHING X-JUNCTION, TRAFFIC LIGHT WAS GREEN. HENCE, I PROCEED FORWARD. OUT OF SUDDEN, VEHICLE B DASHED OUT FROM OPPOSITE DIRECTION. I GOT NO TIME TO REACT, AND COLLIDED ONTO VEHICLE B.

Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKA6103L
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Name of Driver ZAMAKHAIR
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)
Details of Witness
 Name
 Phone Number
 Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




[Signature]

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

I was travelling along Leyang Avenue, when approaching x-junction, traffic light was green hence I proceed forward. Out of sudden, Veh B dashed out from opposite direction. I got no time to react & collided with Vehicle B.

A- YAM 5966 R
B- SKA 6103 L

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

MAJESTIC MACHINERY MOVER PTE LTD
61 KAKI BUKIT AVE 1 #01-12 SHUN LI INDUSTRIAL
PARK
SINGAPORE 417943

Contact : 65425855 96269914

TAX INVOICE

Date : 01/06/2017

Date in : 11/04/2016

Vehicle Num. : YM5966R

Make/Model : HINO FD8JPKA-2006

Chassis/Eng# : FD8JPK10015/J08EUC10123

Accident Date : 10/03/2016

Claim No : CLM13234

Reference : MAR-23/2016

Policy No. : DMCV15S022508 (13/02/2017)

LUMPSUM REPAIR BILL
AS PER SURVEYOR REPORT
REF : 0260-17-TCA DATED 22/05/2017
BY PAR AUTOMOTIVE CONSULTANCY

Amount S\$

11,400.00

E. & O.E. Sub S\$: 11,400.00

Add GST (7 %) S\$: 798.00

Total Amount S\$: 12,198.00



for TWINCAR AUTOMOTIVE PTE LTD

COMMERCIAL VEHICLE (HIRE USE)

CH1
R SB
B000137
Cov.Type: T

CERTIFICATE OF INSURANCE
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

CERTIFICATE NO.

DMCV15S022508

1) Index Mark and Registration
No. of Vehicle:

YM5966R

2) Name of Policyholder:

MAJESTIC MACHINERY MOVER PTE LTD

3) Commencement Date of Insurance:

14 February 2016

ADD XS:YNG&INEXP DRV SGD2,500.00

4) Expiry Date of Insurance:

13 February 2017

5) Persons or Classes of Persons entitled to drive

1) Any person who is driving on the Policyholder's order or permission

6) Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

7) Limitations as to Use

1) Use in connection with the Policyholder's business.

2) Use for carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.

3) Use for social domestic and pleasure purposes.

This policy does not cover

1) Use for racing pace-making reliability trial or speed-testing.

2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings (for Items 6 & 7)

WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Legend

Cov Type:

C - Comprehensive

F - Third Party, Fire & Theft

T - Third Party

For and on behalf of **ERGO Insurance Pte. Ltd.**
Approved Insurer

Authorized Signature

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 1335Z

Vehicle Details

Vehicle No.: YM5966R

Vehicle to be Exported: No

Intended De-registration Date: 24 Mar 2016

Vehicle Make: HINO

Vehicle Model: FD8JPKA

Primary Colour: White

Manufacturing Year: 2006

Engine No.: J08EUC10123

Chassis No.: FD8JPK10015

Maximum Power Output: -

Open Market Value: \$41,994.00

Original Registration Date: 14 Feb 2007

First Registration Date: 14 Feb 2007

Transfer Count: 1

Actual ARF Paid: \$0.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 13 Feb 2017

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$509.00

COE Rebate Amount: \$45.00

Total Rebate Amount: \$45.00

The information contained herein is correct as at 24 Mar 2016

OK



Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2016 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0260-17-TCA

22 May 2017

Majestic Machinery Mover Pte Ltd
61 Kaki Bukit Ave 1 #01-12 Shun Li Ind Park
Singapore 417943

INVOICE No. 0260-17-TCA

Vehicle No. YM5966R

<u>S/NO</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$896.00
Total amount payable		<u>\$896.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



Report No: 0260-17-TCA

22 May 2017

ACCIDENT VEHICLE SURVEY REPORT

Majestic Machinery Mover Pte Ltd
61 Kaki Bukit Ave 1 #01-12 Shun Li Ind Park
Singapore 417943

VEHICLE INFORMATION:

Vehicle Reg No.:	YM5966R	Odometer:	227939km
Make & Model:	Hino FD8JPKA	Colour:	White
Chassis number:	FD8JPK10015	Date of accident:	10/03/2016
Year of Regn.:	14/02/2007	Date inspected:	11/04/2016
Repairer at:	Twincar Automotive Pte Ltd	Date inspected (After Repair):	16/04/2016
	Blk 2 Kaki Bukit Ave 2 #01-17		
	Kaki Bukit Auto Hub		
	Singapore 417921		

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	10mm/Bridgestone	10mm/Bridgestone	8.25R16
Rear: x2	14mm/Bridgestone	14mm/Bridgestone	8.25R16

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the front LH portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
AIRCON AUXILIARY FAN ASSY	1	reuse <i>NN</i>	1,250.00	0.00
AIRCON CONDENSER	1	bent	1,150.00	1,150.00
AIRCON CONDENSER BRACKET	1	repair	125.00	0.00
AIRCON COOLING PIPE	1	reuse	340.00	0.00
AIRCON DISCHARGE PIPE	1	reuse <i>NN</i>	520.00	0.00
AIRCON SUCTION PIPE	1	reuse	410.00	0.00
FRONT BUMPER	1	bent	2,300.00	2,300.00
FRONT BUMPER BRACKET L/R <i>LH - BT</i> <i>RH x NN</i>	2	bent	152.00	152.00 <i>76</i>
FRONT GRILLE 'LOGO' EMBLEM	1	reuse <i>NN</i>	65.00	0.00
FRONT LH DOOR	1	buckled	5,400.80	5,400.80 <i>XR</i>
FRONT LH DOOR PILLAR WEATHERSTRIP	1	reuse <i>NN</i>	123.00	0.00
FRONT LH DOOR RUBBER GUIDE STOPPER	2	deformed	56.00	56.00 <i>x4N</i>
FRONT LH DOOR SIGNAL LAMP	1	fractured	53.00	53.00
FRONT LH DOOR STEP PANEL	1	abraded	315.00	315.00
FRONT LH DOOR STEP PANEL REFLECTOR	1	reuse <i>NN</i>	115.00	0.00
FRONT LH DOOR WEATHERSTRIP	1	reuse <i>NN</i>	281.80	0.00
FRONT LH HEADLAMP	1	fractured	850.00	850.00
FRONT LH HEADLAMP BRACKET	1	bent	60.40	60.40
FRONT LH HEADLAMP CLIPS	4	necessary	26.00	26.00
FRONT LH SIDE MIRROR ARM GARNISH	1	na <i>NN</i>	185.00	0.00
FRONT LH SIDE MIRROR ARM GARNISH CLIPS	4	na <i>NN</i>	26.00	0.00
FRONT LH SIGNAL LAMP	1	fractured	190.00	190.00
FRONT LH SIGNAL LAMP APRON GARNISH	1	fractured	215.00	215.00
FRONT LH SIGNAL LAMP APRON GARNISH CLIPS	4	necessary	26.00	26.00

Subtotal before discount S\$ 14,235.00 S\$ 10,794.20 *5262.2*

Percentage discount 0% and 10%

S\$ 0.00 S\$ 1,079.42

Sub-total 1 S\$ 14,235.00 S\$ 9,714.78 *4735.98*

FRONT BUMPER CLIPS - SET	1	necessary	30.00	30.00
FRONT BUMPER NUMBER PLATE '3D'	1	reuse <i>NN</i>	150.00	0.00
FRONT GRILLE CLIPS	1	necessary	30.00	30.00
FRONT LH DOOR ADVERTISEMENT & ART WORK	1	necessary	800.00	800.00 <i>300</i>
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET	1	necessary	30.00	30.00
FRONT LH HEADLAMP BULB	1	fused	40.00	40.00 <i>x4N</i>
FRONT LH SIGNAL LAMP BULB	1	fused	15.00	15.00 <i>x4N</i>
FRONT PANEL ADVERTISEMENT STICKER	1	necessary	500.00	500.00 <i>200</i>

Subtotal before discount S\$ 1,595.00 S\$ 1,445.00 *590*

Sub-total 2 S\$ 1,595.00 S\$ 1,445.00

Parts-total S\$ 15,830.00 S\$ 11,159.78

PAR Automotive Consultancy


LABOUR

To remove, change air con parts, vacuums, refill air con gas.	180.00	150.00	100
To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	180.00	60.00	30
To remove, reinstall window glass. (to FR)	120.00	100.00	XL
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	160.00	100.00	X7NN
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00	800.00	500
To provide labour, workmanship to change the above damaged bodyparts, repair, reconstruct and re-align body structure, body alignments and damaged consistent to the accident.	1,250.00	1,000.00	600
To apply anti-rust chemical on repaired and replaced panel.	120.00	60.00	40
Labour Total	SS 3,010.00	SS 2,270.00	
Parts & Labour Total	SS 18,840.00	SS 13,429.78	1270

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 11,400.00
and the recommended number of working days for the repairs is within 7 day(s).


B J Loi (I Eng., MIML AIRTE)
Automotive Appraiser

6595.98

20%: 5250

5 days

Text size + -

Enquire Vehicle & Owner Information (Vehicle No. SKA6103L As At 10 Mar 2016 / 13:35:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: N63-MSIC

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S7910773E

Owner Name: ZAMAKHAIR BIN BUJANG

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 561

Registered Street Name: CHOA CHU KANG NORTH 6

Registered Unit No.: # 02 - 98

Registered Building Name: -

Registered Postal Code: 680561

Current Vehicle Details

Vehicle No.: SKA6103L

Make Description/Model: B.M.W. / 318i 2.0 AT D/AB 2WD 4DR GAS/D SR DRL

Insurance Company Name: AXA INSURANCE SINGAPORE PTE LTD



Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above 1024 X 768 resolution

Copyright © 2016 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)

Text size + -

Enquire Vehicle & Owner Information (Vehicle No. SKA6103L As At 10 Mar 2016 / 13:35:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: N63-MSIC

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S7910773E

Owner Name: ZAMAKHAIR BIN BUJANG

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 561

Registered Street Name: CHOA CHU KANG NORTH 6

Registered Unit No.: # 02 - 98

Registered Building Name: -

Registered Postal Code: 680561

Current Vehicle Details

Vehicle No.: SKA6103L

Make Description/Model: B.M.W. / 318i 2.0 AT D/AB 2WD 4DR GAS/D SR DRL

Insurance Company Name: AXA INSURANCE SINGAPORE PTE LTD



Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 8.0 SP3 and above, 1024 X 768 resolution
Copyright © 2016 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YM 5966R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	AIRCON AUXILIARY FAN ASSY	NOT NECESSARY	1,250.00	-
1	AIRCON CONDENSER	BENT	1,150.00	1,150.00
1	AIRCON CONDENSER BRACKET	TO REPAIR SEE LABOUR	125.00	-
1	AIRCON COOLING PIPE	NOT NECESSARY	340.00	-
1	AIRCON DISCHARGE PIPE	NOT NECESSARY	520.00	-
1	AIRCON SUCTION PIPE	NOT NECESSARY	410.00	-
1	FRONT BUMPER	BENT	2,300.00	2,300.00
2	FRONT BUMPER BRACKET L/R	N/S BENT / O/S NOT NECESSARY	152.00	76.00
1	FRONT GRILLE 'LOGO' EMBLEM	NOT NECESSARY	65.00	-
1	FRONT LH DOOR	TO REPAIR SEE LABOUR	5,400.80	-
1	FRONT LH DOOR PILLAR WEATHERSTRIP	NOT NECESSARY	123.00	-
2	FRONT LH DOOR RUBBER GUIDE STOPPER	NOT NECESSARY	56.00	-
1	FRONT LH DOOR SIGNAL LAMP	FRACTURED	53.00	53.00
1	FRONT LH DOOR STEP PANEL	ABRADED	315.00	315.00
1	FRONT LH DOOR STEP PANEL REFLECTOR	NOT NECESSARY	115.00	-
1	FRONT LH DOOR WEATHERSTRIP	NOT NECESSARY	281.80	-
1	FRONT LH HEADLAMP	FRACTURED	850.00	850.00
1	FRONT LH HEADLAMP BRACKET	BENT	60.40	60.40
4	FRONT LH HEADLAMP CLIPS	NECESSARY	26.00	26.00
1	FRONT LH SIDE MIRROR ARM GARNISH	NOT NECESSARY	185.00	-
4	FRONT LH SIDE MIRROR ARM GARNISH CLIPS	NOT NECESSARY	26.00	-
1	FRONT LH SIGNAL LAMP	FRACTURED	190.00	190.00
1	FRONT LH SIGNAL LAMP APRON GARNISH	FRACTURED	215.00	215.00
4	FRONT LH SIGNAL LAMP APRON GARNISH CLIPS	NECESSARY	26.00	26.00
	LESS 10% DISCOUNT		-	-526.14
			14,235.00	4,735.26
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00

Report Ref No. CS3/AXA16005512/Gqbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER NUMBER PLATE '3D' (SN)	NOT NECESSARY	150.00	-
1	FRONT GRILLE CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT LH DOOR ADVERTISEMENT & ART WORK (SN)	NECESSARY	800.00	300.00
1	SET FRONT LH DOOR INNER TRIM BOARD CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT LH HEADLAMP BULB (SN)	NOT NECESSARY	40.00	-
1	FRONT LH SIGNAL LAMP BULB (SN)	NOT NECESSARY	15.00	-
1	FRONT PANEL ADVERTISEMENT STICKER (SN)	NECESSARY	500.00	200.00
			1,595.00	590.00
	LABOUR			
	TO REMOVE, CHANGE AIR CON PARTS, VACUUMS, REFILL AIR CON GAS.		180.00	100.00
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR.		180.00	30.00
	TO REMOVE, REINSTALL WINDOW GLASS. (TO FR)	NOT NECESSARY	120.00	-
	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE.	NOT NECESSARY	160.00	-
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	500.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF AIRCON CONDENSER BRACKET AND FRONT LH DOOR.		1,250.00	600.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	40.00
			3,010.00	1,270.00
GRAND TOTAL			18,840.00	6,595.26
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,250.00

Report Ref No. CS3/AXA16005512/Gqbs2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.