
























PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131

Report No: 0260-17-TCA

22 May 2017

ACCIDENT VEHICLE SURVEY REPORT

Majestic Machinery Mover Pte Ltd
61 Kaki Bukit Ave 1 #01-12 Shun Li Ind Park
Singapore 417943

VEHICLE INFORMATION:

Vehicle Reg No.	YM5966R	Odometer:	227939km
Make & Model:	Hino FD8JPKA	Colour:	White
Chassis number:	FD8JPK10015	Date of accident:	10/03/2016
Year of Regn.:	14/02/2007	Date inspected:	11/04/2016
Repairer at:	Twincar Automotive Pte Ltd	Date inspected (After Repair):	16/04/2016
	Blk 2 Kaki Bukit Ave 2 #01-17		
	Kaki Bukit Auto Hub		
	Singapore 417921		

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis

