

ASS. REC. BY:

REF: CS/C7I18003977/Gqd3n2 Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Angie Foo of CTI Date/Time: 1/3/18 @ 10:32am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLU 74462 Insured: SDW 841 Xat Workshop m/s World Auto Tel: 6362 1776of No. 1 Kranji loopPolicy No: DMPCSN1348381704 Claim No: SNM18D00895C02/1

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 14/02/2018
(Client's Record)CA / REV / REP. / REV 24 HRS 'wp' H.O.D. Endorsement: _____Date/Time: 11:15am 31/3/18 Person Contacted: Vincent Vehicle: IN/OUT

Date/Time	Action/Instruction	Estimate
	<u>SLU 74462-X</u>	
	<u>SDW 841 X-X</u>	
<u>05/6/18 @ 11:17am</u>	<u>confirmed with Sophia final fig #186.87, 3 days.</u>	
	<u>(Red @ 120, 90%)</u>	<u>2/6/18</u>

Surveyor

XHL

REF:

CTI

CB97K

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

World Auto

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLU74468

Yr Regn:

13 Dec 2017

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Hybrid

Make:

Toyota Prius

c.c

1798

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

14744

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTD KB3FU603564801

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

☒ TOYO / ☒ YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

D.O.I.

01-03-18

Survey held at

w/s

12:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

d/s rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 05 JUN 2018

Date/Time, File Pass to?

1) 05/6/18

☐

Preli. Report

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

) \$ + RS \$

) Photos

) Others

Report Format :

MER-TP

Lump Sum / I.B.I. (\$

1186.87

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18003977/Gqd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 01-03-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDW 841X	Veh. Inspected	SLU 7446Z
Policy No.		Coverage (\$)	0.00
Claim No.	SNM18D00895C02/1	Excess (\$)	0.00
Assign From	ANGIE FOO	Assign Date	01/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/02/2018	Inspection Date	01/03/2018
Survey held at	NO 1 KRANJI LOOP		
Repairer	WORLD AUTO PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Thursday, 1 March 2018 10:32 AM
To: assignments
Subject: FW: OUR REF: PRS/SNM18D00895C02/1 & YR REF: SLU7446XNDUCT PRE REPAIR SURVEY -SLU7446Z

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Angie Foo [mailto:angie.foo@sg.cntaiping.com]
Sent: Thursday, 1 March 2018 10:31 AM
To: Ongv16 <ongv16@worldauto.com.sg>
Cc: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: RE: OUR REF: PRS/SNM18D00895C02/1 & YR REF: SLU7446XNDUCT PRE REPAIR SURVEY -SLU7446Z

WITHOUT PREJUDICE

Dear Vincent,

We refer to your email of 28th February 2018.

We had appointed Marcus Chua of M/S LKK Auto Consultants Pte Ltd to conduct survey on your client's vehicle.

Please ensure that your client's vehicle is available for survey within 2 working days.

REMARKS:

Dear Marcus,

Please conduct survey and check consistency of the damages on without prejudice.

Kindly take note, the claim handler on this case is Chong Boon Sen 6389 6171

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E

DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Ongv16 [<mailto:ongv16@worldauto.com.sg>]
Sent: Wednesday, 28 February, 2018 5:38 PM
To: Angie Foo
Subject: Re: OUR REF: PRS/SNM18D00895C02/1 & YR REF: SLU7446XNDUCT PRE REPAIR SURVEY -SLU7446Z

Dear Angie,

Kindly appoint macus chua.

Thanks

Vincent ong

-----Original Message-----

From: "Angie Foo" <angie.foo@sg.cntaiping.com>
To: Ongv16 <ongv16@worldauto.com.sg>
Cc: "Claims Dept of CTI" <claimsdept@sg.cntaiping.com>, "Chong Boon Sen" <boonsen.chong@sg.cntaiping.com>
Date: 28/02/2018 16:17
Subject: OUR REF:PRS/SNM18D00895C02/1 & YR REF: SLU7446XNDUCT PRE REPAIR SURVEY -SLU7446Z

WITHOUT PREJUDICE

Dear Sir/Mdm,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
SAMUEL PHUN
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
DEREK OH SIONG WEE
KALVIN ANG
MARCUS CHUA
SIMON HO
LOW SAR HUEI
HONG FOOK CHOY

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Kindly let us hear from you.

REMARKS:

Kindly take note, the claim handler on this case is Chong Boon Sen 6389 6171

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Ongv16 [<mailto:ongv16@worldauto.com.sg>]
Sent: Wednesday, 28 February, 2018 11:17 AM
To: Claims Dept of CTI
Subject: Pre-Repair Inspection

Dear Sir/Mdm,

We would like to request for a Third Party Motor Claim Survey, details as follow;

Our Vehicle: SLU 7446 Z

Your Insured: SDW 841 X

DOA: 14/2/18

Our vehicle is currently in the workshop, address as follow;

World Auto Pte Ltd

No.1, Kranji Loop

Singapore 739535

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Shiau Chan (LKKAUTO)

From: tggtan@worldauto.com.sg
Sent: Tuesday, 5 June 2018 11:17 AM
To: Shiau Chan (LKKAUTO)
Subject: RE: SLU7446Z Our ref: TP/1849/18 *LKK REF: CS/CTI18003977/Gqd3

Hi Shiau Chan

Confirmed COR @ \$1,186.87/3 days of repairs.

Rdgs
Sophia Tan
World Auto Pte Ltd (Kranji)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Tuesday, 5 June 2018 10:11 AM
To: tggtan@worldauto.com.sg
Cc: SUR <sur@lkkauto.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Subject: RE: SLU7446Z Our ref: TP/1849/18 *LKK REF: CS/CTI18003977/Gqd3

Dear Sophia,

Offer final fig \$1,186.87 and 3 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAUTO)
Sent: Tuesday, 5 June 2018 7:38 AM
To: tggtan@worldauto.com.sg
Cc: SUR <sur@lkkauto.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Subject: RE: SLU7446Z Our ref: TP/1849/18 *LKK REF: CS/CTI18003977/Gqd3

Without Prejudice

Hi Sophia,

Received with thanks.

By copy to Guo Qiang/ Shiau Chan,

FYNA. CS/CTI18003977/Gqd3

Enquire Transfer Fee

Vehicle Details	
Vehicle No.:	SLU7446Z
Vehicle Type:	Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Chassis No.:	JTDKB3FU603564801
Propellant:	Petrol-Electric
Engine No.:	2ZRS065575
Motor No.:	1NMS065575
Engine Capacity:	1798 cc
Power Rating:	53.0 kW
Maximum Power Output:	90.0 kW (120 bhp)
Maximum Laden Weight:	1790 kg
Unladen Weight:	1375 kg
Year Of Manufacture:	2017
Original Registration Date:	13 Dec 2017
Lifespan Expiry Date:	-
COE Category:	B - Car above 1600cc or 97kW (130bhp)
Quota Premium:	\$49,996.00
COE Expiry Date:	12 Dec 2027
Road Tax Expiry Date:	12 Jun 2018
PARF Eligibility Expiry Date:	12 Dec 2027
Inspection Due Date:	12 Dec 2020
Intended Transfer Date:	05 Mar 2019
CO2 Emission:	87.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$27,610.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/02/2018 12:41
Date Of Accident	14/02/2018 09:20
Exact Location Of Accident	23 FLORA RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU7446Z
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201604597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995174
Cover Note Number	

Driver

Name of Driver	TAN KIM SIONG CHRISTOPHER
NRIC No	S7500636E
Date Of Birth	10/01/1975
Occupation	OUTDOOR
Date Of Driving Pass	26/11/1998
Driving Experience	19 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NOADDRESS
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NONAME
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO OVERWRITTEN
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDW841X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

SKETCH PLAN



Sketch Plan #2

Describe Circumstances of the Accident

On 14/02 2018 at around 0920hrs I driving vehicle No. 511 34462, under LCE. I was on the way to pick up my friends. At the Carpark of 23 Horn Rd I was on the straight lane towards my friends house. Suddenly the vehicle saw 841x from his parking reverse and hit into my Rear Ribs

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
Time

2

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Estimate : ES005756

Attention : Motor Claim Department

Date : 19/02/2018
Vehicle Num. : SLU 7446Z (LCR)
Make/Model : TOYOTA PRIUS HYBRID 1.8S
Chassis/Eng# :
Accident Date : 19/02/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.		LIST ITEMS :		423.90
2.		REAR BUMPER		118.60
		REAR BUMPER RIGHT PAD		
		List TotalS\$:		542.50
		25.00% Discount S\$:		135.63
				406.87
1.		SPECIAL NETT ITEMS :		30.00
		REAR BUMPER CLIP		30.00
		Special Nett Total S\$:		
		LABOUR :		
		LABOUR TO RENEW REAR BUMPER & REAR BUMPER R/S PAD	350	420.00
		SPRAY PAINT TO R/R FENDER, REAR BUMPER & REAR BUMPER PAD	400	450.00
		Labour Total S\$:		870.00
		3 Days .		
		Part by part .		
		before part photo's.		
		E. & O.E.	Total S\$:	1,306.87

for WORLD AUTO PTE LTD

Guo Qiang - 82880282

Guo Qiang @ HK Auto . Com

01/3/18

Signature
Date: 01/3/18

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18003977/GQD3N2

Date: 06/06/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1348381704
Claimant Vehicle No :	SLU7446Z	Insured Vehicle No :	SDW841X
Date of Loss:	14/02/2018	Nature of Claim:	TP
		Claim No:	SNM18D00895C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU7446Z	Engine No:	2ZRS065575
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU603564801
Reg. Date:	13/12/2017 (Man. Year: 2017)	Odometer:	14744 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	436.87	436.87	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	870.00	750.00	120.00	13.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,306.87	1,186.87	120.00	9.18
+ GST 7.00/7.00% (\$\$)	91.48	83.08	8.40	9.18
Nett Amount (\$\$)	1,398.35	1,269.95	128.40	9.18

INSPECTION

Date of Assignment:	07/03/2018		
Date Inspected:	01/03/2018	Inspected At:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop Singapore 739535
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Jun 2018)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLU7446Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	423.90 FL	*423.90 FL
2	1		*REAR BUMPER RIGHT PAD	Cut	118.60 FL	*118.60 FL
3	1		*REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					572.50	572.50
- List Item Discount on L Items 25.00/25.00% (S\$)					135.63	135.63
Total Parts (S\$)					436.87	436.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO RENEW REAR BUMPER & REAR BUMPER R/S PAD	New	420.00	350.00
2	SPRAY PAINT TO R/R FENDER,REAR BUMPER & REAR BUMPER PAD	New	450.00	400.00
Gross Labour Cost (S\$)			870.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >