

INS. CASE OWNER:

CC 6/AIG1800

3979, 4/1/18

LKK  
IDAC

Surveyor:

MARVINS

DOI:

ASSIGNMENT

1/7/18

Date / Time:

1/7/18

Registered in Merimen:

1/7/18

Pre-assign / CCU / FTE

SGK 2706



Insured Vehicle No.:

Jamun Ravi Plo Thayalam

Claim No.:

5117777656

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

27/7/18

Place of Accident:

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SC 2788



INSRS:

WSP:

Tel:

Liability:

RMKS:

WPK



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

5/7/18

WPK

no oi bia, sent out 1st letter.

20/5/18

Call OIA N/A

20/3/18

OIA called confirm accident details  
or mentioned no collision TP sent  
promptly and told him he have 7P  
TP unable to show to give evidence  
from TP

3/9/19 - FILE PASS TO LSP TO CLARE

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

7 BEVAN

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

N/A

If NO or B 28, Ass. Lia:

Repair Cost:

SS

No Collision

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

(S

x

days)

Loss of Income (LOI):

SS

(S

x

days)

LOR only ☐ LOU only ☐

LOR + LOU ☐

LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS

Medical:

SS

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS

(e.g. Tow/ Independent)

2) Report Format:

WP

Legal Cost

SS

3) Survey fee:

320.00

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18003979/Uyb3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 01-03-2018



Code : AIG

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGK 2770G	Veh. Inspected	SCL 2138A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	01/03/2018

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	27/02/2018	Inspection Date	01/03/2018
Survey held at	NPH AUTO SERVICE BLK 9005 TAMPINES STREET 93 #01-246/254 SINGAPORE 528839		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
----------------------------------------------------------------------------------------------------------------------------------------



# NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692  
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D  
E-mail: nphauto@pacific.net.sg



Your Ref : Page : 1/2  
Our Ref : TP0020/02/18 Date : 28/02/2018

## THIRD PARTY CLAIM

M/S : SIA CHYE SENG  
27 BEDOK PLACE  
SINGAPORE 486100

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SCL2138A - LEXUS E250  
INSURED : SIA CHYE SENG  
DATE OF ACCIDENT :  
POLICY NO : A2809263SMF

ENGINE# :  
CHASSIS# :

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
<b>Replacement of Parts</b>				
1 rear bumper	10	895.00	895.00	895.00 ✓
2 rear bumper reinforcement	18	621.00	621.00	621.00
3 rear bumper sponge	10	104.63	104.63	104.63
4 rear bumper parking sensor	10	425.00	425.00	425.00
				2,045.63
Less 10%				-204.56
<b>Total Material</b>				<b>\$1,841.07</b>
<b>Labour &amp; Misc</b>				
1 Remove & install r/bumper, r/lamp, bumper reinforcement and restraigten body.			250.00	200
2 Spray painting.			350.00	200
3 Check wiring system.			25.00	20
4 Renew parking sensor.			80.00	50
			705.00	
<b>Total Labour</b>				<b>\$705.00</b>
<b>Nett Total Before Gst</b>				<b>\$2,546.07</b>

Not Authorised  
LH

to high to be party.  
2 day.  
1/3/18

Service notify

Following:

- 1. 10% discount on painting
- 2. 10% discount on bodywork
- 3. 10% discount on labour
- 4. 10% discount on material
- 5. 10% discount on tax
- 6. 10% discount on insurance
- 7. 10% discount on other

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

## Bevan Lim (LKK Auto)

---

**From:** Bevan Lim (LKK Auto)  
**Sent:** Tuesday, 20 March 2018 5:23 PM  
**To:** 'nphauto@pacific.net.sg'  
**Cc:** Vic (LKKAuto)  
**Subject:** Your Ref: TP0020/02/18 ,Our Ref: CC6/AIG18003979/Umb3 ACCIDENT INVOLVING SGK 2770G AND SCL 2138A ON 27.02.2018  
**Attachments:** OI GIA REPORT (3).pdf

### WITHOUT PREJUDICE

Your Ref: TP0020/02/18  
Our Ref: CC6/AIG18003979/Umb3

Dear Sir/Madam,

### ACCIDENT INVOLVING SGK 2770G AND SCL 2138A ON 27.02.2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is unclear / our Insured is disputing for the above mentioned case. Our insured also filing Third Party claim against your client's insurer. Enclosed herewith is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request the CCTV footage / accident scene photos / evidence in order to seek further instruction from our principal.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Bevan Lim | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749-4274 | email: [BevanLim@lkkauto.com](mailto:BevanLim@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

## Jia Le (LKK Auto)

---

**From:** Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>  
**Sent:** Tuesday, 28 May 2019 3:39 PM  
**To:** CS A Team  
**Cc:** Olivia Lau (LKKAuto)  
**Subject:** RE: Our Ref: 5112123276SG-003 || Accident Involving SGK2770G / SCL2138A on 27/02/2018

Hi LKK Team

Our email dated 29<sup>th</sup> April 2019 refers.

Kindly furnish us your WP report and billings for closed to this matter since we have received no response from TP.

Best Regards

**Bennie Tan**  
**AIG**  
Senior Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1718

[Bennie-WZ.Tan@aig.com](mailto:Bennie-WZ.Tan@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** Tan, Bennie-WZ  
**Sent:** Monday, April 29, 2019 6:01 PM  
**To:** nphauto@pacific.net.sg  
**Cc:** CS A Team; Olivia Lau (LKKAuto)  
**Subject:** Our Ref: 5112123276SG-003 || Accident Involving SGK2770G / SCL2138A on 27/02/2018

Dear Sir / Mdm

We are the insurer of SGK2770G at the material time of the Accident.

We note that you are acting for SIA CHYE SENG, the owner of SCL2138A, in their claim for Property Damages against the Auto Insurance Policy of our Insured as a result of the above Accident.

The Claim has been outstanding for more than 12 months. If we do not hear from you in writing within the next 10 working day from the date of this email, we shall proceed to close our file.

Best Regards

**Bennie Tan**  
**AIG**  
Senior Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1718

[Bennie-WZ.Tan@aig.com](mailto:Bennie-WZ.Tan@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## View Received Message

This mail is associated with :

**\*SCL2138A (5112123276SG)  
[SGK2770G]**

TP  
SIA CHYE SENG  
Feb 27 2018 12:00AM  
[Jamuna Rani D/O Thayalam]  
NPH Auto Service

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 02/03/2018 11:34 AM,  
**To** LKK\_HQ  
**Subject** No OI GIA Report

Hi

Pls be advice that no OI GIA report received  
Pls find OI details below for your further actions

OI name : Jamuna Rani D/O Thayalam

Address :  
178B  
Rivervale Crescent  
#04-433  
Singapore 542178

Mobile No: 90079385

Thank you.

Regards,  
Darshene

### DOCUMENTS SUMMARY

There are no documents.







Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563501 FAX : (065) 62564315

Our Ref: CC6/AIG18003979/Uyb3

05<sup>TH</sup> MAR 2018

**Jamuna Rani D/O Thayalam**

178B Rivervale Crescent

#04-433

Singapore 542178

Dear Sirs,

**ACCIDENT INVOLVING SGK 2770G AND SCL 2138A ON 27.02.2018 ALONG/ AT  
BARTLEY ROAD TOWARDS BARTLEY ROAD EAST**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Jas Khine

Claims

Tel : 6841 2928

Fax: 6741 4108

Email : jaskhine@lkkauto.com

c.c. *Claims Manager*  
*AIG Asia Pacific Insurance Pte Ltd*  
*(Motor Claims Dept)*

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8755B
Vehicle Details	
Vehicle No.:	SCL2138A
Vehicle to be Exported:	No
Intended De-registration Date:	01 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS ES250 LUXURY AUTO
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	2ARF010705
Chassis No.:	JTHBJ1GG102078837
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$39,966.00
Original Registration Date:	17 Apr 2015
First Registration Date:	17 Apr 2015
Transfer Count:	0
Actual ARF Paid:	\$47,953.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Apr 2025
PARF Rebate Amount:	\$35,964.00
Intended COE Rebate Details	
COE Expiry Date:	16 Apr 2025
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$76,790.00
COE Rebate Amount:	\$54,712.00
<b>Total Rebate Amount:</b>	<b>\$90,676.00</b>

The information contained herein is correct as at 01 Mar 2018

OK

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

Revoked / No settlement

**CLAIM SUBFOLDER TRACKING**

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Mar 2018 <a href="#">Edit Reg</a>		01 Mar 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$1,275.50</b> <a href="#">Edit Estimates</a>	<b>S\$1,275.50</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	Jamuna Rani D/O Thayalam, ID: S1409374E								
Main Claimant:	SIA CHYE SENG, ID: S1438755B								
Vehicle Reg. No.:	SCL2138A	Date of Loss:	27/02/2018 19:00 - :59 [34 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5112123276SG	Policy/Cover Note No.:	2100422397-02 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	SGK2770G	Policy No. (Claimant):	S2890263SMF						
		Excess:							
Repairer:	NPH Auto Service (HQ) Blk 9005 Tampines Steet 93, #01-246/254, 528839 Tampines - Tel: 6784 0663								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 12/03/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (02/03/2018): No OI GIA Report</li> <li>AIG_SG (02/03/2018): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SCL2138A (5112123276SG)**  
**[SGK2770G]**  
**TP**  
**SIA CHYE SENG**  
**Feb 27 2018 7:10PM**  
**[Jamuna Rani D/O Thayalam]**  
**NPH Auto Service**

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View <span style="border: 1px solid black; padding: 2px;">View in Browser</span>
------------------	--	---------------	--------------------	--------------	--------------	----------------------------------------------------------------------------------

  

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	19/03/18 12:06	<b>Accident Statement</b> <small>From: SC - Reg. No: SGK2770G, Claimant: JAMUNA RANI D/O THAYALAM</small>		Load HTML	

  

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
2	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
3	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
4	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
5	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
6	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
7	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
8	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
9	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
10	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
11	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
12	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
13	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
14	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
15	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
16	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
17	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
18	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
19	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
20	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
21	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
22	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
23	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
24	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
25	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
26	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
27	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
28	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
29	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
30	01/03/18 17:27	General View		Load JPG	<input checked="" type="checkbox"/>
31	01/03/18 17:27	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
32	01/03/18 17:27	Chassis Number		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/03/18 15:37	TP ESTIMATE- MARKED		Load PDF
2	02/03/18 15:37	TP GIA REPORT.		Load PDF
3	05/03/18 11:27	Non reporting letter		Load PDF

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18003979/UDB3Q2

Date: 10/09/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100422397-02

Claimant Vehicle No : SCL2138A

Insured Vehicle No : SGK2770G

Date of Loss: 27/02/2018

Nature of Claim: TP

Claim No: 5112123276SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SCL2138A

Make &amp; Model: LEXUS ES250, 2.5 (A)

Engine No: 2ARF010705

Reg. Date: 17/04/2015 (Man. Year: 2015)

Chassis No: JTHBJ1GG102078837

Colour: Black

Odometer: 64558 km

Engine Capacity: 2494 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/55Z R17

Rear Tyre Size: 215/55Z R17

Front Left Side: Michelin 7 mm

Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,841.07	805.50	1,035.57	56.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	705.00	470.00	235.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,546.07</b>	<b>1,275.50</b>	<b>1,270.57</b>	<b>49.90</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>178.22</b>	<b>89.29</b>	<b>88.93</b>	<b>49.90</b>
<b>Nett Amount (S\$)</b>	<b>2,724.29</b>	<b>1,364.79</b>	<b>1,359.50</b>	<b>49.90</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

## INSPECTION

Date of Assignment: 01/03/2018

Date Inspected: 01/03/2018 Inspected At:

NPH Auto Service (HQ)  
Blk 9005 Tampines Steet 93, #01-246/254  
Singapore 528839

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	895.00 FL	*895.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Repair	621.00 FL	*- FL
3	1		*REAR BUMPER SPONGE	*Check	104.63 FL	*- FL
4	1		*REAR BUMPER PARKING SENSOR	*Check	425.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,045.63</b>	<b>895.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>204.56</b>	<b>89.50</b>
<b>Total Parts (\$\$)</b>	<b>1,841.07</b>	<b>805.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & INSTALL R/BUMPER ,R/LAMP ,BUMPER REINFORCEMENT AND RESTRAIGHTEN BODY	New	250.00	200.00
2	SPRAY PAINTING	New	350.00	200.00
3	CHECK WIRING SYSTEM	New	25.00	20.00
4	RENEW PARKING SENSOR	New	80.00	50.00
Gross Labour Cost (S\$)			705.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >