

ASS. REC. BY:

REF: CS3/AIG/18004000/Gd3ch

Special Instruction:

DAR 8 days.

Surveyor:

GQ

## ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

28/2/18 @ 11.59am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBA 10711

Insured:

FBK 351E

at Workshop m/s

Eng Soon Painting

Tel:

6760 6271

of

Bik 4, Yew Tee Ind. Est 343-J Woodlands Rd

Policy No:

2100403569

Claim No:

122676058586

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22/01/2018

CA / REV / REP. / REV 24 HRS

1wpi

H.O.D. Endorsement:

Date/Time:

10.41am 3/13/18

Person Contacted:

Mr. Teo

Vehicle

IN/OUT

| Date/Time | Action/Instruction (X) Estimate |
|-----------|---------------------------------|
|           | FBA 10711 - X                   |
|           | FBK 351E - X                    |
|           | Dismantle: 9/3/2018             |
|           | After repair: 16/3/2018         |
|           |                                 |
|           |                                 |

PRS xxx

REF: AG.

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Eng Soon  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 14 days Res: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: FBA1071J Yr Reg: 06  
 Type: M.Car / M.Cysa / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Honda wave 125 c.c. 125  
 Colour: Red A/C: Insured / Std / NI / NA  
 Sp. Reading: 12034 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: NF125PSE0002278  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: N/A / S/Rim / STD A/Rim or

Tyre Size: F: 70/90-17  
 R: 80/90-17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or IRC

Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 4 mm R/Bal. 4 mm  
 L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm  
 D.O.A. \_\_\_\_\_ D.O.I. 01-03-18  
 Survey held at w/s 12pm  
 Des. of Damages Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
20/4 Submit DAR report.

RECEIVED 20 APR 2013

Date/Time, File Pass to? ☐ : Preli. Report  
☐ : Final Report

1) \_\_\_\_\_  
 Date/Time, File Return to?

2) \_\_\_\_\_

Report Format : DAR.

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: 4  
 Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_

TOTAL

|     |
|-----|
| 180 |
| 20  |
| 200 |

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED  
VEHICLE FBK351E AND FBA1071J ON 22/01/2018**

From: Chin, Lee-Ying  
To: 'assignments', Admin A  
Cc: Fong, Andy-SY  
Sent: Wednesday, 28 February, 2018 11:59:15 AM  
Attachments:  FaxDC44 (2).tif

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**BONNIE KWOK LLC***Advocates & Solicitors*

101A Upper Cross Street  
#08-12 People's Park Centre  
Singapore 058358

Tel : (65) 6536 6026  
Fax : (65) 6536 2279  
[Not for service of court documents]  
GST Reg No. 201203472

Your Vehicle: FBK 351 E  
Our Vehicle: EngSoon-FBA 1071 J

Date : 27 February 2018

M/s AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

By Fax 6835 7416 only


Dear Sirs,

**ACCIDENT INVOLVING FBA 1071 J & FBK 351 E ON 22 JANUARY 2018**

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle FBA 1071 J at M/s Eng Soon Painting Services, Block 4 Yew Tee Industrial Estate 393-J Woodlands Road Singapore 677978.

Your faithfully



**BONNIE KWOK**

c.c. Client

**Enquire PARF/COE Rebate for Registered Vehicle**

|                                                                                                                                                                                                                         |                   |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|
| <b>Vehicle Owner Particulars</b>                                                                                                                                                                                        |                   |
| Owner ID Type:                                                                                                                                                                                                          | Singapore NRIC    |
| Owner ID:                                                                                                                                                                                                               | 3698J             |
| <b>Vehicle Details</b>                                                                                                                                                                                                  |                   |
| Vehicle No.:                                                                                                                                                                                                            | FBA1071J          |
| Vehicle to be Exported:                                                                                                                                                                                                 | No                |
| Intended De-registration Date:                                                                                                                                                                                          | 20 Apr 2018       |
| Vehicle Make:                                                                                                                                                                                                           | HONDA             |
| Vehicle Model:                                                                                                                                                                                                          | WAVE 125R A       |
| Primary Colour:                                                                                                                                                                                                         | Red               |
| Manufacturing Year:                                                                                                                                                                                                     | 2005              |
| Engine No.:                                                                                                                                                                                                             | NF125PSE0002278   |
| Chassis No.:                                                                                                                                                                                                            | NF125PS0002278    |
| Maximum Power Output:                                                                                                                                                                                                   | -                 |
| Open Market Value:                                                                                                                                                                                                      | \$1,636.00        |
| Original Registration Date:                                                                                                                                                                                             | 03 Feb 2006       |
| First Registration Date:                                                                                                                                                                                                | 03 Feb 2006       |
| Transfer Count:                                                                                                                                                                                                         | 4                 |
| Actual ARF Paid:                                                                                                                                                                                                        | \$246.00          |
| <b>Intended PARF Rebate Details</b>                                                                                                                                                                                     |                   |
| PARF Eligibility:                                                                                                                                                                                                       | No                |
| PARF Eligibility Expiry Date:                                                                                                                                                                                           | -                 |
| PARF Rebate Amount:                                                                                                                                                                                                     | \$0.00            |
| <b>Intended COE Rebate Details</b>                                                                                                                                                                                      |                   |
| COE Expiry Date:                                                                                                                                                                                                        | 31 Jan 2021       |
| COE Category:                                                                                                                                                                                                           | D - Motorcycle    |
| COE Period(Years):                                                                                                                                                                                                      | 5                 |
| PQP Paid:                                                                                                                                                                                                               | \$3,169.00        |
| COE Rebate Amount:                                                                                                                                                                                                      | \$1,761.00        |
| <b>Total Rebate Amount:</b>                                                                                                                                                                                             | <b>\$1,761.00</b> |
| <b>Message</b>                                                                                                                                                                                                          |                   |
| Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. |                   |

The information contained herein is correct as at 20 Apr 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 27/02/2018 15:31  
Date Of Accident 22/01/2018 15:30  
Exact Location Of Accident PIE > KJE  
Country/State Of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number FBA1071J  
Insured/Policyholder  
Name Of Registered Owner FANG KWI FONG  
NRIC No S2113698J  
Email Address NOEMAIL  
Mobile Phone No (LOCAL) +65-83123163  
Alternative Phone No OFFICE-83123163

### Vehicle Particulars

Manufacturer HONDA  
Model WAVE 125R A  
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY  
Vehicle Category MOTORCYCLE

### Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Type Of Coverage THIRD PARTY  
Fleet Policy NO  
Policy Number 5090251170  
Cover Note Number

### Driver

Name of Driver FANG KWI FONG  
NRIC No S2113698J  
Date Of Birth 07/07/1949  
Occupation INDOOR  
Date Of Driving Pass 19/08/2003  
Driving Experience 14 YEARS AND 5 MONTHS  
Gender MALE  
Mobile Number (LOCAL) +65-83123163  
Fax Number  
Contact Number OFFICE-83123163  
EMail Address NOEMAIL



Address BLK 213 MARSILING CRESCENT #13-69  
Postcode 730213  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OWNER  
Vehicle Registration Number of Driver's Own Vehicle -  
Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident SIDE SWIPE  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident  
Was any body injured in the Accident? YES  
Was any injured conveyed to hospital by ambulance? YES  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? YES  
If Yes, Please state which Police Station  
Police Station Name WOODLANDS WEST NPC  
Police Station Address ROAD: 9 MARSILING LANE, POSTCODE: 739146, COUNTRY: SINGAPORE  
Police Station Contact TEL NO: - FAX NO:  
Was notice of Intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

REFER TO ATTACHMENT

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBK351E  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category MOTORCYCLE  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage

Number (Including Driver)

Immediate Age  
Injuries Sustained  
Injured person in vehicle  
Were seat belts worn  
Was the driver licensed

# Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to sparking the traffic police.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insured or the insured's company.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the CUA Roadside Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copy of this report will for a fee be made available to interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the storing of this report in the system and the report of the report being made available stored.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may use and submit to others, may disclose and/or process my personal data/personal information (set out in this Form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and/or submit my Personal Information to all insurers who have insured vehicles involved in the accident (collectively the "Insurers") and to the Monetary Authority of Singapore and any relevant government institutions such as the Police for the purposes of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claim;
  - (iii) carrying out and/or dealing with my instructions or liaising to my employees by me;
  - (iv) administering my claims (including the making of correspondence, statements, notices, reports, etc.) which could involve disclosure of certain personal data about me to bring about delivery of the claim as well as written external cover of envelope/mail packages; and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurers who have insured vehicles involved in this accident and the insurers' lawyers, law firms, may use and submit to others, may disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their own party and/or third party agents including their lawyers, law firms, which may be sent outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will/can be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared/disclosed:
  - (i) to all insurers and/or any other third parties that assist in its handling, managing, controlling or handling of claims;
  - (ii) regulators, law enforcement and government agencies as requested for the purposes stated; and
  - (iii) for complying with requirements under any regulatory laws or court order.

Policyholder's Signature  
Date & Time

Driver's Signature  
(if driver is not the policyholder)  
Date & Time

Insurers' Centre for Roadside Management  
Date  
Signature



Figure 1. The effect of the concentration of the *Agrobacterium* suspension on the transformation efficiency of *Agrobacterium* strains.

2 FR35/C

REFER TO POLICE REPORT

6/20/2009



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin  
Woodlands West N P C  
9 Marsiling Lane SINGAPORE 739146  
Tel No: 1800-363 9999



1205/1025/12095

1.48.3

Report No: 1205/1025/12095

15/2018/0122/0151

FBA 5516

**REPORT OF A TRAFFIC ACCIDENT**

|                                            |            |                                                                       |                             |                         |
|--------------------------------------------|------------|-----------------------------------------------------------------------|-----------------------------|-------------------------|
| Date/Time Report Made:<br>12/02/2018 09:56 |            | Vide Report No.                                                       |                             | Station Diary No.<br>19 |
| <b>Informant's Particulars</b>             |            |                                                                       |                             |                         |
| Name of Informant<br>FANG KWI FONG         |            | Address:<br>APT BLK 213 MARSILING CRESCENT #13-69 SINGAPORE<br>730213 |                             |                         |
| ID Type / ID No.:<br>NRIC NO / S2113698J   |            | Contact No.:<br>Home/Office:                                          |                             | Mobile: 83123163        |
| Nationality<br>SINGAPORE CITIZEN           |            | Email:                                                                |                             |                         |
| Sex:<br>Male                               | Age:<br>68 | Date of Birth:<br>07/07/1949                                          | Type of Informant:<br>Rider |                         |
| Race:<br>Chinese                           |            | Language:<br>English                                                  | Institution / School Name:  |                         |
| Occupation:<br>CLEANER                     |            | Driving Licence Information:<br>Class: 2B, 2A, 2, 3, 4                |                             | Date of Expiry:         |

**General Information of the Accident**

|                                                                             |                              |                                    |                                            |                                      |
|-----------------------------------------------------------------------------|------------------------------|------------------------------------|--------------------------------------------|--------------------------------------|
| Type of Accident:                                                           | Injury Conveyed By Ambulance | Drink Driver:<br>No                | Date/Time of Accident:<br>22/01/2018 15:30 | Type of Location:<br>Straight Road   |
| Location:<br>Along Road 1<br>PAN ISLAND EXPRESSWAY<br>TOWARDS KJE           |                              |                                    |                                            |                                      |
| Weather:<br>Clear                                                           |                              | Road Surface:<br>Dry               | Road Speed Limit:                          |                                      |
| Traffic Flow:                                                               |                              | Traffic Control:<br>Not Controlled | Traffic Volume:<br>Moderate                |                                      |
| Type of Collision:<br>Between Moving Vehicles - Side Swipe - Same Direction |                              |                                    |                                            | Anyone conveyed by ambulance:<br>Yes |

**Details of Vehicle Involved**

| Vehicle No | Type       | Make  | Model          | Color | Condition | No of Passenger |
|------------|------------|-------|----------------|-------|-----------|-----------------|
| FBA1071J   | Motorcycle | HONDA | WAVE 125R<br>A | Red   |           | 0               |

**Details of Vehicle Insurance**


| Vehicle No | Insurance Company                          | Insurance No | Effective  | Expiry Date |
|------------|--------------------------------------------|--------------|------------|-------------|
| FBA1071J   | NTUC Income Insurance Co-Operative Limited | 5090251170   | 20/04/2017 | 19/04/2019  |



## Sketch Plan #4



**SINGAPORE  
POLICE FORCE**



T 201802120030

Police Station Of Origin  
Woodlands West N.P.C  
9 Marsiling Lane SINGAPORE 739146  
Tel No: 1800-363 9999

Page 3

Report No: T201802120030

## CONTINUATION OF REPORT

|                                   |                              |                                        |                                               |
|-----------------------------------|------------------------------|----------------------------------------|-----------------------------------------------|
| <b>Details of Person Involved</b> |                              |                                        |                                               |
| Any Pedestrian Involved: No       |                              |                                        |                                               |
| No. of Pedestrians Injured: NIL   |                              | Use of Pedestrian Crossing: NA         |                                               |
| <b>Rider</b>                      |                              |                                        |                                               |
| Name                              | FANG KWI FONG                | ID No.                                 | S2113698J                                     |
| Related Vehicle                   | FBA1071J (Motorcycle)        | Contact No.                            | 63123163                                      |
| Hospital/Clinic                   | NATIONAL UNIVERSITY HOSPITAL | Class of Driving Licence & Expiry Date | Class: 2B, 2A, 2, 3, 4<br>Date of Expiry: NIL |
| Date Treatment                    | 22/01/2018                   | Date Discharge                         | 09/02/2018                                    |
| No. of Days granted Medical Leave | 63                           | Degree of Injury                       | Slight                                        |


**Brief Details.**

On 22 January 2018 at about 1532hrs, I was riding my motorcycle along Pan Island Expressway (PIE) towards Kranji Expressway (KJE) at the third lane. While I was riding, a motorcycle suddenly side swiped me on my right. Both motorcycles lost balance and I fell off my motorcycle. I was badly injured and could not remember what happened next. I was then conveyed to National University Hospital in a conscious state however I could not move my body. I was discharged from the hospital on 09 February 2018 and I was given hospitalization leave for a period of 63 days from 22 January 2018 to 25 March 2018.



SINGAPORE  
POLICE FORCE

Police Station Of Origin:  
Woodlands West N.P.C  
9 Marsiling Lane SINGAPORE 730143  
Tel No: 1800-363 9999



T/201802122030

2 of 2

Report No: T/201802122030

## CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report.

J /

Staff Sgt SITI AISYAH BINTE AIDIL

Signature Of Interpreter:  
Not applicableOfficer In Charge Of Case  
TP / GIT /  
Sgt 2 MARIAH BINTE ZAKARIA  
Contact No: 65476433Authentication Stamp  
HP103

Signature Of Informant.

Date/Time:  
12/02/2018 09:56

Classification Of Case



Vehicle No: FBA 1071J

[illegible]

### Assessor:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

| CLAIM SUBFOLDER TRACKING |                                         |               |                                                   |                                                  |                                            |            |                                                                 |
|--------------------------|-----------------------------------------|---------------|---------------------------------------------------|--------------------------------------------------|--------------------------------------------|------------|-----------------------------------------------------------------|
| Case                     | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt                                          | Adj Submitted                              | Ins Auth'd | Status                                                          |
| Main                     | 13 Feb 2018<br><a href="#">Edit Reg</a> |               | 28 Feb 2018 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

|             |                  |                      |                  |                          |
|-------------|------------------|----------------------|------------------|--------------------------|
| <b>Main</b> | <b>Reference</b> | <b>Claim Details</b> | <b>Documents</b> | <a href="#">Show All</a> |
|-------------|------------------|----------------------|------------------|--------------------------|

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

|                             |                                                                                                                                  |                        |                                                                               |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------|------------------------|-------------------------------------------------------------------------------|
| Insured:                    | <b>Heryawan Bin Kamis</b> , Co. Reg. No.: -                                                                                      |                        |                                                                               |
| Main Claimant:              | -                                                                                                                                |                        |                                                                               |
| Vehicle Reg. No.:           | <b>FBA1071J</b>                                                                                                                  | Date of Loss:          | 22/01/2018 00:00 - :59<br>[143 Months and 19 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | <b>TP / 1226760585SG</b>                                                                                                         | Policy/Cover Note No.: | 2100403569 (Comprehensive)                                                    |
| Vehicle Reg. No. (Insured): | <b>FBK351E</b>                                                                                                                   | Policy No. (Claimant): |                                                                               |
|                             |                                                                                                                                  | Excess:                |                                                                               |
| Repairer:                   | <b>Eng Soon Painting Svc (HQ)</b> BLK 4 YEW TEE IND EST 393J WOODLANDS ROAD, 677969 Woodlands - Tel:                             |                        |                                                                               |
| Handling Insurer:           | <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Kang, Sam-PL</b> ] Sam.Kang@aig.com |                        |                                                                               |
| Adjuster:                   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 13/04/2018] |                        |                                                                               |
| Claimant's Solicitor:       | <b>BONNIE KWOK LLC</b> - Tel: 65366026                                                                                           |                        |                                                                               |

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- AIG\_SG (05/04/2018): TP GIA REPORT

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## Claim Documents

\*FBA1071J (1226760585SG)

[FBK351E]

TP

Jan 22 2018 12:00AM

[Heryawan Bin Kamis]

Eng Soon Painting Svc

|                    |                 |                                                                                 |               |  |  |                    |  |  |              |  |  |              |  |           |            |                                     |                          |                                     |
|--------------------|-----------------|---------------------------------------------------------------------------------|---------------|--|--|--------------------|--|--|--------------|--|--|--------------|--|-----------|------------|-------------------------------------|--------------------------|-------------------------------------|
| Upload Documents   |                 |                                                                                 | Upload Photos |  |  | Compose New Letter |  |  | Upload Video |  |  | Upload Audio |  |           | View       |                                     | View in Browser          |                                     |
| Assessment Reports |                 |                                                                                 |               |  |  |                    |  |  |              |  |  |              |  |           | 1 per page |                                     | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| No                 | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG)                                       |               |  |  |                    |  |  |              |  |  |              |  | Thumbnail |            | Print                               |                          |                                     |
| 1                  | 05/04/18 17:08  | Accident Statement<br>From: SC - Reg. No: FBK351E, Claimant: HERYAWAN BIN KAMIS |               |  |  |                    |  |  |              |  |  |              |  |           | Load HTM   |                                     |                          |                                     |
|                    |                 |                                                                                 |               |  |  |                    |  |  |              |  |  |              |  |           | 3 per page |                                     | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| No                 | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                                               |               |  |  |                    |  |  |              |  |  |              |  | Thumbnail |            | Print                               |                          |                                     |
| 1                  | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 2                  | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 3                  | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 4                  | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 5                  | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 6                  | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 7                  | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 8                  | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 9                  | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 10                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 11                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 12                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 13                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 14                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 15                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 16                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 17                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 18                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 19                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 20                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 21                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 22                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 23                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 24                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 25                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 26                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 27                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 28                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 29                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 30                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 31                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 32                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |
| 33                 | 04/04/18 09:48  | General View                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                          |                                     |



| Assessment Reports |                |                                           | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|--------------------|----------------|-------------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On   | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail                                                                                      | Print                               |
| 34                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 35                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 36                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 37                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 38                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 39                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 40                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 41                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 42                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 43                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 44                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 45                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 46                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 47                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 48                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 49                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 50                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 51                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 52                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 53                 | 04/04/18 09:48 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 54                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 55                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 56                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 57                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 58                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 59                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 60                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 61                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 62                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 63                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 64                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 65                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 66                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 67                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 68                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 69                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 70                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 71                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 72                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 73                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 74                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 75                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 76                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 77                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 78                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 79                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 80                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 81                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 82                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 83                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports |                |                                           | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|--------------------|----------------|-------------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On   | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail                                                                                      | Print                               |
| 84                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 85                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 86                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 87                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 88                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 89                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 90                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 91                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 92                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 93                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 94                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 95                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 96                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 97                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 98                 | 20/04/18 10:37 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 99                 | 20/04/18 10:38 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 100                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 101                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 102                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 103                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 104                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 105                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 106                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG  | <input checked="" type="checkbox"/> |
| 107                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 108                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 109                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 110                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 111                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 112                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 113                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 114                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 115                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 116                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 117                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 118                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 119                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 120                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 121                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 122                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 123                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 124                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 125                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 126                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 127                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 128                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 129                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 130                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 131                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 132                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 133                | 20/04/18 10:38 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |

## Documents Checklist

| DOCUMENTS CHECKLIST                                                           | Reset | Save | Print |
|-------------------------------------------------------------------------------|-------|------|-------|
| There are no document checklists configured.                                  |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>              |       |      |       |
| <div></div>                                                                   |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer             |       |      |       |
| <small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

## LKK Auto Consultants Pte Ltd (Co.Reg.No.199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18004000/GD3E2

Date: 23/04/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100403569  
 Claimant Vehicle No : FBA1071J Insured Vehicle No : FBK351E  
 Date of Loss: 22/01/2018 Nature of Claim: TP Claim No: 1226760585SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FBA1071J  
 Make & Model: HONDA WAVE 125, 125cc Engine No: NF125PSE0002278  
 Reg. Date: 03/02/2006 (Man. Year: 2005) Chassis No: NF125PS0002278  
 Colour: Red Odometer: 12034 km  
 Engine Capacity: 125 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 70/90-17 Rear Tyre Size: 80/90-17  
 Front Left Side: IRC 4 mm Rear Left Side: IRC 4 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

## INSPECTION

Date of Assignment: 28/02/2018  
 Date Inspected: 01/03/2018 Inspected At: Eng Soon Painting Svc (HQ)  
 BLK 4 YEW TEE IND EST 393J  
 WOODLANDS ROAD  
 Singapore 677969

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars               | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------|-----------|------------|--------|
| 1   | 1   |          | *FRONT NUMBER PLATE       | Dented    | 0.00 F     | *- F   |
| 2   | 1   |          | *FRONT RIM                | Scratched | 0.00 F     | *- F   |
| 3   | 1   |          | *FRONT FENDER WHEEL GUARD | Cracked   | 0.00 F     | *- F   |
| 4   | 1   |          | *FRONT FORK ASSY          | Dented    | 0.00 F     | *- F   |
| 5   | 1   |          | *FRONT HEADLAMP           | Scratched | 0.00 F     | *- F   |
| 6   | 1   |          | *FRONT HEADLAMP FAIRING   | Broken    | 0.00 F     | *- F   |
| 7   | 1   |          | *FRONT WING MIRROR        | Broken    | 0.00 F     | *- F   |
| 8   | 1   |          | *ERP UNIT                 | Cut       | 0.00 F     | *- F   |
| 9   | 1   |          | *HANDLE BAR               | Dented    | 0.00 F     | *- F   |
| 10  | 1   |          | *HANDLE BAR SWITCH        | Necessary | 0.00 F     | *- F   |
| 11  | 1   |          | *HANDLE BAR GRIP          | Necessary | 0.00 F     | *- F   |
| 12  | 1   |          | *HANDLE BAR BALANCER LH   | Necessary | 0.00 F     | *- F   |
| 13  | 1   |          | *HANDLE BAR BALANCER RH   | Necessary | 0.00 F     | *- F   |
| 14  | 1   |          | *HAND BRAKE LEVER         | Broken    | 0.00 F     | *- F   |
| 15  | 1   |          | *SIDE FAIRING             | Cut       | 0.00 F     | *- F   |
| 16  | 1   |          | *FAIRING SHIELD           | Cut       | 0.00 F     | *- F   |
| 17  | 1   |          | *CENTER FAIRING           | Cut       | 0.00 F     | *- F   |
| 18  | 1   |          | *ENGINE GUARD             | Broken    | 0.00 F     | *- F   |
| 19  | 1   |          | *FRONT FOOT REST          | Damaged   | 0.00 F     | *- F   |
| 20  | 1   |          | *KICK STARTER RUBBER      | Necessary | 0.00 F     | *- F   |
| 21  | 1   |          | *KICK STARTER LEVER       | Damaged   | 0.00 F     | *- F   |
| 22  | 1   |          | *REAR FOOT REST           | Damaged   | 0.00 F     | *- F   |
| 23  | 1   |          | *REAR FOOT REST BRACKET   | Broken    | 0.00 F     | *- F   |
| 24  | 1   |          | *EXHAUST MUFFLER ASSY     | Damaged   | 0.00 F     | *- F   |
| 25  | 1   |          | *REAR BOX                 | Damaged   | 0.00 F     | *- F   |

F=Franchise part.

|                          |             |             |
|--------------------------|-------------|-------------|
| <b>Total Parts (S\$)</b> | <b>0.00</b> | <b>0.00</b> |
|--------------------------|-------------|-------------|

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >