

ASS. REC. BY:

REF: CS3/MSG18004007/Gd302

Special Instruction:

Surveyor: Manmen

ASSIGNMENT (Office)

From (Person): Linnet Tan

of MS/G

Date/Time: 11/3/18 @ 2:45pm

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SF101K Insured: FBG 8651 H

at Workshop m/s: Kent Seng Car Tel: G 7588367

of Blk 1017, Yishun Ind. Prk A # 01-240

Policy No: MSD/VMS/17-374986-CA Claim No: MSC/V/18-000310

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 26/2/18

(Client's Record) _____

CA / REV / REP. / REV 24 HRS lwp 2/3/18 H.O.D. Endorsement: _____

Date/Time: 1:30pm 01/3/18 Person Contacted: Mr. Toh Vehicle: IN / OUT

Date/Time	Action/Instruction (L) Estimate
	SF101K-X
	Dismantle: 5/3/2018
	After repair: 12/3/2018

PRS xbl

MSIG

ASSIGNMENT

From _____ Date 2/3/18

Estimated Cost: _____

① TP WS / TP RES / OD RES / EVA / INV / MV

To Inspection No: SF 101K

at Workshop No: Kent Seng Car

of: Blk 1017, Yishun Ind-Park A #01-240

Insured: _____


Policy No: _____

Claims No: _____

Sub-Insured: _____ Excess: _____

Claims Record: _____

Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Ball or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / RP Seen: _____ Consistent? : Yes or No

Est. Repairs _____ days Rear: Yes or No

Lift Sum _____ \$ 3 Val: Yes or No

CA / REV / REP. / 24 HRS lwp

Date _____ Person Contacted: _____

Vehicle IN / OUT

Make: SF101K Reg No: Nov 17

Type: Truck Trailer NX200T

Make: Toyota Lexus Year: 1998

Colour: white

Bo. Reading: 4480

Eng No: _____

C/Vo: JTHBAIBL20A006099

Gen. Cond: 0 Gen. Paint: 0 Gen. Burnt: 0

Steering In: 0 Gen. Jammed: 0 Leaked: 0 Burnt: 0

Brake In: 0 Gen. Jammed: 0 Leaked: 0 Burnt: 0

Mod: NI / S/R STZ: 0 Unit: 0

Tyre Size: 225/50R17

R: 11

③ DUN / EXNOVA / GY / RS / LIZA / MIC / HTSL / PIR / SUM

TOYO / YOKO of: _____

Front:		Rear:	
RUBa:	<u>8</u>	RIBa:	<u>8</u>
LBa:	<u>8</u>	LBa:	<u>8</u>
COA:		CO:	<u>02-03-18</u>

Survey held at: w/s 5:30pm

Des of Damages: Front Rear OS NS UO Roof/hood

N/S Rear

The UO / Chassis/frame / Body Structure affected parts of: _____

* Repair Estimate : S\$ 7500 - 8500

* 5 days

f/c Submit PRS report.

RECEIVED 07 MAY 2018

Date The File Pass: Prel. Report Final Report

Days Of Repair: _____

Resurvey No. of This: 2

Add Fee: Site Ins: \$ _____

Heavy: \$ _____

Tech: \$ _____

Resurvey: \$ _____

Record Format: PRS

Signature: _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Mar 2018		01 Mar 2018 14:45 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	RAJENDRAN SOCRATES, ID: S7667094C, Tel: +6590835160		
Main Claimant:	TAN CHENG LONG, ID: S1262046B		
Vehicle Reg. No.:	SF101K	Date of Loss:	26/02/2018 18:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMS/17-374986-CA (TP, Fire & Theft) Coverage: 24/12/2017 - 23/12/2018
Vehicle Reg. No. (Insured):	FBG8651H	Policy No. (Claimant):	
		Excess:	
Repairer:	Kent Seng Car Service () Blk 1017 Yishun Industrial Park A, #01-240, 768759 Yishun - Tel: 67588367		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 02/03/2018]		
Driver/Custodian (Insured):	RAJENDRAN SOCRATES (41 / Male), NRIC: S7667094C, Tel: +6590835160		
Adj Asg. Remarks:	Please contact the workshop directly @ 6758 8367 to arrange for survey .		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SF101K		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	LEXUS GS200T EXECUTIVE		
Chassis No. :	JTHBA1BL20A006099		
Propellant :	Petrol		
Engine No. :	8ARZ094040		
Engine Capacity :	1998 cc		
Maximum Power Output :	180.0 kW (241 bhp)		
Maximum Laden Weight :	2170 kg		
Unladen Weight :	1665 kg		
Year Of Manufacture :	2017		
Original Registration Date :	14 Nov 2017		
Lifespan Expiry Date :	-		
COE Category :	B - Car above 1600cc or 97kW (130bhp)		
Quota Premium :	\$57,414.00		
COE Expiry Date :	13 Nov 2027		
Road Tax Expiry Date :	13 Nov 2018		
PARF Eligibility Expiry Date :	13 Nov 2027		
Inspection Due Date :	13 Nov 2020		
Intended Transfer Date :	07 May 2018		
CO2 Emission :	186.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Additional Levy :			
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2046B
Vehicle Details	
Vehicle No.:	SF101K
Vehicle to be Exported:	No
Intended De-registration Date:	07 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS GS200T EXECUTIVE
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	8ARZ094040
Chassis No.:	JTHBA1BL20A006099
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$50,009.00
Original Registration Date:	14 Nov 2017
First Registration Date:	14 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$62,017.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Nov 2027
PARF Rebate Amount:	\$46,512.00
Intended COE Rebate Details	
COE Expiry Date:	13 Nov 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,414.00
COE Rebate Amount:	\$54,638.00
Total Rebate Amount:	\$101,150.00

The information contained herein is correct as at 07 May 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Mar 2018		01 Mar 2018 14:45 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	RAJENDRAN SOCRATES , ID: S7667094C, Tel: +6590835160								
Main Claimant:	TAN CHENG LONG , ID: S1262046B								
Vehicle Reg. No.:	SF101K	Date of Loss:	26/02/2018 18:00 - :59 [3 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-000310	Policy/Cover Note No.:	MSD/VMS/17-374986-CA (TP, Fire & Theft) Coverage: 24/12/2017 - 23/12/2018						
Vehicle Reg. No. (Insured):	FBG8651H	Policy No. (Claimant):							
		Excess:							
Repairer:	Kent Seng Car Service () Blk 1017 Yishun Industrial Park A, #01-240, 768759 Yishun - Tel: 67588367								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Imm.Advice due 02/03/2018]								
Driver/Custodian (Insured):	RAJENDRAN SOCRATES (41 / Male), NRIC: S7667094C, Tel: +6590835160								
Adj Asg. Remarks:	Please contact the workshop directly @ 6758 8367 to arrange for survey .								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SF101K (MSC/V/18-000310)
 [FBG8651H]
 TP
 TAN CHENG LONG
 Feb 26 2018 6:00PM
 [RAJENDRAN SOCRATES]
 Kent Seng Car Service

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Letters/Correspondences									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail		Print	
1	01/03/18 14:43	Non Reporting Letter to OI						Load HTM		
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
2	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
3	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
4	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
5	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
6	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
7	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
8	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
9	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
10	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
11	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
12	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
13	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
14	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
15	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
16	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
17	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
18	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
19	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
20	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
21	07/05/18 11:14	General View						Load JPG	<input checked="" type="checkbox"/>	
22	07/05/18 11:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
23	07/05/18 11:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
24	07/05/18 11:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
25	07/05/18 11:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
26	07/05/18 11:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
27	07/05/18 11:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
28	07/05/18 11:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
29	07/05/18 11:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
30	07/05/18 11:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
31	07/05/18 11:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
32	07/05/18 11:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
33	07/05/18 11:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
34	07/05/18 11:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	07/05/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	07/05/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	07/05/18 11:26	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
85	07/05/18 11:26	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
86	07/05/18 11:26	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
87	07/05/18 11:26	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/03/18 14:45	TPD SF101K - PRI	Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18004007/GD3E2

Date: 07/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMS/17-374986-CA
 Claimant Vehicle No: SF101K Insured Vehicle No: FBG8651H
 Date of Loss: 26/02/2018 Nature of Claim: TP Claim No: MSC/V/18-000310

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SF101K
 Make & Model: TOYOTA LEXUS, 2.5 ES250 AUTO (A) Engine No: 8ARZ094040
 Reg. Date: 14/11/2017 (Man. Year: 2017) Chassis No: JTHBA1BL20A006099
 Colour: White Odometer: 4480 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
 Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8 mm
 Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	0.00
Labour	0.00	0.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	0.00
Towing	0.00	0.00	0.00	0.00
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 01/03/2018
 Date Inspected: 02/03/2018 Inspected At: Kent Seng Car Service
 Blk 1017 Yishun Industrial Park A, #01-240
 Singapore 768759
 Estimated Period of Repair: 0.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,500.00 -\$8,500.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2018)
Parts: 143	TOYOTA LEXUS 2.5 ES250 AUTO (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SF101K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >