

ASS. REC. BY:

REF:

CS/FCI18004013/UH03/12

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Jasmine Yong

of

FCI

Date/Time:

24/1pm @ 01/03/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE6130T

Insured:

SHD70074

at Workshop m/s

Koon Hong Motor

Tel:

67487348

of

1 Kaki Bkt Ave 6 Bkt E #02-14

Policy No:

Claim No:

D18001728MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/02/2018

S/3/18 @ 3pm-4pm

CA / REV / REP. / REV 24 HRS

Wp!

H.O.D. Endorsement:

Date/Time:

4:23pm @ 1/3/18

Person Contacted:

Winnie

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

GBE6130T-x

SHD70074-CC4/LPC/6016605/H/ub3n2

D.O.A. 2/4/16

12/3/18-

Revert via email.

FCI

ASSIGNMENT

Date **5/3/18**
 Estimated Cost
 To inspect vehicle NO **GBE 6130T**
 at Worked on by **Koon Heng Motor**
 at **1 Kaki Bkt Ave 6, BKE #02-14**
 Insured
 Policy No **SI/ID 70074**
 Claims No
 Sum Insured
 Excess
 Claims Record **3pm - 4pm**
 Make of van

NS	OS

(Policy Condition)

Remark: The van had commenced its repair at the time of inspection.

Bel on Market Value
 IDAC Accident Report Consistent? Yes or No
 CA / PR Seen Consistent? Yes or No
 Est Repairs **2** days Rep Yes or No
 Lm Sum **2** \$ 3 Val Yes or No

CA / REV / REP / 24 HRS **1wp** **7051W**
 Date Person Contacted
 Vehicle IN / OUT

Ver No **GBE 6130T** Reg **1 16**
 Type Motor Vehicle
 Truck / Trailer
 Make **NISSAN** U1U91 **24ff**
 Colour **Silver**
 SO / Pasing **80/63**
 Eng No
 Ch No **JN1MC2E2620004517**
 Gen Cond Good / Fair / Poor / Burning
 Steering Locked / Jammed / Leaked / Burnt /
 Brake Locked / Jammed / Leaked / Burnt /
 Mod **NISSAN / STD A/R**
 Tyre Size **195 R15**
 BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PR / SUM
 TOYO / YOKO
 Front **6** Rear **6**
 R/Ba **6** L/Ba **6**
 D/OA **27/2/18** **5/3/18**
 Survey Report
 Des of Damages Frn Rear OS VS WD Root Cause
015 R.A.
 The U/C / Chassis Frame Body Structure affected due to

Date/Time **2/4/18** Action/Inspection **confined 2/5 @ 1250 with MR Tan.**
 (Red: 2011 95 : 617)

RECEIVED 04 APR 2018

Date/Time File Passed
4/4 Typist
 Date/Time File Returned
☒ Prel. Report
☒ Final Report

Days Of Repair **2**
 Resurvey No. of Trip **1**

Super Fee	130
Transport	50
	19
	199

Add Fee
 Report Format **TP**
 Count **0** **1250/-**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18004013/Utd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 7007U		Veh. Inspected	GBE 6130T
Policy No.			Coverage (\$)	0.00
Claim No.	D18001728MFSH		Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)		Assign Date	01/03/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	27/02/2018		Inspection Date
	Survey held at	KOON HENG MOTOR BLK 1 KAKI BUKIT AVE 6 #02-14 SINGAPORE 417883		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001728MFSH

Date: 12/3/2018

Our Ref: CS/FCI18004013/Utd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBE 6130T

Please be informed that we had conducted the inspection of the abovementioned vehicle on 5/3/2018 at the premises of M/s Koon Heng Motor, and have the following to report: -

Workshop Estimate Amount	: S\$ <u>3,261.95</u>
Revised Estimate Amount	: S\$ <u>1,589.03</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the o/s front.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Marcus

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	28-02-2018	Our Ref No. D18001728MFSH
Accident Date	27-02-2018	Claim Type. Third Party
Insured Vehicle	SHD7007U	Third Party Vehicle. GBE6130T
Survey Location	1 KAKI BUKIT AVE 6 BLK E, #02-14 (AUTO BAY @KAKI BUKIT)	
Contact Person.	MR TAN PENG KOON	
Contact No.	67487348/ 0	Fax No. 67432524
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KOON HENG MOTOR	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 12 March 2018 2:45 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001728MFSH/1
Attachments: PRELI ADVISED GBE 6130T.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **GBE 6130T**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 1 March 2018 4:27 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001728MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 1 March 2018 2:41 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001728MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	7051W
Vehicle Details	
Vehicle No.:	GBE6130T
Vehicle to be Exported:	No
Intended De-registration Date:	06 Mar 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	YD25385376A
Chassis No.:	JN1MC2E26Z0005517
Maximum Power Output:	-
Open Market Value:	\$22,153.00
Original Registration Date:	28 Jan 2016
First Registration Date:	28 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$1,108.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jan 2026
COE Category:	C - Goods Vehicle & Bus

COE Period(Years):	10
PQP Paid:	\$38,521.00
COE Rebate Amount:	\$30,392.00
Total Rebate Amount:	\$30,392.00

The information contained herein is correct as at 06 Mar 2018

OK



SOMPO

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place #06-01/06 Singapore Land Tower, Singapore 048673
Tel: 6461 6555 | Fax: 6221 3302 | Website: www.sompo.com.sg
Co. Reg No. 198905490T | GST Reg No. M200903196

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

- Cert No./Policy No. : D18MTPCVE000256
1. Registration No. : GBE6130T
2. Insured Name : MEGA COOL AIR-CONDITIONING & ELECTRICAL ENGINEERING
3. Commencement Date : 28 JANUARY 2018 00:00
4. Expiry Date : 27 JANUARY 2019 23:59
5. Coverage : Market value at time of loss - Comprehensive
6. Excess : \$500 - Section 1
7. Persons or Classes of Persons entitled to drive*
- b) Any person who is driving on the Insured's order or with their permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

8. Limitations as to use*

- 1) Use in connection with the Insured's business.
- 2) Use for the carriage of passengers (other than for hire or reward) in connection with the policyholder's business
- 3) Use for social, domestic or pleasure purposes.

The Policy does not cover

- 1) Use for hire or reward or racing, pacemaking, reliability trial or speed-testing.
- 2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

9. ExcelDrive Workshops & Accident Reporting

It is a condition precedent to liability that the Policyholder shall, together with the Motor Vehicle, call at the Company's Accident Reporting Center and report the accident within 24 hours of the accident or by the next working day thereof.

It is compulsory to have the accident repairs to the insured vehicle carried out at ExcelDrive Workshops, otherwise claim is not payable.

In an emergency and for directions to the Company's Accident Reporting Centers, please contact our Emergency Hotline : (65) 6461 6555

Visit www.sompo.com.sg for list of ExcelDrive Workshops and Accident Reporting Centers.

(We HEREBY CERTIFY that the policy to which this certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Sompo Insurance Singapore Pte. Ltd.

Date/Time of Issue : 08 JANUARY 2018 12:11

*Limitation rendered inoperative by section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189 and section 85 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

IMPORTANT NOTICE

1. Insureds are hereby warned that under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap.189), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of Insurance under the Act.
2. Insureds are further warned that on the sale of a motor vehicle or if for any reason the insurance is terminated during its currency, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap.189)
3. The Policy will cease to be valid once the motor vehicle has been sold to another person. It is not transferable to a new owner of the Vehicle.
4. Please note that this insurance is subject to the premium being paid and received in full by the Company (a) before the inception date where the Policy is to be issued to an individual; or (b) within the period specified in the Premium Payment Warranty applied to the Policy in all other instances.
5. Insurance coverage under this Policy is subject to the terms and conditions as stipulated in the Motor Insurance Policy

Intermediary Code & Name : 11G05800 & GREAT EASTERN FINANCIAL ADVISERS PTE LTD CI Code: 20D RPDH54KKFD16ZAA

KOON HENG MOTOR

(Reg. No: 24840700K)

BLK 1 KAKI BUKIT AVE 6 #02-14 (AUTO BAY @ KAKI BUKIT) SINGAPORE 417883

TEL: 67487348 FAX: 67432524

email: koonhengmotor@gmail.com

M/S **MS First Capital Insurance Ltd**
No. 36 Robinson Road
16-01 City House
Singapore 068877
Tel : 6507 3848

Estimation No : 27022018 / 6130

Type : TP
Date : 28/2/2018
A/C No : GBE6130T

Re: ESTIMATION ON REPAIR COST TO VEHICLE NO: GBE6130T

Make/ Model : Nissan Urvan NV350
Chassis No : JN1MCZE26Z0005517

Accident Date : 27/02/2018

PARTS REQUIRED

Description	Qty	U/Price (\$\$)	Amount (\$\$)
1 Front Bumper	1	514.70	514.70
2 Front Bumper Side Retainer (RH)	1	147.00	147.00
3 Front Bumper Side Clips	8	6.40	51.20
4 Front Head Lamp (RH)	1	403.00	403.00
5 Front Fog Lamp (RH)	1	311.80	311.80
6 Front Fog Lamp Cover (RH)	1	107.80	107.80
TOTAL			1,535.50
LESS DISCOUNT 10%			153.55
TOTAL SPARE PARTS			1,381.95

LABOUR CHARGES

7 TO KNOCK/REPAIR/WELDING OF DAMAGED PARTS.CHANGING OF ACCIDENT PARTS	800.00	300
8 TO SPRAY PAINT FOR AFFECTED AREAS	800.00	300
9 TO WIRING	80.00	20
10 TO UNDERCOAT	200.00	X
		1,880.00
GRAND TOTAL AMOUNT (PARTS & LABOUR)		3,261.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

not approved
LKK
take photo before repair.
2/2/18
5/3/18
2/5 4/250




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18004013/Utd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 7007U	Veh. Inspected	GBE 6130T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18001728MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	01/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV350 (M)	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JN1MC2E26Z0005517	Colour	SILVER	
Odometer	80163	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	OHTSU	6 mm	
L/H Front Tyre	195 R15	OHTSU	6 mm	
R/H Rear Tyre	195 R15	OHTSU	6 mm	
L/H Rear Tyre	195 R15	OHTSU	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/02/2018	Inspection Date	05/03/2018	
Survey held at	KOON HENG MOTOR BLK 1 KAKI BUKIT AVE 6 #02-14 SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 6130T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (N)	DENTED / DEFORMED	514.70	514.70
1	FRONT BUMPER SIDE RETAINER (RH)(N)	NOT NECESSARY	147.00	-
8	FRONT BUMPER SIDE CLIPS @\$6.40 (N)	NECESSARY	51.20	51.20
1	FRONT HEAD LAMP (RH)(N)	CRACKED	403.00	403.00
1	FRONT FOG LAMP (RH)(N)	NOT NECESSARY	311.80	-
1	FRONT FOG LAMP COVER (RH)(N)	CUT	107.80	107.80
	LESS 10% DISCOUNT		-153.55	-107.67
			1,381.95	969.03
<u>LABOUR</u>				
	TO KNOCK/REPAIR/WELDING OF DAMAGED PARTS, CHANGING OF ACCIDENT PARTS.		800.00	300.00
	TO SPRAY PAINT FOR AFFECTED AREAS.		800.00	300.00
	TO WIRING.		80.00	20.00
	TO UNDERCOAT.	NOT NECESSARY	200.00	-
			1,880.00	620.00
GRAND TOTAL			3,261.95	1,589.03
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,250.00

Report Ref No. CS/FC118004013/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.