

Surveyor

REF:

CC3 / ALH18004014 / Agbn2

ASSIGNMENT

25/08/08.

From: _____ Date: _____

Veh No: SJ702L Yr Regn: 2008 August

Estimated Cost: _____

Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: _____

Make: Audi A6 c.c. 1984

at Workshop m/s _____

Colour: Grey A/C: Insured / Std / NI / NA

of _____

Sp. Reading: 228841 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. 2100095774

C/No: WAN224F48N147045

Claims No. 403761142456

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: 800

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh: _____

Modi: Nil / (S/Rim) / STD A/Rim or

(Policy Condition)

Tyre Size: F: 245/45R17

R: 245/45R17

Remark: The veh had commenced its repair at the time of inspection.

/	
N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA (MIC) / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value: 26.5

Front Rear

IDAC Accident Rpt: _____ Consistent? : Yes or No

R/Bal. 06 mm

GIA / PR Seen: _____ Consistent? : Yes or No

L/Bal. 06 mm

Est. Repairs: _____ days Res.: Yes or No

D.O.A. _____ D.O.I. 01/03/18

Lum Sum: _____ % 3 Val: Yes or No

Survey held at Premium

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

02/3/18 @ 10.47am ODALG. Total Loss.
revert to PRISCILLA SIM via Alanien (I/L).

MV: 26.5K
RV: 22.8K
Nett: 3.7K.

02/3/18 SJ702L - CC3 / ALH18008188 / Agbn2 EXA: 260416
Submit Unconventional Total Loss Report.

RECEIVED 07 MAR 2018

Date/Time, File Pass to? : Preli. Report

Days Of Repair: _____

11/02/13 hnpssr : Final Report

Resurvey No. of Trip: _____

Survey Fee: _____

Date/Time, File Return to? _____

Transportation: 200

2)

Add Fee: : Site Insp (\$) S + RS \$

Report Format : MER-TL-U

: Interview (\$) Photos

Lump Sum / I.B.I: (\$)

: Tech. Invs (\$) Others

: Weekend (\$)

TOTAL

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18004014/Aqb	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 01-03-2018	
		Code : AIG	
1. Policy Particulars :- OWN DAMAGE			
	Insured Veh.	Veh. Inspected	SJJ 702L
	Policy No. 2100095224	Coverage (\$)	0.00
	Claim No.	Excess (\$)	0.00
	Assign From	Assign Date	01/03/2018
2. Vehicle Particulars & Condition			
	Make & Model	c.c	0
	Engine No. HIDDEN	Year of Reg.	
	Chassis No.	Colour	
	Odometer -	Steering	
	Brakes	Modification	
	General		
3. Conditions of Tyres			
		Size	Make
	R/H Front Tyre		Balance
	L/H Front Tyre		mm
	R/H Rear Tyre		mm
	L/H Rear Tyre		mm
4. Description of Damages			
5. General Information			
	Accident Date 25/02/2018	Inspection Date	01/03/2018
	Survey held at PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

Survey Department Check List (Case Handler)

Reference No.: 023/REG18004014/Asp
 Policy Type: OD / TP / TP RES / TL / EVA

SSJ 702L

Case Handler

Typist

Admin (*Cath*): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
C	Customer Code	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
N	Assign From	<input type="checkbox"/>	<input type="checkbox"/>		
C	Assign Date	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
C	Veh No (Inspected)	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
C	Veh No (Insured)	<input type="checkbox"/>	<input type="checkbox"/>		
C	D.O.A	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
C	Policy No	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
C	Claim No	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
C	Insurance Authorisation (CA /REV/REP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
C	Report Type	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
C	Weekend Charges	<input type="checkbox"/>	<input type="checkbox"/>		
N	Survey held at/Repairer	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
C	Excess	<input checked="" type="checkbox"/>	<input type="checkbox"/>		

Surveyor (*Adrian*): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
C	Regn Month/Year	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
N	Vehicle Type	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
N	Make & Model	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
C	Engine Capacity. (C.C)	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
N	Colour	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
C	Odometer. (Sp.Reading)	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
C	Chassis No	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
N	General Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
N	Steering	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
N	Brake	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
N	Modification (Modi)	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
C	Tyre Size	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
N	Tyre Make	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
C	Tyre Balance	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
C	Date of Inspection	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
N	Survey held	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
N	Des.of Damages	<input checked="" type="checkbox"/>	<input type="checkbox"/>		

(2) System - (Views/Merimen)		Y-Date	N-Date	Y-Date	N-Date
C	Damaged Vehicle Photographs Uploaded	<input checked="" type="checkbox"/>	<input type="checkbox"/>		

(3) Workshop Estimate/Assignment Form		Y-Date	N-Date	Y-Date	N-Date
N	ALL Parts condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
C	Market Value for OD cases	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	<input type="checkbox"/>	<input type="checkbox"/>		
C	Days of repair	<input type="checkbox"/>	<input type="checkbox"/>		
C	Finalised Amount	<input type="checkbox"/>	<input type="checkbox"/>		
C	Re-inspection Cases to Finalize within 5 Days	<input type="checkbox"/>	<input type="checkbox"/>		

(4) System - (Views/Merimen)		Y-Date	N-Date	Y-Date	N-Date
C	Resurvey photo Uploaded	<input type="checkbox"/>	<input type="checkbox"/>		

Check By: *Adrian* 02/3/18
Case Handler Date

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 2 March 2018 10:48 AM
To: Sim, Priscilla-LK
Cc: SUR
Subject: VEHICLE SJJ 702L (DOA: 25/02/2018)

Dear Priscilla,

Please inform owner that the vehicle is not economical for repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 02 Mar 2018

Preliminary Advice

Vehicle No	: SJJ702L	Accident Date	: 25/02/2018
Make	: AUDI A6	Policy No.	: 2100095224-09
Assignment Date	: 01/03/2018	Excess	: S\$0.00
Date of Inspection	: 01/03/2018	Est. Duration of Repair	: 0.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion, undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,932.00 (\$9,900.00 + \$8,032.00)
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	26,500.00
COE / PARF Rebate	:S\$	22,762.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,738.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1252G
Vehicle Details	
Vehicle No.:	SJJ702L
Vehicle to be Exported:	Yes
Intended De-registration Date:	01 Mar 2018
Vehicle Make:	AUDI
Vehicle Model:	A6 2.0T FSI MU CVT ABS D/AIRBAG GAS/D
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	BPJ100336
Chassis No.:	WAUZZZ4F48N147045
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$44,196.00
Original Registration Date:	25 Aug 2008
First Registration Date:	25 Aug 2008
Transfer Count:	0
Actual ARF Paid:	\$44,196.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Aug 2018
PARF Rebate Amount:	\$22,098.00
Intended COE Rebate Details	
COE Expiry Date:	24 Aug 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$13,890.00
COE Rebate Amount:	\$664.00
Total Rebate Amount:	\$22,762.00

The information contained herein is correct as at 01 Mar 2018

OK

CHEAPEST CAR
INSURANCE RENEWAL



Free roadside assistance



Free claims support

GET A CHEAPER QUOTE NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Year Coe Renewal Honda Stream 1.8A RSZ



\$2800 Downpayment Monthly
From \$738 Onwards Lowest
3.65% AP Annual Car Financing
GV Credit Pte Ltd [View Ad](#)



Browse by Category ▾

Sort by Date Posted ▾ 20 results/page ▾

2 vehicles

audi a6

Advanced Search 🔍

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	audi a6		Any	Any	2008	Any	Any	Any	Available
	Audi A6 2.0A TFSI MU		\$28,600	\$10,050 /yr	24-Oct-2008	1,984 cc	-	Luxury	Available
	Cheapest In The Market! Non Negotiate, Beautiful Pearl White Paint, Careful And Particular Owner, Well Maintained, 100% Accident Free, Beautiful Beige Interior, Low Depreciation, Great Value, Original...								
	Posted: 22-Feb-2018 Tags: 2008 Audi A6, Audi A6, Audi, A6, Used Audi								
	Audi A6 2.0A TFSI MU		\$26,888	N.A	13-Aug-2008	1,984 cc	119,600 km	Luxury	Available
	Very Good Shape. Very Low Milage. No Accident But Little Bump On Left Bottom.								
	Posted: 21-Feb-2018 Tags: 2008 Audi A6, Audi A6, Audi, A6, Used Audi								

Save this search criteria, to get email alerts whenever a match is found.

Make: Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used audi a6, audi a6 Singapore, used audi a6 Singapore, used audi a6, used vehicles Singapore or even buy used audi a6 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare [3]

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/02/2018 11:22
Date Of Accident	25/02/2018 06:30
Exact Location Of Accident	54 RIVERINA CRESCENT SINGAPORE 518290
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJJ702L
Insured/Policyholder	
Name Of Registered Owner	TAPIS TEKNIK PTE LTD
Co Reg No	198501252G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67426996

Vehicle Particulars

Manufacturer	AUDI
Model	A6 2.0T FSI 4F208H
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100095224-09
Cover Note Number	

Driver

Name of Driver	KOK THOMAS JOHANNES GERARDUS
Passport No/FIN	G3101651M
Date Of Birth	29/11/1986
Occupation	INDOOR
Date Of Driving Pass	18/05/2015
Driving Experience	2 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93524296
Fax Number	
Contact Number	
EMail Address	THOMASKOK1233@GMAIL.COM

Address	104 ELIAS ROAD #04-77
Postcode	519957
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	PRE-DAWN
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

THE DRIVER OF THE OTHER VEHICLE WAS WAITING BESIDE MY CAR FOR SOMEONE TO WAKE UP AS THE ACCIDENT HAPPENED AT AROUND 630AM IN THE MORNING. HE MET MY MOM AND LEFT HIS NAMECARD WITH HIS. HIS CAR WAS ALSO DAMAGED AND HE CLAIMED THAT IT HAD TO BE TOWED AWAY.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV181P
Vehicle Make/Model/Colour	MERCEDES C180
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MAK POH FATT
NRIC/Passport Number	
Contact Number	93839889
Address	89 RIVERINA VIEW
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 26/4/16



Reporting Centre Personnel's Signature
Name: Tony Fong
NRIC/FIN No: G2040197X

Sketch Plan #2

SKETCH PLAN

←  Parked on 54 Riverina Crescent
and damaged by SKV 181P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The driver of the other vehicle was waiting beside my car for someone to wake up as the accident happened at around 630 am in the morning.
He hit my mirror and left his number and with me. His car was also damaged and he claimed that it had to be towed away.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time: 26/2/18


Reporting Centre Personnel's Signature
Name: Tony Hoang
NRIC/FIN No.: G2246197X

Accident Photo





EMPLOYMENT PASS
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer
TAPIS TEKNIK PTE. LTD.



Name
KOK THOMAS JOHANNES GERARDUS
Occupation
BUSINESS CONSULTANT

FIN
G3101651M

Date of Application
21-12-2017

Date of Issue
11-01-2018
Date of Expiry
29-03-2019



L8562745

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number **G3101651M**

Name
KOK THOMAS JOHANNES GERARDUS

Birth Date: **29 Nov 1986**

Issue Date: **18 May 2015**

Valid Till **17/05/2020**




002428592D



VISIT PASS

Immigration Regulations

Name
KOK THOMAS JOHANNES GERARDUS



Date of Birth	Sex	Nationality
29-11-1986	M	NETHERLANDS
FIN	Date of Issue	Date of Expiry
G3101651M	11-01-2018	29-03-2019


YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars =< 3000kg with =<7 passengers; exclusive 18 May 2015 of the driver; and other motor vehicles =< 2500kg



Licence No:G3101651M

NP 428A



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Tapis Teknik Pte Ltd
Period of Insurance : 25 Aug 2017 To 24 Aug 2018
Engine No. : BPJ100336
Chassis No. : WAUZZZ4F48N147045

Vehicle No. : SJJ702L
Policy No. : 2100095224-09
Endorsement No. :
Issued Date : 07 Aug 2017

ABOUT THE COVER

Make/Model : AUDI A6 2.0T FSI
Engine Capacity/Tonnage : 1,999.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2008
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

Any person who is driving on the Policyholder's order or with their permission. This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use (15 days)

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HONG LEONG FINANCE LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

ASPLUS

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Whitt/Summons/Correspondences from third party(ies) to AIG immediately.

15 DAYS LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your policy. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder of the CI.

The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to you.

Steps to activate Loss of Use Car Replacement Benefit and Important Information relating to the Benefit:

1. To activate your Loss of Use Car Replacement Benefit, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within 3 working hours after you contact the Rental Car Company.
3. At the time of collection of the Rental Car, the original Policy Schedule issued by AIG and a copy of the Accident Report from Audi Customer Service Centre must be produced to the Rental Car Company.
4. The number of days of loss of use entitlement is based on the period your vehicle is in the repair workshop subject to a maximum of 15 days.
5. Rental cars are strictly for use in Singapore only.
6. Any extension of use of rental car beyond the period approved by AIG's surveyor will be chargeable by the Rental Car Company on a per day basis and will not be covered under the Loss of Use Car Replacement Benefit but will be payable by you to the Rental Car Company directly.
7. Upgrade of Rental Car is available upon request subject to any additional charges by the Rental Car Company. Any costs relating to such upgrade will not be covered under the Loss of Use Car Replacement Benefit but will be payable by you to the Rental Car Company directly.
8. The rental car will be delivered to you (within Singapore), and YOU MUST RETURN IT TO Audi Customer Service Centre upon collection of your accident car.

Rental Car Company: Premium Automobiles Pte. Ltd.

Activation Hotline: 64741223

55 Ubi Road 1 Singapore 408699

Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 1pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 The AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: 6419 1993
Your Ref: **SJJ 0702 L**

Norah Khai
6768 9828
6841 1183

Nora.khai@premiumauto.com.sg

Body & Paint Dept
PA/OD/TL03/2018

26 February 2018

Dear Sir/Mdm,

RE: ACCIDENT INVOLVING VEHICLE NO: SJJ 0702 L
VEHICLE MODEL: AUDI A6 2.0T FSI
LOCATION: 54 RIVERINA CRESCENT SINGAPORE 518290
DOA: 25 FEBRUARY 2018.

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

We refer to the above-mentioned vehicle.

We have visually inspected the vehicle and would like to inform you that we have come to a conclusion that this vehicle is beyond economical repairs.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

The accident has caused intensive damages including unconfirmed items. The damages incur onto the frontal rhs and rhs undercarriage which estimated to be \$9,900. We estimated labour cost to be \$8,032 before any supplementary.

Kindly arrange for survey.

Kindly be informed that there will be possible additional damages not visible during inspection.

Thank you,



Norah Khai
Claims Manager

Akhian Lij
01/03/18


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

Total Loss

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Mar 2018 10:40		01 Mar 2018 17:45 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	TAPIS TEKNIK PTE LTD, Co. Reg. No.: 198501252G								
Vehicle Reg. No.:	SJJ702L	Date of Loss:	25/02/2018 06:00 - :59						
Claim Type:	OD / 4037611424SG	Policy/Cover Note No.:	2100095224-09 (Comprehensive)						
		Excess:	S\$800.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd-Rasheed, Rashidah - 64191767] Rashidah.Mohamedrasheed@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/03/2018]								
Driver/Custodian:	KOK THOMAS JOHANNES GERARDUS (31 / Male), NRIC: G3101651M, Tel: +6593524296								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG (05/03/2018): SJJ702L / OD / 25/02/2018 / Coverage & Excess update 									
<input type="checkbox"/> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJJ702L (4037611424SG)
OD
Feb 25 2018 6:30AM
[TAPIS TEKNIK PTE LTD]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <input type="checkbox"/> Use Viewer <input type="checkbox"/>	
Assessment Reports														1 per page <input type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	02/03/18 10:44	Adjuster Immediate Advice											Load HTM	<input type="checkbox"/>		
Photos/Images														3 per page <input type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
2	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
3	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
4	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
5	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
6	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
7	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
8	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
9	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
10	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
11	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
12	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
13	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
14	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
15	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
16	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
17	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
18	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
19	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
20	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
21	02/03/18 10:46	General View											Load JPG	<input type="checkbox"/>		
Documentation														1 per page <input type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	02/03/18 10:45	Singapore Accident Statement											Load PDF	<input type="checkbox"/>		
2	02/03/18 10:45	Log card (if available)											Load PDF	<input type="checkbox"/>		
3	02/03/18 10:45	Certificate of Insurance											Load PDF	<input type="checkbox"/>		
4	02/03/18 10:45	Drivers Driving License											Load PDF	<input type="checkbox"/>		
5	02/03/18 10:45	WORKSHOP LETTER											Load PDF	<input type="checkbox"/>		
6	05/03/18 15:08	INTERVIEW FORM											Load PDF	<input type="checkbox"/>		
7	05/03/18 15:08	UNDERTAKING FORM											Load PDF	<input type="checkbox"/>		

Linked Accident Report Documents

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <input type="checkbox"/> Use Viewer <input type="checkbox"/>	
Assessment Reports														1 per page <input type="checkbox"/>		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)										Thumbnail	Print			
1	26/02/18 17:15	Accident Statement											Load HTM	<input type="checkbox"/>		
Photos/Images														3 per page <input type="checkbox"/>		

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	26/02/18 11:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	26/02/18 11:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	26/02/18 11:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	26/02/18 11:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	26/02/18 11:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	26/02/18 11:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	26/02/18 11:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	26/02/18 11:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	26/02/18 11:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	26/02/18 11:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	26/02/18 11:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	26/02/18 11:51	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	26/02/18 11:51	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid gray; height: 40px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18004014/AQBN2

Date: 07/03/2018

REFERENCE

Insured/Claimant: TAPIS TEKNIK PTE LTD	Policy No: 2100095224-09	Claim No: 4037611424SG
Date of Loss: 25/02/2018	Nature of Claim: OD	

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJJ702L	Engine No: BPJ100336
Make & Model: AUDI A6, 2.0 TFSI (A)	Chassis No: WAUZZZ4F48N147045
Reg. Date: 25/08/2008 (Man. Year: 2008)	Odometer: 228841 km
Colour: Grey	
Engine Capacity: 1984 cc	
Market Value/New Car Price: S\$26,500.00	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/45 R17	Rear Tyre Size: 245/45 R17
Front Left Side: Michelin 6 mm	Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm	Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,932.00	0.00	17,932.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,932.00	0.00	17,932.00	100.00
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	17,132.00	-800.00	17,932.00	104.67
+ GST 7.00/7.00% (S\$)	1,199.24	-56.00	1,255.24	104.67
Nett Amount (S\$)	18,331.24	-856.00	19,187.24	104.67

INSPECTION

Date of Assignment: 01/03/2018

Date Inspected: 01/03/2018 **Inspected At:**

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 0.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$26,500.00
OMV :	\$44,196.00
PARF Rebate (1) :	\$22,098.00
Quota Premium Paid :	\$13,890.00
COE Rebate (2) :	\$ 664.00
Total Rebate (1) + (2) = :	\$22,762.00

The total amount incurred will be Market Value \$26,500.00 minus Total Rebate \$22,762.00 = \$3,738.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*THE ESTIMATE COST OF REPAIRS IS APPROXIMATELY			17,932.00 F *-F
						F=Franchise part.
					Total Parts (\$\$)	17,932.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >