





PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS3/AXA18004045/M1d3e2		
8 SHENTON WAY #24-01 AXA TOWER		Date: 19-04-2018		
SINGAPORE 068811		Code: AXA2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SKW 8761H	
Policy No.		Coverage (\$)	0.00	
Claim No.	C0471569	Excess (\$)	0.00	
Assign From	POON DANNY	Assign Date	01/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	RU11105652	Colour	WHITE	
Odometer	32593 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	DUNLOP	8 mm	
L/H Front Tyre	215/55 R17	DUNLOP	8 mm	
R/H Rear Tyre	215/55 R17	DUNLOP	8 mm	
L/H Rear Tyre	215/55 R17	DUNLOP	8 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE ROOF TOP PORTION.			
5. General Information				
Accident Date	23/02/2018	Inspect Date / Time	02/03/2018 (02:50 PM)	
Survey held at	BAK HENG MOTOR REPAIRING CO. BLOCK 5032 ANG MO KIO INDUSTRIAL PARK II, #01-291 SINGAPORE 569535			
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/AXA18004045/M1d3e2

Inspected By

MA CHIN FOOK

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.