

ASS. REC. BY:

REF: CS3/III 17022883 / SHB-1

Special Instruction:

ASSIGNMENT (Office)

From (Person): Sebastian Sunlari

of III

Date/Time: 01-03-2018

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FX 9261G Insured: SHA 2743B

at Workshop n/s Eng Soon Painting Services Tel: 6760 6721

of Blk 4 Yew Tee Ind. Est 393-J, 677998

Policy No: Claim No: MCT 17110951

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 27/11/2017

CA / REV / REP. / REV 24 HRS 'w/p' 1/12/17 @ Morning H.O.D. Endorsement:

Date/Time: 5:10pm @ 11/12/17 Person Contacted: Mr. Teo Vehicle: IN OUT


Date/Time	Action/Instruction ( X ) Estimate
	FX 9261G - CS/MSG17009828 / Grbo? - D.O.A : 22/05/2017
	SHA 2743B - C06/III 15022166 / Ph 3y2 D.O.A : 23/12/2015
	Dismantle Part : 06-12-2017
	Lump Sum \$1900 - (Red: 6100 : 76%)
	Submit. Scrap.

1413- File pass to typist

*[Signature]*  
(3/3/2018)

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OO (TP / WS / TP RES / OD RES / EVA / INV / MV)  
 To inspect Vehicle No: FX 9261 G  
 at Workshop no: Eng Soon  
 of: BK 4 Year Tree 393-J  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
Morning  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / FR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Receipts: \_\_\_\_\_ days Res: Yes or No  
 Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT



Job No: FX 9261 G Reg: 2004 Apr 03  
 Type: M/Car / N/Car / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer  
 Make: Honda CBR150R (M) cc: 150  
 Colour: Multi Colour A.C. Insured / Std / NI / NA  
 Sp Reading: 46008 T Radio: Insured / Std / NI / NA  
 Eng No: \_\_\_\_\_  
 C.No: NCB150G011519  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: NI / S/Rim / STD A/Rim or  
 Tyre Size: =: 90/80-17  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI  
 TOYO / YOKO or Dunlop  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: 6 mm R/Bal: 6 mm  
 L/Bal: \_\_\_\_\_ mm L/Bal: \_\_\_\_\_ mm  
 D.O.A: 4/11/17 D.O.I: 4/12/2017 @ 11:12am  
 Survey held at: Eng Soon  
 Des of Damages: FR / Rear / OS / NS / UIC / Rooftop or  
 The UIC / Chassis frame / Body Structure affected due to collision

Date: Time Action / Instruction  
4/12/2017 13:12 PRS  
No GIA / Estimate.

RECEIVED 13 DEC 2017

Date/Time File Pass to: 13-12-2017  : Preli. Report  
 : Final Report  
 Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Add Fee:  Site Inac \$ \_\_\_\_\_  
 Inter. \$ \_\_\_\_\_  
 Fuel \$ \_\_\_\_\_  
 Other \$ \_\_\_\_\_  
 Report Format: PRs  
 Lump Sum / B: \_\_\_\_\_  
 Survey Fee: \_\_\_\_\_  
 Transport: \_\_\_\_\_  
 \$-PR: \_\_\_\_\_  
 Fuel: \_\_\_\_\_  
 Other: \_\_\_\_\_



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III17022883/Stb-1

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Date : 02-03-2018



Code : III2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 2743B	Veh. Inspected	FX 9261G
Policy No.		Coverage (\$)	0.00
Claim No.	MCT17110951	Excess (\$)	0.00
Assign From	SUNDARI	Assign Date	01/03/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	27/11/2017	Inspection Date	02/03/2018
Survey held at	ENG SOON PAINTING SVC BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Catherine Chong (LKK Auto)

---

**From:** Sundari Nagarajan - III <sundari@iii.com.sg>  
**Sent:** Thursday, 1 March, 2018 10:32 AM  
**To:** Olivia Lau (olivialau@lkkauto.com)  
**Cc:** Pooi Chin Han Daniel; Joel Nah Shern Ern; Mekavathanan Sarangapani; 'assignments@lkkauto.com'; sur@lkkauto.com  
**Subject:** RE: OUr Ref : MCT17110951

Dear Olivia

LOD has been uploaded in merimen for paper survey for your doing the needful.

Best Regards,

**Sundari Nagarajan**  
DID: 63476071

---

**From:** Mekavathanan Sarangapani  
**Sent:** Saturday, 24 February, 2018 11:10 AM  
**To:** Olivia Lau (olivialau@lkkauto.com) <olivialau@lkkauto.com>  
**Cc:** Sundari Nagarajan - III <sundari@iii.com.sg>; Pooi Chin Han Daniel <danielpooi@iii.com.sg>; Joel Nah Shern Ern <JoelNah@iii.com.sg>  
**Subject:** OUr Ref : MCT17110951

Paper survey please IOD thru Bonnie Kwok

Meka

**CLAIM SUBFOLDER DETAILS**


Insured:	-, Co. Reg. No.: -		
Main Claimant:	ETHIRAJAN SATHISHKUMAR, ID: G8444936P		
Vehicle Reg. No.:	FX9261G	Date of Loss:	27
Claim Type:	TP / MCT17110951	Policy/Cover Note No.:	MC
Vehicle Reg. No. (Insured):	SHA2743B	Policy No. (Claimant):	
		Excess:	
Repairer:	Eng Soon Painting Services (HQ) <b>PROFILE</b> 393J WOODLANDS ROAD, 677978 Wo		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sunda		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Ye		
	22/12/2017]		

**CLAIM REGISTERED**

Clm. No (Clm Req Date)	MCT17110951 (11/01/2018)	Intimation (Notify Date)	F
------------------------	--------------------------	--------------------------	---







DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 24 NOV 2017 @ 2030 hrs. I

veh. A was driving along the tube use

CHIEF point. BY Butst paying Exit

veh A <sup>from</sup> she lane further to 3rd lane.

veh B hit veh A rear left. At the

of accident I veh A ferry ~~two~~ <sup>one</sup> person

she was ok. she pay me and walk and

the scene.

## VEHICLE DAMAGE INSPECTION REPORT

Our File No:  
Date:

**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd  
 Claimant Vehicle No : FX9261G  
 Date of Loss: 27/11/2017

Policy No:  
 Insured Vehicle No :  
 Nature of Claim:

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	FX9261G	
Make & Model:	HONDA CBR, 150cc 150M (M)	Engine Type
Reg. Date:	03/04/2004 (Man. Year: 2003)	Chassis
Colour:	Multi-colour	Odometer
Engine Capacity:	150 cc	
Market Value/New Car Price:	N/A	
Amount Insured (S\$):	<b>Market Value/New Car Price</b>	

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-acc

**CONDITION OF TYRES**

Front Tyre Size:	90/80-17	Rear Tyre Size:	
Front Left Side:	Dunlop 6 mm	Rear Left Side:	
Front Right Side:	0 mm	Rear Right Side:	

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's
Parts	0.00	0.00
Miscellaneous Items	0.00	0.00
Labour	0.00	0.00
Paintwork Labour	0.00	0.00
Drawing	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>

**INSPECTION**

Date of Assignment:	01/12/2017	Inspected At:	Eng Soon Painting Services
Date Inspected:	04/12/2017		

Best Regards,

Mekavathanan

HOD

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street, #04/#05 IOB Building, Singapore 049711

DID: 6347 6105 Fax: 6224 4174



Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

\*\*\*\*\*  
\*\*\* FAX TX REPORT \*\*\*  
\*\*\*\*\*

TRANSMISSION OK

JOB NO. 4038  
DESTINATION ADDRESS 965362279  
SUBADDRESS  
DESTINATION ID  
ST. TIME 26/02 09:34  
TX/RX TIME 00' 31  
PGS. 1  
RESULT OK

FAXED  
26 FEB 2018  
MOTCLM DEPT.

**BONNIE KWOK LLC**  
*Advocates & Solicitors*

101A Upper Cross Street  
#08-12 People's Park Centre  
Singapore 058358

Tel : (65) 6536 6026  
Fax : (65) 6536 2279  
(Not for service of court documents)  
GST Reg No. 2012035472



PC

Your Ref: SHA 2743 B  
Our Ref: BK.18404.18.sg

22 February 2018

M/s India International Insurance Pte Ltd  
64 Cecil Street  
#05-01 IOB Building  
Singapore 049711

We are in receipt of your letter, which is receiving our attention. We shall revert shortly. Kindly note that we are preserving our rights to conduct a medical re-examination on your client where necessary.  
By Hand  
Our Ref: MC7/17110951  
Name: *Supriya*  
Date: *23/2/2018*  
India International Insurance Pte Ltd

Dear Sirs

**ACCIDENT INVOLVING FX 9261 G & SHA 2743 B ON 27 NOVEMBER 2017**

We act for Ethirajan Sathishkumar, the owner of vehicle no. FX 9261 G in the above matter.

We are instructed that on the 27 November 2017, your insured driving vehicle no. SHA 2743 B had negligently collided into our client's said vehicle.

We are instructed that as a result of the said collision, our client has suffered loss and damage as follows: -

i.	Cost of Repairs	-\$	8,000.00
ii.	Loss of Use (20days x \$100.00)	-\$	2,000.00
iii.	Survey Report fees	-\$	700.00
iv.	LTA search fees	-\$	8.00
v.	GIA search fees	-\$	29.00
vi.	Transport, Postage, Xerox and other incidental	-\$	53.50
vii.	Costs	-\$	1,605.00
	<b>Total</b>		<b>\$ 12,395.50</b>

We enclose herewith a copy of the LTA search result, GIA report of our client and your insured, survey report and invoice, repair bill, the certificate of insurance and 76 original photographs for your

EX 9261 G

# BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street  
#08-12 People's Park Centre  
Singapore 058358

Tel : (65) 6536 6026  
Fax : (65) 6536 2279  
(Not for service of court documents)  
GST Reg No. 2012035472



PO

Your Ref: SHA 2743 B  
Our Ref: BK.18404.18.sg

22 February 2018

M/s India International Insurance Pte Ltd  
64 Cecil Street  
#05-01 IOB Building  
Singapore 049711

We are in receipt of your letter, which is receiving our attention. We shall revert shortly. Kindly note that we are preserving our rights to conduct a medical re-examination on your client where necessary.  
By Hand  
Our Ref: MCT/17110951  
Name: *Sund*  
Date: *23/2/2018*  
India International Insurance Pte Ltd

Dear Sirs

**ACCIDENT INVOLVING FX 9261 G & SHA 2743 B ON 27 NOVEMBER 2017**

23/2/2018

We act for Ethirajan Sathishkumar, the owner of vehicle no. FX 9261 G in the above matter.

We are instructed that on the 27 November 2017, your insured driving vehicle no. SHA 2743 B had negligently collided into our client's said vehicle.

We are instructed that as a result of the said collision, our client has suffered loss and damage as follows: -

i.	Cost of Repairs	-\$	8,000.00
ii.	Loss of Use (20days x \$100.00)	-\$	2,000.00
iii.	Survey Report fees	-\$	700.00
iv.	LTA search fees	-\$	8.00
v.	GIA search fees	-\$	29.00
vi.	Transport, Postage, Xerox and other incidental	-\$	53.50
vii.	Costs	-\$	1,605.00
	<b>Total</b>		<b>\$ 12,395.50</b>

We enclose herewith a copy of the LTA search result, GIA report of our client and your insured, survey report and invoice, repair bill, the certificate of insurance and 76 original photographs for your attention.

Kindly note that under the NIMA protocol, all requests for resurvey are required to be made during the protocol period in eight (8) weeks from receipt of this letter.

Kindly revert whether liability is admitted.

Yours faithfully

**BONNIE KWOK**

Enc. (by hand)

c.c. Client; and  
M/s Comfort Transportation Pte Ltd

**Enquire Vehicle & Owner Information ( Vehicle No. SHA2743B As At 27 Nov 2017 / 21:00:00 )****Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident  
Law Firm Case No.: ENGSOON-FX9261G

**Current Owner Details**

Owner ID Type: Company  
Owner ID: 199303821R  
Owner Name: COMFORT TRANSPORTATION PTE LTD  
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes  
Registered Block/House No.: 383  
Registered Street Name: SIN MING DRIVE  
Registered Unit No.: -  
Registered Building Name: GAS BUILDING  
Registered Postal Code: 575717

**Current Vehicle Details**

Vehicle No.: SHA2743B  
Make Description/Model: HYUNDAI / SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO  
Insurance Company Name: INDIA INT'L INS PTE LTD

Address 204 BEDOK SOUTH AVE 1  
 Postcode S469333  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured PAID DRIVER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

I WAS TRAVELLING ALONG BKE GOING TOWARDS SLE ON THE LEFT LANE, THERE WAS A TAXI WHICH WAS ON MY RIGHT THAT MAKE A SUDDEN LANE CHANGE INTO MY PATH CAUSED THE SAID DRIVER WANTED TO GET INTO EXIT 3, AS A RESULT, THE SAID TAXI HIT ONTO THE RIGHT SIDE OF MY VEHICLE DUE TO THE IMPACT. MY PILLION AND ME FELL ONTO THE LEFT SIDE. ATTENDED BY : SUSAN

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SHA2743B  
 Vehicle Make/Model/Colour COMFORT TAXI  
 Details Of Properties  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**Details of Witness**

Name FADHIL ; 91440754  
 Phone Number  
 Email Address





Vehicle Number : FX 9261 G

**SPARE PARTS**

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
<i>List Items</i>				
1 pc	Front windshield ✓ CWT	bent/distorted	\$ 102.80	\$ 102.80
1 pc	Headlamp cover ✓ CRK	bent/distorted	\$ 175.00	\$ 175.00
1 pc	Headlamp assy ✓ CRK	Broken	\$ 485.00	\$ <del>485.00</del> 185
1 pc	Front mudguard ✓ CWT	deformed	\$ 88.00	\$ 88.00
1 set	Side mirror assy ✓ SCR	grazed/deformed	\$ 120.00	\$ 120.00
1 pc	Crankshaft cover XNN	grazed/deformed	\$ 155.00	\$ <del>155.00</del>
1 pc	Main stand XNN	bent/distorted	\$ 128.00	\$ <del>128.00</del>
2 pcs	Front side cover ✓ CRK	grazed/deformed	\$ 388.00	\$ 388.00
1 pc	Seat assy XNN	grazed/deformed	\$ 255.00	\$ <del>255.00</del>
1 pc	Body frame assy R	bent - repair	\$ 1,400.00	\$ -
1 pc	Shift gear pedal ✓ BT	distorted	\$ 68.00	\$ 68.00
1 pc	Throttle handle R	distorted	\$ 68.00	\$ <del>68.00</del>
1 pc	Brake lever ✓ CWT	distorted	\$ 45.00	\$ 45.00
1 pc	Clutch lever ✓ CRK	distorted	\$ 45.00	\$ 45.00
1 pc	Exhaust manifold XNN	bent	\$ 352.00	\$ <del>352.00</del>
1 pc	Exhaust pipe ✓ CWT	bent	\$ 1,080.00	\$ 1,080.00 48
		Parts Sub-Total	\$ 4,954.80	\$ 3,554.80
	Discount	0.00%	\$ -	\$ -
			\$ 4,954.80	\$ 3,554.80


1696.80  
 -10%  
 -----  
 1527.12

**LABOUR COST**

S/No	JOB DESCRIPTIONS	Workshop Estimation (\$)	Our Revised Estimation (\$)
------	------------------	--------------------------	-----------------------------

	Spare Parts Total c/f	\$ 7,830.30	\$ 6,430.30
1	Labour charges to repair and panel beat body frame structure cutting/welding and replacing the above mentioned parts.	\$ 1,800.00	\$ 1,600.00 400
2	Transport	\$ 120.00	\$ 120.00 60
	To replace wiring harness system incl checking	\$ 200.00	\$ 180.00 30
4	To tuff coat affected areas	\$ 180.00	\$ 150.00 30
5	To respray affected areas	\$ 1,400.00	\$ 1,200.00 300
6	To remove & replace fuel tank incl drain	\$ 300.00	\$ 280.00 X
	Total	\$ 11,830.30	\$ 9,960.30

The repairer has agreed to undertake the repair under a Sum Basis. We have further adjusted the amount to Sum Repair of :

  
 Fong Kok Heng  
 Qualified Appraiser



\$ 8,000.00

840

Parts = \$ 1527.12  
 Labour = \$ 840.00

2367.12  
 Lump sum - 20%  
 1893.69

U/S = \$ 1900



**CA 481300**  
**MSIG Insurance (Singapore) Pte. Ltd.** (Incorporated in Singapore)  
 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807  
 Tel: +65 6827 7888, Fax: +65 6827 7800  
 www.msig.com.sg

**CERTIFICATE OF INSURANCE**

*For Motor Vehicles (Third Party Risks and Compensation) Act 1997 (Malaysia)*  
*For Motor Vehicles (Third Party Risks and Compensation) Act 1997 (Singapore)*  
*For Motor Vehicle (Third Party Risks and Compensation) Act 1997 (Singapore)*  
 \* For Non-Motor Vehicle Act or Act passed in substitution thereof

REGISTRATION NO : **YSU/WPT/17-160983-CA** / **A0074-001/11001**  
 INURBD : **PP**  
 BSK : **HL**

Index mark and Registration Number of Vehicle : **FA9261G** **150 c.c.**

Name of Policyholder : **HONDA**  
**ETHIRAJAN SATHISHKUMAR**

Effective date of the Commencement of Insurance for the purposes of the Act

Date of Expiry of Insurance : **1201AM** **03/04/2017**  
**02/04/2018**

Persons or Classes of Persons entitled to drive : **The Policyholder**

Noted that the person driving is permitted in accordance with the Licensing Act and regulations to drive the Motor Vehicle or has been so permitted by order of a Court of Law or by reason of any enactment in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered and licensed under the Road Traffic Act and its provisions and the accident loss or damage is not covered as it is not in accordance with the provisions of the Road Traffic Act.

Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession, the Policy does not cover

Use for hire or reward.

Use for racing, pace-making, reliability trial or speed-testing, use for the carriage of goods (other than samples) in connection with any trade or business.

Use for any purpose in connection with the Motor Trade, including the use of the Motor Vehicle for the purpose of the Motor Vehicle (Third-Party Risks and Compensation) Act 1997 (Singapore) and Section 95 of the Road Transport Act 1997 (Singapore) or may be included under these headings.

HEREBY CERTIFY that the Policyholder has read this Certificate and is satisfied in accordance with the provisions of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and the Road Transport Act (Chapter 189A).



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CS3/III17022883/Stbs2-1	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 14-03-2018	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 2743B	Veh. Inspected	FX 9261G
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT17110951	Excess (\$)	0.00
Assign From	SUNDARI	Assign Date	01/03/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA CBR 150R (M)	c.c	150
Engine No.	HIDDEN	Year of Reg.	2004
Chassis No.	NCB1500011519	Colour	MULTI COLOUR
Odometer	46008	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	90/80-17	DUNLOP	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	90/80-17	DUNLOP	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/11/2017	Inspection Date	04/12/2017
Survey held at	ENG SOON PAINTING SVC BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FX 9261G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT WINDSHIELD	CUT	102.80	102.80
1	HEADLAMP COVER	CRACKED	175.00	175.00
1	HEADLAMP ASSY	CRACKED	485.00	185.00
1	FRONT MUDGUARD	CUT	88.00	88.00
1	SET SIDE MIRROR ASSY	SCRATCHED	120.00	120.00
1	CRANKSHAFT COVER	NOT NECESSARY	155.00	-
1	MAIN STAND	NOT NECESSARY	128.00	-
2	FRONT SIDE COVER	CRACKED	388.00	388.00
1	SEAT ASSY	NOT NECESSARY	255.00	-
1	BODY FRAME ASSY	TO REPAIR SEE LABOUR	1,400.00	-
1	SHIFT GEAR PEDAL	BENT	68.00	68.00
1	THROTTLE HANDLE	TO REPAIR SEE LABOUR	68.00	-
1	BRAKE LEVER	CUT	45.00	45.00
1	CLUTCH LEVER	CRACKED	45.00	45.00
1	EXHAUST MAINFOLD	NOT NECESSARY	352.00	-
1	EXHAUST PIPE	CUT	1,080.00	480.00
	LESS 10% DISCOUNT		-	-169.68
			4,954.80	1,527.12
<b><u>LABOUR</u></b>				
	LABOUR CHARGES TO REPAIR AND PANEL BEAT BODY FRAME STRUCTURE CUTTING / WELDING AND REPLACING THE ABOVE METIONED PARTS. INCLUSIVE OF THE REPAIR OF BODY FRAME ASSY AND THROTTLE HANDLE.		1,800.00	400.00
	TRANSPORT.		120.00	60.00
	TO REPLACE WIRING HARNESS SYSTEM INCL CHECKING.		200.00	30.00
	TO TUFF COAT AFFECTED AREAS.		180.00	30.00
	TO RESPRAY AFFECTED AREAS.		1,400.00	300.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REPLACE FUEL TANK INCL DRAIN.	NOT NECESSARY	300.00	-
			4,000.00	820.00
<b>GRAND TOTAL</b>			<b>8,954.80</b>	<b>2,347.12</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,900.00</b>

Report Ref No. CS3/III17022883/Stbs2-1

**YEANG WAI KEEN**  
Automotive Assessor

**HO LEONG CHUAN**  
Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**