

ASS. REC. BY:

REF:

CS/SPF 18004058/Urbn2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Abdul Rahman of SPF Date/Time: 02032018

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLL 6017H Insured: QX 95Zat Workshop m/s Pegasus Tel: 6958 1846of 51 Defu Lane 10Policy No: _____ Claim No: ACMD/105/009/2018/020

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 27022018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

0703.2018

H.O.D. Endorsement: _____

Date/Time: 02032018 1025am Person Contacted: Alvin Vehicle ID: OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLL 6017H - X</u>
	<u>QX 95Z - X</u>

Surveyor: Morans REP: SPF

ASSIGNMENT

Date: 7/3/18

Estimated Cost:

OD: (P) WS / TP RES / OD RES / EVA / INV / MV

Trusted Vehicle No: SLL 6017H

at Worksite (ms): Pogasus

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

Claims Record:

Name of Ver:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NS	OS

Salvage/Wreck Value:

Accident Report: Consistent? Yes or No

PP Seen: Consistent? Yes or No

Est. Repairs: 4 1/2 days Res: Yes or No

Lim Sum: 1.3.1 is: 3 Val: Yes or No

CA / REV / REP / 24 HRS wp

Date: Person Contacted:

Vehicle IN / OUT

Date Time Action Instruction

Refury 7-3-18

2/3/18 Summary Lin/ly R 2507.60

Ref: 2691.52, 521.

SLL 6017H Page: 317

Truck Theat: CA /

Make: mercedes

Model: 3

Color: Black

Chassis: 66510

Engine:

Year:

VIN: JM6BN22A8H044802

Gen Cond: 2000 Fair Poor Burnt

Steering: OK Jammed / Leaked / Burnt

Brake: OK Jammed / Leaked / Burnt

Mod: MT S Rim STD A Rim

Tyre Size: 205/60R16

ES DUN / EXNOVA GY FS LIZA MID / OHTSL RIR SUM

TOYO / YOKO

Front:

R/Rs:

L/Rs:

D/OA:

Surveyed at:

Des of Damages: OK Res / OS / NS / UO / Roofed

OK Res

The UO Chassis frame Body Structure affected due to collision

RECEIVED 22 MAR 2018

Date Time File Pass No:

☐ Preli. Report
☒ Final Report

Days Of Repair: 4.5 day

Resurvey No. of Trip: 1

Survey Fee:

Transport Fee:

Other Fee:

Add Fee:

Storage: \$

Ref: \$

Ref: \$

Ref: \$

Report Format:

TP

Amount: \$

2507.60

280



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18004058/Urb

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE)
1 MOUNT PLEASANT ROAD
BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

Date : 02-03-2018



Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 95Z	Veh. Inspected	SLL 6017H
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/020	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	02/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	27/02/2018	Inspection Date	07/03/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref: SLL6017H

Our Ref: AEMD/105/009/2018/020

Date: 2 March 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir/Madam,

ACCIDENT ON 27 FEBRUARY 2018 INVOLVING POLICE VEHICLE QX95Z AND OTHER VEHICLE SLL6017H

We refer to the above matter.

- 2 Please arrange for a Pre-Repair Inspection of vehicle no. SLL6017H at M/s Pegasus Engrg & Tdg Pte Ltd of 51 Defu Lane 10, Singapore 539216.
- 3 For appointment kindly contact Wee Tze Fah at Tel: 68581846.
- 4 Estimates were provided by the workshop.
- 5 Thank you.

Yours faithfully,

Abdul Rahman
Accident Claims Officer
for ASST DIRECTOR

A FORCE FOR THE NATION

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLL6017H
Vehicle to be Exported:	No
Intended De-registration Date:	07 Mar 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	P520432144
Chassis No.:	JM6BN22A8H0144802
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,688.00
Original Registration Date:	02 Mar 2017
First Registration Date:	02 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$9,688.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Mar 2027
PARF Rebate Amount:	\$7,266.00
Intended COE Rebate Details	
COE Expiry Date:	01 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,401.00
COE Rebate Amount:	\$43,473.00
Total Rebate Amount:	\$50,739.00

The information contained herein is correct as at 07 Mar 2018

OK

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

Fax sent SPF AG
02/03/2018
at 0920

not Authorized

P/P 2507.60 7/3/18

From :
PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
539216
Officer in Charge : WEE TZE FAH
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960
Attn :
Tel :
Fax :
Teh...
4/2/18
Luk - Marcos
07/03/18 01/150

Quotation No : QO18/02-1201	Quotation Date : 28/02/2018	Terms : 30 DAYS
Vehicle No : SLL6017H	Chassis No : JM6BN22A8H0144802	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: SPF AG, INSURED'S VEH NO: QX95Z, DATE OF ACCIDENT: 27.02.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER	Deep 1 cur	1,075.0000	1,075.00 ✓
2	REAR BUMPER SIDE RETAINER MS 0/5	1 Set	92.0000	92.00 ✓
3	REAR BUMPER SIDE HOLDER MS 0/5	1 Set	46.0000	46.00 ✓
4	REAR BUMPER SIDE HOLDER RIVETS	4 11	9.1000	36.40 X
5	REAR LAMP MS 0/5	1 3/20	509.0000	509.00 ✓
6	REAR LAMP CLIP HOLDER	2 11	8.0000	16.00 X
7	REAR FENDER MS 0/5	1 11	1,175.0000	1,175.00 X
8	REAR FENDER AIR VENT	1 11	72.0000	72.00 X
9	REAR FENDER INNER LINER MS 0/5	1 11	146.0000	146.00 X
10	REAR FENDER INNER LINER CLIPS	4 11	5.0000	20.00 X
11	REAR WINDSHIELD GLASS WEATHERSTRIP	1 11	124.0000	124.00 X
12	LESS 20% (ITEM 1 - 11)	1	-662.2800	-662.28
13	REAR WINDSHIELD GLASS SEALANT	1 11	180.0000	180.00 X
14	REAR WINDSHIELD GLASS SPONGE SEAL	1 11	100.0000	100.00 X
15	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	900.0000	600 900.00
16	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	800.0000	400 800.00
17	TO REMOVE AND REFIT REAR WINDSHIELD GLASS	1	180.0000	11 180.00 X
18	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	120.0000	60 120.00
19	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	50 120.00
20	TO RUST-PROOFING OF THE AFFECTED AREAS	1	100.0000	11 100.00 X
21	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	50.0000	20 50.00

C/F 0.00

Page 1 of 2

P-1722
202
1377.60
2507.60



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/02-1201	Quotation Date : 28/02/2018	Terms : 30 DAYS
Vehicle No : SLL6017H	Chassis No : JM6BN22A8H0144802	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: SPF AG, INSURED'S VEH NO: QX95Z, DATE OF ACCIDENT: 27.02.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total	5,199.12
GST(7.00%)	363.94
Total (SGD)	5,563.06

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/02/2018 12:04
Date Of Accident	27/02/2018 20:15
Exact Location Of Accident	MCE EXIT INTO ECP EXPRESSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL6017H
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.5 SEDAN L SP.6EAT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	

Driver

Name of Driver	TAN SIEW PENG
NRIC No	S6808879H
Date Of Birth	01/04/1968
Occupation	OUTDOOR
Date Of Driving Pass	23/01/1995
Driving Experience	23 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-86800236
Fax Number	
Contact Number	
Email Address	JEFF_SPTAN@GMAIL.COM

Address	BLOCK 482 ADMIRALTY LINK #16-13
Postcode	750482
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	MARINE PARADE N.P.C
Police Station Address	ROAD: 300 MARINE PARADE ROAD , POSTCODE: 449296 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to police report T/20180227/2213

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX95Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	MR. PREM
NRIC/Passport Number	
Contact Number	91991065
Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 28/7/18 1120AM


Reporting Centre Personnel's Signature
Name: CARMEN DW
NRIC/FIN No.: 62859646X

SKETCH PLAN

A: SLE 6017 F1

B: Q x 957

Marina Coastal
Expressway Exit
to East Coast Park
Expressway



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report T/20180227/2213

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 28/2/18 11:20AM

Reporting Centre Personnel's Signature

Name: Cayman JW

Name: Laymon, C
NRIC/FIN No.: G2859646X



SINGAPORE POLICE FORCE



T/20180227/2213

1 of 3

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

Report No. T/20180227/2213

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/02/2018 22:48	Vide Report No.:	Station Diary No.: 88
--	------------------	--------------------------

Informant's Particulars

Name of Informant: TAN SIEW PENG			Address: APT BLK 482 ADMIRALTY LINK #16-13 SINGAPORE 750482		
ID Type / ID No.: NRIC NO / S6808879H			Contact No.: Home/Office: Mobile: 86800236		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 49	Date of Birth: 01/04/1968	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 27/02/2018 20:15	Type of Location: Bend
Location: Along Road 1 EAST COAST EXPRESSWAY				
Marina Coastal Expressway exit East Coast Park Expressway. Outside of the tunnel				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX95Z	Van				No Damage	0
SLL6017H	Car				Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180227/2213

2 of 3

Report No. T/20180227/2213

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

CONTINUATION OF REPORT

Driver			
Name	Prem Kumar Rai	ID No.	G5505368K
Related Vehicle	QX95Z (Van)	Contact No.	91991065
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAN SIEW PENG	ID No.	S6808879H
Related Vehicle	SLL6017H (Car)	Contact No.	86800236
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 27/02/2018, at around 2015hrs, I was driving along Marina Coastal Expressway towards East Coast Park Expressway, after exiting the tunnel and approaching ECP at around the bend, my vehicle's rear right end was hit by the front left of the Police Van.

There was no damage seen on the Police van, but my the right backlight cover of my vehicle was broken and there was severe scratches on the right rear end of my vehicle. No one was injured from the collision, however I am feeling discomfort on the back of my neck from the impact of the collision and I might be seeking medical treatment.



SINGAPORE
POLICE FORCE



T/20180227/2213

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

3 of 3

Report No. T/20180227/2213

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 JEREMY GOH ZEN KIAT

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / DDGVT /

SI CHEONG CHYUAN LIH KENNY

Contact No.: 65476224

Signature Of Informant:

Date/Time:

27/02/2018 22:48

Classification Of Case:

Authentication Stamp
NP158



SINGAPORE
POLICE FORCE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18004058/Urbn2

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE)

1 MOUNT PLEASANT ROAD

BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

Date : 23-03-2018



Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 95Z	Veh. Inspected	SLL 6017H
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/020	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	02/03/2018

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0144802	Colour	BLACK
Odometer	66510	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	27/02/2018	Inspection Date	07/03/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4.500 Working Days
-------------------------------------	--------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 6017H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEEP CUT	1,075.00	1,075.00
1	REAR BUMPER SIDE RETAINER O/S	BENT	92.00	92.00
1	REAR BUMPER SIDE HOLDER O/S	BENT	46.00	46.00
4	REAR BUMPER SIDE HOLDER RIVETS @\$9.10	NOT NECESSARY	36.40	-
1	REAR LAMP O/S	BROKEN	509.00	509.00
2	REAR LAMP CLIP HOLDER @\$8.00	NOT NECESSARY	16.00	-
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	1,175.00	-
1	REAR FENDER AIR VENT	NOT NECESSARY	72.00	-
1	REAR FENDER INNER LINER O/S	NOT NECESSARY	146.00	-
4	REAR FENDER INNER LINER CLIPS @\$5.00	NOT NECESSARY	20.00	-
1	REAR WINDSHIELD GLASS WEATHERSTRIP	NOT NECESSARY	124.00	-
	LESS 20% DISCOUNT		-662.28	-344.40
			2,649.12	1,377.60
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSHIELD GLASS SEALANT (SN)	NOT NECESSARY	180.00	-
1	REAR WINDSHIELD GLASS SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
			280.00	-
<u>LABOUR</u>				
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION.REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REAR FENDER O/S.		900.00	600.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		800.00	400.00
	TO REMOVE AND REFIT REAR WINDSHIELD GLASS.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMMINGS,GARNISH AND OTHER,TO ENABLE REPAIR.		120.00	60.00
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.00	50.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	100.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		50.00	20.00
			2,270.00	1,130.00
GRAND TOTAL			5,199.12	2,507.60

Report Ref No. CS/SPF18004058/Urbn2



RECOMMENDED COST OF REPAIRS			2,507.60
-----------------------------	--	--	----------

Report Ref No. CS/SPF18004058/Urbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.