COMFORTDELGRO ENGINEERING PTE LTD

ALG

DUM: 01.03.18

REPAIR ESTIMATE*

VEHILCE NO: SH 8536B

: TOYOTA MAKE

: PRIUS MODEL

Date: 01.03.2018

Qty	Parts Description / Labour	Type	Unit Price	Am	ount
1	REAR BUMPER × 19 No			3	458.60
1	REAR BUMPER UNDER SIDE CENTRE COVER	_	ı		552.60
10	REAR BUMPER CLIPS *				22.00
	SUB TOTAL	•		\$	1,033.20
	LESS 25%		1		514.60
	DISCOUNTED TOTAL	-		\$	518.60
1	REVERSE SENSOR X	ļ			135.70
				\$	135.70
	Labour Charge				100
1	Panel Beating			\$	200.00
1	Spray Painting Charge	ř		\$	200.00
1	Wiring Charge			\$	200:00 200:00 50:00
1	Remove/refix reverse sensor			\$	80.00
	TOTAL LABOU	R		\$	530.00
Laity	ESTIMATE TOTA	L		\$	1,184.30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum be prepared after the vehicle is surveyed by a motor Surveyor appoint the president of the prepared after the vehicle is surveyed by a motor Surveyor appoint the president of the prepared after the vehicle is surveyed by a motor Surveyor appoint the prepared after the vehicle is surveyed by a motor Surveyor appoint to the prepared after the vehicle is surveyed by a motor Surveyor appoint to the prepared after the vehicle is surveyed by a motor Surveyor appoint to the prepared after the vehicle is surveyed by a motor Surveyor appoint to the prepared after the vehicle is surveyed by a motor Surveyor appoint to the prepared after the vehicle is surveyed by a motor Surveyor appoint to the prepared after the vehicle is surveyed by a motor Surveyor appoint to the prepared after the vehicle is surveyed by a motor Surveyor appoint to the prepared after the vehicle is surveyed by a motor Surveyor appoint to the prepared after the prepared

Page 10

All Page 10

All Page 10

All Page 10

All Page 10

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to conformation.
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Compary

Acknowledged by Repairer

Signature:

Date: