S. REC. BY: Inveyor	Kenneth Angie FOD	CS C711800 ASSIGNME of C	11	Da	instruction: ste/Time: 2 3 18 0 4-07 pn
D TP WS /	TP RES / OD RES / I	SLW2	DOLLER -	Insured: _ Tel: _	SJF1166Z 62628888
of Policy No: Sum Insured:_	160 Sing 1	ling brive #1	06-02 Claim No: _ Excess: _	SNMI	8D00897C02/6
Make of Veh. (Client's Record) CA / REV / Date/Time:	REP. / REV 24 HR 5:11pm @ 2/3/18	S ^{lwp?} Person Contacted	Dann	06 03 18	H.O.D. Endorsement.
Date/Time	Action/Instruction (SJW 22 Z - SJF 11667 -	✓) Estimut	15		
	USp 84	Fod emoil	LS 6543	0 (Re	d \$ 10825.85, 67%

220

5450

Lump Sum / LP 0 13

0.01151150111111111	Affiliated to Federation Interna	tionale Des Experts En Autom	nobile
8 SHENTON WAY #2 AXA TOWERSINGAP		Date: 01-03-2018 Code: ASM	
	Policy Partic	ulars :- OWN DAMAGE	
Insured Veh.		Veh. Inspected	SGV 6825Z
Policy No.		Coverage (\$)	0.00
Claim No.	S8M009R9	Excess (\$)	0.00
Assign From	SMARTCLAIM (WINNIE HO)	Assign Date	01/03/2018
	Vehicle Par	ticulars & Condition	Mary Parkets May 1
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	5	Steering	
Brakes		Modification	
General			
	Cond	itions of Tyres	
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
	Descript	tion of Damages	dis a firm substitution and
A STANKE AND	Gener	al Information	
Accident Date	26/02/2018	Inspection Date	NICE CONSTRUCTION
Survey held at	SME MOTOR PTE LTD	- Processi Dute	
	1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUI SINGAPORE 417883	KIT)	
	Francisco de la Comp	Remarks	
THE REPAIRER W	ON WAS CONDUCTED ON A "W STIMATE WAS NOT PRESENTE VAS TOLD TO PREPARE THE ES EASE FIND DAMAGED VEHICL	D AT THE TIME OF INSPEC	S. TION.

** *, *

Nivitha (LKK Auto)

From:

Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Sent:

Friday, 2 March 2018 4:27 PM

To:

assignments

Subject:

FW: OUR REF: PRS/SNM18D00897C02/6 & YR REF: SLW22Z -TO CONDUCT SURVEY

AND DIRECT SETTLEMENT -SLW22Z

Attachments:

SNM18D00897C02 TPP ESTIMATE.pdf

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Angie Foo [mailto:angie.foo@sg.cntaiping.com]

Sent: Friday, 2 March 2018 4:03 PM

To: Danny Ong <danny.ong@mbmwheelpower.com.sg>

Cc: joseph.tan@mbmwheelpower.com.sg; kenneth@mbmwheelpower.com.sg; Irene Tay

<irene.tay@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>; SUR <sur@lkkauto.com>;

Denise Tay (LKKAuto) <denisetay@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: OUR REF: PRS/SNM18D00897C02/6 & YR REF: SLW22Z -TO CONDUCT SURVEY AND DIRECT

SETTLEMENT -SLW22Z

WITHOUT PREJUDICE

Dear Danny,

We refer to your email on even date.

We had appointed Kalvin Ang of M/S LKK Auto Consultants Pte Ltd to conduct survey on your client's vehicle.

Please ensure that your client's vehicle is available for survey within 2 working days.

We are prepared to do a Direct Settlement based on our surveyor's recommendation on Cost of Repairs and Loss of Use/Rental is

strictly to our surveyor's recommendation on duration of repairs.

REMARKS:

Dear Kalvin,

Please conduct survey, check consistency of the damages and do a direct settlement.

Kindly take note, the claim handler on this case is Irene Tay 6389 6192

Thank you.

Regards, Angie Foo Executive Motor Division Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E

DID: 6389 6186

Fax: 6224 7478 /6224 7175

Email: angie.foo@sg.cntaiping.com Email: claimsdept@sg.cntaiping.com Website: www.sg.cntaiping.com

Disclaimer.

This message is confidential, its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Danny Ong [mailto:danny.ong@mbmwheelpower.com.sg]

Sent: Friday, 2 March, 2018 3:46 PM

To: Angie Foo

Cc: joseph.tan@mbmwheelpower.com.sg; kenneth@mbmwheelpower.com.sg; Irene Tay; Claims Dept of CTI Subject: RE: OUR REF: PRS/SNM18D00897C02/6 & YR REF: SLW22Z -TO CONDUCT PRE REPAIR SURVEY -SLW22Z

Dear Angie

We would like to select "Kalvin Ang" to conduct the survey.


Kindly arrange on Monday 05/03/2018 @ 10AM as customer will be waiting.

Please arrange.

Kindly take note of the new mailing address

Best regards,

Danny Ong | Claims Advisor



T 6262 8888 | F 6250 9015 | M 9328 8668

Email: danny.ong@mbmwheelpower.com.sg
MBM Wheelpower Pte Ltd
160 Sin Ming Drive • #06-02
Sin Ming AutoCity • Singapore 575722

www.mbmwheelpower.com.sg

From: Angie Foo [mailto:angie.foo@sg.cntaiping.com]

Sent: Friday, 2 March 2018 10:50 AM

To: Danny Ong <danny.ong@mbmwheelpower.com.sg>

Cc: joseph.tan@mbmwheelpower.com.sg; kenneth@mbmwheelpower.com.sg; Irene Tay

<irene.tay@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: OUR REF: PRS/SNM18D00897C02/6 & YR REF: SLW22Z -TO CONDUCT PRE REPAIR SURVEY -SLW22Z

WITHOUT PREJUDICE

Dear Danny,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE	
SAMUEL PHUN	
SEE CHEW SENG	
MOHD FADHILAH BIN OSMAN	
DEREK OH SIONG WEE	
KALVIN ANG	
MARCUS CHUA	
SIMON HO	
LOW SAR HUEI	
HONG FOOK CHOY	

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Kindly let us hear from you.

REMARKS:

Kindly take note, the claim handler on this case is Irene Tay 6389 6192.

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E

DID: 6389 6186

Fax: 6224 7478 /6224 7175

Email: angie.foo@sg.cntaiping.com Email: claimsdept@sg.cntaiping.com Website: www.sg.cntaiping.com

Disclaimer.

This message is confidential: its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Danny Ong [mailto:danny.ong@mbmwheelpower.com.sg]

Sent: Thursday, 1 March, 2018 6:16 PM

To: Claims Dept of CTI

Cc: joseph.tan@mbmwheelpower.com.sg; kenneth@mbmwheelpower.com.sg

Subject: RE: Liability Status - Accident involving SLW22Z & SJF1166Z (CHINA) on 13/02/2018 - TP CLAIM

Dear All

Kindly revert back soonest with the liability status and arrange for a survey.

I have called earlier to claims department and they mentioned that they will look into it.

Email was send on 26/02/2018 but till this date and time there was no respond from the "Claims Department"

Kindly take note of the new mailing address

Best regards,

Danny Ong | Claims Advisor

mbm wheelpower

T 6262 8888 | F 6250 9015 | M 9328 8668

Email: danny.ong@mbmwheelpower.com.sg

MBM Wheelpower Pte Ltd 160 Sin Ming Drive • #06-02

Sin Ming AutoCity • Singapore 575722

www.mbmwheelpower.com.sg

From: Danny Ong [mailto:danny.ong@mbmwheelpower.com.sg]

Sent: Monday, 26 February 2018 3:54 PM

To: 'claimsdept@sg.cntaiping.com' <<u>claimsdept@sg.cntaiping.com</u>>

Cc: 'joseph.tan@mbmwheelpower.com.sg' < joseph.tan@mbmwheelpower.com.sg >;

'kenneth@mbmwheelpower.com.sg' < kenneth@mbmwheelpower.com.sg>

Subject: Liability Status - Accident involving SLW22Z & SJF1166Z (CHINA) on 13/02/2018 - TP CLAIM

Dear Sir / Madam,

Appreciate if you can advise us on the liability status for the below loss and arrange a pre-survey for the above mentioned vehicle.

Kindly refer to the attached GIA report and estimate.

Our Client's Vehicle Number:	SLW22Z
CNTAIPING Vehicle Number:	SJF1166Z
Date/Time of Loss:	13/02/2018 1545hrs

Kindly arrange your surveyor to survey the vehicle at 160 Sin Ming Drive #06-02 Sin Ming Autocity
Singapore 575722

Please contact Danny - 93288668 for the survey arrangement.

Kindly take note of the new mailing address

Best regards,

Danny Ong | Claims Advisor



www.mbmwheelpower.com.sg

T 6262 8888 | F 6250 9015 | M 9328 8668

Email: danny.ong@mbmwheelpower.com.sg MBM Wheelpower Pte Ltd 160 Sin Ming Drive • #06-02 Sin Ming AutoCity • Singapore 575722

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit http://www.symanteccloud.com

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	91541
Vehicle Details	
Vehicle No.:	SLW22Z
Vehicle to be Exported:	No
Intended De-registration Date:	30 May 2018
Vehicle Make:	PORSCHE
Vehicle Model:	911 CARRERA S GEN 2
Primary Colour:	Yellow
Manufacturing Year:	2016
Engine No.:	DCH015065
Chassis No.:	WP0ZZZ99ZHS115091
Maximum Power Output:	309.0 kW (414 bhp)
Open Market Value:	\$156,099.00
Original Registration Date:	01 Dec 2017
First Registration Date:	01 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$252,979.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Nov 2027
PARF Rebate Amount:	\$189,734.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

By the ladgement of this report to the insurers, you aforesaid.	tu hereby consent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	14/02/2018 11:02
Date Of Accident	13/02/2018 15:45
Exact Location Of Accident	ALONG CAVENAGH SLIP ROAD INTO BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLW22Z
Insured/Policyholder	
Name Of Registered Owner	HONG LENA
NRIC No	S7229154I
Email Address	CHRISCHONG8888@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91380221
Alternative Phone No	OFFICE-91380221

Vehicle Particulars

Manufacturer PORSCHE

Model 911 CARRERA S GEN 2

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY PRIVATE CAR

Vehicle Category

Insurance Company

Name of Insurance Company ERGO INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number DMPC17S023087

Cover Note Number 28/12/2017 - 30/11/2018

Driver

Name of Driver CHONG WENG CHIEW

 NRIC No
 S6929743I

 Date Of Birth
 14/09/1969

 Occupation
 INDOOR

 Date Of Driving Pass
 28/04/1989

Driving Experience 28 YEARS AND 9 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-82680313

Fax Number

Contact Number

EMail Address CHRISCHONG8888@GMAIL.COM

50 BERWICK DRIVE Address

Postcode 559929

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

SPOUSE

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

NO YES

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO 1

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

SJF1166Z Vehicle Registration Number Vehicle Make/Model/Colour MERCEDEZ

Details Of Properties

PRIVATE CAR Vehicle Category

Name of Driver GEAJAINDREN SO MARIAPAN MARUDAPAN

NRIC/Passport Number S7720189J

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful</u> and <u>accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to coilect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (II) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN DESCRIBE CIRCUMSTANCES OF THE ACCIDENT At about 3.45pm on 13/2/2018, I was towards Buyest Timah Rd. As I was a Reporting Only You had been advised by workshop that in the event that you wish to claim Claim OD against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from Claim TP the day of occurance. Claim OD / TP at other workshop DECLARATION I/We declare the foregoing particulars are true in every respect. Policyholder's Signature Driver's Signature Reporting Centre Personnel's Signature (If driver is not the policyholder) Date & Time: Name:

NRIC/FIN No.:

GIARMC SketchPlanForm_V3

Date & Time:

MBM WHEELPOWER PTE LTD

Your Ref: SJF1166Z Our Ref: SLW22Z

Fax

To: **CHINA TAIPING**

CC

ESTIMATE FOR VEHICLE NO. : SLW22Z

DESCRIPTION	
EXHAUST PIPE RH	
EXHUAST PIPE CHROME	
REAR BUMPER	
REAR BUMPER CLIPS	
RIVET	
REAR BUMPER LOWER COVER	

	mbm wheelpower

Date: 26/2/2018 From: Danny

Fax: 62509015 Contact: 93288668

Make / Model: PORSCHE 911 CARRERA S GEN

Chassis No.: WP0ZZZ99ZHS115091

Engine No.: DCH015065

2016 Year of Make:

Accident Date: 13 February 2018

QTY		List Price
1	\$	n 7,200.00 ₹
1	\$	n 2,000.00 X
1	\$	Bully 3,800.00 -
10	\$	MG 250.00 -
10	\$	Ma 250.00 -
1	\$	nd 1,100.00 -
Total	: \$	14,600.00
LESS 10%	\$	(1,460.00)
Parts Total	: \$	13,140.00

Not botheras

Purny By pains

Golass

- To resurvey before/after spray painting
- To display damaged part(a) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Mbm wheelpower pte ltd 160 SIN MING DRIVE

SIN MING AUTOCITY

t 62828888 f 64529823

Company Registration Number: 200204110W

SPECIAL NETT		
BODY SEALANT	1	\$ Na 80.00 X
REAR BUMPER SENSOR	1 SET	\$ sn 300.00 X
LABOUR		359
TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS KNCOK-OUT, STRAIGHTEN, ON THE AFFECTED PARTS.	S. INCLUDING TO	\$ 800.00
TO REMOVE & REPLACE EXHAUST PIPE SYSTEM TO FACIL	IATE REPAIR	\$ N~ 80.00 X
TO REMOVE & REPLACE BUMPER SENSORS		\$ 601 80.00
TO CHECK & RECONNECT ALL NECESSARY WIRING		\$ 301 80.00
TO SPRAY PAINTING ON THE AFFECTED AREAS		\$ 400 600.00
	Total:	\$ 15,160.00
	7% GST:	\$ 1,061.20
	Grand Total:	\$ 16,221.20

16-27/5-95

Mbm wheelpower pte ltd 160 SIN MING DRIVE #06-02

> SIN MING AUTOCITY ± 62828888 ± 64529823

Company Registration Number : 200204110W

MBM WHEELPOWER PTE LTD

Your Ref: SJF1166Z Our Ref: SLW22Z

To:

CC

Fax

Date:

27/6/2018

From:

Danny

Fax:

62509015

Contact:

93288668

Make / Model:

PORSCHE 911 CARRERA S GEN

wheelpower

Chassis No.:

WP0ZZZ99ZHS115091

Engine No.:

DCH015065

Year of Make:

2016

Accident Date:

TOTAL:

13 February 2018

SUPPLE, MENTARY ESTIMATE FOR VEHICLE NO.: SLW22Z

DE	SC	RI	PT	ION

CHINA TAIPING

REAR BUMPER "PORSCHE" EMBLEM
REAR BUMPER "911" EMBLEM
REAR BUMPER "CARRERA" EMBLEM

REAR BUMPER "S" EMBLEM

QTY		List Price		
1	\$	na	280.00	_
1	s	M	220.00	,
1	\$	Na	221.50	_
1	\$	Na	185.00	_
To	tal: \$		906.50	
LESS 10	0% \$		(90.65)	
Parts Tot	al: \$		815.85	

SPECIAL NETT

NUMBER PLATE & HOLDER

G-GUARD COATING FOR REAR BUMPER

\$ Bill 250.00 3 \$ 1,115.85

Po.ts - \$ 5675.85 5/N - \$300 C-\$840 Total 6815.85

1/3 - 95450 / Volc

Mbm wheelpower pte ttd 160 SIN MING DRIVE #06-02 SIN MING AUTOCITY

t 62828888 f 64529823

Company Registration Number: 200204110W

Attn: Mr Danny
NAME: MBM WHEELPOWER PTE LTD
No. 160 Sin Ming Drive
#06-02, Sin Ming Autocity
S(575722)

Vehicle No.: SLW22Z



INVOICE

GST REG NO:

200504627K

Tax Invoice:

INV8222009

Invoice Date:

30.5.2018

S/N	Qty	Particular	Unit Price		Amount	
01.		Being charge polish and ceramic coating on rear bumper	\$	250.00	\$ 250.00	
		G-GUARD 'RADIANT' 3-LAYER COAT				

	SUB TOTAL:	\$ 250.00
	7% GST:	\$ 17.50
E. & O.E	Total S\$ (SGD)	\$ 267.50

The above items are received in good order and condition by

Customer's Signature/Co.Stamp

for KBS Motorsport Pte Ltd

Terms & Conditions:

MBM WHEELPOWER PTE LTD

Your Ref: SJF1166Z Our Ref: SLW22Z

To:

Fax

CHINA TAIPING

CC

. ·

ESTIMATE FOR VEHICLE NO. : SLW22Z

DESCRIPTION

EXHAUST PIPE PH

EXHUAST PIPE CHROME

REAR BUMPER

REAR BUMPER CLIPS

RIVET

REAR BUMPER LOWER COVER

Date:

26/2/2018

From:

Danny

Fax:

62509015

Contact:

93288668

Make / Model:

PORSCHE 911 CARRERA S GEN

wheelpower

Chassis No.:

WP0ZZZ99ZHS115091

Engine No.:

DCH015065

Year of Make:

2016

Accident Date:

13 February 2018

QTY		List Price
1	\$	1 7,200.00 X
1	\$	£ 2,000.00 X
1	\$	Burlas 3,800.00 -
10	\$ -	1℃ 250.00 C
10	\$	na 250.00 -
1	\$	nes 1,100.00 -
Tota	al: \$	14,600.00
LESS 10	% \$	(1,460.00)
Parts Tota	1: \$	13,140.00

Not Notherhol Minny By pains Golass

		Grand Total:	\$ 16,221.20
	2	7% GST:	\$ 1,061.20
	100	Total:	\$ 15,160.00
Т	O SPRAY PAINTING ON THE AFFECTED AREAS	###	\$ GOO 600.00
T	O CHECK & RECONNECT ALL NECESSARY WIRING	•	\$ 301 80.00
T	O REMOVE & REPLACE BUMPER SENSORS		\$ 601 80.00
Т	O REMOVE & REPLACE EXHAUST PIPE SYSTEM TO FACILIA	ATE REPAIR	\$ 80.00
	O REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. NCOK-OUT, STRAIGHTEN, ON THE AFFECTED PARTS.	INCLUDING TO	\$ 800.00
L	ABOUR		359
R	EAR BUMPER SENSOR	1 SET	\$ Sh 300.00 TV
В	ODY SEALANT	1	\$ Na 80.00 X
SI	PECIAL NETT		

Mbm wheelpower pte ltd 160 SIN MING DRIVE #06-02

SIN MING AUTOCITY

t 62828888 f 64529823

Company Registration Number: 200204110W



TAX INVOICE

Conti Motors Pte Ltd 2 KUNG CHONG ROAD

SINGAPORE 159140

Contact	3.1	CARL	0000

Account No. C0223	Service Advisor Patrick Lim	Involced By Patrick Lim	Invoice/Credit Note No. 21001048	W.I.P. No. 10839
Reg. No. WPOZZZ99ZH	Make & Model Porsche 911 Carrera S Gen 2	Chassis No. WPOZZZ99ZHS115091	Engine No. 015065	Reg. Date
Date & Time In 21/11/2017 9.39	Date & Time Out) 29/11/2017 12.53	Mileage 40	Invoice Date & Time 29/11/2017 12:53	
Attending Servi Should you requ	ce Advisor: Patrick Lim uire further explanation, please reach r	ne at 83833775	Next Service Date & I	Mileage:
Description of	Goods / Services	Qty.	Price Disc	% Net Total
Process 4 layers Interior cleaning Spray coat on 4 2 years warranty	& steaming rims with T&C apply	8.00 8.00 4.00 30.00		1388.0
Next maintenand	ce coat-21/05/2017	PARK II C. LINE OF THE CO.	0.00 Subtotal	0.00
Sunroof coating Polish & apply of		3.50ML		1388.0 0.0

Currency S	GE)
------------	----	---

at the second	Currency SGD
Net	1188.00
Add GST @7%	83.16
Discount	0.00
Total	1271. 16
Paid/Deposit	(0.00)
Balance	1271, 16

Customer's Signature

Inquiries to invoice must be lodged within 7 days from invoice date.

Cashier's Signature

KBS Motorsports Pte Ltd

160 Sin Ming Drive
#06-03 Sin Ming Autocity
Singapore 575722
T 6262 888 | F 6452 3333
Www.kbsmotorsports.com/sg
Company Registration Number: 200504627K
GST Registration Number: M90368446L



TAX INVOICE

Conti Motors Pte Ltd 2 KUNG CHONG ROAD

SINGAPORE 159140

Contact No.: 64515333

Account No. C0223	Service Advisor Patrick Lim	Involced By Patrick Lim	Invoice/Credit Note No. 21001048	W.I.P. No. 10839
Reg. No. WPOZZZ99ZH	Make & Model Porsche 911 Carrera S Gen 2	Chassis No. WPOZZZ99ZHS115091	Engine No. 015065	Reg. Date
Date & Time In 21/11/2017 9.39	Date & Time Out 29/11/2017 12.53	Mileage 40	Invoice Date & Time 29/11/2017 12:53	
	e Advisor: Patrick Lim ire further explanation, please reach r	ne at 83833775	Next Service Date &	Mileage:
Description of G	Goods / Services	Qty.	Price Disc	% Net Total
G-GUARD 'RADI Process 4 layers Interior cleaning Spray coat on 4 r 2 years warranty	& steaming ims with T&C apply	8,00 8,00 4.00 30.00		1388.00
Next maintenanc	e coat-21/05/2017		0.00	0.00
Sunroof coating Polish & apply co) F) (() () () () () () () () (TR Subtotal	1388.00
Discount Goodwill discoun	L		-200.00	-200.00
			Subtotal	-200.00

	Currency SGD
Net	1188.00
Add GST @7%	83. 16
Discount	0.00
Total	1271, 16
Paid/Deposit	(0.00)
Balance	1271, 16

Customer's Signature

Inquiries to invoice must be lodged within 7 days from invoice date.

Cashier's Signature

KBS Motorsports Pte Ltd

160 Sin Ming Drive #06-03 Sin Ming Drive #06-03 Sin Ming Autority Singapore 575722 T 6262 8888 | F 6452 5333 www.kbsmotorsports.com.su Company Registration Number: 200504627K GST Registration Number: M903684461.

Attn:	Mr Danny
NAME:	MBM WHEELPOWER PTE LTD
	No. 160 Sin Ming Drive
	#06-02, Sin Ming Autocity
	S(575722)



INVOICE

GST REG NO:

200504627K

Tax Invoice:

INV8222009

invoice Date:

30.5.2018

S/N	Qty	Particular	U	Init Price	Amount
01.		Being charge polish and ceramic coating on rear bumper	\$	250.00	\$ 250.00
		G-GUARD 'RADIANT' 3-LAYER COAT			

	SUB TOTAL:	\$ 250.00
	7% GST:	\$ 17.50
E. & O.E	Total S\$ (SGD)	\$ 267.50

The above items are received in good order and condition by

Customer's Signature/Co.Stamp

for KBS Motorsport Pte Ltd

Terms & Conditions:

kbs motorsports pte ltd 160 Sin Ming Drive, #06-03 Sin Ming Autocity, S575722 t 64515 333 f 64525 333

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

DMPCSN3019531700

CS/CTI18004093/KQD3N2

DCH015065

2857 km

Date:

26/11/2018

REFERENCE

Handling Insurer: Claimant China Taiping Insurance

(Singapore) Pte. Ltd.

No:

Policy No:

Nature of

Claim:

Vehicle No: Date of Loss:

13/02/2018

SLW22Z

Insured Vehicle SJF1166Z

TP

Claim No:

SNM18D00897C02

WP0ZZZ99ZHS115091

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLW22Z

Make & Model: Reg. Date:

PORSCHE 911, CARRERA S

01/12/2017 (Man. Year: 2016)

Yellow Colour: 2981 cc

Engine Capacity: Market Value/New Car

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable): No Pre-accident Condition:

Engine No:

Chassis No:

Odometer:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 245/35ZR20 Front Left Side:

Pirelli 9 mm Pirelli 9 mm

Rear Tyre Size: Rear Left Side: Rear Right Side: 305/30ZR20 Pirelli 9 mm

Pirelli 9 mm

Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,385.85	5,720.85	8,665.00	60.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,890.00	1,090.00	800.00	42.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,275.85	6,810.85	9,465.00	58.15
Approved Total (Overridden) (S\$)		5,450.00		
(S\$)	16,275.85	5,450.00	10,825.85	66.51
+ GST 7.00/7.00% (S\$)	1,139.31	381.50	757.81	66.51
Nett Amount (S\$)	17,415.16	5,831.50	11,583.66	66.51

INSPECTION

Date of Assignment:

07/03/2018

Date Inspected:

06/03/2018 Inspected At:

MBM Wheelpower Pte Ltd (Sin Ming) 176 Sin Ming Drive #01-15, Sin Ming

AutoCare

Singapore 575721

Estimated Period of Repair:

4.0 days

Manager: SHIAU CHAN Adjuster: KENNETH KONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 26 Nov 2018)

Parts:

M1-COUPE

PORSCHE 911 CARRERA S (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLW22Z)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommend	led	Parts
Recommend	ieu	1 alto

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EXHAUST PIPE LH	Repair	7,200.00 FL	*-FL
2	1		*EXHAUST PIPE CHROME	Repair	2,000.00 FL	*- FL
3	1		*REAR BUMPER *REAR BUMPER CLIPS	Buckled/Dented Necessary	3,800.00 FL 250.00 FL	*3,800.00 FL *250.00 FL
5	10 1		*RIVET *REAR BUMPER LOWER COVER	Necessary Dented	250.00 FL 1,100.00 FL	*250.00 FL *1,100.00 FL
7 8	1		*REAR BUMPER PORSCHE EMBLEM *REAR BUMPER 911 EMBLEM	Necessary Necessary	280.00 FL 220.00 FL	*280.00 FL *220.00 FL
9	1		*REAR BUMPER CARRERA EMBLEM *REAR BUMPER S EMBLEM	Necessary Necessary	221.50 FL 185.00 FL	*221.50 FL *185.00 FL
11	1		*BODY SEALANT	Not Necessary	80.00 FS	*- FS
12	1		*SET REAR BUMPER SENSOR	Serviceable	300.00 FS	*- FS
13 F=Fra	1 anchise	part. S=SpcN	*NUMBER PLATE & HOLDER lett. L=ListItemDisc.	Dented	50.00 FS	*45.00 FS
				Sub Total (S\$)	15,936.50	6,351.50
	- List Item Discount on L Items 10.00/10.00% (S\$)				1,550.65	630.65
				Total Parts (S\$)	14,385.85	5,720.85
			Report was unsubmitted du	ring this print-out.		

1,090.00

1,890.00

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

ommended Labour	1 1 7		
A COMPANIE OF STATE O	Lab.Type	Repairer's	Amount
ur Items			
G-GUARD COATING FOR REAR BUMPER	New	250.00	250.00
TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS INCLUDING TO KNOCK-OUT, STRAIGHTEN ON THE AFFECTED PARTS	New	800.00	350.00
TO REMOVE & REPLACE EXHAUST PIPE SYSTEM TO FACILIATE REPAIR	New	80.00	
TO REMOVE & REPLACE BUMPER SENSORS	New	80.00	60.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	New	80.00	30.00
TO SPRAY PAINTING ON THE AFFECTED AREAS	New	600.00	400.00
	G-GUARD COATING FOR REAR BUMPER TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS INCLUDING TO KNOCK-OUT, STRAIGHTEN ON THE AFFECTED PARTS TO REMOVE & REPLACE EXHAUST PIPE SYSTEM TO FACILIATE REPAIR TO REMOVE & REPLACE BUMPER SENSORS TO CHECK & RECONNECT ALL NECESSARY WIRING	G-GUARD COATING FOR REAR BUMPER TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS INCLUDING TO KNOCK-OUT, STRAIGHTEN ON THE AFFECTED PARTS TO REMOVE & REPLACE EXHAUST PIPE SYSTEM TO FACILIATE REPAIR TO REMOVE & REPLACE BUMPER SENSORS New TO CHECK & RECONNECT ALL NECESSARY WIRING	G-GUARD COATING FOR REAR BUMPER TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS INCLUDING TO KNOCK-OUT, STRAIGHTEN ON THE AFFECTED PARTS TO REMOVE & REPLACE EXHAUST PIPE SYSTEM TO FACILIATE REPAIR TO REMOVE & REPLACE BUMPER SENSORS New 80.00 TO CHECK & RECONNECT ALL NECESSARY WIRING New 80.00

Report was unsubmitted during this print-out.

Gross Labour Cost (S\$)

< END OF ESTIMATES >