

ASS. REC. BY:

REF: CS/CTI18004094/Gtd30k

Special Instruction:

m & m

Surveyor: GO

ASSIGNMENT (Office)

From (Person):

Angie Foo

of

CTI

Date/Time:

2/3/18 @ 3:49pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 1690T

Insured:

SKC 3857D

at Workshop m/s

World Auto

Tel:

6362 1776

of

No. 1 Krungi Loop

Policy No:

Claim No:

SNM18D01091002/7

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/02/18

CA / REV / REP. / REV 24 HRS lwp!

H.O.D. Endorsement:

Date/Time:

5:04pm @ 2/3/18

Person Contacted:

Vincent

Vehicle IN / OUT

Date/Time	Action/Instruction	Estimate
	SLC 1690T-X	
	SKC 3857D - NA/INC/4006672/1-3	D.O.A. 7/4/18
	Agreed Part by Part \$1838/- (Red: 2530.40, 57%)	

3/2/2018

KBR

REF: GTI

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s World Auto  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	
N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Veh No: SLC1690T Yr Regn: 03 May 2016  
 Type:  M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Honda Shuttle cc 1496  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp. Reading: 177813 T. Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: GK 8100 4794  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  In Order / Jammed / Leaked / Burnt or  
 Brake:  In Order / Jammed / Leaked / Burnt or  
 Modi:  Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 185/60 R15  
 R: 11  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or ROVELO  
 Front Rear  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 01-03-18  
 Survey held at WIS 1 pm  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
N/S PA  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED

Date/Time. File Pass to?  : Preli. Report  
 : Final Report  
 Date/Time. File Return to?

Days Of Repair: 3  
 Resurvey No. of Trip: \_\_\_\_\_

Report Format: TP  
 Lump Sum /  (B) (\$) 1838

Add Fee:  Site Insp (\$)  
 Interview (\$)  
 Tech. Invs (\$)  
 Weekend (\$)

Survey Fee:	<u>220</u>
Transpation	
FUEL S + RES. COST	
Photos	
Others	
TOTAL	<u>220</u>

## Denise Tay (LKKAuto)

---

**From:** Ainee31 <ainee31@worldauto.com.sg>  
**Sent:** Wednesday, 14 March 2018 12:30 PM  
**To:** Denise Tay (LKKAuto)  
**Subject:** Fw: Re[2]: Request for Finalized SLC1690T // SKC3857D DOA: 25/02/2018 TP/1871/18

Hi, Denise

Already reply on 08/03/2018.

Thanks and Rgds,

World Auto Pte Ltd

Tel HQ: 64513933

Kranji: 63621776

Fax: 64557576

---

-----Original Message-----

From: Ainee31 <ainee31@worldauto.com.sg>  
To: "Guo Qiang (LKKAuto)" <guoqiang@lkkauto.com>, "Denise Tay (LKKAuto)" <denisetay@lkkauto.com>  
Date: 08/03/2018 17:01  
Subject: Re[2]: Request for Finalized SLC1690T // SKC3857D DOA: 25/02/2018 TP/1871/18

Dear All,

Agreed.

Thanks and Rgds,

World Auto Pte Ltd

Tel HQ: 64513933

Kranji: 63621776

Fax: 64557576

---

-----Original Message-----

From: "Denise Tay (LKKAuto)" <denisetay@lkkauto.com>

## Nivitha (LKK Auto)

---

**From:** Shiau Chan (LKKAuto) <siewsc@lkkauto.com>  
**Sent:** Friday, 2 March 2018 3:49 PM  
**To:** assignments  
**Subject:** FW: OUR REF: PRS/SNM18D01091C02/7 & YR REF: SLC1690T -TO CONDUCT PRE REPAIR SURVEY -SLC1690T

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Angie Foo [mailto:[angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)]

**Sent:** Thursday, 1 March 2018 10:37 AM

**To:** Ongv16 <[ongv16@worldauto.com.sg](mailto:ongv16@worldauto.com.sg)>

**Cc:** Irene Tay <[irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)>; Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Denise Tay (LKKAuto) <[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)>

**Subject:** RE: OUR REF: PRS/SNM18D01091C02/7 & YR REF: SLC1690T -TO CONDUCT PRE REPAIR SURVEY -SLC1690T

WITHOUT PREJUDICE

Dear Vincent,

We refer to your email of 28<sup>th</sup> February 2018.

We had appointed Marcus Chua of M/S LKK Auto Consultants Pte Ltd to conduct survey on your client's vehicle.

Please ensure that your client's vehicle is available for survey within 2 working days.

REMARKS:

Dear Marcus,

Please conduct survey and check consistency of the damages on without prejudice.

Kindly take note, the claim handler on this case is Irene Tay 6389 6192

Thank you.

Regards,  
Angie Foo  
Executive  
Motor Division  
Claims Department  
China Taiping Insurance (Singapore) Pte Ltd  
3 Anson Road #16-00  
Springleaf Tower  
Singapore 079909  
Co.Reg.No.200208384E  
DID: 6389 6186  
Fax: 6224 7478 /6224 7175  
Email: [angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

Disclaimer:

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** Ongv16 [<mailto:ongv16@worldauto.com.sg>]

**Sent:** Wednesday, 28 February, 2018 5:39 PM

**To:** Angie Foo

**Subject:** Re: OUR REF: PRS/SNM18D01091C02/7 & YR REF: SLC1690T -TO CONDUCT PRE REPAIR SURVEY -SLC1690T

Dear Angie,

Kindly appoint macus chua.

Thanks

Vincent ong

---

-----Original Message-----

**From:** "Angie Foo" <[angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)>

**To:** Ongv16 <[ongv16@worldauto.com.sg](mailto:ongv16@worldauto.com.sg)>

**Cc:** "Irene Tay" <[irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)>, "Claims Dept of CTI" <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Date:** 28/02/2018 15:25

**Subject:** OUR REF: PRS/SNM18D01091C02/7 & YR REF: SLC1690T -TO CONDUCT PRE REPAIR SURVEY -SLC1690T

WITHOUT PREJUDICE

Dear Sir/Mdm,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
SAMUEL PHUN
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
DEREK OH SIONG WEE
KALVIN ANG
MARCUS CHUA
SIMON HO
LOW SAR HUEI

HONG FOOK CHOY

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Kindly let us hear from you.

**REMARKS:**

Kindly take note, the claim handler on this case is Irene Tay 6389 6192

Thank you.

Regards,  
Angie Foo  
Executive  
Motor Division  
Claims Department  
China Taiping Insurance (Singapore) Pte Ltd  
3 Anson Road #16-00  
Springleaf Tower  
Singapore 079909  
Co.Reg.No.200208384E  
DID: 6389 6186  
Fax: 6224 7478 /6224 7175  
Email: [angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer:*

*This message is confidential, its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** Ongv16 [<mailto:ongv16@worldauto.com.sg>]

**Sent:** Tuesday, 27 February, 2018 7:01 PM

**To:** Claims Dept of CTI

**Subject:** Pre-Repair Inspection

**Dear Sir/Mdm,**

**We would like to request for a Third Party Motor Claim Survey, details as follow;**

**Our Vehicle: SLC 1690 T**

**Your Insured: SKC 3857 D**

**DOA: 25/2/18**

**Our vehicle is currently in the workshop, address as follow;**

**World Auto Pte Ltd**

**No.1, Kranji Loop**

**Singapore 739535**

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18004094/Gtd3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 02-03-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKC 3857D	Veh. Inspected	SLC 1690T
Policy No.		Coverage (\$)	0.00
Claim No.	SNM18D01091C02/7	Excess (\$)	0.00
Assign From	ANGIE FOO	Assign Date	02/03/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	25/02/2018	Inspection Date	02/03/2018
Survey held at	NO 1 KRANJI LOOP		
Repairer	WORLD AUTO PTE LTD		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/02/2018 12:34
Date Of Accident	25/02/2018 09:30
Exact Location Of Accident	JUNCTION OF SUNGEI RD & JALAN BESAR
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC1690T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201604597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992

### Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995174
Cover Note Number	

### Driver

Name of Driver	LEE CHUN LOONG
NRIC No	S7621046B
Date Of Birth	16/07/1976
Occupation	OUTDOOR
Date Of Driving Pass	06/09/2015
Driving Experience	2 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address NOADDRESS  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured PAID DRIVER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - CHANGE/CROSS LANE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 3  
 Passenger 1 NAME: : NONAME  
 GENDER: : MALE  
 Passenger 2 NAME: : NONAME  
 GENDER: : MALE

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes,Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes,against whom?

**Circumstances of Accident**

REFER TO SKETCH PLAN

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: VIDEO OVERWRITTEN  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SKC3857D  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE



- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

A. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may have permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Ministry Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time      Driver's Signature (if driver is not the policyholder) / Date & Time      Witnessed by Reporting Centre Personnel

SKETCH PLAN

KINDLY SEE ATTACHED

Sketch Plan #2

HIRSE → GANTUP



→ JALAN BESAR

A - SLC 1690 T

B - SEC 2857 D

SUKSES (G+D)

Sketch Plan #3

Describe Circumstances of the Accident



As I was about turning towards  
John Roger (Convent Street) with 2  
passengers in my vehicle I was stationary  
waiting for the traffic light when  
a dog suddenly ran out  
to enter the left hand part  
of my vehicle

Declaration

We declare the foregoing particulars are true in every respect

Policyholder's Signature / Date & Time

   
Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

## Enquire Transfer Fee

### Vehicle Details

Vehicle No.:	SLC1690T
Vehicle Type:	Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5G A
Chassis No.:	GK81004794
Propellant:	Petrol
Engine No.:	L15B3535605
Engine Capacity:	1496 cc
Maximum Power Output:	97.0 kW ( 130 bhp)
Maximum Laden Weight:	1405 kg
Unladen Weight:	1130 kg
Year Of Manufacture:	2016
Original Registration Date:	03 May 2016
Lifespan Expiry Date:	-
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium:	\$45,504.00
COE Expiry Date:	02 May 2026
Road Tax Expiry Date:	02 May 2018
PARF Eligibility Expiry Date:	02 May 2026
Inspection Due Date:	02 May 2019
Intended Transfer Date:	05 Mar 2018
CO2 Emission:	119.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$10,000.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 02 May 2018. You may renew the road tax from 03 Feb 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 02 May 2018, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

**Amount Payable (From 03 May 2018 to 02 Nov 2018)**

# WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03  
 Halcyon 2, S'pore 577200  
 Tel No. : 6451 3933 Fax No. : 6455 7576  
 E-Mail : worldaut@singnet.com.sg  
 Website : www.worldauto.com.sg  
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Estimate : ES005769

Attention : Motor Claim Department

Date : 27/02/2018  
 Vehicle Num. : SLC 1690T (LCR)  
 Make/Model : HONDA SHUTTLE  
 Chassis/Eng# :  
 Accident Date : 27/02/2018  
 Claim No. :  
 Reference :  
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	L/F FENDER <i>Repair X</i>		489.90 <i>X</i>
2.	1	HEADLAMP ASSY LH <i>X NN</i>		1,450.00 <i>X</i>
3.	1	FRONT BUMPER <i>cut</i>		1,380.00 <i>X</i>
4.	1	FRONT BUMPER RETAINER LH <i>cut</i>		88.50 <i>X</i>
List Total S\$ :				3,408.40
SPECIAL NETT ITEMS :				
1.	1 SET	FRONT BUMPER CLIP <i>cut</i>		30.00 <i>X</i>
Special Nett Total S\$ :				30.00
LABOUR :				
LABOUR TO RENEW FRONT DAMAGE PARTS AND ALIGN L/F FENDER INNER PANEL ETC.			<i>750</i>	450.00
SPRAY PAINT TO ABOVE AFFECTED AREAS			<i>400</i>	480.00
Labour Total S\$ :				930.00

*3 Days.  
 part by part.*

*[Signature]*  
 5/3/18

*1838*

E. & O.E.

Total S\$ : 4,368.40

*before paint photos.*

for WORLD AUTO PTE LTD

*Emo Qian - 82880282  
 01/3/18.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03  
 Halcyon 2, S'pore 577200  
 Tel No. : 6451 3933 Fax No. : 6455 7576  
 E-Mail : worldaut@singnet.com.sg  
 Website : www.worldauto.com.sg  
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Estimate : ES005769

Attention : Motor Claim Department

Date : 27/02/2018  
 Vehicle Num. : SLC 1690T (LCR)  
 Make/Model : HONDA SHUTTLE  
 Chassis/Eng# :  
 Accident Date : 27/02/2018  
 Claim No. :  
 Reference :  
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	L/F FENDER <i>Repair X</i>		<del>400.00</del>
2.	1	HEADLAMP ASSY LH		<del>1,450.00</del>
3.	1	FRONT BUMPER		<del>          </del>
4.	1	FRONT BUMPER RETAINER LH <i>MC</i>		<del>          </del>
List Total S\$ :				3,408.40

*1468.50*

SPECIAL NETT ITEMS :				
1.	1 SET	FRONT BUMPER CLIP <i>MC</i>		<del>          </del>
Special Nett Total S\$ :				30.00

LABOUR :				
<del>LABOUR TO RENEW FRONT DAMAGE PARTS AND ALIGN L/R FENDER</del>				
<del>INNER PANEL ETC.</del>				
SPRAY PAINT TO ABOVE AFFECTED AREAS				
Labour Total S\$ :				<u>750</u> 930.00

*3 Days.  
 part by part.*

E. & O.E.		Total S\$ :	4,368.40
<i>before paint photos.</i>			<u>          </u>
<i>Emo Qicq - 82880282</i>		<i>parts -</i>	<i>1468.50</i>
<i>01/3/18.</i>		<i>-20%</i>	<i>293.70</i>
			<u>1174.80</u>
		<i>sn -</i>	<i>30.00</i>
		<i>labour -</i>	<i>750.00</i>
		<i>nets</i>	<u>1954.80</u>

*3 days.*

for WORLD AUTO PTE LTD

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Mar 2018		07 Mar 2018 17:28 <a href="#">Edit Adj Rpt</a>	<b>S\$1,838.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,838.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>				[Created by insurer]					
Insured:	<b>LIM THYE HAUT</b> , Co. Reg. No.: -								
Main Claimant:	<b>LCRF PTE LTD</b>								
Vehicle Reg. No.:	<b>SLC1690T</b>	Date of Loss:	25/02/2018 09:00 - :59						
Claim Type:	<b>TP / SNM18D01091C02</b>	Policy/Cover Note No.:	DMPCSN3080871701						
Vehicle Reg. No. (Insured):	<b>SKC3857D</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>World Auto Pte Ltd - Kranji (HQ)</b> No 1 Kranji Loop, 739535 Kranji - Tel: 63621776								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 16/03/2018]								
Adj Asg. Remarks:	PLEASE CONDUCT SURVEY, CHECK CONSISTENCY OF THE DAMAGES ON WITHIOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR SURVEY								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a>   <a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>									
				<a href="#">View All</a>   <a href="#">Search Tasks</a>   <a href="#">Create New Task</a>   <a href="#">Complete</a>					
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

### Claim Documents

**\*SLC1690T (SNM18D01091C02)**  
**[SKC3857D]**  
**TP**  
**LCRF PTE LTD**  
**Feb 25 2018 9:00AM**  
**[LIM THYE HAUT]**  
**World Auto Pte Ltd - Kranji**

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<b>View</b> <a href="#">View in Browser</a> <input type="checkbox"/>		
<b>Photos/Images</b>				3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	14/03/18 14:26	General View		Load JPG	<input checked="" type="checkbox"/>	
2	14/03/18 14:26	General View		Load JPG	<input checked="" type="checkbox"/>	
3	14/03/18 14:26	General View		Load JPG	<input checked="" type="checkbox"/>	
4	14/03/18 14:26	General View		Load JPG	<input checked="" type="checkbox"/>	
5	14/03/18 14:26	General View		Load JPG	<input checked="" type="checkbox"/>	
6	14/03/18 14:26	General View		Load JPG	<input checked="" type="checkbox"/>	
7	14/03/18 14:26	General View		Load JPG	<input checked="" type="checkbox"/>	
8	14/03/18 14:26	General View		Load JPG	<input checked="" type="checkbox"/>	
9	14/03/18 14:26	General View		Load JPG	<input checked="" type="checkbox"/>	
10	14/03/18 14:26	General View		Load JPG	<input checked="" type="checkbox"/>	
11	14/03/18 14:26	General View		Load JPG	<input checked="" type="checkbox"/>	
12	14/03/18 14:26	General View		Load JPG	<input checked="" type="checkbox"/>	
13	14/03/18 14:26	General View		Load JPG	<input checked="" type="checkbox"/>	
14	14/03/18 14:26	General View		Load JPG	<input checked="" type="checkbox"/>	
15	14/03/18 14:26	General View		Load JPG	<input checked="" type="checkbox"/>	
16	14/03/18 14:26	General View		Load JPG	<input checked="" type="checkbox"/>	
<b>Documentation</b>				1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print	
1	07/03/18 17:29	THIRD PARTY SLC1690T -PRS EMAIL BTW CIC AND WORLD AUTO		Load PDF		
2	08/03/18 11:12	THIRD PARTY SAS REPORT SLC1690T		Load PDF		

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer  
Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18004094/GTD3E2

Date: 19/03/2018

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN3080871701		
Claimant Vehicle No: SLC1690T	Insured Vehicle No: SKC3857D		
Date of Loss: 25/02/2018	Nature of Claim: TP	Claim No: SNM18D01091C02	

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLC1690T		Engine No: L15B3535605	
Make & Model: HONDA SHUTTLE, 1.5 G (A)		Chassis No: GK81004794	
Reg. Date: 03/05/2016 (Man. Year: 2016)		Odometer: 177813 km	
Colour: White			
Engine Capacity: 1496 cc			
Market Value/New Car Price: N/A			
Sum Insured (\$\$): Market Value/New Car Price			

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Rovelo 6 mm	Rear Left Side:	Rovelo 6 mm
Front Right Side:	Rovelo 6 mm	Rear Right Side:	Rovelo 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,438.40	1,088.00	2,350.40	68.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	930.00	750.00	180.00	19.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>4,368.40</b>	<b>1,838.00</b>	<b>2,530.40</b>	<b>57.93</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>305.79</b>	<b>128.66</b>	<b>177.13</b>	<b>57.93</b>
<b>Nett Amount (\$\$)</b>	<b>4,674.19</b>	<b>1,966.66</b>	<b>2,707.53</b>	<b>57.93</b>

#### INSPECTION

Date of Assignment:	07/03/2018		
Date Inspected:	01/03/2018	Inspected At:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop Singapore 739535
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

**Part Source:** (Last Synchronised: 19 Mar 2018)  
**Parts:** N/A HONDA SHUTTLE 1.5 G (A) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SLC1690T)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*L/F FENDER	Repair	489.90 F	*- FL
2	1		*HEADLAMP ASSY LH	Not Necessary	1,450.00 F	*- FL
3	1		*FRONT BUMPER	Cut	1,380.00 F	*1,278.50 FL
4	1		*FRONT BUMPER RETAINER LH	Necessary	88.50 F	*44.00 FL
5	1		*SET FRONT BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
<b>Sub Total (\$\$)</b>					<b>3,438.40</b>	<b>1,352.50</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>					<b>0.00</b>	<b>264.50</b>
<b>Total Parts (\$\$)</b>					<b>3,438.40</b>	<b>1,088.00</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO RENEW FRONT DAMAGE PARTS AND ALIGN L/F FENDER INNER PANEL ETC	New	450.00	350.00
2	SPRAY PAINT ABOVE AFFECTED AREAS	New	480.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>930.00</b>	<b>750.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >