

INS. CASE OWNER

C.S3, ASM18004105, Saz32

LKK:

IDAC:

33227

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II : S\$

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$100.00

RECEIVED 10 APR 2018

RECEIVED 03 MAY 2018

COPY SENT

REF:

Shawn 96450023

Signature

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time | Action / Instruction

22/3/18 : Dismantle

26/3/18 : After Repair

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I. (\$) :

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

) \$ + RS. \$

) Photos

) Others

TOTAL

Veh No:

SLB 25147

Yr Regn:

31/3/2016

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Note

C.C. 1178

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

29174

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN1TBAE12 20782402

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

28/2/18

D.O.I.

5/5/18

9.35AM

Survey held at

Koh Mook TC Amoo Clinic

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M009VS
Our ref: CC4/ASM18004105/Sua3

Date: 07.03.2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLB 2514T

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 05.03.2018 at the premises of M/s TC Autoclinic Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	9,459.72
Revised Estimate Amount	: S\$	4,802.36
"Check" Items Amount	: S\$	2,037.68
Total (Including Check Items)	: S\$	6,840.04

Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
Rear Portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 6.0 days

Yours faithfully,

SEBASTIAN YEANG
Licensed Appraiser

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 047/IC/TCAC/CCR/2018
DATE : 01-MAR-2018

AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MR THNG HENG GUAN
ADDRESS : 31 ALEXANDRA ROAD
#03-02
S(159967)
TELEPHONE NO : 96853063

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 10727584
VEHICLE NO : SLB2514T
MODEL CODE : TOWAREZE12VDAY406Z
MODEL/YEAR : NISSAN NOTE 1.2 SUPER CHARGE
ENGINE NO : HR121735288
CHASSIS NO : JN1TBAE12Z0982402
MILEAGE : 28977 KM
DATE IN : 01/03/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 28/02/2018

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian

5/3/18

- Part by part repair

- Question Mark Item Photo

- Photo Before Paint

90036121

sebastianyeang@lkkauto.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLB2514T

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 CONI	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT	240.00	X
2 NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS	60.00	X
3 RCI	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	120.00	✓
4 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	240.00	120
5 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	✓
6 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	300.00	100
7 WHI	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/ SHORT CIRCUIT, REPAIR WHEN NECESSARY	240.00	X
8 ZZ/001	RENEW REAR BUMPER, BRACKETS, ENERGY ABSORBER, UPPER PANEL, STAYS, TAILGATE, WEATHERSTRIP, LUGGAGE PLATE		
9 ZZ/002	ETC PANELS & REPAIR <i>250/day</i>	2000.00	1000
10 ZZ/003	REMOVE & INSTALL REAR CARPETING TO FACILITATE REPAIR	120.00	✓
11 ZZ/004	REPLACE TAILGATE GLASS TO FACILITATE REPAIR	150.00	✓
12 ZZ/005	INSTALL SOLAR FILM ON TAILGATE GLASS	144.00	✓
13 ZZ/006	RESPRAY REAR BUMPER, TAILGATE, UPPER PANEL ETC <i>200/panel</i>	1000.00	600
14 ZZ/007	QC, RETUNE & CONSULT CHECK		
15 ZZ/008	WASH & VACUUM, POLISH & WAX, SHINE ALL TYRES	120.00	X
TOTAL LABOUR CHARGES		4789.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLB2514T

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	REAR W/SCREEN SEALANT ✓ NEC	SEALANT - 4			?	80.00
2	REVERSE SENSOR { ✓ DMC	SENSOR-TE5140			✓	180.00
3	DIGI-S EMBLEM nbs ✓ NEC	90893-3VU0A	✓			51.20
4	NOTE EMBLEM ✓ NEC	90892-3VA0A				73.60
5	NISSAN EMBLEM ✓ NEC	90890-3VA0A				59.70
6	TAILGATE HANDLE ?	90606-3VA0A				215.30
7	ACTUATOR ?	90550-1HMOA				156.90
8	LOCK ?	90502-1HM1A				116.70
9	STRIKER ?	90570-1HMOB				31.70
10	LUGGAGE PLATE ?	84992-3VA0A				63.50
11	WEATHERSTRIP ?	90830-3VA0A				64.80
12	TAILGATE CENTRE PANEL ?	90810-3VA5C				243.90
13	TAILGATE GLASS ✓ NEC	90300-3VA0A				1240.00
14	TAILGATE ✓ DT	K010M-3VAMA				976.40
15	RIGHT BUMPER BRACKET ?	85220-3VA0C				44.00
16	LEFT BUMPER BRACKET ?	85221-3VA0C				44.00
17	BUMPER STAY (\$86.60 EA X 2) ✓ NEC	H5212-1HMMA				173.20
18	ENERGY ABSORBER ?	85090-3VA0A				111.90
19	CLIP (\$1.20 EA X 3) ✓ NEC	01553-10501				3.60
20	REAR BUMPER ✓ Deform	85022-3VA0H				414.00
21	REAR UPPER PANEL (End panel) ?	79100-3VA0A				552.80
22	LEFT CLOSING PLATE ?	78819-3VA0A				45.00
23	RIGHT CLOSING PLATE ?	78818-3VA0A				45.00
24	FUEL LID X	78830-3VA0A				74.60
25	RIGHT TAIL LAMP ?	26550-3VA5B				293.70

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLB2514T

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
26	LEFT TAIL LAMP ?	26555-3VA5B	293.70			
27	LICENSE PLATE LAMP ASSY (\$62.10 EA X 2) ?	26510-8991B	124.20			
SUB TOTAL			5513.40	0.00	260.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1102.68	0.00	0.00	
GRAND TOTAL			4410.72	0.00	260.00	
OVERALL TOTAL			4670.72			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLB2514T

TOTAL LABOUR CHARGES	4789.00
TOTAL SPARE PARTS CHARGES	4670.72
GRAND TOTAL	9459.72 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

4105/na3



Service Request Details

Claim

S8M009VS

Reference

None

Loss Date

February 28, 2018

Request Date

March 2, 2018

Due Date

March 9, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

02032018 @ 2.28pm
Shawn veh nr/in
9645 0023

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLB2514T

Make

TPVD NISSAN

Service Address

...

Primary Contact/Insured

KHIM SEAH ENTERPRISE PTE. LTD.

206 WOODLANDS IND PARK E5, WOODLANDS BIZHUB, 757284, Singapore

Claim Handler

TAY Ernest

6568804835

ernest.tay@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: RUTH CHUA

Ref: CS3/ASM18004105/Sa3s2
Date: 03-05-2018
Code: ASM



1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	PC 8182A	Veh. Inspected	SLB 2514T
Policy No.	P0902358	Coverage (\$)	0.00
Claim No.	S8M009VS	Excess (\$)	0.00
Assign From		Assign Date	02/03/2018

2. Vehicle Particulars & Condition

Make & Model	NISSAN NOTE	c.c	1198
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JN1TBAE12Z0982402	Colour	GREY
Odometer	29174 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65R15	CONTINENTAL	6 mm
L/H Front Tyre	185/65R15	CONTINENTAL	6 mm
R/H Rear Tyre	185/65R15	CONTINENTAL	6 mm
L/H Rear Tyre	185/65R15	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.	
--	--

5. General Information

Accident Date	25/02/2018	Inspect Date / Time	05/03/2018 (09:35 AM)
Survey held at	HAN CAR REPAIRS BLK 1001 #01-49 BUKIT MERAH LANE 3 ALEXANDRA VILLAGE SINGAPORE 159718		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Report Ref No. CS3/ASM18004105/Sa3s2

Inspected By

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.