

INS. CASE OWNER:

CC 4/AIG1800 4149, K j23h

LKK:
IDAC:

Surveyor:

FSL

DOI:

ASSIGNMENT

14/7/18

Date / Time:

5/8/18

Registered in Merimen:

5/8/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SLV 4802R.

Name of Insured : HANNA BEL

Insured Tel No. : HP:

Excess Sec II : S\$ D.O.A. : 1/2/18

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : YU XIANDONG

Driver Tel No. : 90730657 (V/L: YES / NO)

Claim No. : 64298210859

Policy No. :

Make / Model : AVO1

Place of Accident : DIE HOUSE TO EAT 16

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

INSRS:
WSP: cheng
Tel: hoe
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time:

7/8/18

709.

12-3-18
C 345SLV 4802R - 64298210859
THIN 2 & 01, CONFIRMED ACC.
AGREED & AWAKE NCD ISSUE.

RECEIVED 03 SEP 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OF:

After call ltr to OF:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup) X

After call ltr to OF:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice: X

Towing Invoice X

LTA / GIA: X

Medical Bill: X

PIR: X

Mandate/Reject Instruction: X

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No. : 27

If NO or B 28, Ass. Lia :

Repair Cost:

S\$

3,189.56

01 HIT TP FROM REAR.

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

400

(S 100 x 4 days)

Loss of Income (LOI):

S\$

-

(S x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost:

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

3,589.56

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

3,589.56

Name 1:

CHENG HOE MOTOR PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

X

Payee 3: (Strike if N.A.)

S\$

Name 3:

X

ASS. REC. BY:

REF:

A/G/1

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STS 8998Y

Yr Regn:

05, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mer 21A 220 c.c. 2143

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading:

79165

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD 117 3032 N070394

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

235/35R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) SUMI /
TOYO / YOKO or

Front

Rear

R/Bal:

7

mm

R/Bal:

7

mm

L/Bal:

7

mm

L/Bal:

7

mm

D.O.A.

9/2/18

D.O.I.

12/3/18

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/3 File sent to Catherine

2980.90 Confirmed Time (3+1 x 100)

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/AIG18004149/jb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 05-03-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLV 4803R	Veh. Inspected	SLS 8999Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	05/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	09/02/2018	Inspection Date	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@chmotor.com.sg
 GST:201001158E RCB NO:201001158E

SJS 8999Y

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000 FAX: 64153727

ATTN: Motor Claim Department \ THE MOTOR

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 09/02/2018

TP Veh Reg No: SLV4803R

Estimate No: ES1890241/YISHUN
 Date: 12 Mar 2018
 Policy No: 8-V0010530-MVA-R002
 Veh Reg No: SJS8999Y
 Make/Model: MERCEDES CLA 220
 Chassis No: WDD1173032N010394
 Engine No: 65193031640599
 Reg. Date: 06/05/2014

Not Authorized
1-3-1
Survey by pass
3 days

Estimate Repair Cost to Vehicle No :SJS8999Y

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 REAR BUMPER	1,440.00	1 PC	1,440.00	✓
2 REAR BUMPER REINFORCEMENT	560.00	1 PC	560.00	X
3 REAR BUMPER CENTRE LOWER GRILLE	215.00	1 PC	215.00	✓
4 REVERSE SENSORS	173.00	2 PCS	346.00	✓
			2,561.00	
		Less 10%	256.10	2,304.90
Labour				
5 REMOVE & REFIX REAR BUMPER ASSY,CENTRE LOWER GRILLE,REINFORCEMENT,REVERSE SENSOR & REALIGN THE SAME	380.00	1 LA	380.00	280
6 PUTTY & RESPRAY ON REAR BUMPER	300.00	1 LA	300.00	250
7 TO REPLACE REAR BUMPER WRAPPING	750.00	1 LA	750.00	650
			1,430.00	1,430.00
			Total	S\$ 3,734.90
			Add GST @ 7%	261.44
			Total Amount Payable	S\$ 3,996.34

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

CASH BILL

M/s.

Mr. GARY

558999



No: 1055

Date: 20 03 18

數量 Quantity	摘要 Description	價格 Price	銀額 Amount
1x	Bumper (back) wrap color matte red.	\$550.00	

Total \$550



Signature

Received By

Transfer Fee Enquiry

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SJS8999Y
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	With Sun Roof
Vehicle Scheme :	Normal
Vehicle Make :	MERCEDES BENZ
Vehicle Model :	CLA 220 CDI A
Chassis No. :	WDD1173032N010394
Propellant :	Diesel
Engine No. :	65193031640599
Engine Capacity :	2143 cc
Maximum Power Output :	125.0 kW (167 bhp)
Maximum Laden Weight :	2005 kg
Unladen Weight :	1525 kg
Year Of Manufacture :	2013
Original Registration Date :	06 May 2014
Lifespan Expiry Date :	-
COE Category :	E - Open Category
Quota Premium :	\$73,810.00
COE Expiry Date :	05 May 2024
Road Tax Expiry Date :	05 May 2018
PARF Eligibility Expiry Date :	05 May 2024
Inspection Due Date :	05 May 2019
Intended Transfer Date :	10 Feb 2018
CO2 Emission :	117.00 (g/km)
CEV/VES Rebate Utilised Amount :	\$15,000.00
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

The current road tax expiry is 05 May 2018. You may renew the road tax. If the road tax is renewed after 05 May 2018, late renewal fee(s) will check on the late fee(s) payable.

PAYMENT ADVICE

Your Ref : AIG Vehicle no.	:	SLV4803R
Claimant Vehicle No.	:	SJS8999Y
Date of Accident	:	09/02/2018
Traffic Accident involving vehicle/s No.	:	PIE (29KM MARKER) - BEFORE EXIT 28

BREAKDOWN OF PAYMENT/S

<u>S/No.</u>	<u>Items</u>	<u>Amount</u>	<u>Remark</u>
1	Repair cost	\$ 3,189.56	
2	Loss of Use	\$ 400.00	\$100 X 4 days
3	LTA Search	-	
TOTAL		\$ 3,589.56	

All payment should be made payable to Cheng Hoe Motor Pte Ltd.

Service Adviser : LKK
Contact No. : 6256 3561

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Saturday, 17 March 2018 3:19 PM
To: 'bei.zhang@puentradings.com.sg'
Cc: Vivian Lau (LKKAuto); Thin Thin (LKKAuto); Admin A
Subject: ACCIDENT INVOLVING SLV 4803R AND SJS 8999Y ON 09/02/2018

Our ref: CC4/AIG18004149/Kjb3

ZHANG BEI

Policy Holder

Dear Sir/Madam,

ACCIDENT INVOLVING SLV 4803R AND SJS 8999Y ON 09/02/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

AUTHORISATION TO ACT
(AIG Asia Pacific - Express Third Party Claim)

I, Ang Johnny (the third party claimant) of 1 Jalan
Kemuning S 769720 (address), owner of SJS8999Y (vehicle no.) hereby
authorize CHENG HOE MOTOR PTE LTD ("the workshop") to act for me with respect to
my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SJS8999Y that
was damaged pursuant to the accident which occurred on 9/2/2018 (date) along PIE (29km
Marker) - before Exit 28 (location) involving vehicle no/s SLV4803R ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the
workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s
being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice
and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is
concerned.

Dated this 10 (day) of Feb (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

This Discharge Voucher applies strictly for Claimant's claim for property damages only does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident.

This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

RELEASE VOUCHER

(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

"We/I, **CHENG HOE MOTOR PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$3189.56** (Repair Cost), **S\$400.00** (Loss of Use), **S\$ —** (Disbursement), for vehicle no **SJS8999Y** that was damaged pursuant to the accident which occurred **09/02/2018** (date) along **PIE (29KM MARKER) –Before Exit 28** (location) involving vehicle no/s **SLV4803R**

This is pursuant to the inspection conducted on **12/03/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **Ang Johnny** ("the third party claimant") of vehicle no. **SJS8999Y** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage **SJS8999Y** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 4 (day) of SEPT. (month) 2018 (year)


Signed by appointed surveyor


Signed by "the workshop" (with chop)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/YS
Claim Type: Third Party
Accident Date: 09/02/2018
TP Veh Reg No: SLV4803R

NO: CL8180917
Date: 21 Aug 2018
Policy No: 8-V0010530-MVA-R002
Veh Reg No: SJS8999Y
Make/Model: MERCEDES CLA 220
Job No: JC1598120

Description	Quantity	List Price	PAGE:1
			Amount
To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges. (As recommended by your appointed surveyor)	1 PC	SS 2,980.90	SS 2,980.90

Total	SS 2,980.90
Add GST @ 7%	208.66
Total Amount payable	SS 3,189.56

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Feb 2018 Edit Reg		05 Mar 2018 00:00 Edit Adj Rpt	\$2,980.90 Edit Estimates	\$2,980.90 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	ZHANG BEI , ID: S7087327C								
Main Claimant:	ANG JOHNNY , ID: S1637993Z								
Vehicle Reg. No.:	SJS8999Y	Date of Loss:	09/02/2018 17:00 - :59 [45 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6479832158SG	Policy/Cover Note No.:	1700090252 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLV4803R	Policy No. (Claimant):	8-V0010530-MVA-R002						
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com								
Claimant's Insurer:	QBE Insurance (Singapore) Pte Ltd (HQ) - Tel: 62246633								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 14/03/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJS8999Y (6479832158SG)
[SLV4803R]
TP
ANG JOHNNY
Feb 9 2018 5:00PM
[ZHANG BEI]
Cheng Hoe Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences				
			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	
Assessment Reports				
			1 per page <input type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	06/03/18 11:31	Accident Statement <small>From: OD - Reg. No: SLV4803R, Claimant: ZHANG BEI</small>	Load HTM	
Photos/Images				
			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/09/18 09:54	General View	Load JPG	<input checked="" type="checkbox"/>
2	04/09/18 09:54	General View	Load JPG	<input checked="" type="checkbox"/>
3	04/09/18 09:54	General View	Load JPG	<input checked="" type="checkbox"/>
4	04/09/18 09:54	General View	Load JPG	<input checked="" type="checkbox"/>
5	04/09/18 09:54	General View	Load JPG	<input checked="" type="checkbox"/>
6	04/09/18 09:54	General View	Load JPG	<input checked="" type="checkbox"/>
7	04/09/18 09:54	General View	Load JPG	<input checked="" type="checkbox"/>
8	04/09/18 09:54	General View	Load JPG	<input checked="" type="checkbox"/>
9	04/09/18 09:54	General View	Load JPG	<input checked="" type="checkbox"/>
10	04/09/18 09:54	General View	Load JPG	<input checked="" type="checkbox"/>
11	04/09/18 09:54	General View	Load JPG	<input checked="" type="checkbox"/>
12	04/09/18 09:54	General View	Load JPG	<input checked="" type="checkbox"/>
13	04/09/18 09:54	General View	Load JPG	<input checked="" type="checkbox"/>
14	04/09/18 09:54	General View	Load JPG	<input checked="" type="checkbox"/>
15	04/09/18 09:54	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation				
			1 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/03/18 13:55	EMAIL FROM AIG DD 05032018	Load PDF	
2	05/03/18 13:55	TP GIA REPORT	Load PDF	
3	13/03/18 18:46	TP ESTIMATE- MARKED	Load PDF	
4	17/03/18 15:22	LETTER TO INSURED	Load PDF	
5	10/09/18 10:52	WORKSHOP INVOICE	Load PDF	
6	10/09/18 10:52	AUTHORISATION TO ACT FORM	Load PDF	
7	10/09/18 10:52	Release Voucher	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset Save Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLV4803R (Insd veh)	Model:	MERCEDES-BENZ CLA 220
	SJS8999Y (TP veh)		2.1 CDI (C117) (A)
Date of Accident:	09/02/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	3,996.34	
Final Repair Cost	:	\$	3,189.56	
Loss of Use	:	\$	400.00	4.00 days at \$100.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	0.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	3,589.56	

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Cheng Hoe Motor Pte Ltd	:	\$ 3,589.56
2)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

10 Sep
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18004149/KJB3Q2

Date: 10/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700090252
Claimant Vehicle No : SJS8999Y **Insured Vehicle No :** SLV4803R
 Date of Loss: 09/02/2018 Nature of Claim: TP Claim No: 6479832158SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJS8999Y**
 Make & Model: MERCEDES-BENZ CLA 220, 2.1 CDI (C117) (A) Engine No: 65193031640599
 Reg. Date: 06/05/2014 (Man. Year: 2013) Chassis No: WDD1173032N010394
 Colour: White Odometer: 79165 km
 Engine Capacity: 2143 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35 R19 Rear Tyre Size: 235/35 R19
 Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm
 Front Right Side: Pirelli 7 mm Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,304.90	1,800.90	504.00	21.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	1,180.00	250.00	17.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,734.90	2,980.90	754.00	20.19
+ GST 7.00/7.00% (S\$)	261.44	208.66	52.78	20.19
Nett Amount (S\$)	3,996.34	3,189.56	806.78	20.19
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
	Nett Liability (S\$)	3,589.56		

INSPECTION

Date of Assignment: 05/03/2018
 Date Inspected: 12/03/2018 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761
 Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Buckled	1,440.00 FN	*1,440.00 FN
2	1		*REAR BUMPER REINFORCEMENT	Repair	560.00 FN	*- FN
3	1		*REAR BUMPER CENTRE LOWER GRILLE	Dented	215.00 FN	*215.00 FN
4	2		*REVERSE SENSORS	Shorted	346.00 FN	*346.00 FN
					Sub Total (S\$)	2,561.00 2,001.00
					- Nett Item Discount on N Items 10.00/10.00% (S\$)	256.10 200.10
					Total Parts (S\$)	2,304.90 1,800.90

F=Franchise part. N=NetItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX REAR BUMPER ASSY ,CENTRE LOWER GRILLE ,REINFORCEMENT ,REVERSE SENSOR & REALIGN THE SAME	New	380.00	280.00
2	PUTTY & RESPRAY ON REAR BUMPER	New	300.00	250.00
3	TO REPLACE REAR BUMPER WRAPPING	New	750.00	650.00
Gross Labour Cost (S\$)			1,430.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >