

ASS. REC. BY:

REF:

CS/ASM/8004164/Agd3er

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Peter wang

of

ASMDate/Time: 5/3/18

Estimated Cost:

Bill to:

 TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP6072Y

Insured:

at Workshop m/s

United SG Automobile

Tel:

90077556 / 67474454

of

53 Ubi Ave 1 # 01-56

Policy No:

Claim No:

S8M009NH

Sum Insured:

Excess:

\$2,800.00

Make of Veh:

(Client's Record)

D.O.A. 23 / 02 / 18CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:01am 5/3/18

Person Contacted:

SeanVehicle IN / OUT

Date/Time	Action/Instruction	Estimate
		<u>YP6072Y-X</u>
<u>07/31/18 @ 10:44am</u>	<u>revert to Peter Wang via Smart Claims.</u>	
<u>19/3/18 @ 11:40am</u>	<u>Yvonne Ang informed CIA on US \$47K via Smart Claims.</u>	
<u>19/3/18 @ 1:57pm</u>	<u>Informed Sean CIA not more than US \$40K & Ex: \$2800 by email.</u>	
	<u>US \$25000, 24 days (red \$74906.88, 75%)</u>	
	<u>*</u>	

REF:

Surveyor

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 85K

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 74 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: YP6072Y. Yr Regn: 2017 April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hino XZU70R. c.c. 4009.

Colour: White. A/C: Insured / Std / NI / NA

Sp.Reading: 25234 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHHUCS3H20K019494.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 7.00R16.

R: 7.00R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 05/03/18.

Survey held at United SG.

Des. of Damages: Fr / Rear / O/S / NI / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

AXA OD.

MV: 85K
PV: 35.21K
Nett: 49.8K.

RECEIVED 08 MAR 2019

90077556 skaa.

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 24

1) 08/3 typist

: Final Report

Resurvey No. of Trip: _____

Survey Fee: _____

Date/Time, File Return to?

Transportation: _____

2) _____

Add Fee:

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

) \$ + RS. \$ _____

) Photos _____

) Others _____

) _____

Report Format: Smart Claim

Lump Sum / I.B.I. (\$ _____)

25000

TOTAL

300



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CS/ASM18004164/Aqd3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 05-03-2018	
		Code : ASM	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	YP 6072Y
Policy No.		Coverage (\$)	0.00
Claim No.	S8M009NH	Excess (\$)	2,800.00
Assign From	SMARTCLAIM (PETER WANG)	Assign Date	05/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/02/2018	Inspection Date	05/03/2018
Survey held at	-		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

◀ Service Request Details

Claim

S8M009NH

Reference

None 

Loss Date

February 23, 2018

Request Date

March 2, 2018

Due Date

March 9, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

YP6072Y

Make

HINO

Service Address

53 UBI AVENUE 1, , 408934

Primary Contact/Insured

CHIT HUAT PTE LTD

BLK 18 PASIR PANJANG, #01-123 WHOLESALE CENTRE, 110018, Singapore
65674755

Claim Handler

WANG Peter

peter.xiao@axa.com.sg

Additional Instructions

Excess: \$800+\$2000 (DL<1yr) United SG Automobile Please also check for any tire and mechanical issu...
(expand)

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 19 March 2018 1:52 PM
To: claims@unitedsg.com.sg
Cc: SUR
Subject: VEHICLE YP 6072Y (DOA: 23/02/18)

Dear Sean,

As spoken with you.

As instructed by our client AXA Insurance, please proceed to repair the insured vehicle **YP 6072Y** at repair cost not more than Lump Sum \$40,000.00 (excess \$2,800/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Authorized

Type

🔗 Question

Message

Hi Shiau Chan As spoken to proceed with lump sum repair at \$42K

Reply

◀ **RE: Comment on tyre & mechanical condition based on service record**

Type

🔗 Question

Message

Dear Peter, the service record provided only described the normal routine maintenance of the vehicle, which does not related to any mechanical / tyre issue. - Shiau Chan

Reply

◀ Comment on tyre & mechanical condition based on service record

Type

🗨 Question

Message

Our investigator provided us the investigation report. Please refer to the linked service record and comment again if there is any related mechanical / tyre issue. Policy covers attached canopy.

Reply

The service record ~~is~~ provided only described the normal routine maintenance of the vehicle, which does not relate to any mechanical, tyre issue.

13-03-18;13:42 ;From:

To:67796251

;63856097

1/ 1

FAX: 67796251

ATTN: MR TAN

TAX INVOICE

Hino Service Centre
No. 2 PANDAN CRESCENT
SINGAPORE 120462
Tel no.: 6631 1188 / 6631 1818

Hino Care Program-Prepaid
REV8

15500502 /BHSC

41015409

28/12/2017

M/s Chit Huat Pte Ltd
18 Wholesale Centre
#01-123
Singapore 110018

Home: 67792118

16 HKFMS3 XZU710R 18/04/2017 YP6072Y 20799 18540 YP6072Y

JNHUCS3H20K019494 N04CUS30526 00 Henry Lau 28/12/2017 10.09 28/12/2017 12.52

M	HN20-XZU710				
1 *	HN20	20 000KM HINO SERVICE PACKAGE	29		364.49
		MR LAM/91361072			
		MS TAN(PIC)/92734759			
		NEXT SVC AT 30799KM OR 4TH WEEKS OF MARCH 2018			
		WHICHEVER COMES FIRST.			
2 *	O-CJ4	2L DIESEL ENGINE OIL, CJ4, 15W40	8.00		
3 *	H15613-EV015	ELEMENT, OIL FILTER	1.00		
4 *	H23304-78091	ELEMENT SET, FUEL	1.00		
5 *	H52430-10009	GASKET DRAIN PLUG	1.00		
6 *	H23304-EV051	ELEMENT SET, FUEL FILTER	1.00		

364.49

0.00 GST 0.00% 0.00

0.00 0.00

0.00 0.00

0.00 0.00

364.49 364.49

28/12/2017
12:53

YP6072Y

« IA OF VEHICLE YP 6072Y UPLOADED.

Type

🔔 Question

Message

Dear Peter, please be informed that the IA of YP 6072Y uploaded. Damages consistent. Repair cost economical. According to our surveyor, no mechanical issue and tires are in servicing condition. Kindly advice the canopy is under insured policy. Lump Sum repair letter uploaded. The vehicle repair on Lump Sum basis. We have not authorise repair. - Shiau Chan

[Reply](#)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S8M009NH

Date: 06th March 2018

Our Ref: CS/ASM18004164/Aqd3

The Motor Claims Department
AXA Insurance Singapore Pte L td

Attn: Peter

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. YP 6072Y .


We thank you for the instruction on 05/03/2018 .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 05/03/2018 (2.38am) at the premises of M/s UNITED SG AUTOMOBILE and have the following to report:-

Workshop Estimate Amount	: S\$	<u>99,906.88</u>	.
Revised Estimate Amount	: S\$	<u>34,877.24</u>	.
"Check" Items Amount	: S\$	<u>14,377.85</u>	.
Total	: S\$	<u>49,255.09</u>	.
Market Value	: S\$	<u>85,000.00</u>	.
LTA Reimbursement Value	: S\$	<u>35,228.00</u>	.
Nett Value	: S\$	<u>49,772.00</u>	.

Description of Damage:

The vehicle sustained damages at the front, rear, n/s & o/s portion and undercarriage.



Comments/ Present Status:

Damages consistent. Repair cost economical.

No mechanical issue and tires are in servicing condition.

Recommend days of repair: 24 days

We have NOT authorised the repairs.

Yours faithfully

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

LETTER OF UNDERTAKING/ AUTHORIZATION FOR LUMP SUM REPAIR

1. I, [Name] [NRIC] TAN ENY CHUAN S2086836H, the owner/ authorized driver of vehicle [Registration No.] YP 6072Y ("Vehicle") do hereby authorize the [Workshop/Insurer] to repair the Vehicle on a lump sum basis instead of part by part.
2. The [Workshop/Insurer] has explained to me the difference between lump sum repair and part by part repair and the consequences of my authorization for lump sum repair for the Vehicle.
3. I understand that with lump sum repair, the Workshop may use a mixture of genuine parts, original equipment manufacturer (OEM) parts, reconditioned and second hand parts to carry out the repair and I note that the [Workshop/Insurer] will not be furnishing a detailed breakdown of parts or price for such lump sum repair.
4. I am aware that AXA Insurance Pte Ltd ("AXA Insurance") does not encourage lump sum repair as AXA Insurance strongly recommends repairs for vehicles on a part by part basis for transparency reasons. I confirm that I will hold AXA Insurance harmless from any claims arising from the lump sum repair of the Vehicle which I have authorized.
5. * To be applicable where person authorizing is the authorized driver.
I confirm that I have the authority from the owner of the Vehicle to authorize the lump sum repairs and that I have duly notified the owner of the Vehicle of the contents of this Letter of Authorization.

Signed and acknowledged by:

陳英宇



Signature of policyholder/ authorized driver* and company stamp (where applicable)

Date:

UNITED SG AUTOMOBILE PTE LTD
CO. REG. NO: 201729521C
53 PAYA UBI INDUSTRIAL PARK #01-56
SINGAPORE 408931

Sean Lian

Name and signature of workshop personnel including workshop stamp

Date:

6/3/18

*authorized driver to either the named drivers as per motor insurance policy or in the case of commercial vehicles, permitted drivers who are permitted to drive the insured Vehicle.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6362H
Vehicle Details	
Vehicle No.:	YP6072Y
Vehicle to be Exported:	Yes
Intended De-registration Date:	05 Mar 2018
Vehicle Make:	HINO
Vehicle Model:	HINO XZU710R-HKFMS3
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	N04CUS30526
Chassis No.:	JHHUCS3H20K019494
Maximum Power Output:	-
Open Market Value:	\$30,585.00
Original Registration Date:	18 Apr 2017
First Registration Date:	18 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$1,530.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 Apr 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$44,036.00
COE Rebate Amount:	\$35,228.00
Total Rebate Amount:	\$35,228.00

The information contained herein is correct as at 05 Mar 2018

OK

FREE VALUATION
 Let us tell you how much your car can sell for!
No obligations and it's FREE!

How much is my car worth?

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

New 5 Year Coe Renewal Toyota Vios 1.5A



\$2500 Downpayment Monthly
 From \$580 Onwards. Lowest
 3.68%PA @ GV Cars Financing.
 GV Credit Pte Ltd StarAd

Think One Automobile

NEW & USED COMMERCIAL VEHICLES

Post an Ad Advertiser Login Ways of Selling

Browse by Category

Sort by Date Posted 20 results/page

6 vehicles

Hino XZU710R

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Hino	XZU710R	Any	Any	Any	Any	Any	Any	Available



Hino XZU710R **\$62,800** **\$10,540 /yr** **18-Feb-2014** **4,009 cc** **17,000 km** **Truck** **Available**

Fuel Type: Diesel
 Box With Tailgate 14ft Lorry, Still Under Agent Warranty, Original Paint Work, Vehicle Like New Condition, In House Loan Available, Trade In Are Welcome, Door Step Viewing Can Be Arranged. Call Now Be...

ABWIN (1994) Pte Ltd
 Posted: 09-Jan-2018 Tags: 2014 Hino XZU710R, Hino XZU710R, Hino, XZU710R, Used Hino

PREMIUM AD



Hino XZU710R **\$71,800** **\$9,090 /yr** **25-Jan-2016** **4,009 cc** **-** **Truck** **Available**

Fuel Type: Diesel
 Cheapest Hino 14 Foot Canopy Lorry. Manual With 6 Gear Transmission. Vehicle In Tip Top Condition, Low Mileage And No Repair Needed. In House Loan Available. Trade In Are Welcome. Door Step Viewing Ca...

ABWIN Bus Pte Ltd
 Posted: 21-Feb-2018 Tags: 2016 Hino XZU710R, Hino XZU710R, Hino, XZU710R, Used Hino

PREMIUM AD



Hino XZU710R **\$69,999** **\$8,860 /yr** **27-Jan-2016** **4,009 cc** **16,500 km** **Truck** **Available**

Fuel Type: Diesel
 1 Owner. Very Low Mileage. Hino Care 5 Years.

Posted: 08-Feb-2018 Tags: 2016 Hino XZU710R, Hino XZU710R, Hino, XZU710R, Used Hino

DIRECT OWNER



Hino XZU710R **\$89,800** **\$10,320 /yr** **16-Nov-2016** **4,009 cc** **20,000 km** **Truck** **Available**

Fuel Type: Diesel
 No Agent Please, 1 Careful Owner, New Road Tax, Used 1 Year, 4 Years Agent Warranty, 20k Mileage, Free Servicing, Free Warranty, Serving At Agent, Need VPC.

Posted: 05-Feb-2018 Tags: 2016 Hino XZU710R, Hino XZU710R, Hino, XZU710R, Used Hino

DIRECT OWNER

Car Buying Car Selling Car Aftermarket
 Car Ownership On The Move Lifestyle

42233E **Bidded Carplates For Sale!**



Hino XZU710R **\$99,800** **\$10,070 /yr** **01-Feb-2018** **4,009 cc** **18 km** **Truck** **Available**

Fuel Type: Diesel
 Latest Euro 6 Hino XZU710R 14ft From Borneo Motors. 3 Or 100,000km Warranty. Free 20 Times Servicing Packages. Call Us Now For More Enquiries.

Posted: 07-Feb-2018 Tags: 2018 Hino XZU710R, Hino XZU710R, Hino, XZU710R, Used Hino

PREMIUM AD



Hino XZU710R **\$99,800** **\$9,990 /yr** **28-Feb-2018** **4,009 cc** **18 km** **Truck** **Available**

Fuel Type: Diesel
 Latest Euro 6 Hino XZU710R 14ft From Borneo Motors. 3 Or 100,000km Warranty. Free 20 Times Servicing Packages. Call Us Now For More Enquiries.

Posted: 02-Mar-2018 Tags: 2018 Hino XZU710R, Hino XZU710R, Hino, XZU710R, Used Hino

PREMIUM AD

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old adv view Expired ads

20 results/page

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate** as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	27/02/2018 15:18
Date Of Accident	23/02/2018 16:30
Exact Location Of Accident	CLEMENTI ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	YP6072Y
Insured/Policyholder	
Name Of Registered Owner	CHIT HUAT PTE LTD
Co Reg No	200306362H
Email Address	CHIT_HUAT@HOTMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-67792118
Vehicle Particulars	
Manufacturer	HINO
Model	XZU710R-HKFMS3-4.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1931732
Cover Note Number	
Driver	
Name of Driver	LAM HON HOU
Passport No/FIN	G8353712X
Date Of Birth	27/05/1985
Occupation	OUTDOOR
Date Of Driving Pass	09/09/2017
Driving Experience	0 YEAR AND 5 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91361072
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	18 WHOLESALE CENTRE #01-123
Postcode	110018
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CLEMENTI NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: NO. 20 CLEMENTI AVENUE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8729999 - FAX NO: 67748639
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN & POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE	YD 60727	ACCIDENT DATE & TIME	23.2.18 4.30pm.
CONTACT NUMBER	BA 67742118	E MAIL ADDRESS	chit_huat@hotmail.com
LOCATION	Clementi Road.		
Refer to Police report.			
<p>The lorry was travelling along Clementi Road towards AYE on 23 Feb 2018 at 4.30pm when the lorry skidded and lost control and hit the curb after the bus stop. Then hit the metal barrier and the lorry bounced off and hit the overhead bridge and finally stopped at the road sign.</p>			
<p>NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION</p>			
Please state:			
<input type="checkbox"/> Claim Own Policy <input type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only			

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Reporting Centre Personnel's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180223/2169

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

1 of 3

Report No. T/20180223/2169

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/02/2018 21:37	Vide Report No.: D/20180223/0090	Station Diary No.: 148
--	-------------------------------------	---------------------------

Informant's Particulars

Name of Informant: LAM HON HOU			Address:		
ID Type / ID No.: FIN NO / G8353712X			Contact No.: Home/Office: Mobile: 91361072		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 32	Date of Birth: 27/05/1985	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Lorry driver			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 23/02/2018 10:30	Type of Location: Straight Road
Location: Along Road 1 CLEMENTI ROAD Clementi Rd, Road Divider				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Road Divider/Kerb/Railings				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
YP602Y	Lorry				Seriously Damaged	0



**SINGAPORE
POLICE FORCE**



T/20180223/2169

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

2 of 3

Report No. T/20180223/2169

CONTINUATION OF REPORT

Brief Details.

On 23/02/2018 at around 1030hrs, I was driving along Clementi Rd towards AYE, the new lane towards AYE and my lorry skidded and banged into the road divider. I felt my tires give out and due to the wet weather, I skidded thus causing me to swerve and hit the divider. I did not suffer any injuries but my lorry YP602Y, suffered heavy damages at the front. The traffic Police soon arrived at my scene, Ref to incident no. D/20180223/0090.

I am lodging a report for record and insurance purposes.



**SINGAPORE
POLICE FORCE**



T/20180223/2169

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

3 of 3
Report No. T/20180223/2169

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
D /
NABIL FIKRI BIN ADNAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Sgt 2 LIM HONG LEE
Contact No.: 65476438

Signature Of Informant:

Date/Time:
23/02/2018 21:37

Classification Of Case:

Authentication Stamp
SINGAPORE
POLICE FORCE
SN 37

SIGNATURE

Sketch Plan Pg. 6



TRAFFIC POLICE
AMENDMENT

10 Ubi Avenue 3
Singapore 408865

NP 168 No: T/20180223/2169 Name: Lam Hon Hou
 Accident Date/Time: 23/02/2018 @ 1630hrs Address: _____
 Vehicle(s) involved: ~~YP607Y~~ ↑
YP6072Y NRIC No: G8353712X
 Tel No: 91361072
 Date: 24/02/2018

Dear Sir / Madam

I wish to amend as follows :

I wish to amend the accident time to 1630hrs instead of 1030hrs
 on the 23/02/2018 and the correct registration plate number is
 YP6072Y.


 Yours faithfully

Mr. [Name]
 Tel: [Number]
 Fax: [Number]

Sgt T150347
 YU JING XUAN


United SG Automobile Pte Ltd

"We are always in your journey"....

53 Ubi Ave 1, #01-56 Paya Ubi Industrial Park, Singapore 408934.

Tel : 6747 4454 Fax : 6747 7752

UEN No. 201729521C

ESTIMATION QUOTE

AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #24-01 AXA TOWER
 SINGAPORE 068811
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : YP6072Y
MAKE MODEL : HINO XZU710R
REFERENCE : USGOD-180201
DOA : 23-Feb-18
CLAIM TYPE : OWN DAMAGE

PAGE 1 OF 4

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
FRONT WINDSCREEN RUBBER <i>New</i>	1	\$ 442.40	✓
FRONT WIPER PANEL <i>Distorted</i>	1	\$ 1,536.00	+
FRONT CORNER PANEL <i>RH Corbel, LH Repair</i>	2	\$ 966.44	483-22
FRONT SIDE MIRROR <i>LH Corbel</i>	2	\$ 366.40	182.40 183.70
FRONT SIDE ROUND MIRROR <i>New</i>	2	\$ 293.70	x.
FRONT SIDE ROUND MIRROR ARM <i>New</i>	1	\$ 496.90	x
FRONT PANEL <i>Distorted</i>	1	\$ 2,350.20	898
FRONT REFLECTOR LAMP <i>RH Corbel, LH Repair</i>	2	\$ 565.50	1/2 282.75
HEADLAMP <i>LH</i>	2	\$ 2,450.30	2032
FRONT SIDE LAMP <i>New</i>	2	\$ 309.80	x.
FRONT GRILLE <i>Corbel</i>	1	\$ 739.40	-
FRONT GRILLE EMBLEM <i>New</i>	1	\$ 85.30	-
FRONT BUMPER <i>Distorted</i>	1	\$ 2,428.40	967
FRONT BUMPER BRACKET <i>Best</i>	2	\$ 264.30	✓
FRONT FLOOR PANEL <i>Repair</i>	1	\$ 2,817.39	+
FRONT DOOR PILLAR OUTER <i>Repair</i>	2	\$ 3,772.60	+
FRONT DOOR PILLAR INNER <i>Repair</i>	2	\$ 2,750.30	+
FRONT DOOR PANEL <i>Repair RH Corbel</i>	2	\$ 5,127.40	x. (512740) 1980 2x65.70
FRONT DOOR PANEL GARNISH <i>New</i>	2	\$ 529.40	+
FRONT DOOR HINGE <i>New</i>	4	\$ 458.40	+
FRONT DOOR ARRESTER <i>New</i>	2	\$ 285.40	+
FRONT DOOR GLASS <i>New</i>	2	\$ 1,484.40	+
FRONT DOOR GLASS RUN CHANNEL	2	\$ 598.60	+
FRONT DOOR GLASS OUTER MOULDING	2	\$ 265.90	+
FRONT DOOR GLASS INTER MOULDING	2	\$ 250.97	+
FRONT DOOR INNER TOP HANDLE	2	\$ 569.40	+
FRONT DOOR INNER TRIM TOP	2	\$ 364.20	+
FRONT RH DOOR INNER TRIM	2	\$ 1,924.98	x
FRONT DOOR GLASS REGULATOR	2	\$ 645.80	x
FRONT RH GLASS REGULATOR MOTOR	2	\$ 793.60	x
FRONT DOOR STRIKER	2	\$ 85.46	x

ESTIMATION QUOTE

AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #24-01 AXA TOWER
 SINGAPORE 068811
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : YP6072Y
MAKE MODEL : HINO XZU710R
REFERENCE : USGOD-180201
DOA : 23-Feb-18
CLAIM TYPE : OWN DAMAGE

PAGE 2 OF 4

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
FRONT DOOR WEATHERSTRIP <i>2 green</i>	2	\$ 670.10	+
FRONT DOOR FRAME WEATHERSTRIP <i>2 green</i>	2	\$ 287.40	+
FRONT DOOR ARCH SEAL	2	\$ 168.30	x
FRONT STEP PANEL <i>Not in</i>	2	\$ 809.20	+
FRONT STEP GARNISH <i>Cracked</i>	2	\$ 558.20	✓
FRONT WHEEL ARCH PANEL <i>2 green</i>	2	\$ 994.40	+
FRONT WHEEL ARCH GARNISH	2	\$ 274.50	+
AIR PRESSURE TANK <i>Not Rec</i>	1	\$ 353.40	+
AIRCON CONDENSER <i>Bent</i>	1	\$ 1,945.30	+ 1679
AIRCON DISCHARGER TUBE <i>Bent</i>	1	\$ 455.00	+
AIRCON DISCHARGE HOSE <i>Bent</i>	1	\$ 572.00	+
AIRCON LIQUID TUBE <i>Bent</i>	1	\$ 330.90	+
AIRCON CONDENSER FAN ASSY <i>Cracked</i>	1	\$ 536.90	+
AIRCON CONDENSER BRACKET <i>Bent</i>	1	\$ 317.34	+
DASHBOARD TOP	1	\$ 2,274.10	+
DASHBOARD BOTTOM	1	\$ 1,892.30	+
DASHBOARD SIDE COVER	1	\$ 237.34	+
DASHBOARD REINFORCEMENT <i>Not in</i>	1	\$ 1,925.60	+
SPEEDOMETER ASSY	1	\$ 2,206.89	+
SPEEDMETER GANRISH	1	\$ 246.00	+
STEERING COLUMN ASSY <i>Not Rec</i>	1	\$ 2,723.60	+
STEERING SHAFT JOINT ASSY <i>Not in</i>	2	\$ 1,854.70	+
P/STEERING <i>Not in</i>	1	\$ 3,947.50	+
P/STEERING TIE ROD END <i>Not Rec</i>	2	\$ 343.90	+
FRONT SHOCK ABSORBER <i>Not in</i>	2	\$ 965.20	+
FRONT UPPER ARM <i>Not Rec</i>	2	\$ 851.40	+
FRONT WHEEL HUB ASSY <i>7 Damp</i>	2	\$ 1,032.40	? 650
FRONT KNUCKLE ARM <i>Bent</i>	2	\$ 1,817.43	? 1100
FRONT LOWER ARM <i>Bent</i>	2	\$ 2,506.50	? 850
SIDE REINFORCEMENT BAR <i>Bent</i>	2	\$ 800.30	✓
REAR EXHAUST BRACKET	1	\$ 67.90	x
REAR EXHAUST GASKET	1	\$ 42.34	+
REAR EXHAUST RUBBER MOUNTING <i>Not in</i>	2	\$ 70.40	+
REAR EXHAUST SILENCER BOX <i>Bent</i>	1	\$ 856.32	✓
REAR LH CHASSIS SIDE FRAME <i>Cracked</i>	1	\$ 3,390.44	1200(SN)
REAR SIDE WODDEN GATE <i>200 Cracked</i>	2	\$ 3,855.02	1300(SN)
REAR SIDE GATE FLIP LOCK HANDLE <i>Bent</i>	2	\$ 298.60	✓
REA SIDE GATE HINGE <i>1 piece bent</i>	1	\$ 1,408.68	75
REAR SIDE GATE BRACKET <i>2 pieces bent</i>	2	\$ 124.70	60(SN)
REAR TAILLAMP <i>Cracked</i>	2	\$ 517.90	✓

ESTIMATION QUOTE

AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #24-01 AXA TOWER
 SINGAPORE 068811
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : YP6072Y
MAKE MODEL : HINO XZU710R
REFERENCE : USGOD-180201
DOA : 23-Feb-18
CLAIM TYPE : OWN DAMAGE

PAGE 3 OF 4

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
REAR TAILLAMP BRACKET <i>Best</i>	2	\$ 196.44	✓
REAR WOODEN TAILGATE <i>Buy d.</i>	1	\$ 2,452.30	<i>200 (20)</i>
REAR TAILGATE HINGE <i>new</i>	6	\$ 704.34	✓
REAR TAILLAMP LOWER PANEL <i>Best</i>	1	\$ 747.35	✓
REAR TAILGATE LOWER PANEL NUMBER PLATE BRACKET <i>Best</i>	1	\$ 39.40	✓
REAR TAILGATE LOWER PANEL STEP BRACKET <i>Best</i>	1	\$ 479.40	✓
REAR TAILGATE OUTER LOCK HANDLE <i>Best</i>	1	\$ 221.52	✓
REAR TAILGATE LOWER PANEL NUMBER PLATE LAMP <i>new</i>	2	\$ 162.70	✓
REAR DIFFERENTIAL ASSY <i>not new</i>	1	\$ 5,600.00	✗
REAR FUEL TANK <i>used</i>	1	\$ 1,204.00	✓
REAR FUEL TANK BRACKET <i>Best</i>	1	\$ 301.00	✓
REAR LEAF SPRING <i>not new</i>	4	\$ 950.00	✗

1979512
16795133 *S.N. 3360.*
 \$ 93,608.09
 LESS 15% \$ 14,041.21
SUBTOTAL \$ 79,566.88
BALANCE C/F \$ 79,566.88

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
		BALANCE B/F	\$ 79,566.88

FRONT NUMBER PLATE <i>Best</i>	1	\$ 80.00	✓
REAR NUMBER PLATE <i>missing</i>	1	\$ 80.00	✓
JOINT SEALANT <i>new</i>	1	\$ 150.00	✓
WINDSCREEN SEALANT <i>new</i>	1	\$ 150.00	<i>120</i>
RIM <i>Best</i>	4	\$ 2,400.00	<i>1200</i>
TYRE <i>1 piece deflated</i>	4	\$ 800.00	<i>200</i>
BRAKE FUILD <i>3 new</i>	1	\$ 60.00	<i>40</i>
P/STERRING FUILD <i>3 new</i>	1	\$ 80.00	<i>40</i>
24 PAX STICKER <i>3 new</i>	1	\$ 70.00	<i>15</i>
60/KM STICKER <i>3 new</i>	1	\$ 70.00	<i>15</i>
REAR CANOPY ASSY <i>distorted</i>	1	\$ 8,500.00	<i>3800</i>

SUBTOTAL \$ 12,440.00
BALANCE C/F \$ 92,006.88

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
		BALANCE B/F	\$ 92,006.88

CHECK WIRING AND LIGHTNING SYSTEM	1	\$ 100.00	<i>60</i>
REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	2	\$ 200.00	<i>60</i>
REMOVE AND RENEW FRONT WINDSCREEN	3	\$ 150.00	<i>120</i>
REMOVE AND RENEW FRONT DASHBOARD	4	\$ 500.00	<i>200</i>

7590

ESTIMATION QUOTE

AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #24-01 AXA TOWER
 SINGAPORE 068811
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : YP6072Y
MAKE MODEL : HINO XZU710R
REFERENCE : USGOD-180201
DOA : 23-Feb-18
CLAIM TYPE : OWN DAMAGE

PAGE 4 OF 4

LABOUR	QTY	LIST PRICE (\$)	REMARKS
REMOVE AND RENEW FUEL TANK	5	\$ 150.00	100
CHECK FRONT AND REAR WHEEL ALIGNMENT	6	\$ 200.00	120
REMOVE AND REPLACE FRONT AND REAR UNDERCARRIAGE	7	\$ 400.00	✓
REMOVE AND REPLACE AIRCON CONDENSER AND TOP UP GAS	8	\$ 200.00	100
REMOVE AND REPLACE RADIATOR AND TOP UP COOLANT	9	\$ 200.00	100
TRANSFER PARTS , ATTACHMENT FROM OLD TAILGAETE TO NEW	10	\$ 500.00	x.
MOUNT VEHICLE ON BENCH FOR CHASSIS REPLACEMENT	11	\$ 800.00	300
PANEL BEATING ON AFFECTED AREAS	12	\$ 2,500.00	1400.
SPRAY PAINTING ON AFFECTED AREAS	13	\$ 2,000.00	1400

SUBTOTAL \$ 7,900.00

4380

GRAND TOTAL \$ 99,906.88

h/s Adrian Lj
 05/03/18.

24 Pags

YP6072Y

⏪ Settlement package

Type

🔗 Question

Message

Kindly advise final report and settlement package. Thanks

Reply

53 Ubi Avenue 1 #01-56 Paya Ubi Industrial Park Singapore 408934

Tel: 6747-4454 | Fax: 6747-7752 | Email: claims@unitedsg.com.sg

Register No: 201729521C | ROC No: 201729521C

SATISFACTION AND DISCHARGE OF VEHICLE

Date: 12 Sept 2018.

I/We, CHIT HUAT PTE LTD owner/driver of vehicle no. YP6072Y declare that the repairs of my/our vehicle has been completed and to my/our satisfaction and I/we agree that I/We hereby irrevocable absolutely accept the settlement amount on the repair costs of which are final and that the sum of amount are to be release and payable to **M/S UNITED SG AUTOMOBILE PTE LTD** for such repairs are in full discharge of my/our claim.

I/We further acknowledge that any settlement the workshop may reach on my/our behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s concerned.

I/We acknowledge that the Discharge Voucher applies only to my/our property damage.

CHIT HUAT PTE LTD

Signature of owner / driver : 

Name of owner / driver : CHIT HUAT PTE LTD

NRIC number : 200306362H

United SG Automobile Pte Ltd

"We are always in your journey"....

53 Ubi Avenue 1 #01-56 Paya Ubi Industrial Park Singapore 408934
Tel : 6747-4454 | Fax : 6747-7752 | Email: claims@unitedsg.com.sg
UEN No : 201729521C | GST No : 201729521C

TAX INVOICE

AXA INSURANCE PTE LTD	Invoice number	:	UI-1049
8 SHENTON WAY	Date	:	12-Sep-18
#24-01 AXA TOWER	Vehicle number	:	YP6072Y
SINGAPORE 068811	Make Model	:	HINO XZU710R
ATTN: MOTOR CLAIMS DEPARTMENT	Accident date	:	23-Feb-18
	Reference number	:	

Description		Amount SGD\$
Inclusive of supplying parts, labour, panel beating and spray painting		
Lump Sum Repair (Own Damage Claim)		25000.00
Less excess		-2800.00
	Subtotal	22200.00
GST @ 7%		1554.00
	Total	23754.00

Singdollars: Twenty Three Thousand Seven Hundred and Fifty Four



UNITED SG AUTOMOBILE PTE LTD