

ASS. REC. BY:

REF: CS/EGL18004187 / Ag best

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Bazlin Ahmad

of EGL

Date/Time: 05/03/2018 2:53pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / TNV / MV / CS

To Inspect Vehicle No: GBE 4499T

Insured: GBA 9943T

at Workshop m/s Liang Hee Motor

Tel: 97527252

of Blk T Kaki Bukit Ave 6 # 01-62

Policy No: Claim No: DM18H.000517

Sum Insured: Excess:

Make of Veh: D.O.A. 22022018  
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 05/03/2018 3:39pm

Person Contacted: David

Vehicle IN / OUT

| Date/Time | Action/Instruction ( ✓ ) Estimate                |
|-----------|--------------------------------------------------|
|           | GBA 9943T - x                                    |
|           | GBE 4499T - x                                    |
|           | Final Fig @ 3795.77, 4 days (pad @ 3940.13, 51%) |
|           |                                                  |
|           |                                                  |

Surrey

REF:

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: GBE4499T Yr Regn: 2015/Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV350 C.C. 2488

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 38934 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

Ci/No: JN1MC2E26Z0005386

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: 195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 06/03/18

Survey held at Liany Hee

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP EQ.

RECEIVED 07 MAY 2018

Date/Time, File Pass to?

1) 25/4 Liany Hee

Date/Time, File Return to?

2) \_\_\_\_\_

: Preli. Report  
 : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Photos

Others

TOTAL

Report Format: TP

Lump Sum / I.B.I: (\$) 3795.77

160

160



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                                      |                         |                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|-------------------------|-------------------------------------------------------------------------------------|
| EQ INSURANCE COMPANY LTD                                                                                                                  |                                                                                      | Ref : CS/EQ18004187/Aqb |                                                                                     |
| 5 MAXWELL ROAD<br>#17-00 TOWER BLOCK<br>MND COMPLEX SINGAPORE 069110                                                                      |                                                                                      | Date : 05-03-2018       |  |
|                                                                                                                                           |                                                                                      | Code : EQI              |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                                      |                         |                                                                                     |
| Insured Veh.                                                                                                                              | GBE 4499T                                                                            | Veh. Inspected          | GBA 9943T                                                                           |
| Policy No.                                                                                                                                |                                                                                      | Coverage (\$)           | 0.00                                                                                |
| Claim No.                                                                                                                                 | DM18HO00517                                                                          | Excess (\$)             | 0.00                                                                                |
| Assign From                                                                                                                               | BAZLIN AHMAD                                                                         | Assign Date             | 05/03/2018                                                                          |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                                      |                         |                                                                                     |
| Make & Model                                                                                                                              |                                                                                      | c.c                     | 0                                                                                   |
| Engine No.                                                                                                                                | HIDDEN                                                                               | Year of Reg.            |                                                                                     |
| Chassis No.                                                                                                                               |                                                                                      | Colour                  |                                                                                     |
| Odometer                                                                                                                                  | -                                                                                    | Steering                |                                                                                     |
| Brakes                                                                                                                                    |                                                                                      | Modification            |                                                                                     |
| General                                                                                                                                   |                                                                                      |                         |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                                      |                         |                                                                                     |
|                                                                                                                                           | Size                                                                                 | Make                    | Balance                                                                             |
| R/H Front Tyre                                                                                                                            |                                                                                      |                         | mm                                                                                  |
| L/H Front Tyre                                                                                                                            |                                                                                      |                         | mm                                                                                  |
| R/H Rear Tyre                                                                                                                             |                                                                                      |                         | mm                                                                                  |
| L/H Rear Tyre                                                                                                                             |                                                                                      |                         | mm                                                                                  |
| <b>4. Description of Damages</b>                                                                                                          |                                                                                      |                         |                                                                                     |
|                                                                                                                                           |                                                                                      |                         |                                                                                     |
| <b>5. General Information</b>                                                                                                             |                                                                                      |                         |                                                                                     |
| Accident Date                                                                                                                             | 22/02/2018                                                                           | Inspection Date         |                                                                                     |
| Survey held at                                                                                                                            | LIANG HEE MOTOR WORKSHOP<br>1 KAKI BUKIT AVE 6<br>#01-62 AUTOBAY<br>SINGAPORE 417883 |                         |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                        |                                                                                      |                         |                                                                                     |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                      |                         |                                                                                     |

## Catherine Chong (LKK Auto)

---

**From:** Shu Pei (LKKAuto) <shupeil@lkkauto.com>  
**Sent:** Monday, 5 March, 2018 3:02 PM  
**To:** assignments  
**Subject:** FW: EQ REF : DM18HO00517 - NEW PRS ACCIDENT INVOLVING GBE4499T & GBA9943R on 22.02.2018  
**Attachments:** GBA9943R ~ PRS REQUEST-305102956-0001.pdf; GBA9943R 22.02.2018.pdf; GBE4499T 22.02.2018.pdf

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Bazlin Ahmad [<mailto:bazlin.ahmad@eqinsurance.com.sg>]  
**Sent:** Monday, 5 March 2018 2:58 PM  
**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Cc:** Bernadette Yeo <[bernadette.yeo@eqinsurance.com.sg](mailto:bernadette.yeo@eqinsurance.com.sg)>; Janet Tan <[janet.tan@eqinsurance.com.sg](mailto:janet.tan@eqinsurance.com.sg)>; Francis Ng <[francis.ng@eqinsurance.com.sg](mailto:francis.ng@eqinsurance.com.sg)>; Joel Goh <[joel.goh@eqinsurance.com.sg](mailto:joel.goh@eqinsurance.com.sg)>  
**Subject:** EQ REF : DM18HO00517 - NEW PRS ACCIDENT INVOLVING GBE4499T & GBA9943R on 22.02.2018

Dear LKK

We refer to the new assignment, please find below email and attachments for easy reference.

Thank You.

Regards,  
**Lynn Ahmad**  
Executive | Claims

**eqnsurance**


EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190

[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

 A Member of Citystate

 you've got a friend

*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of*

---

**From:** Sim Teo Koon [[mailto:tk\\_sim@juseq.com.sg](mailto:tk_sim@juseq.com.sg)]

**Sent:** Monday, March 5, 2018 2:18 PM

**To:** Bazlin Ahmad

**Subject:** FW: NEW PRS ACCIDENT INVOLVING GBE4499T & GBA9943R on 22.02.2018

Dear Sir,

We refer to your email.

Our client is agreeable to appoint **Adrian Ling (LKK Auto Consultants Pte Ltd)** as a single joint expert.

Please be informed that our client 's motor vehicle is available for pre-repair inspection at the under-stated Workshop:-

**Liang Hee Motor Workshop**

1 Kaki Bukit Ave 6 #01-62

Singapore 417883

Tel : 9752 7252 (David) / 6747-4416. Fax : 6747-2935

Regards,

Sim Teo Koon

JusEquity Law Corporation

171 Chin Swee Road #02-06, CES Centre

Singapore 169877

Tel: 6506 6488 / 6536 9339

Fax: 6536 5368

E-mail: [tk\\_sim@juseq.com.sg](mailto:tk_sim@juseq.com.sg)

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail, delete this message and you should not disseminate, distribute or copy any information contained herein.

---

**From:** Bazlin Ahmad [<mailto:bazlin.ahmad@eqinsurance.com.sg>]

**Sent:** Monday, March 5, 2018 10:35 AM

**To:** JUSEQ <[juseq@singnet.com.sg](mailto:juseq@singnet.com.sg)>

**Cc:** Janet Tan <[janet.tan@eqinsurance.com.sg](mailto:janet.tan@eqinsurance.com.sg)>; Bernadette Yeo <[bernadette.yeo@eqinsurance.com.sg](mailto:bernadette.yeo@eqinsurance.com.sg)>; Francis Ng <[francis.ng@eqinsurance.com.sg](mailto:francis.ng@eqinsurance.com.sg)>; Joel Goh <[joel.goh@eqinsurance.com.sg](mailto:joel.goh@eqinsurance.com.sg)>


**Subject:** NEW PRS ACCIDENT INVOLVING GBE4499T & GBA9943R on 22.02.2018


**Without Prejudice**

Dear Sir,

We refer to your Notice of Accident of even date.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.





Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

|                                                                                                                                                                                          |                                                                                                                                         |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|
| <p><b>1) AJAX Inspection Services Pte Ltd</b></p> <p>Tel: 6255 0808</p> <p>Fax: 6849 9155</p> <p>Contact person : Joey/Joseh</p>                                                         | <p><b>2) Automobile Inspection Services Pte Ltd</b></p> <p>Tel: 6286 0155</p> <p>Fax: 6284 1539</p> <p>Contact Person: Sophia</p>       |
| <p><b>3) LBS Automotive Appraisal Pte Ltd</b></p> <p><b>L.B.S. Auto Consultants Pte Ltd</b></p> <p>Tel: 6281 6690 / 62832866</p> <p>Fax: 6281 8748</p> <p>Contact Person: Amy/ Grace</p> | <p><b>4) Priority Services</b></p> <p><b>Tel: 62934822</b></p> <p><b>Fax: 62963283</b></p> <p><b>Contact Person: Sharon Kho</b></p>     |
| <p><b>5) RT Appraisal Pte Ltd</b></p> <p>Tel: 67486076</p> <p>Fax: 67480361</p> <p>Contact Person: Ricky Teng</p>                                                                        | <p><b>6) LKK Auto Consultants Pte Ltd</b></p> <p>Tel: 6256-3561</p> <p>Fax: 6741-4108</p>                                               |
| <p><b>7) Kelvin Automotive Appraising Services</b></p> <p>Tel: 81825263</p> <p>Fax: 67461148</p> <p>Contact Person: Kelvin</p>                                                           | <p><b>8) Automotive Appraiser &amp; Surveying Services</b></p> <p>Tel: 96623655</p> <p>Fax: 67655662</p> <p>Contact Person: Mr Chee</p> |
| <p><b>9) JP Knights Pte Ltd</b></p> <p>Tel: 63450068</p> <p>Fax: 63445328</p> <p>Contact Person: Edna Lee</p>                                                                            |                                                                                                                                         |

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Thank You.

Regards,  
**Lynn Ahmad**  
Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6496 9881 | tel 65 6223 9433 ext-881 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

 A Member of Citystate



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of*

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                       |
|----------------------------|-----------------------|
| Date Of Report             | 23/02/2018 16:43      |
| Date Of Accident           | 22/02/2018 22:15      |
| Exact Location Of Accident | 134 CHANGI RD CARPARK |
| Country/State of Loss      | SINGAPORE             |

### DETAILS OF OWN VEHICLE

|                             |                         |
|-----------------------------|-------------------------|
| Vehicle Registration Number | GBE4499T                |
| <b>Insured/Policyholder</b> |                         |
| Name Of Registered Owner    | YX VEGETARIAN FOOD      |
| Co Reg No                   | 52908170M               |
| Email Address               | YXCATERING@YAHOO.COM.SG |
| Mobile Phone No             |                         |
| Alternative Phone No        | OFFICE-98786705         |

### Vehicle Particulars

|              |                     |
|--------------|---------------------|
| Manufacturer | NISSAN              |
| Model        | NV350 PANEL VAN 2.5 |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number

Cover Note Number

### Driver

|                      |                        |
|----------------------|------------------------|
| Name of Driver       | WONG THYE TAI          |
| NRIC No              | S2619447D              |
| Date Of Birth        | 07/05/1967             |
| Occupation           | OUTDOOR                |
| Date Of Driving Pass | 28/02/2000             |
| Driving Experience   | 17 YEARS AND 11 MONTHS |
| Gender               | FEMALE                 |
| Mobile Number        | (LOCAL) +65-98786705   |
| Fax Number           |                        |
| Contact Number       |                        |
| Email Address        | NOEMAIL                |



Liang Hee. GBE4499T  
 Nissan NV350  
 JN1MC2E26 20005388

TPEG  
 Xiao Chan

|                                        |                               |
|----------------------------------------|-------------------------------|
| Front Bumper <i>shd</i>                | 623 ✓                         |
| Front Bumper Clips <i>NE</i>           | 30 ✓                          |
| Front Bumper Side Holder x02. <i>M</i> | 85 x 2 = 170 ✓                |
| Front Bumper Fog Lamp x02              | 279.5 x 2 = 559 (SN) +        |
| Front Bumper Fog Lamp Cover x02        | 114.2 x 2 = 228.40 (N) +      |
| Front Grille * <i>cracked</i>          | 463.30 ✓                      |
| Front Grille Logo. <i>M</i>            | 73.60 (N) ✓                   |
| Hoodlip x02 <i>RH cut</i>              | 485.3 x 2 = 970.60 (N) 485.30 |
| Front Panel. <i>Dented</i>             | 1229.50 ✓                     |
| Front RH Corner Panel <i>Repair</i>    | 535.50 +                      |
| Front Windscreen Moulding. <i>2/NE</i> | 213 (N) ✓                     |
| Front Windscreen Sealant.              | 60 (SN) ✓                     |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey & re-estimate spray painting
- To resurvey & re-estimate parts. Using resurvey
- Parts prices to be with justification
- Third party to be with justification
- No illegal modifications allowed
- Suppliers to be with approval from insurance Company

Approved by Repairer  
 Signature  
 Date:

list: 25158  
 len 30%: 1761.06  
 Nett: 771.90  
 len 10%: 694.71  
 S.N: 60.  
 Labour: 1280  
 total: 3795.77  
 (CP/P)  
 04 Day

Panel Beating.  
 Spray Painting.  
 Wiring.  
 To undress  
 To remove front windscreen.

~~1200~~ 600  
~~1000~~ 500  
~~50~~ 30  
~~150~~ 30  
~~180~~ 120

7735.90



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                      |                            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|----------------------------|-------------------------------------------------------------------------------------|
| EQ INSURANCE COMPANY LTD                                                                                                               |                                                                                      | Ref : CS/EQI18004187/Aqbe2 |                                                                                     |
| 5 MAXWELL ROAD<br>#17-00 TOWER BLOCK<br>MND COMPLEXSINGAPORE 069110                                                                    |                                                                                      | Date : 08-05-2018          |  |
| Code : EQI                                                                                                                             |                                                                                      |                            |                                                                                     |
| 1. Policy Particulars :- THIRD PARTY CLAIM                                                                                             |                                                                                      |                            |                                                                                     |
| Insured Veh.                                                                                                                           | GBA 9943T                                                                            | Veh. Inspected             | GBE 4499T                                                                           |
| Policy No.                                                                                                                             |                                                                                      | Coverage (\$)              | 0.00                                                                                |
| Claim No.                                                                                                                              | DM18HO00517                                                                          | Excess (\$)                | 0.00                                                                                |
| Assign From                                                                                                                            | BAZLIN AHMAD                                                                         | Assign Date                | 05/03/2018                                                                          |
| 2. Vehicle Particulars & Condition                                                                                                     |                                                                                      |                            |                                                                                     |
| Make & Model                                                                                                                           | NISSAN NV350                                                                         | c.c                        | 2488                                                                                |
| Engine No.                                                                                                                             | HIDDEN                                                                               | Year of Reg.               | 2015                                                                                |
| Chassis No.                                                                                                                            | JN1MC2E26Z0005386                                                                    | Colour                     | SILVER                                                                              |
| Odometer                                                                                                                               | 38934                                                                                | Steering                   | IN ORDER                                                                            |
| Brakes                                                                                                                                 | IN ORDER                                                                             | Modification               | NIL                                                                                 |
| General                                                                                                                                | GOOD                                                                                 |                            |                                                                                     |
| 3. Conditions of Tyres                                                                                                                 |                                                                                      |                            |                                                                                     |
|                                                                                                                                        | Size                                                                                 | Make                       | Balance                                                                             |
| R/H Front Tyre                                                                                                                         | 195 R15C                                                                             | YOKOHAMA                   | 6 mm                                                                                |
| L/H Front Tyre                                                                                                                         | 195 R15C                                                                             | YOKOHAMA                   | 6 mm                                                                                |
| R/H Rear Tyre                                                                                                                          | 195 R15C                                                                             | YOKOHAMA                   | 6 mm                                                                                |
| L/H Rear Tyre                                                                                                                          | 195 R15C                                                                             | YOKOHAMA                   | 6 mm                                                                                |
| 4. Description of Damages                                                                                                              |                                                                                      |                            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.<br>DAMAGES SEE DETAILS.                                                            |                                                                                      |                            |                                                                                     |
| 5. General Information                                                                                                                 |                                                                                      |                            |                                                                                     |
| Accident Date                                                                                                                          | 22/02/2018                                                                           | Inspection Date            | 06/03/2018                                                                          |
| Survey held at                                                                                                                         | LIANG HEE MOTOR WORKSHOP<br>1 KAKI BUKIT AVE 6<br>#01-62 AUTOBAY<br>SINGAPORE 417883 |                            |                                                                                     |
| 5a. Remarks                                                                                                                            |                                                                                      |                            |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                      |                            |                                                                                     |
| 5b. Estimate Days of Repair                                                                                                            |                                                                                      |                            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                      | 4 Working Days             |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 4499T

| Qty                         | Description of Parts                                             | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|------------------------------------------------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                                                  |                      |                           |                   |
| 1                           | FRONT BUMPER                                                     | DEFORMED             | 623.00                    | 623.00            |
| 1                           | FRONT BUMPER CLIPS                                               | NECESSARY            | 30.00                     | 30.00             |
| 2                           | FRONT BUMPER SIDE HOLDER @\$85.00                                | NECESSARY            | 170.00                    | 170.00            |
| 1                           | FRONT GRILLE                                                     | CRACKED              | 463.30                    | 463.30            |
| 1                           | FRONT PANEL                                                      | DENTED               | 1,229.50                  | 1,229.50          |
| 1                           | FRONT RH CORNER PANEL                                            | TO REPAIR SEE LABOUR | 535.50                    | -                 |
|                             | LESS 30% DISCOUNT                                                |                      | -                         | -754.74           |
|                             |                                                                  |                      | 3,051.30                  | 1,761.06          |
| <b>NETT ITEMS</b>           |                                                                  |                      |                           |                   |
| 2                           | FRONT BUMPER FOG LAMP COVER @\$114.20 (N)                        | NOT NECESSARY        | 228.40                    | -                 |
| 1                           | FRONT GRILLE LOGO (N)                                            | NECESSARY            | 73.60                     | 73.60             |
| 2                           | HEADLAMP @\$485.30 (N)                                           | O/S CUT              | 970.60                    | 485.30            |
| 1                           | FRONT WINDSCREEN MOULDING (N)                                    | NECESSARY            | 213.00                    | 213.00            |
|                             | LESS 10% DISCOUNT                                                |                      | -                         | -77.19            |
|                             |                                                                  |                      | 1,485.60                  | 694.71            |
| <b>SPECIAL NETT ITEMS</b>   |                                                                  |                      |                           |                   |
| 2                           | FRONT BUMPER FOG LAMP @\$279.50 (SN)                             | NOT NECESSARY        | 559.00                    | -                 |
| 1                           | FRONT WINDSCREEN SEALANT (SN)                                    | NECESSARY            | 60.00                     | 60.00             |
|                             |                                                                  |                      | 619.00                    | 60.00             |
| <b>LABOUR</b>               |                                                                  |                      |                           |                   |
|                             | PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT RH CORNER PANEL. |                      | 1,200.00                  | 600.00            |
|                             | SPRAY PAINTING.                                                  |                      | 1,000.00                  | 500.00            |
|                             | WIRING.                                                          |                      | 50.00                     | 30.00             |
|                             | TO UNDERSEAL.                                                    |                      | 150.00                    | 30.00             |
|                             | TO REMOVE FRONT WINDSCREEN.                                      |                      | 180.00                    | 120.00            |
|                             |                                                                  |                      | 2,580.00                  | 1,280.00          |
| <b>GRAND TOTAL</b>          |                                                                  |                      | <b>7,735.90</b>           | <b>3,795.77</b>   |

Report Ref No. CS/EQI18004187/Aqbe2



|                             |  |  |                 |
|-----------------------------|--|--|-----------------|
| RECOMMENDED COST OF REPAIRS |  |  | <b>3,795.77</b> |
|-----------------------------|--|--|-----------------|

Report Ref No. CS/EQ18004187/Aqbe2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.