

22/03/2018

ASS. REC. BY:

REF:

CS/SM018004191 / Svb22

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Grace Teo

of

SMO

Date/Time:

27/02/2018 4:31pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGN 9239M

Insured:

SJF 11180L

at Workshop m/s

Performance

Tel:

6319 0774 | 8121 4600

of

303 Alexandra Rd

Policy No:

Claim No:

CMTD 1800712 / ACC

Sum Insured:

Excess:

D.O.A.

12/02/2018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS w/p

05/03/2018

H.O.D. Endorsement:

Date/Time:

27/02/2018

Person Contacted:

Caroline

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SGN 9239M - x

SJF 11180L - x

6/3/18

Email preli revised to Grace

25/4/18

Final fig \$ 3223.40 confirmed by email (Red 1000.70, 24/5)

REF:

Jathirani

Srinivas

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time | Action / Instruction

Veh No:

SGN 9239M

Yr Regn: 30/11/2006

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 523i

cc 2497

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

71614

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WISANE 32010CM 23562

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim or

Tyre Size:

F: 225/50R17

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Goodyear

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

12/2/18

D.O.I.

5/3/18

Survey held at

Performance Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 25 APR 2018

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1)

Date/Time, File Return to?

2) SSA - typist

Report Format:

Lump Sum / I.B.I. (\$

TP

3223.40

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$
☐ : Interview (\$
☐ : Tech. Insp (\$
☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Copies

TOTAL

250

Survey Department Check List (Case Handler)

Reference No.: CS SMD1800 4191 Sub
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	/			
C	Finalised Amount	/			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	/			
---	-------------------------	---	--	--	--

Check By: VERON 25/4/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/20




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18004191/Svb		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 05-03-2018		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJF 4180L	Veh. Inspected	SGN 9239M	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1800712/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	27/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/02/2018	Inspection Date	05/03/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: CMTD1800712/AGC

Our ref: CS/SMO18004191/Svb

DATE :6/3/2018

The Motor Claims Department
M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SGN 9239M


We thank you for your instruction on 27/2/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 5/3/2018 at the premises of M/s PERFORMANCE MOTORS LTD and have the following to report:-

	: S\$4,166.50
Revised Estimate Amount	: S\$3,610.50
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front o/s portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

SEBASTIAN YEANG
Automotive Assessor

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 25 April 2018 11:36 AM
To: 'PBSP'; Sebastian Yeang (LKK Auto); SUR
Subject: RE: FINAL REPORT / SGN9239M

Dear Caroline,

WITHOUT PREJUDICE

Confirmed \$3,223.40 before GST.

Repair days: 3 days

Final invoice and all supporting documents sent over to SOMPO

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Tuesday, 24 April 2018 4:18 PM
To: Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT / SGN9239M

Dear Sebastian

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,014.00
Total Parts : 1,209.40
Total Labour & Parts : 3,223.40

Repair days: 3

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 6 March 2018 12:09 PM
To: 'Teo, Grace'
Cc: SUR; 'Chan, Shu Hui Agnes'; 'Henry, Irene James'
Subject: RE: CMTD1800712/AGC - ACCIDENT INVLG SJF4180L & SGN9239M ON 12.02.18
Attachments: SGN 9239M PRELI ADVISED.pdf

Dear Grace,

Enclosed preliminary revised of vehicle SGN 9239M
Date of survey: 5/3/2018
Number of days:3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Tuesday, 27 February 2018 4:31 PM
To: PBSP <pml-pbsp@simedarby.com.sg>; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Inthiran Thurasamy <inthiran.thurasamy@simedarby.com.sg>; Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: CMTD1800712/AGC - ACCIDENT INVLG SJF4180L & SGN9239M ON 12.02.18

Our Claim Reference: CMTD1800712/AGC
Your Reference: SGN9239M

Hi Caroline,

We have appointed LKK AUTO to conduct the survey.

Aside to LKK,

Please make arrangement to conduct the survey for SGN9239M on 05/03/18.

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]

Sent: Tuesday, February 27, 2018 12:59 PM

To: Chan, Shu Hui Agnes

Cc: Teo, Grace; Inthiran Thurasamy

Subject: Re: CMTD1800712/AGC - REQ FOR DIRECT SETTLEMENT - SGN9239M SJF4180L ON 12.02.18

Dear Sirs

Please arrange survey on **5 March 2018**.

Owner leaving car in for survey + repair by 9am.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 27 February, 2018 4:31 PM
To: PBSP; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Inthiran Thurasamy; Chan, Shu Hui Agnes; Henry, Irene James
Subject: CMTD1800712/AGC - ACCIDENT INVLG SJF4180L & SGN9239M ON 12.02.18

Our Claim Reference: CMTD1800712/AGC
Your Reference: SGN9239M

Hi Caroline,

We have appointed LKK AUTO to conduct the survey.

Aside to LKK,

Please make arrangement to conduct the survey for SGN9239M on 05/03/18.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Tuesday, February 27, 2018 12:59 PM
To: Chan, Shu Hui Agnes
Cc: Teo, Grace; Inthiran Thurasamy
Subject: Re: CMTD1800712/AGC - REQ FOR DIRECT SETTLEMENT - SGN9239M SJF4180L ON 12.02.18

Dear Sirs

Please arrange survey on 5 March 2018.

Owner leaving car in for survey + repair by 9am.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2301I
Vehicle Details	
Vehicle No.:	SGN9239M
Vehicle to be Exported:	No
Intended De-registration Date:	06 Mar 2018
Vehicle Make:	B.M.W.
Vehicle Model:	523I
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	05646342N52B25AE
Chassis No.:	WBANE32010CM75562
Maximum Power Output:	130.0 kW (174 bhp)
Open Market Value:	\$51,306.00
Original Registration Date:	30 Nov 2006
First Registration Date:	30 Nov 2006
Transfer Count:	0
Actual ARF Paid:	\$56,437.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Nov 2026
COE Category:	E - Open Category

COE Period(Years):	10
PQP Paid:	\$56,053.00
COE Rebate Amount:	\$48,937.00
Total Rebate Amount:	\$48,937.00

The information contained herein is correct as at 06 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/02/2018 10:10
Date Of Accident	12/02/2018 09:00
Exact Location Of Accident	THOMSON THREE CONDO CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGN9239M
Insured/Policyholder	
Name Of Registered Owner	CHONG HEONG WEE
NRIC No	S7832301I
Email Address	HEONGWEE.CHONG@MSCI.COM
Mobile Phone No	(LOCAL) +65-94792370
Alternative Phone No	OFFICE-94792370

Vehicle Particulars

Manufacturer	BMW
Model	523
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	CHONG HEONG WEE
NRIC No	S7832301I
Date Of Birth	28/10/1978
Occupation	INDOOR
Date Of Driving Pass	09/07/1996
Driving Experience	21 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94792370
Fax Number	
Contact Number	OFFICE-94792370
Email Address	HEONGWEE.CHONG@MSCI.COM

Address	BLK 62 LOR 4 TOA PAYOH #21-109
Postcode	310062
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJF4180L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAKAYOSHI AOSHIMA
NRIC/Passport Number	F1837302P
Contact Number	
Address	
Postcode	
Insurance Company Name	SOMPO INSURANCE SINGAPORE PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18 Feb Monday around 9am, I received a call from Mr Takaguchi Aoshima via the Management Office of Thomson Three Condominiums.

Mr Aoshima informed me that he had hit my front bumper while moving his car out of his parking lot next to my car. My car was parked and there was no passenger in the car.

Mr Aoshima sent me a follow-up email to confirm the accident, and we agreed to make an accident report and to make the insurance claim via his insurance company Somp.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. NO. 197401559M GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

5/03 @ 9:00am

Estimate No. : b1 45933
Date Estimated : 14/02/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 1

- ESTIMATE REPAIR FOR -
Chong Heong Wee (Zhong Xiongwei)
Apt Blk 62 Lorong 4 Toa Payoh
#21-109

Singapore 310062

- ACCOUNT - 509
Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGN9239M	CM75562	30/11/2006	523ia	0

DESCRIPTION

To replace front bumper and attachments.

VALUE
850 1,276.00

Painting front bumper.

954 1,038.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

Sundries.

80.00

Total Labour 1: 2,570.00

DESCRIPTION

Set of mount ✓ ~~mm~~ ~~nn~~
FRT BUMPER (PDC) ✓ ~~cut~~
PDC sensor ✓ ~~mm~~ ~~nn~~

QTY	PRIC	VALUE
1	94.45	94.45
1	1,149.80	1,149.80
1	352.25	352.25

Total Parts : 1,596.50

3 days
LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian. 5/3/18.
- Part by part repair.
- Photo Before Paint.

6/3/18

4226.10

Labour 1	:	2,570.00
Parts	:	1,596.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	291.66
Grand Total	:	4,458.16

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45933
Date Estimated : 14/02/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Chong Heong Wee (Zhong Xiongwei)
Apt Blk 62 Lorong 4 Toa Payoh
#21-109

Singapore 310062

- ACCOUNT - 509
Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SGN9239M	CM75562	30/11/2006	523iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments include knocking out dents caused by the accident	850.00		850.00	
To spray paint front bumper	934.00		934.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT BUMPER LH SIDE BKT	18.15	1.00		18.15
# FRT BUMPER RH SIDE BKT	18.15	1.00		18.15
# FRT BUMPER LH FLAP COVER LEVER	11.65	1.00		11.65
# FRT BUMPER RH FLAP COVER LEVER	11.65	1.00		11.65
FRT BUMPER (PDC)	1,149.80	1.00		1,149.80

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,209.40
Total Labour & Parts :	3,223.40
Deduction for Excess :	
Total Repair Costs less Excess:	3,223.40
GST @7%:	225.64
Grand Total :	3,449.04

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45933
Date Estimated : 14/02/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Chong Heong Wee (Zhong Xiongwei)
Apt Blk 62 Lorong 4 Toa Payoh
#21-109

- ACCOUNT - 509
Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623

Singapore 310062

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SGN9239M	CM75562	30/11/2006	523iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT BUMPER LH SIDE BKT	18.15	1.00		18.15
# FRT BUMPER RH SIDE BKT	18.15	1.00		18.15
# FRT BUMPER LH FLAP COVER LEVER	11.65	1.00		11.65
# FRT BUMPER RH FLAP COVER LEVER	11.65	1.00		11.65

Total Labour :
Total Parts : 59.60
Total Labour & Parts : 59.60



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18004191/Svbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 02-05-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJF 4180L	Veh. Inspected	SGN 9239M
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1800712/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	27/02/2018

2. Vehicle Particulars & Condition

Make & Model	B.M.W 523i	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	WBANE32010CM75562	Colour	BLACK
Odometer	71614	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	GOODYEAR	6 mm
L/H Front Tyre	225/50 R17	GOODYEAR	6 mm
R/H Rear Tyre	225/50 R17	GOODYEAR	6 mm
L/H Rear Tyre	225/50 R17	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/02/2018	Inspection Date	05/03/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGN 9239M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SET OF MOUNT (SN)	NOT NECESSARY	94.45	-
1	FRT BUMPER (PDC)(SN)	CUT	1,149.80	1,149.80
1	PDC SENSOR (SN)	NOT NECESSARY	352.25	-
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
1	FRT BUMPER LH SIDE BKT (ADDITIONAL)(SN)	NECESSARY	18.15	18.15
1	FRT BUMPER RH SIDE BKT (ADDITIONAL)(SN)	NECESSARY	18.15	18.15
1	FRT BUMPER LH FLAP COVER LEVER (ADDITIONAL)(SN)	NECESSARY	11.65	11.65
1	FRT BUMPER RH FLAP COVER LEVER (ADDITIONAL)(SN)	NECESSARY	11.65	11.65
			1,736.10	1,289.40
LABOUR				
	TO REPLACE FRONT BUMPER AND ATTACHMENTS.		1,275.00	850.00
	PAINTING FRONT BUMPER.		1,038.00	934.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.		177.00	150.00
			2,490.00	1,934.00
GRAND TOTAL			4,226.10	3,223.40
RECOMMENDED COST OF REPAIRS				3,223.40

Report Ref No. CS/SMO18004191/Svbn2

YEANG WAI KEEN
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.