

INS. CASE OWNER

Surveyor:

Pre-assign / CCU / FTE



Insured Vehicle No.

Name of Insured

Insured Tel No.

Excess Sec II : \$S

Is driver the owner?

If NO, Driver Name / Age

Driver Tel No.

Slany

CC 4/AXA 1800 4196, Kuba

LKK:
IDAC:

ASSIGNMENT

DOI:

Date / Time:

Registered in Merimen:

BSC

10/7/18

5/11/18

SGK 2342E

WRA SERVICES

HP:

D.O.A:

2/2/18

Nature of Accident:

Claim No.

Policy No.

Make / Model

Place of Accident

88MOOGE (33229)

PIB97H2

HONDA

GEMERAN SQUARE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SGR 563E



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hui Yang



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

6/11/18
TH

SGR 563E - LK (WSP) 7070114 / 11/11/18 08:00 - 10/11/18
SGR 563E -
Smartclaim

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

7 THM ByEmail
20/3

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOI

Payment Breakdown Form:

Post-Repair Photos:

Others:

26/3/18 @ 12:05 Spoke to OI Informed IP claim and he agree to let insurance to handle.

RECEIVED 04 JUN 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$S

(

days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

100 (Agreed)

Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lia :

Repair Cost:

\$S 1406.20

Loss of Rental (LOR):

\$S

200.00

(

2 days) x 100

Loss of Use (LOU):

\$S

(S

x

days)

Loss of Income (LOI):

\$S

(S

x

days)

LOR only ☐

LOU only ☐

LOR + LOU ☐

LOR + LOI ☐

(Tick only one)

GIA/LTA Search

\$S

2.00

Medical:

\$S

Disbursement:

\$S

(e.g. Tow/ Independent)

Legal Cost

\$S

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

\$S

1608.20

Global Sum \$S:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

\$S

1608.20

Name 1:

HUI YANG MOTOR PTE LTD

Payee 2: (Strike if N.A.)

\$S

Name 2:

Payee 3: (Strike if N.A.)

\$S

Name 3:

OK 31/11/18
COPY SENT
20/8/18

ASS. REC. BY:

REF:

A/A/

U

Kenneth

ASSIGNMENT

Front:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

1.41 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLR 563E

Yr Regn:

07, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy with

c.c. 1798

Colour

M. Maroon

A/C:

Insured / Std / NI / NA

Sp. Reading

24413

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTD GG 20W 80 J007448

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

2/3/18

D.O.I.

19/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/3

Rk pass to Corbin

PIP - \$ 1314.21 (Red: \$ 4634.92 / 78%.)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ - RS - \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Ku

part

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Bld 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

02/03/2018

Owner: CLNG SERVICES

ESTIMATE TO REPAIR TOYOTA WISH - SLR563E

1pc rear tailgate
1pc rear tailgate "TOTOTA" logo
1pc rear tailgate "VALVE MATIC" emble
1pc rear tailgate inner rubber
1pc rear bumper *595.90*
2pcs rear bumper side retainer 1 @\$123.05
2pcs rear bumper side retainer 2 @\$132.10
1pc rear end panel
2pcs rear end panel bracket @\$141.40
1pc rear end panel sensor

less 25%

1set reverse sensor

remove & refix rear windscreen glass
sealant
wiring
tuffkote
spray painting
labour charges
Total

*Not Notified
1st
Punong B4 points
81314.21
3 days*

1st
R \$ 1,415.50 X
nn \$ 51.10 X
nn \$ 53.90 X
nn \$ 375.45 X
nn \$ 975.00 ✓
clip \$ 246.10 X
nn \$ 264.20 X
R \$ 581.45 X
R \$ 282.80 X
R \$ 380.00 X
\$ 4,625.50
\$ 1,156.38
\$ 3,469.13

1st s.nett \$ 280.00 X

nn \$ 160.00 X
nn \$ 80.00 X
\$ 80.00 15%
nn \$ 80.00 X
\$ 850.00 364 400
\$ 950.00 364
\$ 5,949.13



LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

02/03/2018

Owner: CLNG SERVICES

ESTIMATE TO REPAIR TOYOTA WISH - SLR563E

1pc	rear tailgate
1pc	rear tailgate "TOTOTA" logo
1pc	rear tailgate "VALVE MATIC" emble
1pc	rear tailgate inner rubber
1pc	rear bumper
2pcs	rear bumper side retainer 1 @\$123.05
2pcs	rear bumper side retainer 2 @\$132.10
1pc	rear end panel
2pcs	rear end panel bracket @\$141.40
1pc	rear end panel sensor

less 25%

1set reverse sensor

remove & refix rear windscreen glass
sealant
wiring
tuffkote
spray painting
labour charges
Total

*Not withair
1.2.1
Punary Bepem
2dm*

1	\$ 1,415.50	X
nn	\$ 51.10	X
nn	\$ 53.90	X
sn	\$ 375.45	X
Bu	\$ 975.00	✓
cl 10.1	\$ 246.10	✓
	\$ 264.20	?
1	\$ 581.45	X
	\$ 282.80	?
sn	\$ 380.00	X
	\$ 4,625.50	
	\$ 1,156.38	
	\$ 3,469.13	

s.nett \$ 280.00 7

nn	\$ 160.00	X
nn	\$ 80.00	X
	\$ 80.00	15/
nn	\$ 80.00	X
	\$ 850.00	3601
	\$ 950.00	3001
	\$ 5,949.13	



LKK Auto Consultants hence notify
the Repairer of the following:

- To survey before later spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be requested and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SERVICE REQUESTS

MESSAGES

CLAIMS

<< Service Request Details

Claim	S8M009XE
Reference	CC4/ASM18004196/Kub3
Loss Date	2 March 2018
Request Date	2 March 2018
Due Date	5 March 2019
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step Finish the work

Complete Work

More

Vehicle Information

Incident	SLR563E
Vehicle	
Registration #	
Make	TPVD TOYOTA
Model	WISH

Service Address

...

Primary Contact/Insured

LURA SOLUTIONS
BLK 89 TANGLIN HALT ROAD, #21-358,
141089, Singapore
96692595
lurie4@singnet.com

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

[Messages](#) [Invoices](#) [History](#) [Documents](#) [Assessment](#) [Metrics](#) [Notes](#)

New Message

TYPE	SENT	FROM	SUBJECT	BODY	
	27/7/18 9:59 PM	NG Stacey	Re:RE: Request for Mandate approval	pls proceed	
	25/7/18 1:59 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	RE: Request for Mandate approval	Dear Sir / Madam, OI rear-ended to TP vehicle. Inf...	
	16/7/18 4:08 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	Request for Mandate approval	Dear Sir / Madam, OI rear-ended to TP vehicle. Inf...	

TYPE	SENT	FROM	SUBJECT	BODY	
1	26/4/18 9:50 PM	NG Stacey	Re:la (Immediate Advise)	Hi, Please proceed for DS at repair cost \$2000.	↩
2	20/3/18 4:51 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	la (Immediate Advise)	----- Repairer Estimate: \$ 5,949.13 ----	↩
1	12/3/18 2:39 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	RE: Re:VNI	As spoken with Bel on 12.03.2018 @ 2.37pm, vehicle...	↩
1	12/3/18 2:01 PM	TAY Ernest	Re:VNI	Hi LKK team, TP repairer email us again. Please a...	↩
2	5/3/18 10:06 AM	LKK AUTO CONSULTANTS PTE LTD (TP)	VNI	Please be informed that vehicle currently not in t...	↩
1	4/3/18 11:53 AM	NG Stacey	Direct settlement	Insured gia report shared. Pls proceed ds	↩



SERVICE REQUESTS

MESSAGES

CLAIMS



Request for Mandate approval

Type

Question

Message

Dear Sir / Madam, OI rear-ended to TP vehicle. Informed TP claim and he agree to settle the claim. Liability(TP) 100% Proposed Nett Value \$1,406.20 Loss of rental \$240.00 no. of 2 days x \$ 120 LTA search fees \$2.00 Proposed Total \$1,648.20 .Thanks. Best Regards, Thin Thin Hlaing | Case Handler

Reply

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

Date: 21/04/2018

AXA Insurance Singapore Pte Ltd
Motor Claims Department
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

**RE: ACCIDENT INVOLVING SLR563E & SGK2352E ON 02/03/2018
ALONG SLIP ROAD TWDS SENGKANG SQUARE**

SETTLEMENT OF OUR CLAIM FOR SLR563E

Part by part repair cost as recommended by surveyor (TP0353)	\$ 1,406.20
02 days Loss of Rental @ \$120.00 per day	\$ 240.00
TP Insurance Enquiry	\$ 2.00
Total	<u>\$ 1,648.20</u>

**The above claim applies only to vehicle damage and expressly exclude all personal injuries and other consequential loss.*

Please let us have your reply soonest possible, thank you.

Best Regards,
Marco Neo
HUI YANG MOTOR PTE LTD
DID: 64515752
Fax: 64514658
email: hui_yang_motor@hotmail.com

Thin Thin (LKKAuto)

From: Thin Thin (LKKAuto)
Sent: Wednesday, 28 March 2018 8:30 PM
To: 'lurie4@singnet.com'
Subject: ACCIDENT INVOLVING SGK 2352E AND SLR 563E ALONG SENGKANG SQUAARE ON 02/03/2018



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

28 MARCH 2018

LURA SOLUTIONS

Dear Sir/Madam,

OUR REF : CC4/ASM18004196/ub3
YOUR REF : SGK 2352E

ACCIDENT INVOLVING SGK 2352E AND SLR 563E ALONG SENGKANG SQUAARE ON 02/03/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s **HUI YANG MOTOR PTE LTD** acting on behalf of the owner of **SLR 563E** against your motor insurance policy.

As spoken, basing on the circumstances of the accident reported by both parties (front-to-rear collision) where you had hit third-party vehicle from the rear, we are of the opinion that we cannot be absolved from liability.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to thinthin@lkkauto.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2360 or email us at thinthin@lkkauto.com

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely

THIN THIN HLAING
LKK Auto Consultants Pte Ltd
DID: 6841 2360
FAX: 6741 4108
Email: thinthin@lkkauto.com

Cc *AXA Insurance Pte Ltd
(Motor Claims Dept)*

AUTHORIZATION LETTER

TO WHOM IT MAY CONCERN

I/We, CLNG SERVICES hereby declare and agree to use the address of **Hui Yang Motor Pte Ltd**, that is at Blk 176 Sin Ming Drive, #04-02 Sin Ming Autocare Singapore 575721 in all my/our correspondences with any party in connection with my/our claim arising from an accident involving my/our motor vehicle registration number SJR 563 E and other vehicles registration number SG K2352 E along Slip Road towards Sengkang Square on 02/03/2018.

I/We, further grant authority to Messrs **Hui Yang Motor Pte Ltd** or any of their representatives to open all my/our letters and to negotiate my/our claim on my/our behalf.

I/We wish to inform you that you could issue the cheque payment in favour of my/our repairer Messrs **Hui Yang Motor Pte Ltd**.

CLNG SERVICE
No. 3 PHOENIX WALK
SINGAPORE 668107

Signature of registered owner



redefining / insurance

CLAIM REF : S8M009XE
INSURED : LURA SOLUTIONS

DISCHARGE VOUCHER

We/I (CLNG SERVICES.53341763E) hereby agree to accept the sum of dollars One Thousand Six Hundred Eight and Cents Twenty Only (S\$ 1,608.20) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. SGK 2352E as a result of an accident along SENGKANG SQUARE on 02/03/2018 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SLR 563E.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. SGK 2352E in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SGK 2352E.

Dated this 27 day of August 2018

Claimant's Signature : 

NRIC no./ Company Stamp : 53341763E

Occupation/ Business : _____

Address : 1163 Phoenix Walk, S1 668107

Telephone No. : 64515752

Witness's Name : See

Witness's Signature : 

Witness's NRIC No. : SP206720E

CL NG SERVICES
NO 3 PHOENIX WALK
SINGAPORE 668107

HUI YANG MOTOR PTE LTD

Bill To:

AXA Insurance Singapore Pte Ltd
Motor Claims Department
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

TAX INVOICE**TP Claim Invoice No: TP0353****Bill Date: 21/04/2018**

	Description	Amount
	Date of Accident : 02/03/2018 Owner : CLNG SERVICES Vehicle No : <u>SLR563E</u> Make & Model : <u>TOYOTA WISH 1.8X</u>	
	<u>Part by part repair cost as recommended by surveyor</u>	\$ 1,314.21
	Sub-Total :	\$ 1,314.21
	Add 7% GST :	\$ 91.99
	Total Amount SGD :	\$ 1,406.20

Reg No.:201629438M

GST No:201629438M

HUI YANG MOTOR PTE LTD

*Authorised Signature***Hui Yang Motor Pte Ltd**

Sin Ming Autocare Blk 176 Sin Ming Drive

#04-02 Singapore 575721

Email: hui_yang_motor@hotmail.com

H/P: 98625891 Office: 64515752 Fax : 64514658

VISIOR CAR PTE LTD

176 SIN MING DRIVE #04-14 SIN MING AUTOCARE S(575721)

RENTAL AGREEMENT

Kindly fill up all of the details below

CAR MODEL/CARPLATE: mit celt Plus SSE3052K

HIRER'S NAME:	Ng cheon Leng
NRIC/PASSPORT NO.:	S7244607J
DOB.:	27/11/1972
ADDRESS:	3 phoenix Walk S668107
CONTACT NO.:	92703521
RENTAL DEPOSIT:	Nil
DATE OF COMMENCE:	19/3/18 9am - (20/3/18 4pm)
EMAIL:	- Return
RENTAL PER DAY:	\$120/-
BANK/ ACCOUNT NO.:	-
1)INSURANCE 1ST PARTY EXCESS \$2000 2)INSURANCE 3 RD PARTY EXCESS \$2000 3)INSURANCE EXCESS FOR OVERSEA WILL BE DOUBLED.	
CONTRACT VAILDITY:	02 day
VEHICLE MILEAGE:	-

REMARKS:

Left Side



Right Side



Back



Front



Top



D=DENT S=SCRATCHES C=CHIPS R=RUST M=MISSING

GENERAL DEFINITIONS



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-032747
Date of Request: 02/03/2018

Your Ref No: Online Purchase

Hui Yang Motor Pte Ltd
176 Sin Ming Drive #04-02
Sin Ming AutoCare
Singapore 575721

Dear Sir/Madam,

Enquiry Date 02/03/2018
Enquiry By Sandra Ee Jing Yi
TP Vehicle No. SGK2352E
Accident Date 02/03/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SGK2352E	AXA Insurance Pte Ltd	01/02/2018-31/01/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGK 2352E (Insd veh)	Model:	TPVD TOYOTA WISH
	SLR 563E (TP veh)		
Date of Accident:	02/03/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	6,365.57
Final Repair Cost	:	\$	1,406.20
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	200.00 2 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	1,608.20

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability ____100____(%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____(%)	Assessed Liability (*): _____(%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____ _____	

Payment Instruction: Payee's Breakdown		
1)	HUI YANG MOTOR PTE LTD	\$ 1,608.20

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

13/09/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

Service Request Details

Claim	SUB0009XE
Reference	CC4/ASAM10004196/Kub3u2
Loss Date	2 March 2018
Request Date	2 March 2018
Due Date	
Vendor Name	LUK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step: Wait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	SLP563E
Make	TM20 TOYOTA
Model	WISH
Service Address	

...

Primary Contact/Insured	
LURA SOLUTIONS BLK 89 TANGLIN HALL ROAD, #21-35B, 141089, Singapore 96692593 lurie4@singnet.com	

Claim Handler	
NG Stacey 65AB804351 stacey.ng@axa.com.sg	

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	---------------

Accident Statement Reports & Statement

Mainmen

LUK Invoice 1.pdf

Surveyor/ Assessor expense

LUK AUTO CONSULTANTS PTE LTD (TP)

13 September 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 payment breakdown SLR 563E.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	13 September 2018
 LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	13 September 2018
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	13 September 2018
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	13 September 2018
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	13 September 2018
 LKK RE INSPECTION PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 August 2018
 LKK RE INSPECTION PHOTO 1.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 August 2018
 LKK INSPECTION PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 August 2018
 MANDATE & IA.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 July 2018
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 July 2018
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	10 July 2018
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 July 2018
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	20 March 2018
 Preliminary Advice.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	20 March 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
EMAIL WITH ATTACHMENT.png	Other	Other	SHAH Kunal	12 March 2018
TP Claim for SLR563E against SGK2352E.png	Other	Other	SHAH Kunal	2 March 2018

Assessment Details

General & Workshop Details Vehicle & Driver Details Taxes & Rates Parts & Labour Miscellaneous Summary Parts

Add

Approve

Done

Submit All

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/L BTRYS	DISC QUANTY	SALV AGEN	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1		REAR TAILGATE			Repair	0	0	0	0	0	Deny	
		2	1		REAR TAILGATE "TOYOTA" LOGO			Serviceable	0	0	0	0	0	Deny	
		3	1		REAR TAILGATE "VALVE MATIC" EMBLEM			Serviceable	0	0	0	0	0	Deny	
		4	1		REAR TAILGATE INNER RUBBER			Serviceable	0	0	0	0	0	Deny	
		5	1		REAR BUMPER			Buckled	595.9		25		446.93	Approve	
		6	1		REAR BUMPER SIDE RETAINER 1 RH			Damaged	123.05		25		92.29	Approve	
		7	2		REAR BUMPER SIDE RETAINER 2			Serviceable	0	0	0	0	0	Deny	
		8	1		REAR END PANEL			Repair	0	0	0	0	0	Deny	
		9	2		REAR END PANEL BRACKET			Repair	0	0	0	0	0	Deny	
		10	1		REAR END PANEL SENSOR			Serviceable	0	0	0	0	0	Deny	
Labour															

edit

Approve

Deny

Submit All

EDIT	SER NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR HLR	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
☐	1		REMOVE & REFIX REAR WINDSCREEN GLASS	0	0	0	Deny		
☐	2		WIRING	15	0	0	Approve		
☐	3		TLUFF KOTE	0	0	0	Deny		
☐	4		SPRAY PAINTING	400	0	0	Approve		
☐	5		LABOUR CHARGES	300	0	0	Approve		

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR 2 DAYS	Approve			
	2	SET REVERSE SENSOR	Deny	0	SERVICEABLE	
	3	SEALANT	Deny	0	NOT NECESSARY	

Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Radio	Parts & Labour	Miscellaneous	Summary	Claim Amount
Claim Amount		\$1,314.22						
CATEGORY	ESTIMATE		REVISED AMOUNT					
Spare Parts	\$539.22		\$539.22					
Labour	\$775.00		\$775.00					