

ASS. REC. BY:

REF:

CS/MSG18004205/Grd3

Special Instruction:

Surveyor:

Mennen

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSG

Date/Time:

5/3/18 @ 9.58am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU 4864U

Insured:

SLL 53S

at Workshop m/s

Motor Image

Tel:

92992693

of

14 Loring St Toa Payoh

Policy No:

D290414270MY

Claim No:

549200

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/02/2018

6/3/18

CA / REV / REP. / REV 24 HRS

/wp

H.O.D. Endorsement:

Date/Time:

10:05am @ 5/3/18

Person Contacted:

Sayed

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLU 4864U-X
	SLL 53S - NA/INCL 7023375/24
	Sent preli thru Mennen
	Confirm \$1585.20 @ 3days (Red \$1696.80, 52%)

REF: MSIG

ASSIGNMENT

Date: 9/3/18
 To inspect Vehicle No: SLU 4864U
 at Workshop/mis: Motor Image
 of: 19 lorong 8 Toa Payoh
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Excess:
 Clients Record:
 Make of Ven:



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Ball or Market Value:
 DAD Accident Report: Consistent? : Yes or No
 G/A PR Seen: Consistent? : Yes or No
 Est. Repairs: 3 days Res: Yes or No
 Lim Sum: % 3 Yal: Yes or No

CA / REV / REP. / 24 HRS 'wup'

Date: Person Contacted: Vehicle IN / OUT

Ref: SLU 4864U Date: 04 Dec 2017
 Title: Motor Insurance Policy

Truck: Trans:
 Make: Suparu XV 1600
 Colour: white
 Sp Reading: 8408
 Eng No:
 Ch No: 5F1G T3KC 5J G 0248 52
 Gen Cond: Good Fair Poor Burnt
 Steering: Inorder Jammed Leaked Burnt or
 Brake: Inorder Jammed Leaked Burnt or
 Mod: M/S STD 4R
 Tyre Size: 225/60 R17

BS / DUN / EXNOVA / BY FS LIZA MIC OHTSU RIR SUM
 TOYO / YOKO or
 Front: R/Ba 8 mm L/Ba 8 mm
 D/D A: 05-03-18
 Surveyed at: w/s 2pm
 Des of Damages: Fr. 1 OS NS UC Ratched or

The UC Chassis frame Body Structure affected due to collision

RECEIVED 14 AUG 2018

Date/Time File Pass: /
 : Prel. Report
 : Final Report

Days Of Repair: 3
 Resurvey No. of Trip: 1

Report Formset: TP
 Lure: 1585.20

Add Fee:
 Gre: 5
 Gre: 5
 Test: 5
 Test: 5

200
 10
 210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Feb 2018		05 Mar 2018 09:58 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LEE CHIN NGEE (LI JINYI), ID: S8109805J, Tel: +6581619056, Email: chinnggee@gmail.com		
Main Claimant:	Tan Kah Hwee (Chen Jiahui), ID: S8838459H		
Vehicle Reg. No.:	SLU4864U	Date of Loss:	08/02/2018 09:00 - :59
Claim Type:	TP / 549200	Policy/Cover Note No.:	D29041427QMY (Comprehensive) Coverage: 15/11/2017 - 14/11/2018
Vehicle Reg. No. (Insured):	SLL53S	Policy No. (Claimant):	
		Excess:	
Repairer:	Motor Image Enterprises Pte Ltd (HQ) 19 LORONG 8 TOA PAYOH, 319255 Toa Payoh - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/03/2018]		
Driver/Custodian (Insured):	LEE CHIN NGEE (LI JINYI) (36 / Male), NRIC: S8109805J, Tel: +6581619056		
Adj Asg. Remarks:	Survey - Car in at 10am. Thanks.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18004205/Grd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 05-03-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLL 53S	Veh. Inspected	SLU 4864U
Policy No.	D29041427QMY	Coverage (\$)	0.00
Claim No.	549200	Excess (\$)	0.00
Assign From	MERIMEN (KATHEIRINE WONG)	Assign Date	05/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	08/02/2018	Inspection Date	
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 13 Mar 2018

Preliminary Advice

Insured Vehicle No : SLL53S
TP Vehicle No : SLU4864U
Make : SUBARU XV
Date of Inspection : 09/03/2018
Inspection At : MOTOR IMAGE ENTERPRISES PTE LTD (HQ)
19 LORONG 8 TOA PAYOH
SINGAPORE 319255
Accident Date : 08/02/2018
Assignment Date : 05/03/2018
Est. Duration of Repair : 3.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,282.00
Revised Amount	:S\$	1,585.20
Check Items (Estimated)	:S\$	711.60
Total	:S\$	2,296.80
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.


Janice Lee (LKKAuto)

From: Sayedinah <sayedinah@motorimage.net>
Sent: Saturday, August 11, 2018 3:24 PM
To: SUR
Cc: Daniel Jude; Kuan Wei Loong; Mohamed Isman
Subject: SLU4864U-AIG-TP(SLL53S)MSIG-FINALIZED
Attachments: SLU4864U MARKED ESTIMATE.PDF; SLU4864U FINALIZED.pdf; BP1.jpg; BP2.jpg; BP3.jpg

Importance: High

Hi Guo Qiang,
Attached for your reference.

Regards
Sayedinah Ali
Service Executive
Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
HP:92992693 DID:67038109 FAX:+65-62535535
Email:sayedinah@motorimage.net
Website:www.tanchong.com :: www.motorimage.net



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/02/2018 12:28
Date Of Accident	08/02/2018 09:30
Exact Location Of Accident	AYE TOWARDS TUAS BEFORE NORMANTON EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU4864U
Insured/Policyholder	
Name Of Registered Owner	TAN KAH HWEE (CHEN JIAHUI)
NRIC No	S8838459H
Email Address	KELVINTKH88@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-91393358
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	SUBARU
Model	XV-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	1700084930

Driver

Name of Driver	TAN KAH HWEE (CHEN JIAHUI)
NRIC No	S8838459H
Date Of Birth	06/10/1988
Occupation	INDOOR
Date Of Driving Pass	22/05/2009
Driving Experience	8 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91393358
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	KELVINTKH88@YAHOO.COM.SG

Address	1
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED SKETCHED PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	TO BE FOLLOW
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL53S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE CHIN NGEE
NRIC/Passport Number	S8109805J
Contact Number	81619056
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

9/2/2018 1120hrs



Driver's Signature
(If driver is not the policyholder)
Date & Time:

9/2/2018 1120hrs


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

WAS TRAVELLING AYE TOWARDS TUAS BEFORE NORMANTON.

CAR A (MYSELF) MANAGE TO STOP IN TIME WHEN THE CAR IN FRONT

CAME TO A COMPLETE STOP.

WHEREBY CAR B DID NOT STOP IN TIME AND HAD BUMP

INTO CAR A.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

9/2/2018 11:20hrs

PLEASE SIGN IN BLUE INK



Driver's Signature

(If driver is not the policyholder)

Date & Time:

9/2/2018 11:20hrs



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLU4864U		
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	SUBARU		
Vehicle Model :	XV 1.6I-S AWD CVT		
Chassis No. :	JF1GT3KC5JG024852		
Propellant :	Petrol		
Engine No. :	FB16YB84307		
Engine Capacity :	1600 cc		
Maximum Power Output :	84.0 kW (112 bhp)		
Maximum Laden Weight :	1940 kg		
Unladen Weight :	1480 kg		
Year Of Manufacture :	2017		
Original Registration Date :	04 Dec 2017		
Lifespan Expiry Date :	-		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium :	\$47,112.00		
COE Expiry Date :	03 Dec 2027		
Road Tax Expiry Date :	03 Jun 2018		
PARF Eligibility Expiry Date :	03 Dec 2027		
Inspection Due Date :	03 Dec 2020		
Intended Transfer Date :	12 Mar 2018		
CO2 Emission :	149.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 03 Jun 2018. You may renew the road tax from 04 Mar 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 03 Jun 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 04 Jun 2018 to 03 Dec 2018)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0625/2018
DATE : 09-FEB-2018

MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
S(048581)
TEL : 66431335/6827 7880
FAX : 66431349/6827 7809
7313 DAVID

OWNER'S NAME : TAN KAH HWEE (CHEN JIAHUI)
ADDRESS : APT BLK 870A TAMPINES STREET 86
#06-14
S(521870)
TELEPHONE NO : 91393358

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700084930
VEHICLE NO : SLU4864U
MODEL CODE : GT3BKGC
MODEL/YEAR : SUBARU XV 1.6i-S AWD CVT
ENGINE NO : FB16YB84307
CHASSIS NO : JF1GT3KC5JG024852
MILEAGE : 1 KM
DATE IN : 09/02/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 08/02/2018

Print Date : 09/02/2018
Print Time : 17:31:20

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLU4864U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM MSIG LOCATION: AYE TOWARDS TUAS BEFORE NORMANTON EXIT DATE: 08/02/2018 TIME: 0930H		
3	ZZ/002	REMOVE/REFIX REAR BUMPER, PANEL	1120.00	560 /
4	ZZ/003	RESPRAY REAR BUMPER, PANEL	840.00	420 /
5	ZZ/004	TO CONDUCT (REAR) LIGHTING TEST	50.00	8 /
6	ZZ/005	TO SUPPLY & INSTALL REVERSE SENSOR - 2 EYES	300.00	X /
7	ZZ/006	SUNDRIES	100.00	X /
TOTAL LABOUR CHARGES			2410.00	NN

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLU4864U

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	SKIRT COMPL R SD / ll .	52401FL0209P	288.00 /			
2	BUMPER FACE R XV / ll	57704PL250	401.10 /			
3	BRKT SD R XV RH /	57707FL400	12.10 /			
4	BRKT SD R XV LH /	57707FL410	12.10 /			
5	BRKT CORNER R SD RH /	57707FL460	21.60 /			
6	BRKT CORNER R SD LH /	57707FL470	21.60 /			
7	BRKT LWR R X	57707FL510	25.20			
8	COVER HOOK R XV X NN	57731FL570NN	6.50			
9	LENS & BODY COMPLRRH X	84913AL120	129.60			
10	LENS & BODY COMPLRLH REFLEX X	84913AL140	64.20			
11	TRIM PNL AY SKIRTT X	94026FL010VH	108.00			
SUB TOTAL			1090.00	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			218.00	0.00	0.00	0.00
GRAND TOTAL			872.00	0.00	0.00	0.00
OVERALL TOTAL			872.00			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLU4864U

TOTAL LABOUR CHARGES	2410.00
TOTAL SPARE PARTS CHARGES	872.00
GRAND TOTAL	3282.00 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	:
LIABILITY	:
REMARKS	:

Guo Qiang - 82880282

09/3/18

before paint photos.
3 Days

[Signature]
13/3/18

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0625/2018
DATE : 09-FEB-2018

MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
S(048581)
TEL : 66431335/6827 7880
FAX : 66431349/6827 7809
7313 DAVID

OWNER'S NAME : TAN KAH HWEE (CHEN JIAHUI)
ADDRESS : APT BLK 870A TAMPINES STREET 86
#06-14
S(521870)
TELEPHONE NO : 91393358

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700084930
VEHICLE NO : SLJ4864U
MODEL CODE : GT3BKGC
MODEL/YEAR : SUBARU XV 1.6I-S AWD CVT
ENGINE NO : FB16YB84307
CHASSIS NO : JF1GT3KCSJG024852
MILEAGE : 1 KM
DATE IN : 09/02/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 08/02/2018

Print Date : 28/06/2018
Print Time : 21:26:40

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLU4864U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM MSG LOCATION:AYE TOWARDS TUAS BEFORE NORMANTON EXIT DATE:08/02/2018 TIME:0930H		
3	ZZ/002	REMOVE/REFIX REAR BUMPER, PANEL	1120.00	560.00
4	ZZ/003	RESPRAY REAR BUMPER, PANEL	840.00	420.00
5	ZZ/004	TO CONDUCT (REAR)LIGHTING TEST	50.00	.00
6	ZZ/005	TO SUPPLY&INSTALL REVERSE SENSOR-2 EYES	300.00	.00
7	ZZ/006	SUNDREIS	100.00	.00
TOTAL LABOUR CHARGES			2410.00	980.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLU4864U

		DAMAGED PARTS & PRICES			
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1 SKIRT COMPL R SD	52401FL0209P	288.00			OK
2 BUMPER FACE R XV	57704FL250	401.10			OK
3 BRKT SD R XV RH	57707FL400	12.10			OK
4 BRKT SD R XV LH	57707FL410	12.10			OK
5 BRKT CORNER R SD RH	57707FL460	21.60			OK
6 BRKT CORNER R SD LH	57707FL470	21.60			OK
7 BRKT LMR R	57707FL510	25.20			X
8 COVER HOOK R XV	57731FL5708N	6.50			X
9 LENS & BODY COMPLRH	84913AL120	129.60			X
10 LENS & BODY COMPLRLH REFLEX	84913AL140	64.20			X
11 TRIM PNL AY SKIRT	94026FL010VH	108.00			X
SUB TOTAL		756.50	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		151.30	0.00	0.00	0.00
GRAND TOTAL		605.20	0.00	0.00	0.00
OVERALL TOTAL		605.20			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLU4864U

NETT ITEM	756.50
LESS 20 %	-151.30
NETT AMOUNT	605.20
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	0.00
S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00
TOTAL LABOUR CHARGES	980.00
TOTAL SPARE PARTS CHARGES	605.20
TOTAL CHARGES	1585.20
ADD 7 % GST	110.96
GRAND TOTAL	1696.16

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18004205/GRD3N2

Date: 15/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	D29041427QMY
Claimant Vehicle No :	SLU4864U	Insured Vehicle No :	SLL53S
Date of Loss:	08/02/2018	Nature of Claim:	TP
		Claim No:	549200

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU4864U	Engine No:	FB16YB84307
Make & Model:	SUBARU XV, 1.6 I-S AWD CVT (A)	Chassis No:	JF1GT3KC5JG024852
Reg. Date:	04/12/2017 (Man. Year: 2017)	Odometer:	8409 km
Colour:	White		
Engine Capacity:	1600 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60R17	Rear Tyre Size:	225/60R17
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	972.00	605.20	366.80	37.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	980.00	1,330.00	57.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,282.00	1,585.20	1,696.80	51.70
+ GST 7.00/7.00% (S\$)	229.74	110.96	118.78	51.70
Nett Amount (S\$)	3,511.74	1,696.16	1,815.58	51.70

INSPECTION

Date of Assignment:	05/03/2018	
Date Inspected:	09/03/2018	Inspected At: Motor Image Enterprises Pte Ltd (HQ) 19 LORONG 8 TOA PAYOH Singapore 319255

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Aug 2018)
Parts: 144	SUBARU XV 1.6 I-S AWD CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLU4864U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SKIRT COMPL R 5D	Deformed	288.00 FN	*288.00 FN
2	1		*BUMPER FACE R XV	Deformed	401.10 FN	*401.10 FN
3	1		*BRKT SD R XV RH	Necessary	12.10 FN	*12.10 FN
4	1		*BRKT SD R XV LH	Necessary	12.10 FN	*12.10 FN
5	1		*BRKT CORNER R 5D RH	Necessary	21.60 FN	*21.60 FN
6	1		*BRKT CORNER R 5D LH	Necessary	21.60 FN	*21.60 FN
7	1		*BRKT LWR R	Not Necessary	25.20 FN	*- FN
8	1		*COVER HOOK R XV	Not Necessary	6.50 FN	*- FN
9	1		*LENS & BODY COMPLRRH	Not Necessary	129.60 FN	*- FN
10	1		*LENS & BODY COMPLRLH REFLEX	Not Necessary	64.20 FN	*- FN
11	1		*TRIM PNL AY SKIRTT	Not Necessary	108.00 FN	*- FN
12	1		*SUNDRIES	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	1,190.00	756.50
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	218.00	151.30
Total Parts (\$\$)	972.00	605.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/REFIX REAR BUMPER,PANEL	New	1,120.00	560.00
2	RESPRAY REAR BUMPER,PANEL	New	840.00	420.00
3	TO CONDUCT (REAR) LIGHTING TEST	New	50.00	-
4	TO SUPPLY & INSTALL REVERSE SENSOR-2 EYES	New	300.00	-
Gross Labour Cost (\$\$)			2,310.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18004205/GRD3N2

Date: 15/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	D29041427QMY
Claimant Vehicle No :	SLU4864U	Insured Vehicle No :	SLL53S
Date of Loss:	08/02/2018	Nature of Claim:	TP
		Claim No:	549200

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU4864U	Engine No:	FB16YB84307
Make & Model:	SUBARU XV, 1.6 I-S AWD CVT (A)	Chassis No:	JF1GT3KC5JG024852
Reg. Date:	04/12/2017 (Man. Year: 2017)	Odometer:	8409 km
Colour:	White		
Engine Capacity:	1600 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60R17	Rear Tyre Size:	225/60R17
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	972.00	605.20	366.80	37.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	980.00	1,330.00	57.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,282.00	1,585.20	1,696.80	51.70
+ GST 7.00/7.00% (\$\$)	229.74	110.96	118.78	51.70
Nett Amount (\$\$)	3,511.74	1,696.16	1,815.58	51.70

INSPECTION

Date of Assignment:	05/03/2018	
Date Inspected:	09/03/2018	Inspected At: Motor Image Enterprises Pte Ltd (HQ) 19 LORONG 8 TOA PAYOH Singapore 319255

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Aug 2018)
Parts: 144	SUBARU XV 1.6 I-S AWD CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU4864U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SKIRT COMPL R 5D	Deformed	288.00 FN	*288.00 FN
2	1		*BUMPER FACE R XV	Deformed	401.10 FN	*401.10 FN
3	1		*BRKT SD R XV RH	Necessary	12.10 FN	*12.10 FN
4	1		*BRKT SD R XV LH	Necessary	12.10 FN	*12.10 FN
5	1		*BRKT CORNER R 5D RH	Necessary	21.60 FN	*21.60 FN
6	1		*BRKT CORNER R 5D LH	Necessary	21.60 FN	*21.60 FN
7	1		*BRKT LWR R	Not Necessary	25.20 FN	*- FN
8	1		*COVER HOOK R XV	Not Necessary	6.50 FN	*- FN
9	1		*LENS & BODY COMPLRRH	Not Necessary	129.60 FN	*- FN
10	1		*LENS & BODY COMPLRLH REFLEX	Not Necessary	64.20 FN	*- FN
11	1		*TRIM PNL AY SKIRTT	Not Necessary	108.00 FN	*- FN
12	1		*SUNDRIES	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	1,190.00	756.50
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	218.00	151.30
Total Parts (\$\$)	972.00	605.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/REFIX REAR BUMPER,PANEL	New	1,120.00	560.00
2	RESPRAY REAR BUMPER,PANEL	New	840.00	420.00
3	TO CONDUCT (REAR) LIGHTING TEST	New	50.00	-
4	TO SUPPLY & INSTALL REVERSE SENSOR-2 EYES	New	300.00	-
Gross Labour Cost (S\$)			2,310.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >