

ASS. REC. BY:

REF: CS3 / SMO18004214 / R1d3

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Grace Teo

of

SMO

Date/Time:

2/3/18 06:09pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SK 1438M

Insured:

SLM 2326L

at Workshop m/s

AMH Automotive

Tel:

8778 3636

of

36 Toh Guan Rd East #01-36

Policy No:

Claim No:

CMTD1800952 / AGC

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/03/2018

CA / REV / REP. / REV 24 HRS / wpl

6/3/18 @ Morning

H.O.D. Endorsement:

Date/Time:

10:25am 05/3/18

Person Contacted:

Melvin

Vehicle IN / OUT


Date/Time	Action/Instruction (X) Estimate
	SK 1438M - X
	SLM 2326L - X
	NO GIA

Signature: Rasul

REF: SMO

ASSIGNMENT

From: _____ Date: 7/3/18
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SJK 1438M
 at Workshop / ms: AMA Automotive
 of: 36 7th Glen Rd East #01-36
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record) _____
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS Wp
 Date: _____ Person Contacted: _____ Vehicle IN / OUT

Ver No: SJK 1438M
 Type: ☒ M Cycle / Bus / Van / Lorry / Taxi / Prime Mover
 Truck / Trailer / _____
 Make: TOYOTA Rush
 Colour: BLACK A/C Insured / Std / NI / NA
 Sp. Reading: 132897 T. Radio: Insured / Std / NI / NA
 Eng No: _____
 O No: _____
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brakes: In order / Jammed / Leaked / Burnt or
 Mod: Nil / ☒ R / STD A / Rim or
 Tyre Size: F: 215/65R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI
 TOYO / YOKO or
 Front: _____ Rear: _____
 R. Bal: 5 mm R. Bal: 5 mm
 L. Bal: 5 mm L. Bal: 5 mm
 D.O.A: 01/03/18 D.O: 07/03/18 12-18
 Survey held at: AMA Automotive
 Des of Damages: Frn / Rear / O/S / N/S / U/C / Roof top or
N/S Frn
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
\$3,500 — \$4,800
4/4/2018

RECEIVED 5 APR 2018

Date/Time File Pass to: ☐ : Preli. Report ☐ : Final Report
 Days Of Repair: _____
 Resurvey No. of Trip: _____
 Date/Time File Return to: _____
 Add Fee: ☐ Stained \$ ☐ _____
☐ _____ \$ ☐ _____
☐ _____ \$ ☐ _____
☐ _____ \$ ☐ _____
 Report Format: _____
 Lum Sum / I.B. / I.S: _____
 Survey Fee: _____
 Transcription: _____

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Friday, 2 March 2018 6:09 PM
To: Alywin; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Chan, Shu Hui Agnes
Subject: CMTD1800952/AGC - PRI - ACCIDENT INVOLVING SLM2326L & SJK1438M ON 01.03.2018
Attachments: 20180302162455527.pdf

Our Reference : CMTD1800952/AGC
Your Reference: SJK1438M (AY)

Without Prejudice

Date: 2nd March 2018

Attention:
M/S CHIA S ARUL LLC

Dear Alywin,

ACCIDENT INVOLVING SLM2326L & SJK1438M ON 01.03.2018

We refer to your reply dated 02/03/2018.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Alywin [<mailto:alywin@chiaarul.com>]

Sent: Friday, March 02, 2018 5:57 PM

To: Teo, Grace

Cc: Chan, Shu Hui Agnes

Subject: RE: CMTD1800952/AGC - PRI - ACCIDENT INVOLVING SLM2326L & SJK1438M ON 01.03.2018

Dear All,

We refer to the above matter and to your email below.

Kindly be inform that our client is not agreeable to the list of your surveyor.

We enclosed herewith the list of our client's workshop surveyor for your consideration.

Sincere Appraisal - Mr Dave

SK Auto Consultants - S. Kumanan

Kindly let us have your reply soon.

Please do not hesitate to contact me should you have any queries thereof.

Best regards,

Mr Alywin Yeo

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]

Sent: 02 March, 2018 5:55 PM

To: Alywin

Cc: Chan, Shu Hui Agnes

Subject: CMTD1800952/AGC - PRI - ACCIDENT INVOLVING SLM2326L & SJK1438M ON 01.03.2018

Our Reference : CMTD1800952/AGC

Your Reference: SJK1438M (AY)

Without Prejudice

Date: 2nd March 2018

Attention:

M/S CHIA S ARUL LLC

Dear Alywin,

ACCIDENT INVOLVING SLM2326L & SJK1438M ON 01.03.2018

We refer to your Notice of Accident dated 02/03/2018.

Please be informed that Agnes Chan the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Alywin [<mailto:alywin@chiaarul.com>]

Sent: Friday, March 02, 2018 4:29 PM

To: Claims - Motor Survey

Subject: PRI FOR SJK 1438M

Dear All,

We enclosed herewith a copy of PRI for your necessary action.

Please do not hesitate to contact me should you have any queries thereof.

Best regards,

Mr Alywin Yeo

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet

communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S

Our Ref : SJK 1438M (AY)

Your Ref :

2 March 2018

Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05 - 01 / 06
Singapore Land Tower
Singapore 048623

BY FACSIMILE ONLY
(Fax: 6221 3147)

Dear Sir,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : ENG CHEW SAY
ACCIDENT INVOLVING SJK 1438M & SLM 2326L ALONG CTE TOWARDS
SLE BEFORE ANG MO KIO AVE 5 EXIT ON 1 MARCH 2018

1. We act for ENG CHEW SAY, the owner of motor vehicle no. SJK 1438M, which was involved in the aforesaid accident.
2. We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. SLM 2326L for damages, costs and disbursements as a result of your insured driver's negligence.
3. Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s AMA Automotive Pte Ltd at 36 Toh Guan Road East #01 - 36 Singapore 608580 and kindly arrange with Mr. Melvin at 8778 3636.
4. If we do not hear from you within the next **two (2) working days**, we shall advise our client to proceed with their own inspection and repairs.
5. Please reply either by fax at 6733 8183 or by email to alywin@chiaarul.com.

Yours faithfully,

MR ARULCHELVAN S
cc: Client (By Email)




LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO18004214/R1d3s2	
50 RAFFLES PLACE #05-01/06		Date: 05-04-2018	
SINGAPORE LAND TOWER SINGAPORE 048623		Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SLM 2326L	Veh. Inspected	SJK 1438M
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1800952/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	02/03/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA RUSH	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	BLACK
Odometer	132897 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/65R16	PIRELLI	5 mm
L/H Front Tyre	215/65R16	PIRELLI	5 mm
R/H Rear Tyre	215/65R16	PIRELLI	5 mm
L/H Rear Tyre	215/65R16	PIRELLI	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.			
5. General Information			
Accident Date	01/03/2018	Inspect Date / Time	07/03/2018 (12:18 PM)
Survey held at	AMA AUTOMOTIVE PTE. LTD. 36 TOH GUAN ROAD EAST #03-36 SINGAPORE 608580		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,800			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	

Report Ref No. CS3/SMO18004214/R1d3s2

Inspected By

MRB

MOMHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.