

ASS. REC. BY:

REF:

C03 / ASM18004225 / Wbet

Special Instruction:

Smart claim

Surveyor: Wilson

ASSIGNMENT (Office)

Smart claim

From (Person):

Stacey Ng

of

ASM

Date/Time:

01/03/2018 11:22am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JRR 9835

Insured:

SCN 338S

at Workshop m/s

Asia motorsport

Tel:

6745 3811

of

568 Geylang Rd

Policy No:

Claim No:

S8M009RZ

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16-03-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

02.03.2018

H.O.D. Endorsement:

Date/Time:

01/03/2018

Person Contacted:

Mr. Loo

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	JRR 9835 - X
	Dismantle: 9/3/2018 (Guo Qiang)

Simone

PRS

Wilson

ASSIGNMENT

From _____ Date _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No JRR 9835

at Workshop no Asia Motor Sports

of 368 Gaylang Rd.

Insured _____

Policy No _____

Claims No _____

Sum Insured _____

Excess _____

(Client's Records)

Make of Veh _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bail or Market Value _____

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen Consistent? : Yes or No

Est. Repairs. days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted _____

Vehicle: IN / OUT

Date / Time Action / Instruction

2/3/18 Mileage Not Available - Not key
12/4 Accident Report Not Given
Submit PRS report

Veh No: JRR 9835

Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make Kawasaki

Colour Dark Grey Insured / Std / NI / NA

Sp Reading No Available Insured / Std / NI / NA

Eng No _____

C No _____

Gen Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size F: 110/70-17 m/c

R: 150/60-17 m/c

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or

Front

R/Bal 3 mm

L/Bal _____ mm

D.O.A.

Rear

R/Bal 4 mm

L/Bal _____ mm

D.O.

Survey held at:

As Above

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 12 APR 2018

Date/Time File Pass to:

☐ : Preli. Report

☐ : Final Report

Date/Time File Return to:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Site - PRS

Other

Other

Other

Other

Other

Add Fee: ☐ Site Insp \$

☐ Interview \$

☐ Tech Insp \$

☐ Weekend \$

Report Format: PRS

Lump Sum / I.B.I. / S

100

100



Service Request Details

Claim

S8M009RZ

Reference

None 

Loss Date

February 16, 2018

Request Date

March 1, 2018

Due Date

March 1, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work

More ▾

Vehicle Information

Incident Vehicle Registration #

JRR9835

Make

TPVD TBC

Primary Contact/Insured

SOH SING HWA THOMAS
BLK 14 SCOTTS ROAD, #04-114, 228213, Singapore

I2IHUB@SINGNET.COM.SG

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

New Message

TYPE



SENT

3/1/18 2:26 PM

FROM

TAN Wancong

SUBJECT

Asia Motorsports - 6745 3811

BODY

Asia Motorsports - contact 6745 3811

