



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

TPVD TBC (JRR9835)

Date of Loss

16 February 2018

Time of Loss

0.00

Loss Description

SCN338S (INSD) C/W JRR9835 (TP)

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Target Date of Completion *

06/05/2018



Days of work completion *

66



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

JRR9835

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

01/01/1900



Mileage

Age of Vehicle

118

CATEGORY

Manufacturing Year

Driver Details

POLICY INFORMAT...

CATEGORY

Driver Name

ASSESSMENT INFO...

FNOL INFORMATI...

TBC TBC

CATEGORY Make

POLICY INFORMAT... TPVD TBC

ASSESSMENT INFO... KAWASAKI

CATEGORY Model

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT...

ASSESSMENT INFO...

POST SURVEY INF...

CATEGORY Date of Birth

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

CATEGORY Engine No

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT...

ASSESSMENT INFO...

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF...



CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF...



CATEGORY Address

FNOL INFORMATI...	TBC, Singapore
POST SURVEY INF...	

CATEGORY	Address type
FNOL INFORMATI...	Personal Correspondence
POST SURVEY INF...	

CATEGORY	Gender
FNOL INFORMATI...	Unknown
POST SURVEY INF...	

CATEGORY	Marital status
FNOL INFORMATI...	Unknown
POST SURVEY INF...	

CATEGORY	Identification #
FNOL INFORMATI...	TBC



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

02/03/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

110/70-17

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Tyre Condition

Spare wheel

Rear Tyre Size

150/60-17

Front left side

DUNLOP3mm

Rear left side

DUNLOP4mm

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Save



PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS3/ASM18004225/Wbe2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date: 16-04-2018		
ATTN : STACEY NG		Code: ASM		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SCN 338S	Veh. Inspected	JRR 9835	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M009RZ	Excess (\$)	0.00	
Assign From	STACEY NG	Assign Date	01/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	KAWASAKI	c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour	DARK ORANGE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/70-17	DUNLOP	3 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	150/60-17	DUNLOP	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
5. General Information				
Accident Date	16/02/2018	Inspect Date / Time	02/03/2018 (05:21 PM)	
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 568 GEYLANG ROAD SINGAPORE 389514			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/ASM18004225/Wbe2

Inspected By



WILSON TEO CHENG MING

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.