

NATIONAL Assessment Centre Services

FWAO

MAA48031054

Date In: 05/03/2018 17:21	Job description	Date & Time Completed	Done by
Ref No: NBAR INC 00042314	SAS e-illing		
Veh No: FBJ 8578 X	E-inoll (within 3hrs, AIC 3hrs)		
D.O.A: 01/03/2018 17:00	I-Motor Claim Form	MAA48031054	06/03/2018 10:22
OD / TP / Reporting Only	I-Motor W/O (within 60 days, TP 30 days)		
	I-Photo Uploaded		
TP Insureh:	Assessment/Survey Report		
	Ass't Report by Fax/Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / OW:	Tel:	Fax:
TP Particulars: Yell No: →	INC () / Non-INC ()	
Owner / Driver: ()	Tel: ()	
Policy No: ()	Period: ()	Cover Type: ()
Confirmed by: ()	Date: ()	Time: ()
Insured/Driver Liability: () %	(Note: Est Status (WO): N: 0-20%; P: 21-79%; P: 80-100%)	
Year of Registration: ()	Warranty: YES () / NO ()	
Excess: (\$)	Loading: \$1,000 () / \$2,000 ()	

General Remarks:

() Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In () / Towed-In () : Invoice: YES () / NO () : Towing Co: ()

Remarks: INC 00042314	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo (Repair Cost > \$3000) ()		

Injury: _____

Date/Time: _____

Actions: _____

NA1801761	Invoice Preparation Checklist	Bill	Check/Bill
1) AR: Accident Reporting (\$30)			
2) DA: Damage Assessment (\$100)	INC (\$30)		
3) TP: Towing Fee	\$40/\$120		
4) FT: Follow-Through Survey	\$120		
5) RT: Follow-Through Survey (Resurvey)	\$30		
Excludes all except INC Only (w/ef 10 Jan 2008)			
6) TR: Re-inspection	\$15		
7) NI: NI DA + SMRT Survey	\$160		
8) NTUC Additional Services			
9) NI: NI DA + SMRT Survey			
10) NI: NI DA + SMRT Survey			
11) NI: NI DA + SMRT Survey			
12) NI: NI DA + SMRT Survey			
13) NI: NI DA + SMRT Survey			
14) NI: NI DA + SMRT Survey			
15) NI: NI DA + SMRT Survey			
16) NI: NI DA + SMRT Survey			
17) NI: NI DA + SMRT Survey			
18) NI: NI DA + SMRT Survey			
19) NI: NI DA + SMRT Survey			
20) NI: NI DA + SMRT Survey			

C. Checked by (Engr-In-Charge): _____

Invoice dated: _____

Invoice total: _____

File Charged: _____

Non-Charged: _____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/03/2018 17:21
Date Of Accident	01/03/2018 17:00
Exact Location Of Accident	NEAR TO PEDAS TOLL PLAZA
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBJ8578X
Insured/Policyholder	
Name Of Registered Owner	ALIF DANIAL BIN BORHAN
NRIC No	S9309675D
Email Address	ALIF_DANIEL@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-90867456
Alternative Phone No	OTHERS-90867456

Vehicle Particulars

Manufacturer	BMW
Model	R1200GS-1.2 (M)
Exact Purpose for which vehicle was being used at time of accident	TOURING
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	MOTORCYCLE
------------------	------------

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097354683
Cover Note Number	

Driver

Name of Driver	ALIF DANIAL BIN BORHAN
NRIC No	S9309675D
Date Of Birth	19/03/1993
Occupation	INDOOR
Date Of Driving Pass	27/01/2018
Driving Experience	0 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90867456
Fax Number	
Contact Number	OTHERS-90867456
Email Address	ALIF_DANIEL@HOTMAIL.COM

Address	BLK 316A ANG MO KIO STREET 31 #06-303
Postcode	562316
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	NO COLLISION
Weather Conditions	CLEAR
Road Surface	A LOT OF FOREIGN OBJECTS

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	1
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TECK GHEE NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 321 ANG MO KIO STREET 31 , POSTCODE: 560321 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4599999 - FAX NO: 64574478
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT F/20180302/2110

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF INJURED PERSON 1

Name	ALIF DANIAL BIN BORHAN
Approximate Age	
Injuries Sustain	SLIGHT INJURY
Injured person in which vehicle?	FBJ8578X
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders,

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Riding at 50km/hr - 70km/hr, foreign object hit left side of bike, skidded to bottom of cliff, flew to the drain after tumbling multiple times.

Start point: After exiting north-south highway.

End point: Right before Pedas Toll Plaza

DECLARATION

I/We declare the foregoing particulars are true in every respect.

ck 05032018

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

05/03/2018
Reporting Centre Personnel's Signature
Name: *Resli*
NRIC/FIN No.: *W071013*



**SINGAPORE
POLICE FORCE**



F/20180302/2110

1 of 2

POLICE REPORT (NP299)

Report No. F/20180302/2110

Police Station Of Origin
Teck Ghee NPP
321 Ang Mo Kio Street 31 SINGAPORE
560321
Tel No: 1800-4599999


Date/Time Report Made 02/03/2018 16:47	Vide Report No.	Station Diary No. 13
Name Of Informant ALIF DANIAL BIN BORHAN	Address APT BLK 316A ANG MO KIO STREET 31 #06-303 SINGAPORE 562316	
ID Type / ID No. NRIC NO / S9309675D	Contact No. Home/Office Mobile 90867456	
Nationality SINGAPORE CITIZEN	Email Address	
Occupation CHEMICAL TECH	Sex Male	Age 24
Institution/School Name	Date of Birth 19/03/1993	Race Boyanese
Date/Time Of Incident 01/03/2018 17:00	Location Of Incident Near to Pedas Toll Plaza MALAYSIA	

Brief details.

01/03/2018 at about 1700hrs, I was riding my motorcycle, FBJ8578X, in Malaysia, near to Pedas Toll Plaza, out of a sudden, I felt an impact on the left side of my motorcycle.

After the impact, I lost control of my motorcycle and skidded together with my motorcycle.

After skidding for about 50 meters, I motorcycle collide onto the foot of the cliff causing me to be thrown off my motorcycle and I landed in a drain about 30 meters away from my motorcycle.

Signature Of Officer Recording The Report: F / Staff Sgt YIP WAI LEONG 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 02/03/2018 16:47
Officer In-Charge Of Case: F / Ang Mo Kio South N.P.C / Staff Sgt YIP WAI LEONG Contact No.: 64519999	Classification Of Case:

Authentication Stamp





**SINGAPORE
POLICE FORCE**



F/20180302/2110

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20180302/2110

Shortly, Police and ambulance came and I was conveyed to the hospital however I did not seek treatment and decided to proceed back to Singapore for treatment.

My motorcycle was seriously damaged and had to be tow back to Singapore and I sustained abrasion on my left shoulder, right ankle, right shin and strain on my neck.

I reported the matter to my insurance company and they advise me to lodge a Police report for their record.

Signature Of Officer Recording The Report:

F / Staff Sgt YIP WAI LEONG

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
F / Ang Mo Kio South N.P.C /
Staff Sgt YIP WAI LEONG
Contact No.: 64519999

Authentication Stamp

Signature Of Informant:

Date/Time:
02/03/2018 16:47

Classification Of Case:

Claim Handling

Accident MT/0984830

Policy No.	5097354683	Vehicle No.	FB18578X	GST Registration No.	
Policyholder Name	ALIF DANIAL BIN BORHAN			Policyholder NRIC	
Product Code	MOTORCYCLE INSURANCE	Cover Type	Comprehensive	Loading	
Contact No.(Mobile)	90867456	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No

Accident Details

Report Date	06/03/2018 10:02	Accident Report Within 24 hrs	Yes	Accident Type	No collision
Date of Accident	01/03/2018	Time of Accident hh:mm	17:00	Country of Accident	Outside Singapore
Reporting Centre		Orange Force		ICM No.	
Accident Location	NEAR TO PEDAS TOLL PLAZA MALAYSIA				

Benefits

Excess

Own damage Excess	1,000.00	Additional Excess		Windscreen Excess	
Unnamed Driver Excess		Outside Singapore OD Excess			
Third Party Excess	0.00	Outside Singapore TP Excess			

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	BLK 316A #06-303	Address 2	ANG MO KIO STREET 31	Address 3	
Address 4	SINGAPORE 562316	Address Type	Singapore address	Post Code	
Unit No.	06-303	Related Policy Number	5097354683		

OI Driver Info

Driver Name	ALIF DANIAL BIN BORHAN	Driver Type	Main Driver	Driver DOB	
Unnamed driver Name		Driver NRIC	593096750	Driving Experience	
Register Date of Driver License	07/01/2012	Driver Age	24	Contact No.(Home)	
Contact No.(Mobile)		Contact No.(Office)		Address 3	
Address 1	BLK 316A #06-303	Address 2	ANG MO KIO STREET 31	Post Code	
Address 4	SINGAPORE 562316	Address Type	Singapore address		
Unit No.	06-303				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.	FB18578X	Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
-------------------------------------	------	-------------	---

Modification History

Claim 001

New

Claim Type *	OD-MD	Insured Name	ALIF DANIAL BIN BORHAN	Insured NRIC	
Contact No.(Mobile)	90867456	Contact No.(Home)		Contact No.(Office)	
Email Address		OI Vehicle Number	FB18578X	TP Vehicle Number	
Claim Description	FB18578X / - ON 1 Mar 2018				
Preferred Workshop Contact No.	63181611(SALLY)	Insured Liability *	Not at Fault	Name of Preferred Workshop	
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop (refer below)	GIA report	
Date Registered	01/03/2018 10:14	Claim Close Date		Date Received	
Report Taken By	ROSLI WAHAB				

☐ Print AK letter

Save Submit

Attachment

Accident No.	MT/0984830	Claim No.	001
Last Doc. Received	☒ Yes ☐ No	Upload Date	06/03/2018 10:22
Path *		Category *	Confidential Urgency
		Browse Clear Please Select	W3 Normal

Browse...	Clear	Please Select	▼	NO	▼	Normal
Browse...	Clear	Please Select	▼	NO	▼	Normal
Browse...	Clear	Please Select	▼	NO	▼	Normal
Browse...	Clear	Please Select	▼	NO	▼	Normal
Browse...	Clear	Please Select	▼	NO	▼	Normal

Attachment List

Attachment	Uploaded By/Date	Category		Urgency	De
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:22	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:22	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:22	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:22	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:19	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:19	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:19	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:19	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:19	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:19	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:18	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:18	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:18	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:18	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:18	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:18	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:18	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:18	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:18	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:18	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:18	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:17	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:17	Photos		Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:17	Photos		Normal	Photo

	Uploaded By/Date	Folder Date	File Name	Status	Sour
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:17		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:17		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:17		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:16		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:16		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:16		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:16		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:16		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:16		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:16		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:16		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:16		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:15		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:15		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:15		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:15		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:15		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:15		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:15		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:15		Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:15		NRIC/ Driving License	Normal	NRIC/ Drivin
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 06 Mar 2018 10:14		SAS	Normal	SAS

[Display in New Window](#) [Scan and uploading](#)

ASSI

R25

Insurance

V-10/10/17

ASSIGNMENT 11By Assessor-1) Features of Accident:

- 1) Vehicle hit Vehicle: ☐ 2) Vehicle hit ☐
- a) Motorcar ☐ a) Pedestrian ☐
- b) Motorcycle ☐ b) Animal ☐
- c) Bicycle ☐
- 3) Vehicle hit/Road Side Objects:
- a) Govn Property ☐ b) Road Work Object ☐
- (Ex: signboards, lights, etc etc)
- c) Private Property ☐
- 4) Vehicle drop into drain ☐
- 5) Damage due to Act of God:
- a) Fallen Object ☐ b) Flood ☐
- c) Other: ☐
- 6) Parked & Found Damaged:
- a) Vandalism ☐ b) Hit by Moving Object ☐
- 7) Theft Case
- a) Stolen ☐ b) Damage found ☐
- when recovered.
- 8) Fire
- a) Whilst driving ☐ b) Parked ☐
- 9) Accident date more than 24hrs ☐

Remarks for Internal InformationRemarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ☐
- 2) SRS Light on ☐
- 3) ABS Light on ☐

By Assessor-1) Vehicle Information:

Veh No: FBJ 2578X Yr Regn: NOV / 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Cab / Prime Mover / MPV

/ Truck / Trailer or

Make & Model: B.M.W R1200GS cc: ☐

Colour: WHITE Transmission Type: Auto / Manual

Eng/No: 122EN21140927 Sp Reading: N/A

C/Nr: WB10AC200EZ208096

Gen. Cond: Good / Fair / Poor / Burnt or

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120-70-19

R: 170-60-17

BS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mm

R/Bol: 6 mm R/Rol: 6 mm

L/Bol: 6 mm L/Rol: 6 mm

Parallel Import: Yes ☒ No ☐ Towed-In: ☒ Yes / No ☐

Repair Type: LS / L.B.I. Towing Required: Yes / ☒ No ☐

No of Repair Days: 07/03/2018 Vehicle in Idoc: Yes / ☒ No ☐

D.O.I. 07/03/2018 Time: ☐

By Assessor-2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
- a. Vehicle ☐ b. Motorcycle ☐ c. Bicycle ☐ d. Pedestrian ☐
- e. Animal ☐ f. Govn Object ☐ g. Road Work Object ☐
- h. Private Property ☐ i. Drain ☐ j. Road Kerb/Grass Verges ☐
- 3) Vehicle does not seem damaged as a result of:
- a. Fallen Object ☐ b. Flood ☐ c. Vandalism ☐ d. Fire ☐
- e. Moving Object ☐ f. Stolen ☐ g. Stolen & Recovered ☐

Date Stamp?

Date Completed?

1) C/S

2) A/S

3) Subject's/Assessor's Signature

Condition (CON)

(01) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

FOR MOTORCYCLE

ACTION (AC)

1. Replace (✓) 2. Repair (X) 3. Check (?)
4. Not Consistent (NC)

May 2005

Motorcycle

Vehicle No: **FRJ858X**

NAC	INC	Item	CON	AC	Qty
1001	991886	Front Number Plate MYOGUARD	CUT	✓	
3001	995065	Front Tyre	CUT	✓	
3002	995095	Front Rim	BT	✓	
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard			
3005	991283	Front Brake Disc LH/RH	BT	✓	2
3006	991281	Front Brake Caliper LH/RH	DIS	✓	2
3007	991785	Front Fork Assy LH/RH	BT	✓	2
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube			
3010	991167	Front Fork Bracket			
3011	991182	Front Fork Oil Seal	MAC	✓	
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp STAY			
3015	992337	Front Headlamp Bracket			
3016	992345	Front Headlamp Fairing			
3017	992130	Front Windshield COVER	SCR	✓	
3018	992134	Front Wing Mirror LH/RH	SCR	✓	2
3019	995245	Front LH Signal Lamp	SCR	✓	
3020	995246	Front Mirror Rubber LH/RH	MAC	✓	2
3021	992556	Meter Casing			
3022	992553	Meter Assy	BR	✓	
1118	991019	ERP Bracket	BR	✓	
1119	991020	ERP Unit			
3023	992446	Front Axle			
3024	992442	11 WHEEL BEARING	MAC	✓	2
3025	990706	11 WHEEL BEARING	MAC	✓	2
3026	994470	Front Axle Bolt	MAC	✓	1
3027	994427	Front Brake Disc Bolt	MAC	✓	10
3028	992299	Handle Bar			
3029	992312	Handle Bar Switch HAND GUARD	SCR	✓	2
3030	992310	Handle Bar SWITCH			
3031	995184	Handle Bar GRIP RH/LH	CUT	✓	
3032	992300	Handle Bar BRACKET			
1252	992179	Fuel Tank SIDE COVER LH/RH	CUT	✓	2
3033	990438	Brake Reservoir	CUT	✓	
3034	990621	Clutch Lever & Reservoir			
3035	992293	Hand Brake Lever	BT	✓	
3036	991119	Side Fairing LH	SCR	✓	
3037	994220	Side Fairing Top Garnish LH/RH	SCR	✓	
3038	994219	Side Fairing Inner Garnish	SCR	✓	
3039	991118	Fairing Shield	SCR	✓	
3040	992047	Front Top Fairing Inner Garnish LH	SCR	✓	
3041	991123	Fairing Top Garnish			
3042	990538	Center Fairing	BR	✓	
3043	993378	Rear Fairing	BR	✓	
3044	991121	Fairing Stopper			
3045	991117	Fairing Lower			
		FOG LIGHT LH/RH	BR	✓	2
		GPS CONTROL	BR	✓	1
		DIR INDICATOR	BR	✓	
		FOG LIGHT BOLT SOCKET			

NAC	INC	Item	CON	AC	Qty
1052	995074	Radiator LH			
1053	992738	Radiator COVER	SCR	✓	
3046	994146	Seat Assy			
3047	990915	Engine Crash Bar	BT	✓	
3048	990928	Engine Guard RH/LH	BT	✓	2
1067	990219	CRASH BAR PROTECTOR	BT	✓	2
1068	990224	HEAD COVER BOLT SOCKET			3
1069	990223	HEAD COVER COIL COVER			2
3049	991144				
3050	991154	Front Foot Rest RH/LH	DIS	✓	2
3051	991779	Front Foot Rest Bracket			
3052	994269	Side Stand			
3053	992549	Main Stand			
3054	990615	SIDE STAND STANDER (GARNISH)			
3055	992478	11 STANDER			
3056	992477	11 BOLT SOCKET			
3057	991145	Foot Gear Shifter			
3058	993500	Rear Foot Rest LH/RH	CUT	✓	2
3059	993501	Rear Foot Rest Bracket RUBBER			
3060	992581	Exhaust Muffler Heat Shield	BT	✓	
3061	991058	Exhaust Muffler Assy	BT	✓	
1405	993719	CYLINDER HEAD GASKET	CUT	✓	2
1445	993720	HEAD GASKET COVER			
3062	995065	CRANKCASE VALVE PROTECTOR	CUT	✓	
3063	991200	Rear Rim	DIS	✓	
3064	994872	OIL PAN GUARD			
3065	993474	11 WING GUARD			
3066	993443				
3067	992940	Rear Brake Disc			
3068	992936	Rear Brake Caliper PROTECTOR			
3069	995236	RUBBER COVER BOX			
3070	990585	11 11 COBRA			
3071	990580	RUBBER SHOCK SPRING			
3072	994530				
1420	993819				
3073	995245				
3074	995246				
3075	995251	SUB FRAME			
1137	993626	Rear Number Plate			
3076	994192	Side Box LH/RH	BR	✓	2
3077	992927	Rear Box TOP	BR	✓	1
3078	992928	Rear Box Bracket TOP	BT	✓	1
3079	991328	SIDE BOX BRACKET	BT	✓	2
1136	990247	EMBLEM	MAC	✓	
		SIDE BOX BRACKET COVER	CUT	✓	2 RH

No of Items:

Assessor:

- (1) FRONT FORK COMP (RH / LH) ✓
 (2) FRONT MUDGUARD ✓
 (3) FRONT BRAKE DISCS (RH / LH) ✓
 (4) FRONT (RIM) WHEEL COMP ✓
 (5) FRONT TYER 120-70-19 ✓
 (6) FRONT FORK UNDER BRACKET ✓
 (7) FRONT BRAKE CALIPER SUB ASSY (RH-LH) ^{BREMBO} ✓
 (8) FRONT AXLE ✓
 (9) FRONT WHEEL BEARING 2PCS ✓
 (10) FRONT WHEEL OIL SEAL 2PCS ✓
 (11) FRONT AXLE BOLT 1PCS ✓
 (12) FRONT BRAKE DISCS BOLT 10PCS ✓
 (13) ~~WINDSHIELD~~ ✓
 (14) WIND SHIELD COVER (LH) }
 (15) HEAD LAMP STAY ✓
 (16) FRONT COWING BRACKET (LH) ^{FAIRING} ✓
 (18) FRONT COWING (LH / RH) ^{FAIRING} ✓
 (19) FRONT COWING MARK (R1200) (LH / RH) ^{FAIRING} ✓
 (20) FRONT CENTER COVER ^{FAIRING} ✓
 (21) FRONT UPPER COVER (LH) ^{FAIRING} ✓
 (22) FRONT ~~SIGNAL~~ SIGNAL LIGHT (LH) ✓
 (23) FRONT UPPER SIDE AIR GUARD (LH) ^{FAIRING} ✓

FBJ
 8578

BMW 1200A
LC

- (24) HANDIE BAR ✓
- (25) HAND GUARD ✓
- (26) MASTER PUMP ASSY BRAKE ✓
- (27) MASTER PUMP ASS CLUTCH ✓
- (28) BRAKE LEVER ✓
- (29) CLUTCH LEVER ✓
- (30) MIRROR (LH - RH) ✓
- (31) MIRROR BOLT (LH) ✓
- (32) MIRROR RUBBER (LH - RH) ✓
- (33) ERP ✓
- (34) ERP BRACKET ✓
- (35) HANDIE GRIP (RH - LH) ✓
- (36) GPS CONTROL ✓
- (37) SWITCH (LH) ✓
- (38) HANDIE BAR BRACKET ✓
- (39) ~~HANDIE BAR~~ CON BEARING ✓
- (40) ~~AIR~~ AIR INTER (LH) ✓
- (41) FRONT AIR INTER SIDE COVER (RH / LH) ✓
- (42) ~~SIDE COVER~~ SIDE BMW MARK (LH / RH) ✓ *FAIRING*
- (43) RADIATOR (LH) ✓ *EXHAUST*
- (44) FUEL TANK SIDE COVER (LH / RH) ✓
- (45) METER COMP ✓

- (46) CRASH BAR ✓
- (47) CRASH BAR BRACKET (RH/LH) ✓
- (48) ENGINE GUARD (RH/LH) ✓
- (49) CYLINDER HEAD / Exhaust ✓
- (50) CYLINDER HEAD GASKET / Exhaust ✓
- (51) HEAD ^{Cylinder} COVER (RH/LH) Fairing Side ✓
- (52) HEAD COVER GASKET (RH/LH) Fairing ✓
- (53) HEAD COVER BOLT SOCKET 3PCS ✓
- (54) IGNITION COIL COVER (RH/LH) ✓
- (55) ~~HEAD COVER~~ Cylinder Head ~~Cover~~ Protector ✓
- (56) FOG LIGHT (RH/LH) ✓
- (57) FOG LIGHT BOLT SOCKET (2PCS RH/LH) ✓
- (58) FRONT MANIFOLD COMP EXHAUST ✓
- (59) FRONT GASKET EX PIPE 2PCS ✓
- (60) BODY COMP MUFFLER (AKRAPOVIC) ✓
- (61) OIL PIN GUARD ✓
- (62) OIL PIN GUARD BRACKET ✓
- (63) SIDE STAND ✓
- (64) SIDE STAND SENSOR GUARD ✓
- (65) SIDE STAND SENSOR ✓
- (66) SIDE STAND BOLT SOCKET ✓

- (67) CENTER STAND ✓
- (68) GEAR LEVER ✓
- (69) BRAKE PEDDLE ✓
- (70) FRONT FOOTREST (RH/LH) ✓
- (71) REAR FOOTREST (RH/LH) ✓
- (72) REAR FOOTREST BRACKET (RH/LH) ✓
- (73) REAR FOOTREST RUBBER (RH/LH) ✓
- (74) SIDE BOX BRACKET (RH/LH) COMP ✓
- (75) TOP BOX BRACKET ✓
- (76) SIDE BOX (RH/LH) COMP ✓
- (77) TOP BOX ✓
- (78) SIDE BOX BRACKET COVER (RH 2PCS)
- (79) TAIL COVER BACK ✓ *FORWARD*
- (80) REAR GEAR BOX COMP ✓
- (81) REAR GEAR BOX COVER ✓
- (81) SIDE CENTER COVER (LH) ✓
- (82) REAR SHOCK SPRING SIDE COVER (LH) ✓
- (83) REAR FRAME COMP RR ✓
- (84) REAR GUARD RR ✓

(85) RADIATOR COVER LH ✓

~~(86) ENGINE OIL LL ?~~

~~(87) GEAR OIL ?~~

~~(88) COOLANT ?~~

~~(89) LABOUR FEE ?~~

89) RADAR RIM ✓ ~~170 60.17~~

Claim Handling

Accident MT/0984830

Policy No.	5097254583	Vehicle No.	FB38578X	GST Registration No.	
Policyholder Name	ALIF DANIAL BIN BORHAN			Policyholder NRIC	59309675D
Product Code	MOTORCYCLE INSURANCE	Cover Type	Comprehensive	Loading	0
Contact No.(Mobile)	90667456	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No *
KFR	☐ No ☒ Yes	TCA	☐ No ☒ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No

Accident Details

Report Date	06/03/2018 10:02	Accident Report Within 24 hrs	No	Accident Type	No collision
Date of Accident	01/03/2018	Time of Accident hh:mm	17:00	Country of Accident	Outside Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTRE	Orange Force	No	ICM No.	
Accident Location	NEAR TO PEDAS TOLL PLAZA MALAYSIA				

Benefits

Excess

Own damage Excess	1,000.00	Additional Excess		Windscreen Excess	
Unnamed Driver Excess		Outside Singapore OD Excess			
Third Party Excess	0.00	Outside Singapore TP Excess			

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	BLK 316A #06-303	Address 2	ANG MO KIO STREET 31	Address 3	TECK GHEE VISTA
Address 4	SINGAPORE 562316	Address Type	Singapore address	Post Code	562316
Unit No.	06-303	Related Policy Number	5097354683		

OI Driver Info

Driver Name	ALIF DANIAL BIN BORHAN	Driver Type	Main Driver	Driver DOB	19/03/1993
Unnamed driver Name		Driver NRIC	59309675D	Driving Experience	0
Register Date of Driver License	27/01/2018	Driver Age	24	Contact No.(Home)	
Contact No.(Mobile)	90667456	Contact No.(Office)		Address 3	TECK GHEE VISTA
Address 1	BLK 316A #06-303	Address 2	ANG MO KIO STREET 31	Post Code	562316
Address 4	SINGAPORE 562316	Address Type	Singapore address		
Unit No.	06-303				
Does he own a Singapore Registered car?	Yes ☒ No ☐	Driver Vehicle No.	FB38578X	Driver Insurer Company	NTUC

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
Modification History	06/03/2018 11:16 s018940 Modify Register Date of Driver License(07/01/2012-->27/01/2018) 06/03/2018 11:16 s018940 Modify Driving Experience(6-->0) 06/03/2018 11:16 s018940 Modify Contact No(Mobile)(-->90667456)		

Investigation

Claim 001 OD-MD

Claim Case Officer Ng Hak Joo

Claim Type	OD-MD	Insured Name	ALIF DANIAL BIN BORHAN	Insured NRIC	59309675D
Contact No.(Mobile)	90667456	Contact No.(Home)		Contact No.(Office)	
Email Address		OI Vehicle Number	FB38578X	TP Vehicle Number	-
Claim Description	FB38578X / - ON 1 Mar 2018			Name of Preferred Workshop	I-MOTORING
Preferred Workshop Contact No.	63161611(SALLY)	Insured Liability	Not at Fault	GIA report	Pending
Require Finalization	Yes	Preferred Repair Option	Preferred Workshop (refer below)	Date Received	15/03/2018 15:27
Date Registered	06/03/2018 10:41	Claim Close Date		Total Loss but Repaired	
Report Taken By	RDSLI WAHAB	Workshop Repairer			

Print AK letter

Modification History

Special Claim Creation Approval

Approval	Reason
Remarks	

damage assessment

Attachment

Vehicle Info

Vehicle Make	Vehicle Model	Engine Capacity
--------------	---------------	-----------------

BMW		R 1200 GS ADVENTURE	
Date of Registration	29/11/2014	Class No.	WB10A0200E2209096
Towing Required *	☐ Yes ☒ No	Vehicle in IDAC *	☐ Yes ☒ No
Type of Tender *	Own Damage	Assessor Name *	ROSLI WAHAB
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA
Windscreen Parts & Labour Cost		Total Loss *	☐ Yes ☒ No
Market Value(\$)		Scrap Value(\$)	
		Economical Repair Value(\$)	

Remark: 1) FRONT MUDGUARD-1 REPLACE,2)FRONT TYRE-1 REPLACE,3)FRONT AND REAR TYRE RIM-2 REPLACE,4)FORK ASSY-2 REPLACE,5)FRONT HEADLAMP STAY-1 UNCONFIRM,6)FUEL TANK SIDE COVER-2 REPLACE,7)HANDLE BAR HAND GUARD-2 REPLACE,8)GPS CONTROL-1-REPLACE,9)FOG LIGHT BOLT SOCKET-1 UNCONFIRM,10)RADIATOR L/H AND COVER-1 UNCONFIRM AND 1 REPLACE,11)SIDE STAND SENSOR GUARD-1 UNCONFIRM,12)SIDE STAND SENSOR-1 UNCONFIRM,13)SIDE STAND BOLT SOCKET-1 UNCONFIRM,14)MAIN STAND-1 UNCONFIRM,15)FRONT AND REAR FOOT REST RH/LH-2 REPLACE,16)REAR BRAKE PEDDLE-1 REPLACE,17)RH SIDE BOX BRACKET COVER-2 REPLACE,18)FRONT AXLE BOLT-1 REPLACE,19)HEADLAMP STAY-1 UNCONFIRM,20)FRONT BRAKE DISC BOLT-10 REPLACE,21)LH/RH MIRROR RUBBER-1 UNCONFIRM,22)HEAD COVER BOLT SOCKET-3 REPLACE,23)LH/RH IGNITION COIL COVER- 1 REPLACE,24)CYLINDER HEAD PROTECTOR-1 REPLACE,25)OIL PIN GUARD AND GASKET-1 UNCONFIRM,26)REAR GEAR BOX AND COVER - 1 UNCONFIRM,27)REAR GUARD RR-1 UNCONFIRM.

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
root	1	15700801	BRAKE CALIPER (FRONT LEFT)	1	Replace	X
Not Applicable	2	15700802	BRAKE CALIPER (FRONT RIGHT)	1	Replace	X
ABS	3	15701101	BRAKE DISC (FRONT LEFT)	1	Replace	X
ABSORBER	4	15701102	BRAKE DISC (FRONT RIGHT)	1	Replace	X
ACCELERATOR	5	452001	WINDSCREEN SHIELD (M/C)	1	Replace	X
ACTUATOR	6	452003	WINDSCREEN SHIELD (M/C) COWLING	1	Replace	X
ADVERTISEMENT STICKER	7	45300101	WING MIRROR (LEFT)	1	Replace	X
	8	45300102	WING MIRROR (RIGHT)	1	Replace	X
	9	317008	MIRROR HOLDER	1	Replace	X
	10	386001	SIGNAL (M/C) LAMP	1	Replace	X
	11	316001	METER (M/C)	1	Replace	X
	12	245001	ERP BRACKET	1	Replace	X
	13	245002	ERP UNIT	1	Unconfirm	X
	14	27400101	HANDLE BAR (M/C) (FRONT)	1	Unconfirm	X
	15	27400401	HANDLE BAR (M/C) BRACKET (FRONT)	1	Unconfirm	X
	16	27400601	HANDLE BAR (M/C) GRIP (FRONT)	2	Replace	X
	17	278005	HEAD LAMP (M/C) SWITCH	1	Unconfirm	X
	18	15701602	BRAKE MASTER PUMP (FRONT RIGHT)	1	Replace	X
	19	159004	BRAKE (M/C) LEVER	1	Replace	X
	20	201001	CLUTCH (M/C) RESERVOIR	1	Unconfirm	X
	21	209011	CLUTCH LEVER	1	Unconfirm	X
	22	25200101	FAIRING (BOTTOM)	2	Replace	X
	23	25200102	FAIRING (CENTRE)	1	Replace	X
	24	25200103	FAIRING (FRONT)	2	Replace	X
	25	25200104	FAIRING (LEFT)	1	Replace	X
	26	25200106	FAIRING (RIGHT)	1	Replace	X
	27	25200107	FAIRING (TOP)	2	Replace	X
	28	25200105	FAIRING (REAR)	1	Replace	X
	29	120001	AIR INTAKE RESONATOR	1	Replace	X
	30	25700101	FOG LAMP (LEFT)	1	Replace	X
	31	25700102	FOG LAMP (RIGHT)	1	Replace	X
	32	220001	CRASH BAR (M/C)	2	Replace	X
	33	244002	ENGINE (M/C) GUARD	2	Replace	X
	34	3840	SIDE STAND	1	Replace	X
	35	261002	FOOT REST (M/C) BRACKET	1	Unconfirm	X
	36	26100403	FOOT REST (M/C) RUBBER (REAR LEFT)	1	Unconfirm	X
	37	26100404	FOOT REST (M/C) RUBBER (REAR RIGHT)	1	Unconfirm	X
	38	225002	CYLINDER HEAD	1	Replace	X
	39	225004	CYLINDER HEAD GASKET	1	Replace	X
	40	407001	SUB FRAME	1	Replace	X
	41	15100101	BOX (M/C) (LEFT)	1	Replace	X
	42	15100102	BOX (M/C) (REAR)	1	Replace	X
	43	225003	CYLINDER HEAD COVER	2	Replace	X
	44	15100103	BOX (M/C) (RIGHT)	1	Replace	X
	45	1520	BOX BRACKET (M/C)	3	Replace	X
	46	24200101	EMBLEM (FRONT)	4	Replace	X
	47	4490	WHEEL AXLE (M/C)	1	Replace	X
	48	448012	WHEEL HUB OIL SEAL	2	Replace	X
	49	44800501	WHEEL BEARING (FRONT LEFT)	1	Replace	X

SO	44800502	WHEEL BEARING (FRONT RIGHT)	1	Replace	X
		Save	Submit		

ACCIDENT STATEMENT

ACCIDENT DATE: 01 / 03 / 2018 (DD/MM/YYYY), TIME: 17 : 00 (HH:MM)

LOCATION: Pedas Toll Plaza (Malaysia)

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: FBJ8578X
 b) INSURANCE COMPANY: NTUC
 c) POLICY NUMBER: _____
 d) POLICY TYPE: (COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE & THEFT)
 e) MAKE & MODEL: BMW GS1200R Adventure
 f) TYPE: (SALOON / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS)
 g) VEHICLE CATEGORY: (PRIVATE / COMMERCIAL / MOTORCYCLE)
 h) PURPOSE OF USING AT ACCIDENT TIME: Touring
 i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)
 IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

2. INSURED / POLICY HOLDER

- a) NAME: Aliif Dantal Bin Burhan (MALE / FEMALE)
 b) NRIC/FIN/PASSPORT: 593096750 CONTACT: 90867456
 c) ADDRESS: Block 316A, Ang Mo Kio Street 31, #06-303, Singapore 562316

* CONTINUE TO 3, d IF DRIVER ALSO POLICY HOLDER

No of passenger
 (including driver)
 ()

- DRIVER
 a) NAME: _____ (MALE / FEMALE)
 b) NRIC/FIN/PASSPORT: _____ CONTACT: _____
 c) ADDRESS: _____

* d) DATE OF BIRTH: 19 / 03 / 1993 (DD/MM/YYYY)

e) OCCUPATION: (INDOOR / OUTDOOR)

f) DATE OF DRIVING PASS

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)
 IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED: _____

5. a) WEATHER CONDITION: (CLEAR / RAINING / OTHERS)
 b) ROAD SURFACE: (DRY / WET / OTHERS) A lot of foreign particles

6. WAS ANYBODY INJURED (YES / NO)

7. a) REPORTED TO POLICE (YES / NO)
 IF YES, PLEASE STATE WHICH POLICE STATION: Teck Ghee NIP

8. THIRD PARTY VEHICLE

No of passenger
 (including driver)
 ()

- a) VEHICLE NUMBER: _____ MODEL: _____
 b) DRIVER'S NAME: _____ CONTACT: _____
 c) NRIC/FIN/PASSPORT: _____

9. THIRD PARTY VEHICLE



No of passenger
 (including driver)
 ()

- d) VEHICLE NUMBER: _____ MODEL: _____
 e) DRIVER'S NAME: _____ CONTACT: _____
 f) NRIC/FIN/PASSPORT: _____

Email = Aliif_dantal@hotmail.sg

Fax =

✓ 1000



eBaoTech

General Claim

Hello, NAC_BUKIT_MERAH_800676

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No. (For Motor)

[Search](#)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5097354663	ALIF DANIAL BIN BORHAN	S93096750	GMC	Comprehensive	FBJ8578X	FBJ8578X	12/01/2018	11/01/2019

[Continue](#)