

22/03/2002

ASS. REC. BY:

REFCS/ASM18004263/M1/d3ST

Special Instruction:

Surveyor:

MA

ASSIGNMENT (Office)

From (Person):

Kitty Teo

of

ASM

Date/Time:

5/3/18 03:22pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV7CS

To Inspect Vehicle No:

SKC 3880K

Insured:

at Workshop m/s

S & H Motor

Tel:

6453 4730

of

160 Sin Ming Drive # 07-02

Policy No:

Claim No:

88M00855

Sum Insured:

Excess:

\$500.00

Make of Veh:

D.O.A.

09/02/18

(Client's Record)

2:30pm - 3pm

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:20am 6/3/16

Person Contacted:

Cynthia

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

7/3-

SKC 3880K-X

Revert via ASM.

lump sum \$4100/- (Red: 3222 : 4490)

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKC 3880K Yr Reg: SEP 2009.Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volvo C30 cc 1999Colour: Black A/C Insured / Std / NI / NASp. Reading: 80789 T/Radio: Insured / Std / NI / NA

Eng No: _____

C No: YVIMK 4343A 2174290Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / STD A/Rim orTyre Size: F: 225/45/R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MIC

Front

Rear

R/Bal: 7 mm R/Bal: 7 mmL/Bal: 7 mm L/Bal: 7 mmD.O.A. 09/02/2018 D.O.I. 6/3/2018

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orFRT NS

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

RECEIVED 13 JUL 2018

Date/Time: File Pass to:



Preli. Report



Final Report

Date/Time: File Return to:

Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

3-4 RI \$

Photos:

Chassis

Add Fee:



Site Insp: \$



Interview: \$



Tech. Insp: \$



Weekend: \$

Report Format:

Lump Sum / I.B.I. / S

ON
4100

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18004263/M1td3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 06-03-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SKC 3880K
Policy No.	Coverage (\$)	0.00
Claim No. S8M008S5	Excess (\$)	500.00
Assign From SMARTCLAIM (KITTY TEO)	Assign Date	06/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	09/02/2018	Inspection Date	06/03/2018
Survey held at	S & H MOTOR PTE LTD 160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Denise Tay (LKKAuto)

From: Doris <doris@sh-motor.com>
Sent: Friday, 13 July 2018 2:22 PM
To: Denise Tay (LKKAuto)
Subject: RE: vehicle no : SKC3880K-Final

Dear Denise

Noted...Thank.. lump sum cost S\$4,100.00

Thank

Doris

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Monday, 9 July 2018 3:12 PM
To: 'Doris'
Subject: RE: vehicle no : SKC3880K-Final

Dear Doris,

Can confirm?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Thursday, 5 July 2018 3:32 PM
To: Doris <doris@sh-motor.com>
Subject: RE: vehicle no : SKC3880K-Final

Dear Doris,

Offer lump sum \$4,100/- , 4days.

Please confirm

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Service Request Details

Claim

S8M008S5

Reference

None 

Loss Date

February 9, 2018

Request Date

March 5, 2018

Due Date

March 12, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKC3880K

Make

VOLVO

Service Address

160 Sin Ming Drive #07-02, . . 575722

Primary Contact/Insured

LEE MEI SABRINA (LI MEI)
227 BISHAN STREET 23, #03-85, 570227, Singapore
96588411

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Additional Instructions
EXCESS \$500

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Nivitha (LKK Auto)

From: Enquiry <enquiry@sh-motor.com>
Sent: Monday, 5 March 2018 3:22 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: FW: Arrange Survey SKC3880K DOA: 09.02.2018
Attachments: Estimate & GIA.PDF

Categories: Shailendra

Forward...

Thank you & Best Regards,

Cynthia

S&H MOTOR PTE LTD

160 Sin Ming Drive #07-02
Sing Ming AutoCity Singapore 575722
Tel: 6453 4730 Fax: 64571931

From: Enquiry [mailto:enquiry@sh-motor.com]
Sent: Wednesday, 28 February 2018 4:55 PM
To: 'motor.survey@axa.com.sg'
Subject: Arrange Survey SKC3880K DOA: 09.02.2018

Dear Sir/Mdm,

Kindly arrange survey for our vehicle SKC3880K DOA: 09.02.2018 (Own Damage)

Thank you & Best Regards,

Cynthia

S&H MOTOR PTE LTD

160 Sin Ming Drive #07-02
Sing Ming AutoCity Singapore 575722
Tel: 6453 4730 Fax: 64571931



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S8M008S5

Our Ref: CS/ASM18004263/M1td3

Date: 7/3/2018

The Motor Claims Department
M/s AXA Insurance Singapore Pte Ltd

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO SKC 3880K

We thank you for the instruction on 5/3/2018

Please be informed that we had conducted the inspection of the abovementioned vehicle on 6/3/2018 at the premises of M/s S & H and have the following to report: -

Workshop Estimate Amount	: S\$ <u>7,322.00</u>
Revised Estimate Amount	: S\$ <u>5,177.00</u>
"Check" Items Amount	: S\$ <u>125.00</u>
Total	: S\$ <u>5,302.00</u>
Market Value	: S\$ <u>28,000.00</u>
LTA Reimbursement Value	: S\$ <u>19,611.00</u>
Nett Value	: S\$ <u>8,389.00</u>

Description of Damage:

The vehicle sustained damages at the n/s front portion.

Comments/ Present Status:

Damages Consistent


Repair cost economical

We have authorized repair @ 6/3/2018 at 4PM

Days of repair: 4

Yours Faithfully,

Ma CF
Automotive Assessor





SERVICE REQUESTS

MESSAGES

CLAIMS



IA UPLOADED SKC 3880K

Type

🔔 Question

Message

Revised Estimate Amount : S\$ 5,177.00 "Check" Items Amount : S\$ _ 125.00 Total : S\$ _ 5,302.00 Market Value : S\$ 28,000.00 LTA

Reimbursement Value : S\$ 19,611.00 Nett Value : S\$ _8,389.00

[Reply](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/02/2018 14:52
Date Of Accident	09/02/2018 19:00
Exact Location Of Accident	ALONG BISHAN STREET 22 TOWARDS SIN MING AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC3880K
Insured/Policyholder	
Name Of Registered Owner	LEE MEI SABRINA
NRIC No	S8218506B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96588411
Alternative Phone No	OFFICE-96588411

Vehicle Particulars

Manufacturer	VOLVO
Model	-

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA260235/1
Cover Note Number	

Driver

Name of Driver	LEE MEI SABRINA
NRIC No	S8218506B
Date Of Birth	01/07/1982
Occupation	INDOOR
Date Of Driving Pass	01/03/2011
Driving Experience	6 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96588411
Fax Number	
Contact Number	OFFICE-96588411
Email Address	NOEMAIL

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire Transfer Fee

Vehicle Details

Vehicle No.: SKC3880K

Vehicle Type: P10 - Passenger Motor Car

Vehicle Attachment
1: No Attachment

Vehicle Scheme: Normal

Vehicle Make: VOLVO

Vehicle Model: C30 2.0L AT ABD D/AB 2WD 3DR

Chassis No.: YV1MK434BA2174290

Propellant: Petrol

Engine No.: B4204S3170416

Engine Capacity: 1999 cc

Maximum Power
Output: 107.0 kW (143 bhp)

Maximum Laden
Weight: 1770 kg

Unladen Weight: 1371 kg

Year Of
Manufacture: 2009

Original
Registration Date: 28 Sep 2009

Lifespan Expiry
Date: -

COE Category: E - Open Category

Quota Premium: \$18,189.00

COE Expiry Date: 27 Sep 2019

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8506B
Vehicle Details	
Vehicle No.:	SKC3880K
Vehicle to be Exported:	No
Intended De-registration Date:	07 Mar 2018
Vehicle Make:	VOLVO
Vehicle Model:	C30 2.0L AT ABD D/AB 2WD 3DR
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	B4204S3170416
Chassis No.:	YV1MK434BA2174290
Maximum Power Output:	107.0 kW (143 bhp)
Open Market Value:	\$30,514.00
Original Registration Date:	28 Sep 2009
First Registration Date:	28 Sep 2009
Transfer Count:	2
Actual ARF Paid:	\$30,514.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Sep 2019
PARF Rebate Amount:	\$16,782.00
Intended COE Rebate Details	
COE Expiry Date:	27 Sep 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$18,189.00
COE Rebate Amount:	\$2,829.00
Total Rebate Amount:	\$19,611.00

The information contained herein is correct as at 07 Mar 2018

OK

The Motor Claims Department
AXA INSURANCE PTE LTD
 BLK 8 #24-01
 SHENTON WAY
 AXA TOWER
 SINGAPORE 068811

File No :
 Date : 13-February-2018

Estimated cost of repair for vehicle no: **SKC3880K VOLVO C30 2.0L**
 Policy no.: **GA260235/1** Accident Date: **09-February-2018**

Description	Quantity	Cost Price
Front Bumper	1 <i>dash</i>	✓ 1,850.00
LH bumper retainer	1 <i>dash</i>	✓ 70.00
LH head lamp	1 <i>dash</i>	✓ 1,062.00
LH head lamp bottom bumper beam	1 <i>dash</i>	✓ 125.00 <i>X-m</i>
LH front fender	1 <i>dash</i>	✓ 810.00
LH front fender wheel garnish	1 <i>dash</i>	✓ 190.00
LH front fender wheel cowling	1 <i>dash</i>	✓ 325.00
Wheel cowling clips @ 1 set	1 <i>dash</i>	✓ 40.00
LH front alloy wheel	1 <i>dash</i>	✓ 1,550.00
To spray painting LH front door fender and bumper	1	\$ <i>400</i> 650.00
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp.	1	\$ <i>30</i> 35.00
TO check steering and reset wheel steering alignment	1	\$ <i>X</i> 65.00
Labour to remove damaged parts, jack out LH head lamp, inner panel, LH front fender, inner panel, bumper reinforcement, repair and panel beating, adjust body door, bumper alignment	1	\$ <i>400</i> 550.00

S 7,322.00

Revert -
PP. to Repair.
After paint done Before paint
WKK Auto (M)
6/8/2018
4-5 days
[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



The Motor Claims Department
AXA INSURANCE PTE LTD
BLK 8 #24-01
SHENTON WAY
AXA TOWER
SINGAPORE 068811

File No :
Date : 13-February-2018

Estimated cost of repair for vehicle no: ~~SKC3880K~~ VOLVO C30 2.0L
Policy no.: GA260235/1 Accident Date: 09-February-2018

Description	Quantity	Cost Price
Front Bumper	1 <i>def</i>	<i>s</i> ✓ 1,850.00
LH bumper retainer	1 <i>def</i>	<i>s</i> ✓ 70.00
LH head lamp	1 <i>over</i>	<i>s</i> ✓ 1,062.00
LH head lamp bottom bumper beam	1	<i>s</i> 2 125.00
LH front fender	1 <i>def</i>	<i>s</i> ✓ 810.00
LH front fender wheel garnish	1	<i>cust</i> <i>s</i> ✓ 190.00
LH front fender wheel cowling	1	<i>s</i> 2 325.00
Wheel cowling clips @ 1 set	1	<i>dis</i> <i>s</i> ✓ 40.00
LH front alloy wheel	1	<i>hms</i> <i>s</i> X 1,550.00
To spray painting LH front door fender and bumper	1	<i>s</i> for 650.00
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp.	1	<i>s</i> 30 35.00
TO check steering and reset wheel steering alignment	1	<i>s</i> X 65.00
Labour to remove damaged parts, jack out LH head lamp, inner panel, LH front fender, inner panel, bumper reinforcement, repair and panel beating, adjust body door, bumper alignment	1	<i>s</i> for 550.00
		<u><u>S 7,322.00</u></u>

Report
LH Repair
After Paint Done
Wok Auto (MA)
6/8/2018
3w days

SERVICE REQUESTS

MESSAGES

CLAIMS

<<

Service Request Details

Claim	S8M008S5	Vehicle Information	
Reference		Incident Vehicle	SKC3880K
None 	Loss Date	Registration #	Service Address
February 9, 2018	Request Date	Model	VOLVO C30 2.0
March 5, 2018	Due Date		160 Sin
June 6, 2018	Vendor Name		Ming Drive #07-02, , ,
LKK AUTO CONSULTANTS PTE LOSS LTD (OD)	Type of	575722	
Own Damage	Services	Primary Contact/Insured	
		LEE MEI SABRINA (LI MEI)	
		227 BISHAN STREET 23, #03-85,	
		570227, Singapore	
		96588411	

Actions

Next Step

PAST DUE: Report that your block modify the Expected Completion Date.

Complete Work More

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
RESURVEY1.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	July 13, 2018
PRELI ADVISED SKC 3880K.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	March 7, 2018
EMAIL.msg	Forms / Claim Documents	Others	KUMAR Shailendra	March 5, 2018
GIA SBS8482R TP.PDF	Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	March 1, 2018
EMAIJL ATTACHED GIA & ESTIMATE INSD (OD).msg	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	March 1, 2018

SERVICE REQUESTS

MESSAGES

CLAIMS



Service Request Details

Claim	S8M008S5	Vehicle Information	
None	Reference	Incident Vehicle	SKC3880K
		Registration #	SKC3880K
		Make	VOLVO
		Model	C30 2.0
February 9, 2018	Request Date	Expected Completion Date	160 Sin
March 5, 2018	Due Date		Ming Drive #07-02, , ,
June 6, 2018	Vendor Name		575722
LKK AUTO CONSULTANTS PTE LOSS LTD (OD)	Type of	Primary Contact/Insured	
		LEE MEI SABRINA (LI MEI)	
		227 BISHAN STREET 23, #03-85,	
		570227, Singapore	
		96588411	
Own Damage	Services		

Actions

Next Step

PAST DUE: Report that your past due block modify the

Complete Work More



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2009 VOLVO C30 2.0 (SKC3880K)

Date of Loss

February 9, 2018

Time of Loss

19.00

Loss Description

SKC3880K (INSD) C/W SBS8482R (TP)

Comment

Workshop Details

Total Rebate Amount

19611

Nett Loss Amount

\$8,389.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

03/12/2018

Days of work completion *

7



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SKC3880K

Purchase Date

mm/dd/yyyy



Registration State

SINGAPORE

Registration Date *

09/28/2009



Mileage

80789

Age of Vehicle

8

CATEGORY

Manufacturing Year

Driver Details

POLICY INFORMAT ... 2009

CATEGORY Driver Name

ASSESSMENT INFO...

2009

FNOL INFORMATI... LEE MEI SABRINA (LI MEI)

POST SURVEY INF...

ASSESSMENT INFO... YV1MK434BA2174290

CATEGORY Engine No
POLICY INFORMAT... B4204S3170416
ASSESSMENT INFO... B4204S3170416

CATEGORY Engine Capacity
POLICY INFORMAT...
ASSESSMENT INFO... 1999 cc

CATEGORY Sum Insured
POLICY INFORMAT... 0
ASSESSMENT INFO... 0

CATEGORY Market Value
POLICY INFORMAT... 0
ASSESSMENT INFO... 28000

FNOL INFORMATI... 7

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Address

POST SURVEY INF...

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Front left side

MICHELIN 7mm

Front right side

MICHELIN 7mm

Rear left side

MICHELIN 7mm

Rear right side

MICHELIN 7mm

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details			Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	Parts				
EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART
	1	1			FRONT BUMPER			Deformed	1850				1850	Reve
	2	1			LH BUMPER RETAINER			Damaged	70				70	Reve
	3	1			LH HEAD LAMP			Cracked	1062				1062	Reve
	4	1			LH HEAD LAMP BOTTOM BUMPER BEAM			Serviceable	0				0	Reve
	5	1			LH FRONT FENDER			Dented	810				810	Reve
	6	1			LH FRONT FENDER WHEEL GARNISH			Cut	190				190	Reve
	7	1			LH FRONT FENDER WHEEL COWLING			Damaged	325				325	Reve
	8	1			SET WHEEL COWLING CLIPS			Necessary	40				40	Reve

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary EDIT SR NO NAME ACTION AMOUNT COMMENT REMOVE

☐		1	DAYS OF REPAIR	Reviewing	4		
--------------------------	---	---	----------------	-----------	---	--	---

SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary	Claim Amount	\$5,177.00	Claim Amount	\$5,177.00	

CATEGORY	ESTIMATE	REVISED AMOUNT
----------	----------	----------------

Labour	\$830.00	\$830.00
--------	----------	----------

Spare Parts	\$4,347.00	\$4,347.00
-------------	------------	------------

Submit for Review

SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
------	-------	------	--------	--------	---------	--------

☐	1	FINAL LUMP SUM	Reviewing	4100		
--------------------------	---	----------------	-----------	------	--	--

SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary	Claim Amount	\$3,600.00	Claim Amount	\$3,600.00	

CATEGORY	ESTIMATE	REVISED AMOUNT
----------	----------	----------------

Miscellaneous	\$4,100.00	\$4,100.00
---------------	------------	------------

Excess	-\$500.00	-\$500.00
--------	-----------	-----------

Submit for Review